

Plant Service Record

Date: 18- V - 2023	Date: 18-V-2023 Fitter's name: 00 M		
Plant Item: COMACCHIO - 405	Plant no.:	R-76	
Hour reading: 912.4			
Description of work carried out		Time taken (hours)	Initials
INVESTIGATE NOT WORKING RC			77
FOUND ISSUE WITH CABLE			
· · · · · · · · · · · · · · · · · · ·			
RE-WIRE RC WITH NEW			
CABLE			171/
Parts/materials used		Quantity	
NEW 20 COR CABLE (16 (IN in USE)			5,5 m
		2/2	
Fitter's comments:			
WIRING DIAGRAMS ARE VERY POOR IN THIS CASE.			
LUCUILY FOUND AND THER ISSUE WHICH WAS			
LUCUIL POUND INVESTIGATION OF THE POUND OF T			
BLOWN FUSE DIFFERENT NUMBER THAN ONE			
ON DIAGRAMS			
Fitter's Signature (work complete)	26	V - 20 2 3	0