268



## WORKS ORDER/INSPECTION RECORD SHEET

mer: Socotec	Date: 14-12-21
ict: Comacchio	Order Ref No: 108569
iption: GEO 205 2979	Engine Hours:

Instructions:		

о.	Task/Operation	Time to complete	Inspected by:
	Wash the rig prior to jobs undertaken. Grease all the grease points on the machine.	1.5	AN
	Fitted the new mist pump with new fittings and directional valve. Test the pump and drain the water.	1.5	AN
	Disconnected the hydraulic hoses and water hoses of the broken belling pump. Removed pump from chassis and fitted new bellin onto the side of the machine. Hosed pump up and fitted new fittings.	2.5	AN
	Removed the swivel of the rotary head. Stripped swivel down and replaced shaft. Bearings and seals.	1.5	AN
	Rebuild existing belling pump ready for work. Replacing various parts in the process.	4	AN
	TOTAL (hours)	11	