

FIELD SERVICE REPORT

R71



PSR - Skis - 606.20

DATE-DAY 13 MONTH 7 YEAR 20	CUSTOMER: Socotec
SERIAL No. 3137 PLANT No. GEO 305	SITE ADDRESS: APPLETREE LANE DAVENTRY NN11 6TN
HOURS ENGINE 1146	
HOURS AIR	
DRILL APPEARANCE GOOD	
DID PROBLEM MAKE RIG INOPERABLE? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	

SPARES USED ON MACHINE

QTY:	PART No.	DESCRIPTION	TIME ARRIVED ON SITE:		MILEAGE:	
			SERVICEMAN'S NAME(S)	HOURS WORKED	OUT	RETURN
1	3-3021-138	FUEL FILTER	[REDACTED]	6		
1	3-3021-139	FUEL FILTER				
1	3-3021-141	INNER AIR FILTER				
1	3-3021-140	OUTER AIR FILTER				
TOTAL						
TOTAL MILEAGE				210	105	105
TRAVELLING TIME					2 Hrs	2 Hrs
TIME LEFT SITE			2.00PM			
SERVICEMAN'S HOME TELEPHONE No.			[REDACTED]			
CAR REG No.			[REDACTED]			

ACCOUNT OF THE TIME SPENT ON SITE AND DETAILS OF REPAIR CARRIED OUT

Investigated Customers Complaint of ENGINE Cutting out monitored MACHINE FOR 6 HOURS NO FAULT FOUND.
 REPAIRED FUEL & AIR FILTERS AS SERVICE WAS OVERDUE

SERVICEMAN'S SIGNATURE

[Signature]

CUSTOMER'S SIGNATURE

[Signature]