

FIELD SERVICE REPORT

8

108657  
£ 298.75



UK LIMITED

DATE-DAY 22 MONTH 11 YEAR 21			CUSTOMER: SOCOTEC			
SERIAL No. 3137		PLANT No. GEO305		SITE ADDRESS:		
HOURS ENGINE 1.909			COVENTRY CV3 2TF			
HOURS AIR						
DRILL APPEARANCE						
DID PROBLEM MAKE RIG INOPERABLE? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>						
SPARES USED ON MACHINE						
TIME ARRIVED ON SITE: 8:00 AM			MILEAGE: 150			
QTY:	PART No.	DESCRIPTION	SERVICEMAN'S NAME(s)	HOURS WORKED	OUT	RETURN
			[REDACTED]	3:15		
			TOTAL	3:15		
			TOTAL MILEAGE		75	75
			TRAVELLING TIME		1:45 Hrs	1:45 Hrs
			TIME LEFT SITE	11:15 AM		
			SERVICEMAN'S HOME TELEPHONE No.	[REDACTED]		
			CAR REG No.	[REDACTED]		

ACCOUNT OF THE TIME SPENT ON SITE AND DETAILS OF REPAIR CARRIED OUT

UNBOLTED THE ALL COVERS OF THE HYDRAULIC VALVES.  
DISCONNECTED THE HYDRAULIC HOSES OF THE DIVERTER VALVE  
FIXED THE VALVE PUT THE HYDRAULIC HOSES BACK TO THE VALVE.  
DO THE WIRE LINE WINCH TEST. ALL OK!  
LIVER OF THE WIRE LINE WINCH WORKING ON CORRECT WAY.

ALL LEFT IN GOOD WORKING AT THE TIME OF INSPECTION

SERVICEMAN'S SIGNATURE

A NOWACKI

CUSTOMER'S SIGNATURE

[Signature]