

⑥ T3132.

CUSTOMER ORDER No.

FIELD SERVICE REPORT



169915
£520.70

DATE-DAY <u>5</u> MONTH <u>4</u> YEAR <u>22</u>	CUSTOMER: <u>SOCOTEC</u>
SERIAL No. <u>3666</u> PLANT No. <u>GEO 305</u>	
HOURS ENGINE <u>958</u>	SITE ADDRESS: <u>COVENTRY</u> <u>CVS 2TF</u>
HOURS AIR	
DRILL APPEARANCE	
DID PROBLEM MAKE RIG INOPERABLE? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	

SPARES USED ON MACHINE

QTY:	PART No.	DESCRIPTION	TIME ARRIVED ON SITE:		MILEAGE:	
1	3.3021.027	ENG. OIL FILTER	11:30 AM		0	
1	3.3021.138	FUEL FILTER				
1	3.3021.139	FUEL FILTER	A. NOWACKI	5:15	OUT	RETURN
1	3.3021.140	AIR FILTER				
1	3.3021.141	AIR FILTER				
1	3.3271.001	HYDR. OIL FILTER				
9L	15W40	ENGINE OIL FILTER	TOTAL	5:15		
6L	80/90	GEAR OIL	TOTAL MILEAGE		0	0
			TRAVELLING TIME		0 Hrs	0 Hrs
			TIME LEFT SITE	4:45 PM		
			SERVICEMAN'S HOME TELEPHONE No.	07774946283		
			CAR REG No.	B621LGL		

ACCOUNT OF THE TIME SPENT ON SITE AND DETAILS OF REPAIR CARRIED OUT

CHECK ALL OVER, DO THE LOCKWAS SERVICE, GREASE ALL GREASE POINTS, TESTED THE WATER PUMPS (SIDEMOND AND M16 PUMP) CHANGED ONE SA FUSE ON THE FUSE BOX.

ALL LEFT IN GOOD WORKING AT THE TIME OF INSPECTION

SERVICEMAN'S SIGNATURE

CUSTOMER'S SIGNATURE