

FIELD SERVICE REPORT

6

108656
£209.10



DATE-DAY 24 MONTH 11 YEAR 21	CUSTOMER: SOCOTEC
SERIAL No. 3666 PLANT No. 6E0305	SITE ADDRESS: AS1 SWINNETON ST15 0QS
HOURS ENGINE 777	
HOURS AIR	
DRILL APPEARANCE	
DID PROBLEM MAKE RIG INOPERABLE? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	

SPARES USED ON MACHINE

QTY:	PART No.	DESCRIPTION	TIME ARRIVED ON SITE: 8:00AM			
			SERVICEMAN'S NAME(S) A. NOWACKI	HOURS WORKED 1	MILEAGE: 140	
					OUT	RETURN
			TOTAL	1		
			TOTAL MILEAGE		70	70
			TRAVELLING TIME		1.5 Hrs	1.5 Hrs
			TIME LEFT SITE			
			SERVICEMAN'S HOME TELEPHONE No.	0777 4946263		
			CAR REG No.	36 21 L6L		

ACCOUNT OF THE TIME SPENT ON SITE AND DETAILS OF REPAIR CARRIED OUT

DISCONNECTED HYDRAULIC HOSES AND FITTINGS OF THE MAST CYLINDER. CLEAN THE FITTINGS AND CHANGED FOUR 3/8" DOWTY WASHER. FITTED BACK ALL THE PARTS AND TESTED. ALL WORKING OK!

TOP PART OF THE MAST HYDRAULIC CYLINDER ~~IS~~ PISTON ARE DAMAGED. (MAKE PICTURE) MAY CAUSE A SMALL LEAK.

ALL LEFT IN GOOD WORKING AT THE TIME OF INSPECTION!

SERVICEMAN'S SIGNATURE

A. NOWACKI

CUSTOMER'S SIGNATURE

John Brown