

# J.H. (Lifting Gear Hire) LTD.

UNIT Q, LONDON ROAD TRADING ESTATE  
SITTINGBOURNE, KENT, ME10 1NQ

Tel: +44 (0)1795 425760 and 472168

Web: [www.jhlifting.co.uk](http://www.jhlifting.co.uk)

E-mail: [info@jhlifting.co.uk](mailto:info@jhlifting.co.uk)



Full Member



Certificate No: 173512020

# REPORT OF THOROUGH EXAMINATION

Customer Order Number T02396		Sales Job No 135774
Date of Examination 17/07/2024	Date of Report 17/07/2024	Report Number 147428

<b>Organisation for whom the thorough examination was made</b> Socotec UK Limited ESG House Bretby Business Park Ashby Road Burton on Trent Kent DN15 0YZ	<b>Location at which the thorough examination was made</b> J.H. (Lifting Gear Hire) Ltd Unit Q London Road Trading Estate Sittingbourne Kent ME10 1NQ
--	---

Qty	Description & Identification of the Equipment	Safe Working Load / Standard	Date of Last Thorough Examination (If Known)
2	30 metres x 10mm dia 7/19 IWRC galvanised RHOL wire rope, thimble eye one end taiturit secured, other end fused and tapered M.B.L. 7233 kg  ID Mark: W24722 to W24723	1446 kg @ 5:1 F.o.S. 2410 kg @ 3:1 F.o.S	

<b>Has this Equipment been...</b> Supplied New Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Supplied Reconditioned Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Examined Only Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Examined & Tested Only Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Examined, Repaired & Tested Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	<b>Was the Examination carried out...</b> Before being issued for the first time Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Within an interval of 6 months Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Within an interval of 12 months Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> As part of an Examination Scheme Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> After Exceptional Circumstances Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
---	---

Identification of any part found to have a defect that could become a danger to persons and a description of the defect. (If none, state NONE)  
 NONE

Is the above a defect which is of immediate danger to persons? Yes  No

If not an immediate danger, when might it become dangerous to persons without rectification? Date: \_\_\_\_\_

Particulars of any repair, renewal or alteration required to remedy the defect identified above

Particulars of any tests carried out as part of the examination. (If none, state NONE)  
 NONE

**IS THIS EQUIPMENT SAFE TO USE / OPERATE?** Yes  No

Person making this report Jason Ashworth Qualifications: LEEA Foundation	Person authenticating this report Roger Oliveira Qualifications: LEEA TEAM Card Signature	Latest date by which next thorough examination must be carried out: 16/01/2025
--	---	---

This equipment was manufactured in accordance with the Machinery Directive, Declaration of Conformity issued and is available to view at our offices on request.

Rope ID W24722 fitted to R74 on 22-07-24 by Daniel Perrett