

5 R75 T3133

CUSTOMER ORDER No.

FIELD SERVICE REPORT



109911  
£813.30

DATE-DAY <u>5</u> MONTH <u>4</u> YEAR <u>22</u>	<b>CUSTOMER:</b> <u>SOCOTEC</u>
SERIAL No. <u>3200</u> PLANT No. <u>GEO 305</u>	
HOURS ENGINE <u>868</u>	
HOURS AIR	
DRILL APPEARANCE	
<b>DID PROBLEM MAKE RIG INOPERABLE?</b> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	<b>SITE ADDRESS:</b> <u>COVENTRY</u> <u>CV32TF</u>

SPARES USED ON MACHINE

QTY:	PART No.	DESCRIPTION	TIME ARRIVED ON SITE:			
1	3.3021.022	ENG. OIL FILTER	8:00AM			
1	3.3021.138	FUEL FILTER	<b>SERVICEMAN'S NAME(s)</b> [REDACTED]	<b>HOURS WORKED</b> 3.5	<b>MILEAGE:</b>	
1	3.3021.139	FUEL FILTER			OUT	RETURN
1	3.3021.140	AIR FILTER				
1	3.3021.141	AIR FILTER				
1	3.3271.046	HYDRAULIC OIL FILTER				
2	2-2102.043	SWIVEL SEALS				
9L	15W40	ENGINE OIL	TOTAL	3.5	70	70
1		JET WASH LANCE	TOTAL MILEAGE		70	70
			TRAVELLING TIME		15 Hrs	15 Hrs
			TIME LEFT SITE	11:30AM		
			SERVICEMAN'S HOME TELEPHONE No.	[REDACTED]		
			CAR REG No.	[REDACTED]		

ACCOUNT OF THE TIME SPENT ON SITE AND DETAILS OF REPAIR CARRIED OUT

TIGHTEN THE SWIVEL SHAFT TO THE SPINDLE  
 CHECK ALL OVER, DO THE 250WS SERVICE, GREASE ALL GREASE POINTS, UNSCREWED ONE BROKEN GREASE NIPPLE AND FITTED NEW ONE. TIGHTEN CORRECT THE SPRING OF THE WINCH ROLLER BAR.  
 FIXED ONE BROKEN FITTING OF THE WINCH AND ONE BROKEN HYDRAULIC HOSE BY THE SOCOTEC FILTER  
 TESTED THE WATER PUMP (SIDE MOUNT AND MISS PUMP)  
 FITTED NEW JET WASH LANCE.  
 LEFT TWO SWIVEL RUBBER O-RING SEALS FOR THE RIG.  
 ALL LEFT IN GOOD WORKING AT THE TIME OF INSPECTION

SERVICEMAN'S SIGNATURE

CUSTOMER'S SIGNATURE