

5 R75 T3133

CUSTOMER ORDER No.

FIELD SERVICE REPORT

109911  
£813.30



|                                                                                                             |                                            |
|-------------------------------------------------------------------------------------------------------------|--------------------------------------------|
| DATE-DAY 5 MONTH 4 YEAR 22                                                                                  | <b>CUSTOMER:</b><br>SOCOTEC                |
| SERIAL No. 3200 PLANT No. GEO 305                                                                           |                                            |
| HOURS ENGINE 868                                                                                            |                                            |
| HOURS AIR                                                                                                   |                                            |
| DRILL APPEARANCE                                                                                            |                                            |
| <b>DID PROBLEM MAKE RIG INOPERABLE?</b> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> | <b>SITE ADDRESS:</b><br>COVENTRY<br>CV32TF |

SPARES USED ON MACHINE

| QTY: | PART No.   | DESCRIPTION          | TIME ARRIVED ON SITE:                     |                            |                 |        |
|------|------------|----------------------|-------------------------------------------|----------------------------|-----------------|--------|
| 1    | 3.3021.022 | ENG. OIL FILTER      | 8:00AM                                    |                            |                 |        |
| 1    | 3.3021.138 | FUEL FILTER          | <b>SERVICEMAN'S NAME(S)</b><br>[REDACTED] | <b>HOURS WORKED</b><br>3.5 | <b>MILEAGE:</b> |        |
| 1    | 3.3021.139 | FUEL FILTER          |                                           |                            | OUT             | RETURN |
| 1    | 3.3021.140 | AIR FILTER           |                                           |                            |                 |        |
| 1    | 3.3021.141 | AIR FILTER           |                                           |                            |                 |        |
| 1    | 3.3271.046 | HYDRAULIC OIL FILTER |                                           |                            |                 |        |
| 2    | 2-2102.043 | SWIVEL SEALS         |                                           |                            | TOTAL           | 3.5    |
| 9L   | 15W40      | ENGINE OIL           | TOTAL MILEAGE                             |                            | 70              | 70     |
| 1    |            | JET WASH LANCE       | TRAVELLING TIME                           |                            | 15 Hrs          | 15 Hrs |
|      |            |                      | TIME LEFT SITE                            | 11:30AM                    |                 |        |
|      |            |                      | SERVICEMAN'S HOME TELEPHONE No.           | [REDACTED]                 |                 |        |
|      |            |                      | CAR REG No.                               | [REDACTED]                 |                 |        |

ACCOUNT OF THE TIME SPENT ON SITE AND DETAILS OF REPAIR CARRIED OUT

TIGHTEN THE SWIVEL SHAFT TO THE SPINDLE  
 CHECK ALL OVER, DO THE 250WS SERVICE, GREASE ALL GREASE POINTS, UNSCREWED ONE BROKEN GREASE NIPPLE AND FITTED NEW ONE. TIGHTEN CORRECT THE SPRING OF THE WINCH ROLLER BAR.  
 FIXED ONE BROKEN FITTING OF THE WINCH AND ONE BROKEN HYDRAULIC HOSE BY THE SOCOTEC FILTER  
 TESTED THE WATER PUMP (SIDE MOUNT AND MISS PUMP)  
 FITTED NEW JET WASH LANCE.  
 LEFT TWO SWIVEL RUBBER O-RING SEALS FOR THE RIG.  
 ALL LEFT IN GOOD WORKING AT THE TIME OF INSPECTION

SERVICEMAN'S SIGNATURE

CUSTOMER'S SIGNATURE