

# Lifting Machines and Accessories Report



Lifting Operations & Lifting Equipment Regulations 1998  
 Provision & Use of Work Equipment Regulations 1998

**Regular** Thorough Examination

Name of User: **SOCOTEC UK HOLDING LTD AND/OR  
 SOCOTEC UK LIMITED AND/OR ANY**

Policy **NV10405624**

Number:

Contract

Number:

Report **E50317001624**

Number:

Location: **SOCOTEC UK LTD (GLASTONBURY),  
 BARTLETTS FARM UNIT 11,  
 GLASTONBURY, SOMERSET, BA6 9AF**

<b>Item No.</b>  <b>Examination Dates:</b> Last Current Next	<b>Description</b> Serial No. Make/Model Year of Manufacture Location Examination Scheme Number	<b>Safe Working Load(s)</b>	<b>A. Defects which could cause a danger to persons. Particulars of any repairs, renewals or alterations to rectify those defects and the time within which those defects shall be rectified.</b> <b>B. Identification of any parts that require rectification</b> <b>C. Observations and recommendations (Issues relating to health and safety. Any actions stipulated should be suitably and satisfactorily completed.)</b>
NORA7750KMA770059 29-Apr-2024 30-Apr-2024 30-Apr-2025	Telescopic Handler A770059 Norcar / A7750 Tracked 2021 Main Workshop	Not Marked	<b>A</b> Rated capacity indicator inoperative. This should be suitably rectified immediately. <b>B</b> Lacerations observed to front rubber caterpillar tracks, with off-side track beginning to cut through centre of track rubber. Seat belt warning light intermittent in operation. <b>C</b> Hours run meter reading: 522 Seen fitted with Taylor pallet fork attachment c/w Bolozoni load forks at time of examination. The safe working load markings are not clear. The approved safe working load should be ascertained and clearly marked. Evidence of hydraulic creep. Maintenance provider to investigate cause and remedy as necessary.

The above items were seen at: (If blank, refer to the Location details)

Visit made on behalf of:

Client Name

SOCOTEC UK HOLDING LTD AND/OR SOCOTEC UK LIMITED AND/OR ANY

Address

SOCOTEC UK LTD (GLASTONBURY)  
 BARTLETTS FARM UNIT 11

GLASTONBURY  
SOMERSET  
BA6 9AF

This notification shall not be reproduced except in full without the approval of Allianz Engineering and the client for whom it was produced.

---

**Client's Report Notes** [These notes DO NOT form part of the Allianz Inspection Report]

---

Date of commencement of examination and tests 30-Apr-2024

Competent Person  
Allianz Engineering

Date of Report 30-Apr-2024

UK Tel: +44 (0) 1428 722407  
ROI Tel: +00353 (0) 1 613 4081

Engineer Surveyor



T. Martin

Allianz Engineering Inspection Services Ltd, 57 Ladymead, Guildford, Surrey, GU1 1DB  
Allianz Engineering Inspection Services Ltd. Registered in England Number: 5441840. Registered Office: 57 Ladymead, Guildford, Surrey, GU1 1DB, United Kingdom.  
Allianz plc, Allianz House, Elmpark, Merrion Road, Dublin 4, Republic of Ireland. Allianz plc trading as Allianz is regulated by the Irish Financial Regulator. Registered in Ireland number 143108.  
www.allianzengineering.co.uk



This is an electronically produced copy of an original report held on the Allianz Engineering computer database called FACE

[Print](#)

[Close](#)

[Print/email friendly page](#)

Attachments

Type

Comments

No Attachments