

**SOCOTEC****Plant Service Record**

Date: 08-XI-2024	Fitter's name: DOM
Plant Item: R-74 COMACCHIO 305	Plant no.: R-74
Hour reading: 1798.2	

Description of work carried out	Time taken (hours)	Initials
SEIZED WINCH ROPE LEVER (STRIP IT OUT, CLEAN, GREASE IT)		DI
REMOVE WINCH ROPE DUE TO KINK ON IT		DI DS PS
INSTAL NEW ROPE SO24955-3		DI+DS+PS

Parts/materials used	Quantity
ROPE 6MM-200M SO24955-3	1

Fitter's comments: ATTEND TO SITE AND FOUND A SEIZED WINCH ROPE LEVER WHICH CAUSED DAMADGE TO WINCH ROPE RECTIFY LEVER BY STRIPPING IT OUT AND GREASING COMEBACK SITE TO REPLACE KINKED ROPE

Fitter's Signature (work complete)	8-XI-2024
------------------------------------	-----------