

**SOCOTEC****Plant Service Record**

Date: 4-XI-2024	Fitter's name: DOM
Plant Item: COMACCHIO 405	Plant no.: R-72
Hour reading: 3004.6	

Description of work carried out	Time taken (hours)	Initials
TR-200 PUMP REBUILD		DI
TOP UP WITH FRESH OIL		DI

Parts/materials used	Quantity
NEW OIL SEALS + NEW RODS	3+3
NEW WATER CYLINDERS + RED PISTONS	3+3
NEW CAP GASUETS + STUFFING BOX PACKING	3+3

Fitter's comments: MIDDLE SECTION OF PUMP HAD TO BE
RETHREADED DUE TO ~~THE~~ AFFECTED THREAD PITCH BY
~~THE~~ COMPACTING A STUFFING BOX

PUMP WAS TESTED BY JOHN GOWAN

BUILT UP. PRESSURE UP TO 20 Bar PULSATING but
IT LOOKS LIKE IT'S A NATURE OF THIS PUMP.

Fitter's Signature (work complete)	05-XI-2024
------------------------------------	------------