

**SOCOTEC****Plant Service Request and Works Required**

Date: 03-01-20		Date/Time required:	
Plant Item: Dando 100		Plant no: CT64	
Hour reading:	N/A	Last Service	
Description of work required		Time required (hours)	Initials of assigned fitter
building up when back from paint		8	JK / CD
big drive sprocket to be replaced - worn beyond limit		12	JK / CD
Service		2	JK / CD
requires rope			
on need msc			
requires a load test			
need rig testing			
Parts/materials required		Quantity	
Comments:			
Fitter assigned the works.		STW	
Managers signature		[Signature]	

If any other issues with the item of plant in question are identified at any time during the above list of works being completed the workshop manager must be informed and all workshop documentation must be updated.