

Fitted CT65 on 01/05/2021

J.H. (Lifting Gear Hire) LTD.

UNIT Q, LONDON ROAD TRADING ESTATE
SITTINGBOURNE, KENT, ME10 1NQ

Tel: +44 (0)1795 425760 and 472168

Fax: +44 (0)1795 429476

Web: www.jhlifting.co.uk

E-mail: info@jhlifting.co.uk



Lifting Equipment Engineers Association



REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

Customer Order Number

TO0693

Sales Job No

121403

Date of Examination

04/03/2021

Date of Report

05/03/2021

Report Number

123863

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations

Organisation for whom the thorough examination was made

Socotec UK Limited
ESG House
Bretby Business Park
Ashby Road
Burton on Trent
DN15 0YZ

Location at which the thorough examination was made

J.H. (Lifting Gear Hire) Ltd
Unit Q
London Road Trading Estate
Sittingbourne
Kent
ME10 1NQ

Qty	Description & Identification of the Equipment	Safe Working Load(s)	Date of Last Thorough Examination (If Known)
1	65 metre x 16mm dia 6/36 IWRC 1960N/mm ² galv wire rope with thimble eye one end talurit secured, other end fused and tapered MBL 179 kN 5:1 for lifting (LOLER) - 3:1 for pulling/towing only (BS EN 16228) ID Mark: <u>W24187</u>	3277 kg @ 5:1 F.o.S. 5462 kg @ 3:1 F.o.S	

Has this Equipment been...			Was the Examination carried out...		
Supplied New	Yes <input checked="" type="checkbox"/>	No	Before being issued for the first time	Yes <input checked="" type="checkbox"/>	No
Supplied Reconditioned	Yes	No <input checked="" type="checkbox"/>	Within an interval of 6 months	Yes	No <input checked="" type="checkbox"/>
Examined Only	Yes	No <input checked="" type="checkbox"/>	Within an interval of 12 months	Yes	No <input checked="" type="checkbox"/>
Examined & Tested Only	Yes	No <input checked="" type="checkbox"/>	As part of an Examination Scheme	Yes	No <input checked="" type="checkbox"/>
Examined, Repaired & Tested	Yes	No <input checked="" type="checkbox"/>	After Exceptional Circumstances	Yes	No <input checked="" type="checkbox"/>

Identification of any part found to have a defect that could become a danger to persons and a description of the defect. (If none, state NONE)
NONE

Is the above a defect which is of immediate danger to persons?

Yes No

If not an immediate danger, when might it become dangerous to persons without rectification?

Date:

Particulars of any repair, renewal or alteration required to remedy the defect identified above

Particulars of any tests carried out as part of the examination. (If none, state NONE)

NONE

IS THIS EQUIPMENT SAFE TO USE / OPERATE?

Yes No

Person making this report

Roger Oliveira

Person authenticating this report

Roger Oliveira

Latest date by which next thorough examination must be carried out:

Qualifications: LEEA TEAM Card

Qualifications: LEEA TEAM Card Signature

03/09/2021

This equipment was manufactured in accordance with the Machinery Directive, Declaration of Conformity issued and is available to view at our offices on request.

Fitted to CT65 by James + Milton 01/05/2021

J.H. (Lifting Gear Hire) Ltd. Registered in England No: 1041586 VAT No: GB 203 2419 16

D. Gollish