

Fitted to **CT65** on 01/05/2021

J.H. (Lifting Gear Hire) LTD.

UNIT Q, LONDON ROAD TRADING ESTATE
SITTINGBOURNE, KENT, ME10 1NQ

Tel: +44 (0)1795 425760 and 472168

Fax: +44 (0)1795 429476

Web: www.jhlifting.co.uk

E-mail: info@jhlifting.co.uk



Lifting Equipment Engineers Association



REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

Customer Order Number T00807		Sales Job No 122188
Date of Examination 27/04/2021	Date of Report 29/04/2021	Report Number 125091

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

Organisation for whom the thorough examination was made Socotec UK Limited ESG House Bretby Business Park Ashby Road Burton on Trent DN15 0YZ	Location at which the thorough examination was made J.H. (Lifting Gear Hire) Ltd Unit Q London Road Trading Estate Sittingbourne Kent ME10 1NQ
--	---

Qty	Description & Identification of the Equipment	Safe Working Load(s)	Date of Last Thorough Examination (If Known)
3	20 metre x 8mm dia 7/19 IWRC 1960N/mm ² galv wire rope with thimble eye one end talurit secured with captive eye latch hook, other end fused and tapered MBL 4629 kg 5:1 for lifting (LOLER) - 3:1 for pulling/towing only (BS EN 16228) ID Mark: W24229 to W24231	925 kg @ 5:1 F.o.S. 1157 kg @ 3:1 F.o.S.	

Has this Equipment been...		Was the Examination carried out...	
Supplied New	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Before being issued for the first time	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
Supplied Reconditioned	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Within an interval of 6 months	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Examined Only	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Within an interval of 12 months	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Examined & Tested Only	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	As part of an Examination Scheme	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Examined, Repaired & Tested	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	After Exceptional Circumstances	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>

Identification of any part found to have a defect that could become a danger to persons and a description of the defect. (If none, state NONE)
NONE

Is the above a defect which is of immediate danger to persons? Yes No

If not an immediate danger, when might it become dangerous to persons without rectification? Date:

Particulars of any repair, renewal or alteration required to remedy the defect identified above

Particulars of any tests carried out as part of the examination. (If none, state NONE)
NONE

IS THIS EQUIPMENT SAFE TO USE / OPERATE? Yes No

Person making this report Dave Merner Qualifications: LEEA TEAM Card	Person authenticating this report Shaun Broad Qualifications: LEEA TEAM Card Signature	Latest date by which next thorough examination must be carried out: 26/10/2021
---	--	--

This equipment was manufactured in accordance with the Machinery Directive, Declaration of Conformity issued and is available to view at our offices on request.

W24230 fitted by James + Milton 1/5/2021