



**Plant Service record**

Please complete fully and as accurately as possible.

Report Number-
----------------

Date:	04-11-19	Fitter:	Jack Keeton
Asset Number:	CT 65	Plant Item:	Dando 2500
Engine Hours:			
Return Inspection- (Tick Box)		Breakdown-	
Pre Mob Inspection-	<input checked="" type="checkbox"/>	Routine Maintenance / Service -	<input checked="" type="checkbox"/>

Diagnosis / Faults Reported / Inspection Findings:	
1	Big sprocket in needs replacing
2	Brakes needed checking
3	
4	
5	
6	
7	
8	
9	
10	

Description of works undertaken-

Time taken

1	Fitted new sprocket, cleaned chain + fitted chain; adjusted engine and chain + fitted covers.	
2	took 10 min for brake test which was good	
3		
4		
5		
6		
7		
8		
9		
10		