

FIELD SERVICE REPORT

R71

CUSTOMER ORDER No.

7

JKS BOYLES

UK LIMITED

106083

DATE-DAY 27 MONTH 4 YEAR 21	CUSTOMER: SOCOTEC
SERIAL No. 3137 PLANT No. GEO 305	SITE ADDRESS: LOWER RADBOURNE SOUTHAM CV47 1NH £70.00
HOURS ENGINE 1631	
HOURS AIR	
DRILL APPEARANCE GOOD	
DID PROBLEM MAKE RIG INOPERABLE? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	

SPARES USED ON MACHINE

QTY:	PART No.	DESCRIPTION	TIME ARRIVED ON SITE: 10.30		MILEAGE:	
			SERVICEMAN'S NAME(s)	HOURS WORKED	OUT	RETURN
			[REDACTED]	2		
			TOTAL			
			TOTAL MILEAGE		—	—
			TRAVELLING TIME		— Hrs	— Hrs
			TIME LEFT SITE	12.30		
			SERVICEMAN'S HOME TELEPHONE No.	[REDACTED]		
			CAR REG N	[REDACTED]		

ACCOUNT OF THE TIME SPENT ON SITE AND DETAILS OF REPAIR CARRIED OUT

INVESTIGATED CUSTOMERS COMPLAINT OF JETWASH INOPERATIVE & REQUIRES RESCALING. STRIPPED PUMP SEALS WERE O.K., REMOVED PIPE TO REEL, WATER FLOW ALL OK, TRACED FAULT TO WASHER LANCE, FOUND STEEL OBJECT STUCK IN WATER JET, REMOVED JET & CLEANED, REBUILT & TESTED ALL OK.

SERVICEMAN'S SIGNATURE

[Signature]

CUSTOMER'S SIGNATURE

[Signature]