

RTL

| Comacchio Service Report |                                 | Machine Serial No:  | 3195                            |                       |            |      |   |
|--------------------------|---------------------------------|---|---------------------------------|-----------------------|------------|------|---|
| Customer:                | Socotec                         | Engine Hours:   | 1120                            |                       |            |      |   |
| Machine Type:            | GE0 405                         | Service Type:   | PDI - 250 - 500 1000 2000 - C/O |                       |            |      |   |
|                          | Check                           | Change  | Qty.                            | Part No./ Description | Ltrs       | Done |   |
| Engine                   | Engine oil                      | ✓   |                                 | 10/40                 | 11         | ✓    |   |
|                          | Oil filter                      |   | ✓                               | 1                     | 3-3021-022 |      | ✓ |
|                          | Fuel filter                     |   | ✓                               | 1                     | 3-3021-138 |      | ✓ |
|                          | In line fuel filter             |   | ✓                               | 1                     | 3-3021-139 |      | ✓ |
|                          | Inner air filter                |   | ✓                               | 1                     | 3-3021-140 |      | ✓ |
|                          | Outer air filter                |   | ✓                               | 1                     | 3-3021-141 |      | ✓ |
|                          | Water coolant level anti-freeze |   | ✓                               |                       | yellow     | 1    | ✓ |
|                          | Fan belt tension                | ✓   |                                 |                       |            |      | ✓ |
|                          | Coolant and oil leaks           | ✓   |                                 |                       |            |      | ✓ |
| Hydraulics               | Hydraulic filter                |   | ✓                               | 1                     | 3-3271-001 |      | ✓ |
|                          | Pilot hydraulic filter          | N/A   |                                 |                       |            |      | ✓ |
|                          | Hydraulic tank breather         | ✓   |                                 |                       |            |      | ✓ |
|                          | Hydraulic oil                   | ✓   |                                 |                       |            |      | ✓ |
|                          | Clean out hydraulic tank        | N/R   |                                 |                       |            |      | ✓ |
|                          | All cylinders for leaks         | ✓   |                                 |                       |            |      | ✓ |
| Rotary head              | Main gearbox                    | ✓   |                                 |                       |            | ✓    |   |
|                          | Reduction gearbox               | N/A   |                                 |                       |            | ✓    |   |
|                          | Gear settings and operation     | ✓   |                                 |                       |            | ✓    |   |
|                          | Head slides                     | ✓   |                                 |                       |            | ✓    |   |
| Undercarriage            | Drive gearboxes                 |   | ✓                               |                       | 80/90      | 25   | ✓ |
|                          | Track tension                   | ✓   |                                 |                       | Adjusted   |      | ✓ |
|                          | Idler bearing and rollers       | ✓   |                                 |                       |            |      | ✓ |
| Mast                     | Gearbox oil                     | N/A   |                                 |                       |            |      | ✓ |
|                          | Chain                           | ✓   |                                 |                       |            |      | ✓ |
|                          | Bearings                        | ✓   |                                 |                       |            |      | ✓ |
|                          | Mast slides                     | ✓   |                                 |                       |            |      | ✓ |
| Service winch            | Oil                             | ✓   |                                 |                       |            |      | ✓ |
|                          | Rope                            | ✓   |                                 |                       |            |      | ✓ |
|                          | Rollers                         | ✓   |                                 |                       |            |      | ✓ |
|                          | Inspect hook                    | ✓   |                                 |                       |            |      | ✓ |
|                          | LOLER inspection                | If required, see table on reverse page and fill out 4 & 5 |                                 |                       |            |      |   |
| Water pump               | Oil                             | ✓   | ✓                               |                       | 80/90      | 62L  | ✓ |
|                          | Suction hose and fittings       | ✓   |                                 |                       | Tested     |      | ✓ |
| Mist pump                | Oil                             | N/A   |                                 |                       |            |      | ✓ |
|                          | Suction hose and fittings       | ✓   |                                 |                       | Tested     |      | ✓ |
| Machine                  | Swivel                          | ✓   |                                 |                       | Tested     |      | ✓ |
|                          | All life line operation         | ✓   |                                 |                       |            |      | ✓ |
|                          | All lifting eyes                | ✓   |                                 |                       |            |      | ✓ |
|                          | Gate lock switch and gate locks | ✓   |                                 |                       |            |      | ✓ |
|                          | Electrics: ROM, lights etc.     | ✓   |                                 |                       |            |      | ✓ |
|                          | Fire Extinguisher               | ✓   |                                 |                       |            |      | ✓ |
|                          | Battery level/ terminals        | ✓   |                                 |                       |            |      | ✓ |
|                          | Grease all grease points        | ✓   |                                 |                       |            |      | ✓ |

x = Fault    ✓ = OK/ Done    N/R = Not Required    N/A = Not Applicable

**WORKS ORDER/INSPECTION RECORD SHEET**

|                              |
|------------------------------|
| Customer: Socotec            |
| Product: Comacchio           |
| Description: Geo 405 HT 3195 |

|                      |
|----------------------|
| Date: 23-03-21       |
| Order Ref No: 105733 |
| Delivery Date:       |

Special Instructions:

| Task No. | Task/Operation  | Time to complete | Inspected by: |
|----------|---|------------------|---------------|
| 1        | Wash down machine prior to service  | 4                | JB            |
| 2        | Carry out service and inspection. 1000-hour service carried out and all necessary filters and oils changed.                                 | 4                | JB            |
| 3        | Remove engine fan belt guard and repair damaged welds. Also removed guard for front of head and repaired as weld had cracked but not broke. | 1                | JB            |
| 4        | Removed damaged door hinge on engine panel and replace with new.  | 0.5              | JB            |
| 5        | Remove top jaw inserts and replace with new and with new bolts.   | 1                | JB            |
| 6        | Strip down diesel pump and replace damaged fins inside pump. Tested pump all ok.  | 1                | JB            |
| 7        | Greased machine and adjusted track.   | 1                | JB            |
|          |   |                  |               |
|          |   |                  |               |
|          |   |                  |               |
|          |   |                  |               |
|          |   |                  |               |
|          |   |                  |               |
|          |   |                  |               |
|          |   |                  |               |
|          |   |                  |               |
|          | <b>TOTAL (hours)</b>  | <b>12.5</b>      |               |

R72

COST  
~~£994.60~~  
 Order No. T00679  
 £1,236.55

|                   |               |       |
|-------------------|---------------|-------|
| Final Inspection: | Inspected by: | Date: |
|-------------------|---------------|-------|

27

FIELD SERVICE REPORT



106414  
£424.40

DATE: 10 MONTH: 05 YEAR: 21  
SERIAL NO: 3175 PLANT NO: Geo 405  
HOURS ENGINE: 1210  
HOURS AIR: N/A  
DRILL APPEARANCE: v good

CUSTOMER: Sorelec  
SITE ADDRESS: Leisure drive  
Hurdwick  
CV47 7SR

OLD PROBLEM MAKE  
RECI INOPERABLE? YES  NO

SPARES USED ON MACHINE

| QTY | PART NO    | DESCRIPTION |
|-----|------------|-------------|
| 1   | 2-3265 011 | coil 2hp    |
| 1   | 3-3261 010 | plug 2hp    |
| 1   | 2-2602 136 | to the fuse |

TIME ARRIVED ON SITE: 10:15  
SERVICEMAN'S NAME: [REDACTED]  
HOURS WORKED: 2:45  
MILEAGE: OUT 100 RETURN 100  
TOTAL: [REDACTED]  
TOTAL MILEAGE: [REDACTED]  
TRAVELLING TIME: 2 100 2 100  
TIME LEFT SITE: 12:50  
SERVICEMAN'S HOME TELEPHONE No: [REDACTED]  
CAR REG No: [REDACTED]

ACCOUNT OF THE TIME SPENT ON SITE AND DETAILS OF REPAIR CARRIED OUT

Remove and replace damaged coil clean hydraulic  
valve shaft and grease.  
cut plug off and replace with new one on  
wiring from coil to fusebox.  
Remove and replace damaged fuse.  
Test rig all okay

SERVICEMAN'S SIGNATURE  
*[Signature]*

CUSTOMER'S SIGNATURE  
*[Signature]*

106414 £424.40

R72

FIELD SERVICE REPORT



1. 8610  
 £ 670 40

DATE: DAY 10 MONTH 05 YEAR 21  
 SERIAL NO 3195 PLANT NO 600 605  
 HOURS T/MONS 1210  
 FUEL AIR N/A  
 DRILL APPRANICE v good  
 DID PROBLEM MAKE AND INOPERABLE? YES  NO

CUSTOMER: Soro Lec  
 SITE ADDRESS: Leisure drive  
 Hurdwick  
 CV47 75R

SPARES USED ON MACHINE

| QTY | PART NO   | DESCRIPTION    |
|-----|-----------|----------------|
| 1   | 33465.011 | coil 24v       |
| 1   | 33241.010 | plug 24v       |
| 1   | 22602.236 | to clean fuse. |

TIME ARRIVED ON SITE: 10:15

| SERVICEMAN'S NAME              | HOURS WORKED | MILEAGE    |        |
|--------------------------------|--------------|------------|--------|
|                                |              | OUT        | RETURN |
| [REDACTED]                     | 2.45         | 60         | 100    |
| TOTAL                          |              |            |        |
| TOTAL MILEAGE                  |              |            |        |
| TRAVELLING TIME                |              | 2          | 2      |
| TIME LEFT SITE                 |              | 12:50      |        |
| SERVICEMAN'S HOME TELEPHONE NO |              | [REDACTED] |        |
| CAR REG NO                     |              | [REDACTED] |        |

ACCOUNT OF THE TIME SPENT ON SITE AND DETAILS OF REPAIR CARRIED OUT

Remove and replace damaged coil clean hydraulic valve shaft and grease.

cut plug off and replace with new fast on wiring from coil to fusebox.

Remove and replace damaged fuse

Test rig on clay

SERVICEMAN'S SIGNATURE  
 JBe

CUSTOMER'S SIGNATURE  
 A. B

3

R72