SUPERINTENDENT'S REPORT STATISTICS

METERS

NEW RADIO READ HEADS
60 MODEL 25
2 MODEL 70

METERS REPAIRED
2 METERS TESTED

REPLACEMENT BASES 8 MODEL 25

LEAKS	REPAIRS
4 8" WATER MAINS	3 HYDRANTS REPAIRED
1 6" WATER MAIN	4 VALVE BOXES REPAIRED
1 4" WATER MAIN	32 SERVICE BOXES REPAIRED
5 3/4" WATER SERVICE	46 VALVE BOXES LOCATED
2 1" WATER SERVICE	59 SERVICES LOCATED
	14 MAINS LOCATED
WATER TESTING	
84 BACTERIOLOGICAL TESTS	INSPECTIONS
TURBIDITY & CHLORINE	365 FILTER PLANT
RESIDULE IS MONITORED	365 PUMP HOUSE
CONTINUALLY	36 WHATELY RESERVOIR
1 PFAS TEST	30 CONWAY RESERVOIR
4 HALOACETIC ACID TESTS	4 HILLSIDE TANK
4 TRIHALOMETHANES TESTS	24 RIDGE ROAD TANK
1 SECONDARY CONTAMINANTS	24 STILLWATER TANK
1 SODIUM TEST	
1 VOLATILE ORGANIC	ALARMS
CONTAMINANT TEST	21 FILTRATION PLANT
2 MANGANESE TESTS	13 RIDGE ROAD TANK
2 IRON TESTS	
1 NITRATE	TOTAL SERVICES
84 LEAD AND COPPER	1570

MAXIMUM DAILY CONSUMPTION

JUNE 24, 2020

918,356 GALLONS