


2006 TF Gemini Pet CT Brilliance 64

PET detector: GSO



CT HOST MONITOR 2

History Maintenance Form

Notes

System Location Info

Submit

Request Date From RHOST

Report For the Tube

Save Report

21057 M 111636

Exposure Seconds

Exposure Counts

Anode Arcs

Cathode Arcs

Total Arcs

Tube Current Data

728812

286332

8

3

9

Tube History Report from TubeHistoryInfo Database

8/9/2021 11:03:41 AM

7029

919206

358971

21

13

28

21057 M 111636

639163

246540

TUBE HISTORY	
Date :	8/9/2021 11:03:41 AM
Action :	None
System (Gantry) ID :	
Tube Serial No :	
Field Service Eng. ID :	
First Name :	
Last Name :	
Phone :	
e-mail :	
Last Entry was at :	11/13/2019 6:15:04 PM
Current Data From RHOST	
Exposure Seconds :	1008855
Exposure Counts :	398763
Anode Arcs :	21
Cathode Arcs :	13
Total Arcs :	28
21057 M 111636	
*Yellow fields are optional	
21057 M 111636	
Created :	

--	System/Gantry ID :
1	System Scan Seconds :
	System Scan Counts :
	System Anode Arcs :
	System Cathode Arcs :
	System Arc Events :

--	Tube Serial No :
2	Tube Scan Seconds :
	Tube Scan Counts :

Help! Tube History Form