

CT SCANNER SPECIFICATIONS & INFORMATION

Manufacturer: Siemens	Model: Somatom Emotion 16	Date Manufactured: 12/2005
Date Installed: 12/2011		
What is System Type: <input type="checkbox"/> Spiral <input type="checkbox"/> Multi-Slice (# Slices): 16 <input type="checkbox"/> Other		
Tube mAs or Scan/Sec: as of 6/11/19 29412 tube scan sec, and 728302 system scan sec	Size (mHu):	Tube age: 11/30/2018
Manufacturer:		
# Slices on Gantry:	Generator Model:	Generator Size:
Independent Workstation: <input type="checkbox"/> Yes <input type="checkbox"/> No	Type of Computer:	Software level: EB28B
Consoles: <input type="checkbox"/> xSingle <input type="checkbox"/> Dual	DICOM: <input type="checkbox"/> XYes <input type="checkbox"/> No	
Any upgrades: Tube	<input type="checkbox"/> Yes <input type="checkbox"/> No	If yes, please, describe: new tube in 2018 Dura 422MV
Is there a Camera:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If yes, Model #:
Is there an Injector:	<input type="checkbox"/> Yes <input type="checkbox"/> No	If yes, Model #: Not for sale
Is there a Chiller?	<input type="checkbox"/> Yes <input type="checkbox"/> No	Is the System in use: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
If <u>NO</u> , how long out of use:	Where is it located (e.g. ground floor): ground floor	Loading Dock: <input type="checkbox"/> Yes <input type="checkbox"/> No No loading dock
Known defects:	The system is in really good condition	
Mechanical Condition of Equipment (10 being best):	<input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5 <input type="checkbox"/> 6 <input type="checkbox"/> 7 <input type="checkbox"/> 8 <input type="checkbox"/> 9 <input type="checkbox"/> 10- 8	
Cosmetic Condition of Equipment (10 being best):	<input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5 <input type="checkbox"/> 6 <input type="checkbox"/> 7 <input type="checkbox"/> 8 <input type="checkbox"/> 9 <input type="checkbox"/> 10- 9	
When is the System Available for removal? 1 st quarter 2020	Who Serviced Equipment: 3 rd Party	
Last PM: 6/11/19		