
PLAT of SURVEY

FOX SURVEYING COMPANY

Ph. 740-494-2028



BEING PART OF F.L. 10 OF QUARTER TWP. 4 TWP.-4-NORTH. RANGE-17-WEST. VILLAGE OF,



DESCRIPTION OF A 1.094 ACRE TRACT

As Shown on the Plat Recorded in

VOLUME /5, PAGE 86 of the SURVEY RECORDS

of the DELAWARE COUNTY ENGINEER
as Found in the

DELAWARE COUNTY MAP DEPARTMENT
DELAWARE COUNTY, OHIO

Being part of Quarter-Township 4, Township – 4 North, Range – 17 – West, Village of Sunbury, Delaware County, State of Ohio and being all of Parcel 1 and Parcel 2 as conveyed to 157 S Vernon St., LLC as recorded in Official Record 1407, pages 538 through 543, and being more particularly described as follows:

COMMENCING at a Railroad Spike found at the intersection of the centerline of Columbus Street with the extension of the North right-of-way line of Letts Avenue, thence with said centerline of Columbus Street (66' R/W), North 12 deg. 13 min. 20 sec. East for a distance of 421.07 feet to a survey nail set at a Southwest corner of the hereinafter described 1.094 acre tract and the **TRUE POINT OF BEGINNING**

Thence continuing with said centerline of Columbus St. North 12 deg. 13 min. 20 sec. East for a distance of 43.74 feet to a survey nail set;

Thence along a North line of said Parcel 2 **South 86 deg. 48 min. 19 sec. East** for a distance of **220.61 feet** to an iron pin set (passing over a 5/8 inch dia. iron pin found at a distances of 38.42 feet, and a 5/8 inch dia. iron pin found at a distances of 210.61 feet;

Thence along the West line of said Parcel 1 North 3 deg. 26 min. 38 sec. East for a distance of 156.30 feet to an iron pin set;

Thence along a North line of said Parcel 1 South 85 deg. 33 min. 26 sec. East for a distance of 188.16 feet to a survey nail set in a drill hole on the West line of Vernon Street (45' R/W);

Thence along the West line Vernon St. and the East line of said Parcel 1 and Parcel 2 South 3 deg. 18 min. 32 sec. West for a distance of 111.40 feet to a survey nail set;

Thence along the South line of said Parcel 2 South 54 deg. 48 min. 56 sec. West for a distance of 267.90 feet to a 5/8 inch dia. iron pin found;

Thence along a West line of said Parcel 2 North 14 deg. 56 min. 08 sec. West for a distance of 20.21 feet to a 5/8 inch dia. iron pin found;

Thence along a North line of said Parcel 2 North 55 deg. 29 min. 29 sec. East for a distance of 67.68 feet to a survey nail set;

Thence along a South line of said Parcel 2 North 81 deg. 54 min. 09 sec. West for a distance of 254.22 feet to a survey nail set (passing over a survey nail set in a drill hole at a distance of 221.13 feet) to the TRUE PLACE OF BEGINNING.

Containing **1.094 acres**, more or less, of which 0.545 acres are out of Parcel 1 and 0.549 acres are out of Parcel 2, and subject to legal highways, easements, restrictions and agreements of record. This description prepared from a survey performed by Steven A. Fox, Registered Professional Surveyor and dated August 11, 2018. All 5/8 inch dia. Iron pins set have a plastic identity cap with the inscription "Fox Surveying Co."

Prior Deed: Official Record 1407, Pages 538 - 543

Basis of bearings, Ohio State Plane Coordinate System (North Zone) as observed along the West line of Vernon St. (North 3 deg. 18 min. 32 sec. East)

Steven A. Fox, P.S. 7000

aug .11, 2018 Date of Survey

Job No. 18288