



**CorrosionCOPS**  
When it's Rust Call US!

## CASE HISTORY

### Enviroklean Stain CarWell CP90/Rust Cop

**Date**  
March 30, 2015

**Customer**  
C&C Honolulu—Liberty Bell

**Location**  
Honolulu, Hawaii, USA

#### Problem

C&C Honolulu has historic Liberty Bell of Aloha mounted on white concrete pedestal. The pedestal was repainted December 2014 and the metal plate has been bleeding unsightly rust stains down the sides of the pedestal. Left as is—the staining would get larger and darker and shorten the life of the paint. Not to mention an eyesore as this historic bell is located right next to City and County of Honolulu Hale main building.

#### Solution and Procedure

1. Apply Enviroklean Stain Remover by rag or brush.
2. Rinse with fresh water.
3. Apply CarWell CP90/Rust Cop to all exposed metal surfaces to control further bleeding.

#### Conclusion

Simple—No repainting involved! Use of environmentally friendly, water based Enviroklean Stain Remover easily removed the rust staining on the painted surface. CarWell Rust Cop rust inhibitor will provide temporary corrosion protection to metal plate. Follow up maintenance as required due to corrosion on underside of metal plate until refurbished will keep bleeding rust.



**Before**



**After**

### Solutions for Rust and Corrosion

94-463 Alapine Street, Waipahu, Hawaii 96797 Phone (808) 676-1963 Fax (808) 678-1677 [www.corrosioncops.com](http://www.corrosioncops.com)