



**CorrosionCOPS**  
When it's Rust Call US!

## CASE HISTORY

### Enviroklean Stain Remover CarWell CP90

**Date**  
May 2010

**Customer**  
**Mauna Kea Resort**  
Clyde Takayama  
Director of Engineering

**Location**  
**Kohala Coast, Hawaii, USA**

#### Problem

The October 15, 2006 Big Island earthquake caused the entire south end of the Mauna Kea Resort to collapse, and destroyed the hotel's top floor. The hotel closed December 1, 2006 after a month-long inspection revealed that the building was unsafe and in danger of collapse. After a \$150 million renovation, the hotel reopened in December, 2008.\* As part of the renovations, Mauna Kea Resort installed stainless steel cable pickets in existing railings to bring railings up to current building code.


These Stainless Steel Cable pickets were rusting and unsightly. Left unprotected—pitting and corrosion would eat into the cables and would reduce the life and effectiveness of these pickets.

#### Solution and Procedure

1. Apply Enviroklean Stain Remover by brush or sponge
2. Rinse with fresh water.
3. Apply CarWell CP90 to all exposed metal surfaces.

#### Conclusion

Use of Enviroklean Stain Remover easily removed the rust staining on the Stainless Steel Cable Pickets and applying CarWell CP90/Rust Cop rust inhibitor will provide further corrosion protection. Follow up maintenance required on yearly basis.



\*Lehrer, John (September, 2009). "Welcome Home". Westways.

Note:

Go to Products Link on our site for details on Enviroklean Stain Remover and CarWell Rust COP  
Go to Buy Now Link on our site for Enviroklean Stain Remover and CarWell Rust Cop retail locations.  
Go to Contact Link on our site for industrial sales and further questions.

#### Solutions for Rust and Corrosion

94-463 Alapine Street, Waipahu, Hawaii 96797 Phone (808) 676-1963 Fax (808) 678-1677 [www.corrosioncops.com](http://www.corrosioncops.com)