



**CorrosionCOPS**

When it's Rust Call US!

## CASE HISTORY

### CarWell CP90 Enviroklean Stain Remover

**Date**  
February 2012

**Customer**  
Moana Pacific Condominium  
Michael McDonagh  
Assistant Manager/Chief Engineer

**Location**  
Hawaii, USA

#### Problem

Moana Pacific had roof top Stainless Steel Control Boxes were being ravaged by the chlorides in our island atmosphere. Left unprotected—pitting and corrosion would eat into the cabinets and would reduce the life and effectiveness of these units.

#### Solution and Procedure

1. Apply Enviroklean Stain Remover by brush
2. Rinse with fresh water.
3. Apply CarWell CP90 to all exposed metal surfaces.

#### Conclusion

Use of Enviroklean Stain Remover easily removed the rust staining on the Stainless Steel Cabinets and applying CarWell CP90/Rust Cop rust inhibitor will provide further corrosion protection. Follow up maintenance required on yearly basis.

After



Before

### Solutions for Rust and Corrosion

94-463 Alapine Street, Waipahu, Hawaii 96797 Phone (808) 676-1963 Fax (808) 678-1677 [www.corrosioncops.com](http://www.corrosioncops.com)