

Date September 2010

Customer
McCully Bicycle & Sporting Goods

Location Oahu, Hawaii, USA





CASE HISTORY

Enviroklean Stain Remover CarWell CP90

Problem

McCully Bicycle & Sporting Goods had roof top parking deck exterior wall with ugly rust stain. The metal trim was causing the bleeding as well as the security light was holding water causing another stain down the wall. Left as is and unprotected—the stain would cause and even bigger rust stain on the wall as well as on the ground and would reduce the life of the paint finish.

Solution and Procedure

- 1. Apply Enviroklean Stain Remover by brush.
- 2. Rinse with fresh water. For old stains, such as this wall, leave wet Enviroklean on surface longer and repeat if needed.
- **3.** Apply CarWell CP90/RUST COP to all exposed metal surfaces annually or as needed.
- **4.** When you see staining reappear—a quick brush with Enviroklean will immediately remove stain.

Conclusion

Use of Enviroklean Stain Remover easily removed the rust staining on the concrete exterior wall without harming painted surface. Enviroklean is an environmentally friendly formulation, which means clean up is plain water.

Applying CarWell CP90/Rust Cop rust inhibitor will provide further corrosion protection. Follow up maintenance required on yearly basis.