

Invest Secure Survey

Outside Photos of Home > Gas Meter?	No
Inside Electrical Information > Are there Breakers Inside of the home?	Yes
Inside Electrical Information > Is there an electrical box with breakers in it inside?	Yes
Inside Electrical Information > Is inside Electrical Panel #1 located on same wall as outside electric meter?	No
Inside Electrical Information > Is there a second box with breakers in it inside?	No
Site Assessment Info > Are there any permitting/building code violations concerns?	No
Outside Electrical Information > Overhead or Underground Service to Electric Meter?	Underground
Outside Electrical Information > Grounding Type	Ground Rod
Outside Electrical Information > Clearance Issues	No
Outside Electrical Information > Is there an electrical box with breakers in it outside?	Yes
Outside Electrical Information > Is there a second breaker?	No
Outside Electrical Information > Is there an existing solar system?	No
Roof Photos > Roof Type	Shingles
Roof Photos > Number of Roofing Layers	1
Roof Photos > Is there roof damage?	Yes
Roof Photos > Is the roof suitable for Solar Installation?	Yes
Roof Photos > How will you capture the required rooftop horizon photos?	Standing on the highest peak
Attic > Is there attic access?	Yes
Attic > Attic Decking Plywood, OSB, Sheathing?	Plywood
Attic > Truss/Rafter Type	Manufactured Truss
Attic > Truss/Rafter Spacing	24"
Attic > Truss/Rafter Size (top cord)	2x4
Attic > Are there areas of concern?	No
Attic > Is there a SECOND Attic Access?	No

Attic > Truss/Rafter Spacing Other/Comments

Note for file this home is being converted into a nursing home and has an independent fire suppression system and additional life support and backup style machines. photos of trusses, waters stains and overview of remaining trusses showing no additional damage uploaded. Exterior photo of roof uploaded showing where broken truss is located also

Quality Check

> Selfie with House Number



Outside Photos of Home

> Front of Home



Outside Photos of Home

> Front of Home



Outside Photos of Home

> Front of Home



Outside Photos of Home

> Right Side of Home



Outside Photos of Home

> Right Side of Home



Outside Photos of Home

> Right Side of Home



Outside Photos of Home

> Right Side of Home



Outside Photos of Home

> Right Side of Home



Outside Photos of Home

> Back of Home




Outside Photos of Home

> Back of Home



Outside Photos of Home

> Back of Home



Outside Photos of Home

> Back of Home



Outside Photos of Home

> Back of Home



Outside Photos of Home

> Back of Home



Outside Photos of Home

> Back of Home



Outside Photos of Home

> Back of Home



Outside Photos of Home

> Left Side of Home




Outside Photos of Home

> Left Side of Home



Outside Photos of Home

> Left Side of Home



Outside Photos of Home

> Access Photos



Outside Photos of Home

> Access Photos




Inside Electrical Information

> Main Breaker Box Location




Inside Electrical Information

> Main Breaker Box Location



Inside Electrical Information

> Electrical Panel #1 Main Breaker Label




Inside Electrical Information

> Electrical Panel #1 Photos of Main Breaker (Dead Front ON)




Inside Electrical Information

> Electrical Panel #1 Photos of Main Breaker (Dead Front OFF)




Inside Electrical Information

> Electrical Panel #1 Photos of Main Breaker (Dead Front OFF)




Inside Electrical Information

> Electrical Panel #1 Photos of Main Breaker (Dead Front OFF)



Inside Electrical Information

> Electrical Panel #1 Photos of Main Breaker (Dead Front OFF)




Inside Electrical Information

> Electrical Panel #1 Photos of Main Breaker (Dead Front OFF)



Inside Electrical Information

> Electrical Panel #1 Photos of Main Breaker (Dead Front OFF)




Inside Electrical Information

> Electrical Panel #1 Photos of Main Breaker (Dead Front OFF)




Inside Electrical Information

> Electrical Panel #1 Photos of Main Breaker (Dead Front OFF)




Site Assessment Info

> Layout Map



Outside Electrical Information

> Close Up of Electric Meter



Outside Electrical Information

> Step Back Photo of Electric Meter Placement



Outside Electrical Information

> Step Back Photo of Electric Meter Placement



Outside Electrical Information

> Step Back Photo of Electric Meter Placement



Outside Electrical Information

> METER WALL




Outside Electrical Information

> METER WALL



Outside Electrical Information

> METER WALL



Outside Electrical Information

> METER WALL



Outside Electrical Information

> METER WALL



Outside Electrical Information

> METER WALL



Outside Electrical Information

> METER WALL



Outside Electrical Information

> METER WALL



Outside Electrical Information

> METER WALL



Outside Electrical Information

> Grounding Type Photo



Outside Electrical Information

> Outside Breaker Box 1: Location Photos



Outside Electrical Information

> Outside Breaker Box 1: Location Photos



Outside Electrical Information

> Outside Breaker Box 1: Dead Front On



Outside Electrical Information

> Outside Breaker Box 1: Largest Breaker



Outside Electrical Information

> Outside Breaker Box 1: Panel Label



Outside Electrical Information

> Outside Breaker Box 1: Dead Front Off (Top Section) Left and Right



Outside Electrical Information

> Outside Breaker Box 1: Dead Front Off (Top Section) Left and Right



Outside Electrical Information

> Outside Breaker Box 1: Dead Front Off (Top Section) Left and Right



Outside Electrical Information

> Outside Breaker Box 1: Dead Front Off (Middle Section) Left and Right



Outside Electrical Information

> Outside Breaker Box 1: Dead Front Off (Middle Section) Left and Right



Outside Electrical Information

> Outside Breaker Box 1: Dead Front Off (Middle Section) Left and Right



Outside Electrical Information

> Outside Breaker Box 1: Dead Front Off (Bottom Section)



Outside Electrical Information

> Outside Breaker Box 1: Dead Front Off (Bottom Section)



Outside Electrical Information

> Outside Breaker Box 1: Dead Front Off (Bottom Section)



Outside Electrical Information

> Outside Breaker Box 1: Main Wire Size



Outside Electrical Information

> Outside Breaker Box 1: Main Wire Size



Outside Electrical Information

> Outside Breaker Box 1: Dead Front Reattached



Outside Electrical Information

> Outside Breaker Box 1: Dead Front Reattached



Roof Photos

> Number of Roofing Layers Photos




Roof Photos

> Close-Up Roof Quality




Roof Photos

> Close-Up Roof Quality




Roof Photos

> Close-Up Roof Quality



Roof Photos

> Close-Up Roof Quality




Roof Photos

> Close-Up Roof Quality



Roof Photos

> Close-Up Roof Quality



Roof Photos

> Roof Damage Photos



Roof Photos

> Roof Damage Photos




Roof Photos

> Roof Damage Photos



Roof Photos

> Drip Edge Photos



Damaged truss is in this valley

Roof Photos

> Drip Edge Photos



Roof Photos

> Photo of Eaves



Roof Photos

> Photo of Eaves



Roof Photos

> Photo of Eaves



Roof Photos

> North-facing Horizon Photos



Roof Photos

> North-facing Horizon Photos




Roof Photos

> North-facing Horizon Photos



Roof Photos

> Northeast-facing Horizon Photos




Roof Photos

> Northeast-facing Horizon Photos



Roof Photos

> East-facing Horizon Photos



Roof Photos

> East-facing Horizon Photos



Roof Photos

> East-facing Horizon Photos



Roof Photos

> Southeast-facing Horizon Photos



Roof Photos

> Southeast-facing Horizon Photos




Roof Photos

> South-facing Horizon Photos



Roof Photos

> South-facing Horizon Photos



Roof Photos

> South-facing Horizon Photos



Roof Photos

> Southwest-facing Horizon Photos



Roof Photos

> Southwest-facing Horizon Photos



Roof Photos

> West-facing Horizon Photos



Roof Photos

> West-facing Horizon Photos




Roof Photos

> Northwest-facing Horizon Photos




Roof Photos

> Northwest-facing Horizon Photos



Attic

> Attic Access Photos



Attic

> 360 Degree photos in Attic



Attic

> 360 Degree photos in Attic




Attic

> 360 Degree photos in Attic



Attic

> 360 Degree photos in Attic



Attic

> 360 Degree photos in Attic



Attic

> 360 Degree photos in Attic



Attic

> 360 Degree photos in Attic



Attic

> 360 Degree photos in Attic



Attic

> Damaged or Stained Decking Photos



Attic

> Damaged or Stained Decking Photos



Attic

> Damaged or Stained Decking Photos



Attic

> Damaged or Stained Decking Photos



Attic

> Damaged or Stained Decking Photos



Attic

> Damaged or Stained Decking Photos



Attic

> Damaged or Stained Decking Photos



Attic

> Damaged or Stained Decking Photos



Attic

> Damaged or Stained Decking Photos



Attic

> Damaged or Stained Decking Photos



Attic

> Damaged or Stained Decking Photos



Attic

> Damaged or Stained Decking Photos



Attic

> Truss/Rafter Spacing Verification



Attic

> Truss/Rafter Spacing Verification



Attic

> Truss/Rafter Spacing Verification



Attic

> Truss/Rafter Spacing Verification



Attic

> Truss/Rafter Spacing Verification



Attic

> Truss/Rafter Spacing Verification

