# Report

## Camp Checkers Inspection Report

### **Inspection Type**

Monthly Service Plan

#### **Date Time 3**

5/6/2025 3:38 PM

### **Valued Camper**

Waters - CSC #60

### **Items Inspected by Camp Checkers**

✓ Main Roof Assembly

✓ Window/Doors

Exterior Walls

✓ Porch/Deck

Storage Shed

✓ Hitch/Propane

Exterior Devices

Utilities

✓ Trees/Branches

### **Camp Checkers Notes:**

Some branches have fallen. Otherwise, everything looks great. With the heavy snowfall we checked the roof on the screen house very well and looks like it's doing well. No concerns this month!

#### **Locations of Concern**

#### **North**



## South



East



West



**Report Number**