



NORTHWEST FIRE DISTRICT FIRE INSPECTION REPORT

Date: 2/15/2022
Inspector: Arneson, Dave
Inspection Type: Fire Department Access

Jurisdiction: Pima County
Inspection Number: 22-0266

Occupant Information

Name: Monica Aiponte
Phone: (520) 301-4483
Email:

Address: 4907 West Doria Drive
Suite:

State: AZ **Postal Code:** 85742

Primary Contact

Contact: Aiponte, Monica
Work Phone: 520-301-4483

Position: Manger
Email: Countrysidevillashoa@yahoo.com

Inspection Findings

Violation Code	Violations Violation Location
503.2.1	Doria Alley Access

Comments

Inspection Notes: Countryside Villas Homeowner Association,

Thank you for the invitation to evaluate your neighborhood for Fire Department access. You have done a phenomenal job at making a defensible space behind your homes.

The Arizona Department of Forestry and the Northwest Fire District recommends creating and maintaining a defensible space around your homes.

The Doria Alley access is blocked with permanent bollards. It is recommended to replace the permanent bollards with pad locking sleeve bollards that can be removed in the event of a fire. With removable bollards and the palo verde tree at the end of the alley removed, wildland firefighting vehicles would be able to make access to the back of your homes.

Examples of locking sleeve bollards were provided to Ms. Monica Aiponte.

Your dedication to fire and life safety is appreciated.

Please contact me with any questions or concerns. Dave Arneson, NWFD Fire Inspector.
darneson@nwfdaz.gov 520-887-1010 ext. 5002

Type	First Name	Last Name	Signatures Signature
Inspector	Dave	Arneson	

Violation Photos

File Name: image

Violation Code: 503.2.1

Specific Location: Doria Alley Access

Inspected Date: 02/15/2022 08:42:32



File Name: image
Violation Code: 503.2.1
Specific Location: Doria Alley Access
Inspected Date: 02/15/2022 08:42:32





