

LANDSCAPING REPORT (7-22-2022): REPLENISH BOULDER BARRIER

(along West side of Camino de Oeste at Joanna & Electric Transformer box)

Report by Monica Alponte, Countryside Villas HOA President, Friday, 7-22-2022

Installed 7-22-22 by MSM LANDSCAPING
6a-4p (10 hrs labor) Receipts attached

1. Purchased 15 Catalina Large Boulders from **AZ Trucking & Materials** to replace boulders that were removed in 2010 and used to place at Doria dead end.
2. Transported and installed 15 boulders to location (along west side of Camino de Oeste at Joanna) to protect electric transformer box and residences, pedestrians, and property from being damaged by out of control vehicles jumping the curb into and across the Joanna hammerhead parking lot.
3. **REF: See attached incident report dated 5-28-22**, in which out of control vehicle crashed into tree directly in front of electric transformer thankfully preventing vehicle from crashing into electric transformer.



Electric Transformer box (red arrow)



Traveling northbound on Camino de Oeste



Boulders placed around front and side of electric transformer where vehicle jumped curb back on 5-28-22.

Smaller rock circled in yellow marks exact spot where tree had been that prevented out of control vehicle from crashing at high speed into electric transformer back in May (see attached incident report dated 5-28-22)





Boulders also placed boulders in front of bushes, because bushes won't stop vehicles



View going opposite direction (southbound)



