


Before




After




Before




After



Before




After







Before




After



S2 - Before




S2 - After



S1 - Before



S1 - After



S1 - Final



Before




After




Before



After



Before



After



Before





After



Before



After



Before

After




Before




After



Before



After



Before




After



Before



After



Before



After



Before




After



Before




After



Before




After



Before




After




Before




After



Before




After




Before



After



Before



After



Before




After



Before



After



Before



After



Before (Oh NO) ☹️




After (Oh YES) 😊



Before



After



Everything under UPS




Before

Server setup on the floor, monitor on the desk



After

**Server in the rack, off the floor
Security monitoring in one place**



Before



After




Before



After



Before



After



Before



After



Before



After



Before




After




Before




After




Before



After







Before




After



Before



After




Before



After






Before



After



Before




After



Before



After



Top



Bottom




Behind




Before




After



Before



After



Before



After




Before




After



Before




After



Before



After



Before



After



Before




After




Before




After



Before



After



Before



After




Before



After



Before




After



Before


After



Before



After



Before




After




Before




After



Before



After



Before



After



Before




After




Before



After





Before




After




Before




After



Before



After



Before



After



Before



After



Before



After



Before




After



Before




After




Before


After




Before





After



Before



After



Before



After



Before



After



Before



After



Before



After





Before




After



Before



After



Before



After



Before



After




After



Before




After



Before




After




Before



After





Before



After



After




After




Before



As of 12-5-2019




Before (Front & Back)



After (Front & Back)




All switch's got cleaned up & wires organized in IT cabinet



Before



After



Before



After