



View from above



View from side



Below picture shows damage caused by overtight ratchet straps slung over top of generator

