

The RM of Nipawin continues to experience higher-than-normal water flow, resulting in road failures and flooding in areas. Water levels are being closely monitored as snowmelt progresses, and crews are actively inspecting drainage systems to ensure proper flow and reduce the risk of further flooding.

At this time, we are facing a number of challenges. Significant road surface failures, including complete washouts, are being repaired, while some roads remain entirely under water. Residents are asked to use caution when traveling, reduce speed and to respect all road closures and barricades in place.

Residents are encouraged to:

- Ensure sump pumps are in good working condition
- Keep culverts and drainage areas near your property clear of debris
- Avoid driving through flooded roads or standing water
- Report any road damage, flooding, or drainage concerns to the RM office

We appreciate your patience and cooperation as crews continue to respond to these conditions. Updates will be provided as the situation evolves.

Areas highlighted on the map reflect known road issues within the RM. Please note that as spring runoff progresses, conditions can change rapidly. Use caution when travelling and obey all posted signage, road closures, and barricades.

