
Fail - Cleared Throughout FL NFPA 101 2021 Chapter 7 Means of Egress 7.9.2.1.1 - Emergency Light Repair/Replace

 **Cleared on 12/23/2025**

Code Text:

Emergency lighting facilities shall be arranged to provide initial illumination that is not less than an average of 1 foot-candle (10.8 lux) and, at any point, not less than 0.1 foot-candle (1.1 lux), measured along the path of egress at floor level.

Fail - Cleared Throughout Office FL NFPA 01 2021 Chapter 14 Means of Egress 14.14.5.2.1 - Exit sign; illumination

 **Cleared on 12/23/2025**

Code Text:

Every sign required to be illuminated by 14.14.6.3, 14.14.7, and 14.14.8.1 shall be continuously illuminated as required under the provisions of Section 14.12, unless otherwise provided in 14.14.5.2.2. [**101**:7.10.5.2.1]

Fail - Cleared Under Stairs FL NFPA 01 2021 Chapter 10 General Safety Requirements 10.19.5.1 - No storage in mechanical rooms

 **Cleared on 12/23/2025**

Code Text:

Combustible material shall not be stored in boiler rooms, mechanical rooms, or electrical equipment rooms.

Thank you for your cooperation in keeping your business and our community safe! If you have any questions, please contact the fire inspector listed at the top of this report.