


The white on this jamb is a result of the Patio Door not having the 7402 interior snap jamb cover installed. This jamb cover is sent (un-installed) but with the door. This area is where one is to anchor the door on the fixed side and after anchoring; the cover is then to be put in place to enclose the fasteners and the cover is to be color matched to the interior of the door, which in this case would be woodgrain. If this cover is missing, not on the job, it can be ordered via our inside sales department. This cover is generally taped to the top of the mainframe and may have gone unnoticed...



Jamb Cover Missing
Jamb cover location



If you have any questions, please let me know.

Regards,
Johnny Miller