



Conigliaro Block's Construction Division in Action!

The photos below are from a recently completed project on the Charles River in Waltham, MA which involved the demolition of an existing retaining wall and the installation of a new retaining wall, guard rail and drainage structures.

We performed the work under extremely challenging weather conditions and completed the job in just 17 days.



Before – a failing retaining wall and sinking parking lot just feet away from the Charles River



Demolition of failing creosote timber wall within two feet of the river



Installation of new retaining wall base blocks using Conigliaro Blocks



Installation of wall corner and pipe penetrations blocks using Conigliaro Blocks



Completed retaining wall using Conigliaro Blocks



Installation of guard rail system




Installation of precast catch basin manholes




Installation of precast leach pits



Installation of below grade connecting piping



Backfill of leach pit and installation of manhole covers



Mortaring of catch basin covers



Completed site awaiting final grading and pavement in the Spring!



701 Waverly Street
Framingham, MA 01702
(888) CONIG – 25