

SURVEYOR: DELTA LAND SURVEYING, LLC
CONTACT: JNELSON@DELTA LBK.COM
PHONE: 806-701-5707

The survey information shown hereon was prepared from the result of an on the ground survey of the property shown hereon, and has been completed substantially in compliance with the Professional and Technical Standards promulgated by the Texas Board of Professional Land Surveying Practices Act, Section 663.13.

PLAT LIMBS LIST		
LINE	BEARING	DISTANCE
L1	N 01°46'44"E	20.00
L2	N 46°47'06"E	21.22
L3	S 43°12'33"E	10.43
L4	N 46°47'27"E	21.21
L5	S 01°47'27"W	100.47
L6	S 46°47'27"E	21.21
L7	N 46°47'27"E	21.42
L8	N 46°47'27"E	21.21
L9	N 46°47'27"E	21.21
L10	N 88°12'33"E	20.00
L11	S 43°12'33"E	21.42
L12	N 46°47'27"E	21.21
L13	S 40°54'41"E	13.56
L14	S 08°56'20"E	20.15
L15	S 51°32'27"E	20.00
L16	N 46°47'27"E	36.96
L17	S 72°04'40"E	18.57
L18	N 17°55'20"E	33.00
L19	N 46°47'27"E	21.21
L20	N 72°04'40"E	18.57
L21	S 40°40'38"E	13.50
L22	N 05°59'43"E	20.05
L23	N 46°47'27"E	21.21
L24	S 43°12'33"E	21.21
L25	N 46°45'34"E	42.40
L26	N 46°47'27"E	21.21
L27	N 46°47'27"E	21.21
L28	N 01°46'16"E	40.00
L29	N 46°46'51"E	14.14
L30	N 01°47'27"E	20.00
L31	N 46°47'27"E	21.21
L32	S 46°47'27"E	21.42
L33	N 88°12'33"E	3.07
L34	N 01°47'27"E	52.00
L35	N 46°47'27"E	21.21
L36	N 61°44'59"E	25.97
L37	S 35°28'04"E	18.16
L38	S 34°51'36"E	15.92
L39	N 46°47'27"E	21.21
L40	S 37°51'09"E	19.14
L41	N 49°08'00"E	14.71
L42	N 05°40'47"E	20.05

Adam N. Light
Registered Professional Land Surveyor No. 6684
Survey Date: July 5, 2019
Delta Land Surveying Project No. 19085

Attest _____ Secretary



DELTA LAND SURVEYING, LLC
 TBPLS # 10194496
 3307 82ND STREET, STE. J
 LUBBOCK, TX 79423
 806-701-5707
WWW.DELTALBK.COM