

#### **FUGRO TECHNICAL SERVICES LIMITED**

Fugro Development Centre 5 Lok Yi Street, Tai Lam Tuen Mun, NT Hong Kong



Client Ref. : --

Report No.

: 220501ST220118(6)A

Page 1 of 2

# REPORT ON DETERMINATION OF MECHANICAL FASTENER - NAIL

# Information Supplied by Client

Client : Fountain WPC Company Limited
Project : Testing of Recycled Timber

Sample Description : Recycle Timber

## **Laboratory Information**

Lab. Sample I.D. : ST220118/A1-A3
Date Received : 13 April 2022
Date Tested : 25 April 2022
Test Method : ASTM D6117-13e1

### **Test Results**

Lab. Sample I.D.	Surfaced to be tested	Failure Load (N)
ST220118/A1	Тор	578
ST220118/A2	Side	550
ST220118/A3	End	545

Remarks:

- 1.) The test results relate only to the samples tested.
- 2.) The results apply to the sample as received.
- 3.) The test samples are shown in the photograph on page 2 of this report.
- 4.) This report is to supersede our previous test report no. 220501ST220118(6).

Checked by :	h	Date : _	2 6 JUL 2023	_Certified by:	No	_ Date : <u>2 6 JUL 2023</u>
					Chan Chun Wai Ivan	

Manager (Product Testing Laboratory)



### **FUGRO TECHNICAL SERVICES LIMITED**

Fugro Development Centre 5 Lok Yi Street, Tai Lam Tuen Mun, NT Hong Kong

Client Ref.

Page of 2

Report No.

: 220501ST220118(6)A



Test Sample Sample I.D.: ST220118/A1-A3

\*\*End of Report\*\*