
Investigation of data points along two specific cables that have been identified in Lake Tahoe and Emerald Bay.

## May 5, 2023

7/9/2023, 5:22:10 PM UTC



#### CREATED

④ 5/5/2023, 5:24:01 PM UTC
④ by Monique Rydel

#### UPDATED

① 7/9/2023, 5:22:10 PM UTC

by Monique Rydel

#### LOCATION

◎ 38.934139, -120.002678





## **General Report Information**

Start Date	May 5, 2023	
River/Body of Water	Lake Tahoe	
Personnel	Seth Jones, Monique Rydel, Richard Panuschka	
Start Time	10:24	
Travel Method	Boat	

## Weather Information

Wind Speed (mph) 9.4	
Wind Speed (mph) 9.4	

## Site Locations (13 Items)

#### Site Locations - 1. Lake Tahoe - LT, 1.5

## Weather

Air Temperature (c)	3.3	
Weather Condition	Overcast	
Wind Speed (mph)	13.6	
Humidity (%)	64	
Precipitation (mm)	0.9	

#### **Details for Site**

Way Point Prefix	Lake Tahoe - LT
Way Point Number	1.5
Time at Way Point	11:35
Way Point Description	Sediment
Are there visible signs indicating a cable crossing?	N/A
Is there visible cable at location?	See Notes
Was there a general site sample collected?	Yes

## General Sample (GS) Information (1 Item)



## General Sample (GS) Information - 1. Sediment: Under Cable, 1.5

Type of Sample for GS	Sediment: Under Cable
Location of Collected Sample - GS	Under cable
Time of Collection - GS	11:37
Sample Prefix - GS	Lake Tahoe - LT
Sample ID (#) - GS	1.5
Additional Notes - GS (if any)	None.

#### Photo of GS Sample(s)



#### **General Site Notes**

Sediment on cable

#### Site Photos



Site Locations - 2. Lake Tahoe - LT, 4

#### Weather



Air Temperature (c)	5
Weather Condition	Partly cloudy
Wind Speed (mph)	15
Humidity (%)	60
Precipitation (mm)	0.2

Way Point Prefix	Lake Tahoe - LT
Way Point Number	4
Time at Way Point	12:26
Way Point Description	Control
Are there visible signs indicating a cable crossing?	N/A
Is there visible cable at location?	No
Was there a general site sample collected?	Yes

## General Sample (GS) Information (1 Item)

## General Sample (GS) Information - 1. Water: Surface, 4

Type of Sample for GS	Water: Surface
Location of Collected Sample - GS	Control
Time of Collection - GS	12:27
Sample Prefix - GS	Lake Tahoe - LT
Sample ID (#) - GS	4
Additional Notes - GS (if any)	None.

Photo of GS Sample(s)





**General Site Notes** 

Control

**Site Photos** 



## Site Locations - 3. Lake Tahoe - LT, 1.4

-		
Air Temperature (c)	3.3	
Weather Condition	Light rain	
Wind Speed (mph)	11.9	
Humidity (%)	79	
Precipitation (mm)	0.1	

## **Details for Site**

Way Point Prefix

Lake Tahoe - LT



Way Point Number	1.4
Time at Way Point	13:15
Way Point Description	Cable Location
Are there visible signs indicating a cable crossing?	N/A
Is there visible cable at location?	See Notes
Was there a general site sample collected?	Yes

## **General Sample (GS) Information (2 Items)**

#### General Sample (GS) Information - 1. Sediment: Under Cable, 1.4

Type of Sample for GS	Sediment: Under Cable
Location of Collected Sample - GS	Under cable
Time of Collection - GS	13:16
Sample Prefix - GS	Lake Tahoe - LT
Sample ID (#) - GS	1.4
Additional Notes - GS (if any)	None.

#### Photo of GS Sample(s)



#### General Sample (GS) Information - 2. Water: Directly on Cable, 1.4

Type of Sample for GS	Water: Directly on Cable
Location of Collected Sample - GS	Under cable
Time of Collection - GS	13:20
Sample Prefix - GS	Lake Tahoe - LT
Sample ID (#) - GS	1.4






Additional Notes - GS (if any)

Recollection

#### Photo of GS Sample(s)



#### **General Site Notes**

Recollection of water and sediment.

#### Site Photos



#### Site Locations - 4. Emerald Bay - EB, 1.1

#### Weather

Air Temperature (c)	18.3	
Weather Condition	Sunny	
Wind Speed (mph)	9.4	
Humidity (%)	36	
Precipitation (mm)	0	

## **Details for Site**




Way Point Prefix	Emerald Bay - EB
Way Point Number	1.1
Time at Way Point	13:47
Way Point Description	Cable Location
Are there visible signs indicating a cable crossing?	N/A
Is there visible cable at location?	See Notes
Was there a general site sample collected?	Yes

## **General Sample (GS) Information (2 Items)**

#### General Sample (GS) Information - 1. Water: Directly on Cable, 1.1

Type of Sample for GS	Water: Directly on Cable
Location of Collected Sample - GS	Under cable
Time of Collection - GS	13:48
Sample Prefix - GS	Lake Tahoe - LT
Sample ID (#) - GS	1.1
Additional Notes - GS (if any)	Recollection

#### Photo of GS Sample(s)



#### General Sample (GS) Information - 2. Sediment Collection, 1.1

Type of Sample for GS	Sediment Collection
Location of Collected Sample - GS	Under cable
Time of Collection - GS	13:56
Sample Prefix - GS	Emerald Bay - EB



Sample ID (#) - GS	1.1
Additional Notes - GS (if any)	Recollection

#### Photo of GS Sample(s)



**General Site Notes** 

Recollection

#### Site Photos



## Site Locations - 5. Emerald Bay - EB, 1.2

## Weather

Air Temperature (c)	18.3	
Weather Condition	Sunny	
Wind Speed (mph)	9.4	
Humidity (%)	36	
Precipitation (mm)	0	






Way Point Prefix	Emerald Bay - EB
Way Point Number	1.2
Time at Way Point	13:49
Way Point Description	Cable Location
Are there visible signs indicating a cable crossing?	N/A
Is there visible cable at location?	See Notes
Was there a general site sample collected?	Yes

## General Sample (GS) Information (1 Item)

#### General Sample (GS) Information - 1. Water: Bottom, 1.2

Type of Sample for GS	Water: Bottom
Location of Collected Sample - GS	Under cable
Time of Collection - GS	13:53
Sample Prefix - GS	Emerald Bay - EB
Sample ID (#) - GS	1.2
Additional Notes - GS (if any)	Sample collected 5' from cable end towards shore.

#### Photo of GS Sample(s)



**General Site Notes** 

Site Photos





## Site Locations - 6. Emerald Bay - EB, 1.3

#### Weather

Air Temperature (c)	18.3	
Weather Condition	Sunny	
Wind Speed (mph)	9.4	
Humidity (%)	36	
Precipitation (mm)	0	

## **Details for Site**

Way Point Prefix	Emerald Bay - EB
Way Point Number	1.3
Time at Way Point	14:02
Way Point Description	Other
Are there visible signs indicating a cable crossing?	N/A
Is there visible cable at location?	See Notes
Was there a general site sample collected?	Yes

#### **General Sample (GS) Information (1 Item)**

#### General Sample (GS) Information - 1. Water: Bottom, 1.3


Type of Sample for GS

Water: Bottom



Location of Collected Sample - GS	Under cable
Time of Collection - GS	14:03
Sample Prefix - GS	Emerald Bay - EB
Sample ID (#) - GS	1.3
Additional Notes - GS (if any)	Sample collected 10' from cable end towards shore.

#### Photo of GS Sample(s)



#### **General Site Notes**

#### Site Photos



## Site Locations - 7. Emerald Bay - EB, 1.4

Weather
---------

Air Temperature (c)	5
Weather Condition	Overcast
Wind Speed (mph)	5.6



Humidity (%)	73
Precipitation (mm)	0.3

Way Point Prefix	Emerald Bay - EB
Way Point Number	1.4
Time at Way Point	14:05
Way Point Description	Control 20'
Are there visible signs indicating a cable crossing?	N/A
Is there visible cable at location?	See Notes
Was there a general site sample collected?	Yes

## General Sample (GS) Information (1 Item)

#### General Sample (GS) Information - 1. Water: Bottom, 1.4

Type of Sample for GS	Water: Bottom
Location of Collected Sample - GS	20' from cable towards shore
Time of Collection - GS	14:05
Sample Prefix - GS	Emerald Bay - EB
Sample ID (#) - GS	1.4
Additional Notes - GS (if any)	None.

#### Photo of GS Sample(s)



**General Site Notes** Site Photos

20' towards shoreline



#### Site Locations - 8. Emerald Bay - EB, 3

#### Weather

Air Temperature (c)	5
Weather Condition	Overcast
Wind Speed (mph)	5.6
Humidity (%)	73
Precipitation (mm)	0.3

#### **Details for Site**

Way Point Prefix	Emerald Bay - EB
Way Point Number	3
Time at Way Point	14:11
Way Point Description	Water Intake
Are there visible signs indicating a cable crossing?	N/A
Is there visible cable at location?	See Notes
Was there a general site sample collected?	See Specific Cable or Water

#### Water Control, Intake, or Drinking Fountain Information (1 Item)

#### Water Control, Intake, or Drinking Fountain Information - 1. Water: Intake

Type of Sample for Water Control, Intake or Drinking Fountain	Water: Intake
Was there a Water Control, Intake, or Drinking Fountain sample collected?	Yes
How many Water Control, Intake, or Drinking Fountain samples collected?	1

#### Sample Information - Water Control, Intake, or Drinking Fountain (1 Item)


#### Sample Information - Water Control, Intake, or Drinking Fountain - 1. Emerald Bay - EB, 3

Location of Collected Water Control, Near Intake Intake or Drinking Fountain Sample



Time of Collection - Water Control, Intake, or Drinking Fountian	14:12
Sample Prefix - Water Control, Intake, or Drinking Fountain	Emerald Bay - EB
Sample ID (#) - Water Control, Intake, or Drinking Fountain	3
Additional Notes - Water Control, Intake, or Drinking Fountain Sample (if any)	None.

Photo of Water Control, Intake, or Drinking Fountain Sample(s)



#### **General Site Notes**

**Site Photos** 



Site Locations - 9. Emerald Bay - EB, 4

Weather



Air Temperature (c)	5.6
Weather Condition	Partly cloudy
Wind Speed (mph)	16.1
Humidity (%)	57
Precipitation (mm)	0.3

Way Point Prefix	Emerald Bay - EB
Way Point Number	4
Time at Way Point	14:15
Way Point Description	Control
Are there visible signs indicating a cable crossing?	N/A
Is there visible cable at location?	See Notes
Was there a general site sample collected?	Yes


## General Sample (GS) Information (1 Item)

## General Sample (GS) Information - 1. Water: Surface, 4

Type of Sample for GS	Water: Surface
Location of Collected Sample - GS	Control
Time of Collection - GS	14:16
Sample Prefix - GS	Emerald Bay - EB
Sample ID (#) - GS	4
Additional Notes - GS (if any)	Control

Photo of GS Sample(s)





**General Site Notes** 

#### Site Photos



## Site Locations - 10. Emerald Bay - EB, 1

#### Weather

Air Temperature (c)	5.6
Weather Condition	Partly cloudy
Wind Speed (mph)	16.1
Humidity (%)	57
Precipitation (mm)	0.3

## **Details for Site**

Way Point Prefix

Emerald Bay - EB






Way Point Number	1
Time at Way Point	14:26
Way Point Description	Cable Location
Are there visible signs indicating a cable crossing?	N/A
Is there visible cable at location?	See Notes
Was there a general site sample collected?	Yes

## **General Sample (GS) Information (2 Items)**

#### General Sample (GS) Information - 1. Water: Directly on Cable, 1

Type of Sample for GS	Water: Directly on Cable
Location of Collected Sample - GS	Under cable
Time of Collection - GS	14:26
Sample Prefix - GS	Emerald Bay - EB
Sample ID (#) - GS	1
Additional Notes - GS (if any)	None.

#### Photo of GS Sample(s)



#### General Sample (GS) Information - 2. Sediment: Under Cable, 1

Type of Sample for GS	Sediment: Under Cable
Location of Collected Sample - GS	Under cable
Time of Collection - GS	14:28
Sample Prefix - GS	Emerald Bay - EB
Sample ID (#) - GS	1



#### Additional Notes - GS (if any)

#### Photo of GS Sample(s)



None.

#### **General Site Notes**

#### Site Photos



## Site Locations - 11. Emerald Bay - EB, 1.5

#### Weather

-	
Air Temperature (c)	5.6
Weather Condition	Partly cloudy
Wind Speed (mph)	16.1
Humidity (%)	57
Precipitation (mm)	0.3

#### **Details for Site**



Way Point Prefix	Emerald Bay - EB
Way Point Number	1.5
Time at Way Point	14:30
Way Point Description	Other
Are there visible signs indicating a cable crossing?	N/A
Is there visible cable at location?	See Notes
Was there a general site sample collected?	Yes

## General Sample (GS) Information (1 Item)

## General Sample (GS) Information - 1. Water: Bottom, 1.5

Type of Sample for GS	Water: Bottom
Location of Collected Sample - GS	Under cable
Time of Collection - GS	14:31
Sample Prefix - GS	Emerald Bay - EB
Sample ID (#) - GS	1.5
Additional Notes - GS (if any)	None.

#### Photo of GS Sample(s)



General Site Notes 5'

Site Photos





## Site Locations - 12. Emerald Bay - EB, 1.6

#### Weather

Air Temperature (c)	5.6
Weather Condition	Partly cloudy
Wind Speed (mph)	16.1
Humidity (%)	57
Precipitation (mm)	0.3

## **Details for Site**

Way Point Prefix	Emerald Bay - EB
Way Point Number	1.6
Time at Way Point	14:33
Way Point Description	Other
Are there visible signs indicating a cable crossing?	N/A
Is there visible cable at location?	See Notes
Was there a general site sample collected?	Yes

#### **General Sample (GS) Information (1 Item)**

## General Sample (GS) Information - 1. Water: Bottom, 1.6

Type of Sample for GS

Water: Bottom



Location of Collected Sample - GS	Under cable
Time of Collection - GS	14:35
Sample Prefix - GS	Emerald Bay - EB
Sample ID (#) - GS	1.6
Additional Notes - GS (if any)	Sample collected 10' from cable end, towards shore.

Photo of GS Sample(s)



General Site Notes 10'

#### Site Photos



## Site Locations - 13. Emerald Bay - EB, 1.7

Weather
---------

Air Temperature (c)	18.3
Weather Condition	Sunny
Wind Speed (mph)	9.4



Humidity (%)	36
Precipitation (mm)	0


Way Point Prefix	Emerald Bay - EB
Way Point Number	1.7
Time at Way Point	14:39
Way Point Description	Other
Are there visible signs indicating a cable crossing?	N/A
Is there visible cable at location?	See Notes
Was there a general site sample collected?	Yes

## General Sample (GS) Information (1 Item)

#### General Sample (GS) Information - 1. Water: Bottom, 1.7

Type of Sample for GS	Water: Bottom
Location of Collected Sample - GS	Under cable
Time of Collection - GS	14:41
Sample Prefix - GS	Emerald Bay - EB
Sample ID (#) - GS	1.7
Additional Notes - GS (if any)	Sample collected 20' from cable end, towards shore.

#### Photo of GS Sample(s)



General Site Notes

20'

Site Photos





