

www.altamontcmc.org

VOTING MEMBERS

Robert Carling City of Livermore

Valerie Arkin City of Pleasanton

Donna Cabanne Sierra Club

David Tam Northern California Recycling Association

NON-VOTING MEMBERS

Enrique Perez
Waste Management
Altamont Landfill and
Resource Recovery
Facility

Arthur Surdilla / Wing Suen Alameda County

Robert Cooper Altamont Landowners Against Rural Mismanagement (ALARM)

<u>STAFF</u>

Judy Erlandson City of Livermore Public Works Manager

COMMUNITY MONITOR COMMITTEE Altamont Landfill Settlement Agreement AGENDA

DATE: Wednesday, January 13, 2021

TIME: **4:00 p.m.**

PLACE: Online Zoom Meeting

Zoom Link: https://us02web.zoom.us/j/85720312118

Zoom dial in phone number: 1-669-900-6833 Webinar ID: 857 2031 2118

- 1. Call to Order
- 2. Introductions
- 3. Roll Call
- 4. Approval of Minutes (From October 14, 2020)
- 5. <u>Open Forum</u> This is an opportunity for members of the audience to comment on a subject not listed on the agenda.

No action may be taken on these items.

- 6. Matters for Consideration
 - 6.1 Election of Chair (City of Livermore staff)
 - 6.2 Responses to Committee Member Questions:
 - Compost Labeling Requirements
 - Bird Strike Incident
 - 6.3 Five-Year Permit Review
 - 6.4 Review of Documents on GeoTracker website
 - 6.5 Reports from Community Monitor
 - 6.6 Altamont Community Monitor Committee website
 - 6.7 2020 Draft Annual Report
 - 6.8 Announcements (Committee Members)

7. Agenda Building

This is an opportunity for the Community Monitor Committee Members to place items on future agendas.

8. Adjournment

The next regular Community Monitor Committee meeting is tentatively scheduled to take place at 4:00 p.m. on **April 14, 2021**, at 3500 Robertson Park Road, Livermore.

Informational Materials:

- Community Monitor Roles and Responsibilities
- · List of Acronyms
- Draft Minutes of October 14, 2020

City of Livermore TDD (Telecommunications for the Deaf) (925) 960-4104

PURSUANT TO TITLE II OF THE AMERICANS WITH DISABILITIES ACT (CODIFIED AT 42 UNITED STATES CODE SECTION 12101 AND 28 CODE OF FEDERAL REGULATIONS PART 35), AND SECTION 504 OF THE REHABILITATION ACT OF 1973, THE CITY OF LIVERMORE DOES NOT DISCRIMINATE ON THE BASIS OF RACE, COLOR, RELIGION, NATIONAL ORIGIN, ANCESTRY, SEX, DISABILITY, AGE OR SEXUAL ORIENTATION IN THE PROVISION OF ANY SERVICES, PROGRAMS, OR ACTIVITIES. TO ARRANGE AN ACCOMMODATION IN ORDER TO PARTICIPATE IN THIS PUBLIC MEETING, PLEASE CONTACT THE ADA COORDINATOR AT ADACOORDINATOR@CITYOFLIVERMORE.NET OR CALL (925) 960-4170 (VOICE) OR (925) 960-4104 (TDD) AT LEAST THREE (3) BUSINESS DAYS IN ADVANCE OF THE MEETING.

The Community Monitor Committee Agenda and Agenda Reports are prepared by City staff and are available for public review on the Thursday prior to the Community Monitor Committee at the Maintenance Service Center, 3500 Robertson Park Road, Livermore, and on the Community Monitor Committee web site http://www.altamontcmc.org.

Under Government Code §54957.5, any supplemental material distributed to the members of the Community Monitor Committee after the posting of this Agenda will be available for public review upon request at 3500 Robertson Park Road., Livermore or by contacting us at 925-960-8000 and included in the agenda packet available on the Community Monitor Committee web site http://www.altamontcmc.org.

If supplemental materials are made available to the members of the Community Monitor Committee at the meeting, a copy will be available for public review at the Maintenance Service Center, at 3500 Robertson Park Road, Livermore.

NOTICE OF PUBLIC MEETING

The City of Livermore Public Works Department, Environmental Services Division invites you to attend a public Community Monitor Committee Meeting pursuant to the Settlement Agreement governing the expansion of the Altamont Landfill and Resource Recovery Facility (ALRRF), the City of Livermore, the City of Pleasanton, the Sierra Club, the Northern California Recycling Association (NCRA), and Altamont Landowners Against Rural Mismanagement (ALARM). Given the international COVID-19 pandemic, and consistent with the California Department of Public Health's recommendations, Alameda County Health Orders and Governor Newsom's Executive Order N-29-20, the meeting will be held via video teleconference at October 14, 2020 with NO PHYSCIAL LOCATION FOR PUBLIC ATTENDANCE. This teleconference meeting will be recorded. Please follow the instructions below to join the meeting remotely.

Zoom Link: https://us02web.zoom.us/j/85720312118

Zoom dial in phone number: 1-669-900-6833 Webinar ID: 857 2031 2118

Community Monitor Committee Roles and Responsibilities

Below is a summary of the duties and responsibilities of the Community Monitor Committee and related parties as defined by the Settlement Agreement between the County of Alameda, the City of Livermore, the City of Pleasanton, Sierra Club, Northern California Recycling Association, Altamont Landowners Against Rural Mismanagement, and Waste Management of Alameda County, Inc. The purpose of this document is to aid in determining if discussion items are within the scope of the Community Monitor Committee.

Community Monitor Committee's Responsibilities

Under Settlement Agreement section 5.1.2, the CMC is responsible for supervising and evaluating the performance of the Community Monitor as follows:

- A. Interviewing, retaining, supervising, overseeing the payment of, and terminating the contract with the Community Monitor;
- B. Reviewing all reports and written information prepared by the Community Monitor; and
- C. Conferring with the Community Monitor and participating in the Five Year Compliance Reviews (next due in 2015) and the Mid-Capacity Compliance Review (due when the new cell is constructed and capacity is close to 50%, unlikely to occur before 2028) (Condition number 6 of Exhibit A of the Agreement).

Community Monitor's Responsibilities

The Community Monitor supplements and confirms the enforcement efforts of the County Local Enforcement Agency. The Community Monitor is primarily responsible for:

- A. Reviewing any relevant reports and environmental compliance documents submitted to any regulatory agency (sections 5.7.1, 5.7.2, and 5.7.3);
- B. Advising the public and the Cities of Livermore and Pleasanton about environmental and technical issues relating to the operation of the Altamont Landfill via the CMC (section 5.7.4);
- C. Presenting an annual written report summarizing the Altamont Landfill's compliance record for the year to the CMC and submitting the report to Alameda County and the Cities of Livermore and Pleasanton (section 5.7.5);
- D. Notifying the County Local Enforcement Agency and Waste Management of Alameda County of any substantial noncompliance findings or environmental risk (section 5.7.6);
- E. Monitoring and accessing the Altamont Landfill site and conducting inspections (section 5.7.7);
- F. Counting trucks arriving at the Altamont Landfill (section 5.7.8); and
- G. Reviewing waste testing data and source information (section 5.7.9).

Waste Management of Alameda County's Responsibilities

Per the settlement agreement, Waste Management is responsible for:

- A. Paying for the services of the Community Monitor, based on an annual cost estimate (section 5.3.3).
- B. Paying an additional 20% over the annual cost estimate if warranted based on "credible evidence" (section 5.3.3).

HIS PACE WILLIAM AND THE PACE

List of Acronyms

Below is a list of acronyms that may be used in discussion of waste disposal facilities. These have been posted on the CMC web site, together with a link to the CalRecycle acronyms page: https://www.calrecycle.ca.gov/lea/acronyms.

Updates will be provided as needed. This list was last revised on December 23, 2020.

Agencies

ACWMA – Alameda County Waste Management Authority

ANSI - American National Standards Institute

ARB or CARB - California Air Resources Board

ASTM - American Society for Testing and Materials

BAAQMD - Bay Area Air Quality Management District

CDFW – California Department of Fish and Wildlife (formerly California Department of Fish and Game or CDFG/DFG)

CDRRR - California Department of Resources Recycling and Recovery, or CalRecycle

CIWMB - California Integrated Waste Management Board (predecessor to CDRRR - see above)

CMC - Community Monitor Committee

CVRWQCB - Central Valley Regional Water Quality Control Board

DWR – Department of Water Resources

LEA – Local Enforcement Agency (i.e., County Environmental Health)

RWQCB - Regional Water Quality Control Board

SWRCB - State Water Resources Control Board

Waste Categories

C&D - construction and demolition

CDI - Construction, demolition and inert debris

FIT – Fine materials delivered to the ALRRF, measured by the ton.

GSET – Green waste and other fine materials originating at the Davis Street Transfer Station, for solidification, externally processed.

GWRGCT - Green waste that is ground on site and used for solidification or cover (discontinued January 2010)

GWSA – Green waste slope amendment (used on outside slopes of the facility)

MSW - Municipal solid waste

RDW - Redirected wastes (received at ALRRF, then sent to another facility)

RGC - Revenue generating cover

Water Quality Terminology

BMP – Best Management Practice – A general term to identify effective means of pollution control, especially in the contexts of stormwater and air quality.

IDL – Instrument Detection Limit – The smallest concentration of a specific chemical, in reagent grade water, that can be detected, with 99% confidence, with the detection instrument (e.g. the mass spectrometer).

MCL – Maximum Contaminant Level – The legal threshold limit on the amount of a substance that is allowed in public water systems under the Safe Drinking Water Act.

MDL – Method Detection Limit – The smallest concentration of a specific chemical, in a sample that contains other non-interfering chemicals, that can be detected by the prescribed method, including preparatory steps such as dilution, filtration, digestion, etc.

NAL – Numeric Action Level – A concentration of a stormwater pollutant above which, the discharger must plan to reduce this concentration.

RL – reporting limit: in groundwater analysis, <u>for a given substance and laboratory</u>, the concentration above which there is a less than 1% likelihood of a false-negative measurement.

SWPPP - Storm Water Pollution Prevention Plan

Rev. 01/05/2021

Substances or Pollutants

ACM – asbestos-containing material

ACW - asbestos-containing waste

ADC - Alternative Daily Cover. For more information:

https://www.calrecycle.ca.gov/lgcentral/basics/adcbasic

BTEX - benzene, toluene, ethylbenzene, and xylene (used in reference to testing for contamination)

CH₄ - methane

CO₂ - carbon dioxide

COD – Chemical Oxygen Demand – A measure of the degree to which a wastewater discharge can deplete the oxygen in a body of water.

DO - dissolved oxygen

HHW - household hazardous waste

LFG - landfill gas

LNG - liquefied natural gas

MEK - methyl ethyl ketone

MIBK - methyl isobutyl ketone

MTBE - methyl tertiary butyl ether, a gasoline additive

NMOC – Non-methane organic compounds

NTU - nephelometric turbidity units, a measure of the cloudiness of water

PFAS – Per- and polyfluoroalkyl substances

TCE - Trichloroethylene

TDS – total dissolved solids

TKN - total Kjeldahl nitrogen

TSS – Total Suspended Solids

VOC - volatile organic compounds

Documents

CCR - California Code of Regulations (includes Title 14 and Title 27)

ColWMP - County Integrated Waste Management Plan

CUP - Conditional Use Permit

JTD - Joint Technical Document (contains detailed descriptions of permitted landfill operations)

MMRP - Mitigation Monitoring and Reporting Program

RDSI - Report of Disposal Site Information

RWD - Report of Waste Discharge

SRRE – Source Reduction and Recycling Element (part of ColWMP)

SWPPP - Stormwater Pollution Prevention Plan

WDR - Waste Discharge Requirements (Water Board permit)

General Terms

ALRRF - Altamont Landfill and Resource Recovery Facility

ASP – Aerated Static Pile composting, which involves forming a pile of compostable materials and causing air to move through the pile so that the materials decompose aerobically.

BGS - below ground surface

BMP - Best Management Practice

CASP - Covered Aerated Static Pile (ASP) composting

CEQA - California Environmental Quality Act

CQA - Construction Quality Assurance (relates to initial construction, and closure, of landfill Units)

CY – cubic yards

GCL - geosynthetic clay liner

GPS - Global Positioning System

IC engine - Internal combustion engine

LCRS - leachate collection and removal system

LEL – lower explosive limit

mg/L – milligrams per liter, or (approximately) parts per million

Rev. 01/05/2021

General Terms (continued)

μg/L – micrograms per liter, or parts per billion

PPE – personal protective equipment

ppm, ppb, ppt – parts per million, parts per billion, parts per trillion

RAC – Reclaimable Anaerobic Composter – a method developed by Waste Management, Inc., to place organic materials in an impervious containment, allow them to decompose anaerobically, and extract methane during this decomposition.

SCF – Standard cubic foot, a quantity of gas that would occupy one cubic foot if at a temperature of 60°F and a pressure of one atmosphere

SCFM - standard cubic feet per minute, the rate at which gas flows past a designated point or surface

STLC – Soluble Threshold Limit Concentration, a regulatory limit for the concentrations of certain pollutants in groundwater

TTLC – Total Threshold Limit Concentration, similar to STLC but determined using a different method of analysis TPD, TPM, TPY – Tons per day, month, year

WMAC - Waste Management of Alameda County

HIS PACE WILLIAM AND THE PACE OF THE PACE



COMMUNITY MONITOR COMMITTEE

Altamont Landfill Settlement Agreement

Minutes of October 14, 2020

DRAFT

1. Call to Order

The meeting came to order at 4:00 PM.

Mr. Carling noted that pursuant to the provisions of the Brown Act and due to recent executive orders issued by the governor to facilitate teleconferencing in order to reduce the risk of COVID-19 transmission at public meetings, this meeting was being held via Zoom meeting platform. Mr. Carling further explained the process and protocols for the meeting.

2. Roll Call

Members Present: Robert Carling, City of Livermore; Julie Testa, City of

Pleasanton; Donna Cabanne (joined at 4:15 p.m.), Sierra

Club; David Tam, NCRA

Absent: Robert Cooper, Altamont Landowners Against Rural

Mismanagement

Staff: Judy Erlandson, City of Livermore Public Works

Department; Mukta Patil, Langan/Community Monitor; Maria Lorca, Langan/Community Monitor; Kelly Runyon (joined at 4:15 p.m. and left at 5:15 p.m.), Contractor to

Langan

Others: Marisa Gan, Livermore Recycling Specialist; Arthur

Surdilla, Alameda County Department of Environmental Health (LEA); Marcus Nettz II, Senior District Manager, Altamont Landfill and Resource Recovery Facility (ALRRF);

Benjamin Wade (ALRRF)

3. Introductions

All those present introduced themselves.

4. Approval of Minutes of July 8, 2020 meeting

Ms. Testa moved approval, Mr. Tam seconded, and the minutes were approved 3-0.

5. Open Forum

There was no open forum discussion.

6. <u>Matters for Consideration</u>

6.1 Response to Committee Member Questions

Ms. Patil presented the responses to the committee member questions.

Submittal of Concentration Limits

On July 7, 2020 intra-well concentration limits were presented for MW-17R. Monitoring well MW-17R had been installed in 2018 to monitor groundwater downgradient of the Fill Area 2 Class II Surface Impoundment (LSI-3). Concentration limits were established for both inorganic (naturally occurring) and organic (anthropogenic) monitoring parameters and Constituents of Concern (COCs) using monitoring data from 2018 through 2019, on a well/constituent-specific basis. No comments had been provided yet by the CVRWQCB on the Geochem Applications reports.

Evapotranspirative (ET) Cover Test Area Reporting

The community monitor confirmed that based on information provided in the construction quality assurance report (Geosyntec, December 29, 2018), the ET cover was substantially completed on November 14, 2018 and the submittal of Performance Monitoring Technical Report is scheduled for April 1, 2024. ALRRF confirmed via e-mail on June 26, 2020 that the information in the report is correct. The schedule reporting date is one year after the reporting date proposed in the WDR, due to delays in construction of the ET cover.

Methane Concentrations in Perimeter Probes

At the July 8, 2020 meeting, Mr. Carling asked if 40% methane observed in GP-9 was naturally occurring. Mr. Carling also asked if the methane levels were higher than historical concentrations and if so, what the concentrations normally are. Ms. Patil explained that the issue was studied in 2015, when methane was detected after the Napa earthquake occurred. Based on carbon isotopes in the gas, it was identified that the gas was representative of much older "fossil" gas, and not the recently-formed landfill gas. Based on prior investigations at ALRRF, it seems most likely that the recent finding of 40% methane is from naturally occurring gas.

No comments were provided by the Committee members on item 6.1.

6.2 Five-Year Permit Review

Ms. Patil noted that the Five-Year permit had been mostly completed and discussed at the July 8, 2020 meeting. On April 13, 2020, Waste Management submitted a revised application package for the Five Year Solid Waste Facility Permit (SWFP) review and Permit Modification to the LEA. The LEA concluded that no further action was required at this time. Based on the review of the Permit Review Report (PRR) and the Joint Technical Document (JTD), no significant modifications were included with the exception of three bullet points that were listed in the packet: the closure date was modified from 2025 to 2065, with the phased closure in 2070; the area of the site was reduced from 2,170 acres to 2,063 acres; and the revised permit would be consistent with the updated waste discharge requirements that were issued in July 2016. An

update in the Five-Year permit process is that the LEA received comments from one Livermore resident. Ms. Patil summarized the resident's comments, and discussed the responses, as presented in the meeting packet. The LEA provided responses to some of the comments, but noted other comments were under the scope of oversight of BAAQMD and the CVRWQCB.

Ms. Patil explained that the LEA found that the modified SWFP was consistent with and met the requirements of Title 27 of the California Code of Regulations. On August 17, 2020 the LEA conducted a site inspection and CalRecycle participated virtually to determine if the site was meeting all State Minimum Standards. CalRecycle concurred with the Five-Year permit review and modified SWFP. The SWFP was issued on September 2, 2020 and the next five-year permit review due date is on May 8, 2025.

Ms. Cabanne noted that labeling of the composting area and county of origin should be required, and that it would be important to note the facility of origin. She asked to which agency this concern should be raised. Mr. Nettz explained the composting facility is not a part of the landfill, and therefore outside of the purview of the CMC. Mr. Nettz added WM does not sell Altamont compost to consumers at this time, only to commercial customers. Ms. Patil explained that the compost is certified by the US Compost Council. Mr. Carling asked the CM to do more research on this topic. Then, Mr. Carling asked if the LEA would ensure the Livermore resident received responses to the questions from the other agencies. Mr. Surdilla explained that the LEA would follow-up into the status of comments with concerned agencies to ensure that the resident's questions are answered, and then would follow up with the resident directly. Ms. Cabanne followed up by raising concerns regarding greenhouse emissions in the Bay Area, and Mr. Surdilla confirmed he would directly reach out to BAAQMD to get answers on the resident's questions.

6.3 Review of Reports Provided by ALRRF

Groundwater

Ms. Lorca provided an overview of the groundwater monitoring report. She stated that, as planned, two monitoring wells were abandoned and one new well was installed downgradient of the active face of Fill Area 2. Ms. Lorca noted that laboratory quality control for the First Semiannual 2020 sampling events decreased with respect to the previous sampling event, and included issues attributed to cross-contamination and sample hold times. She further explained that the results from the First Semiannual 2020 report were generally consistent and within ranges of previous detections observed at the wells. VOCs detected in E-20B and MW-20 were not detected in downgradient wells PC-1B and PC-1C. No VOCs were detected in E-23 located downgradient of E-05 and E-07. Naphthalene had been detected in PC-1B during July and November 2019 sampling events, but was not detected during the First Semiannual 2020, which likely corroborates the pump contamination hypothesis. Ms. Lorca concluded that the Gas Collection and Control System (GCCS) and LFG extraction wells are performing as expected and VOCs are continuing to decrease over time based on the VOC data, VOC time series plots, and LFG control system data.

Ms. Cabanne noted that the VOC data shows erratic trends, but E-07 and MW-4A appear to trend slightly up, and requested the Community Monitor stay focused on these wells. She also noted that the laboratory hold times have continued to be outside

of the acceptable range. Mr. Carling noted that QA/QC is an ongoing challenge. Mr. Wade explained WM has looked into cross contamination issues, and the frequency of occurrences is elevated, but that they discovered that ALRRF has detection limits for VOCs that are much lower than other landfills within the region, and cross contamination detections were frequently below the reporting limits. Mr. Carling and Ms. Cabanne noted that hold times were still not within the recommended timeframe, and Ms. Cabanne asked why the samples were not sent to Sacramento. Ms. Patil explained that per WM consultant, the Colorado facility is more state of the art and that they are better equipped at handling landfill samples. Mr. Nettz explained the landfill has many permits and follows all of them, including the requirements on analytical methods.

Air Emissions Report

Ms. Lorca summarized that 36 new gas wells were brought online during the reporting period, which made the total number of wells active vary between 110 and 132; no wells showed high temperatures during the reporting period, 17 wells showed oxygen exceedances, nine of which were corrected and eight remained under evaluation. Ms. Lorca further explained that during the second quarter, there were 65 exceedances of methane surface emissions, but during the third quarter, the exceedances decreased to 37. All of the corrective actions to block these emissions were successful and passed their 10-day and 30-day follow-up tests.

Ms. Cabanne asked about surface emissions and perimeter monitoring probes exceedances. Ms. Patil explained that they are different measurements. Corrective actions can be applied to surface emissions, and generally they do pass the follow-up tests. The perimeter probes are installed for permanent monitoring. As discussed in topic 6.1, an increase in methane concentration in the perimeter probes has been attributed to natural sources, and not landfill gas migration. Ms. Cabanne asked when would be the next reporting period for air emissions and landfill gas, and Ms. Lorca explained these reports are submitted on a semiannual basis, and the next report will be described in the April 2021 meeting. Ms. Cabanne also asked about the bird strike incident reported for the system failures. Mr. Nettz noted that WM could follow up with the facility team. Mr. Runyon added that based on his experience, the problems occur when a larger bird gets into the wiring; the small birds were never a problem, but something of a seagull size or larger tends to cause the issue when they contact more than one wire at a time. Ms. Cabanne added that in Sycamore Grove the park rangers have been seeing a lot more geese, and had issues with some of the park facilities.

6.4 Review of Documents on GeoTracker

The review began with a verbal summary of Langan's memo by Ms. Lorca; items from the GeoTracker tables were verbally summarized. Ms. Cabanne asked if the CVRWQCB had commented on WM's request to stop monitoring VOCs in stormwater. Ms. Lorca noted there had been no response to date. Ms. Cabanne asked the CM to follow up on VOCs responses from the CVRWQCB for stormwater testing.

6.5 Reports from Community Monitor

Ms. Patil reported the number of soil profiles reviewed this time (in July) is lower than other times. Langan reviewed 12 profiles, but typically the number had been on the order of 50 to 100. The CM will follow up on that item. From the soil files reviewed, 10 were complete and compliant, but there were two files that were incomplete.

Due to Shelter-in-Place order, the Community Monitors had not been allowed to visit the Landfill. Ms. Patil noted that Waste Management's policy "only allows for agency inspectors, or regulators who perform compliance related activities, to have access to the site at this time." Ms. Patil further explained that in lieu of site visit reports, summaries of LEA inspections were carefully reviewed for June through August 2020. She then summarized in detail the attached inspection reports, tonnage reports, as well as Figure 6.5-1. She also summarized special occurrences that happened during the period.

Mr. Tam commented on the changes in tonnages during the year, and the overall decrease. He noted that the county had generated less waste, and that would have economic implications for the planning department. He explained that the decrease does not solve the recycling industry's problem, as we do not have places developed where the diverted materials can be used.

Ms. Cabanne asked when the CM visits could be resumed. Ms. Patil noted that the CM had been discussing with WM to potentially resume visits in November or December of 2020. Ms. Cabanne then asked if the LEA had received the Remaining Site Capacity with Aerial Survey report that was pending in June, and Mr. Surdilla confirmed the report had been received. Ms. Cabanne and Mr. Carling requested additional details on the Class II soil file review, and noted concern on the reduced profile count. Ms. Patil explained she had not had the chance to follow up in detail, but that the CM team would coordinate with WM to understand why there were less profiles than expected.

6.6 ALRRF Operations During Shelter-In-Place

Ms. Patil reminded the committee members that as a result of COVID-19, WM had requested an emergency waiver. The waiver was in effect for 120 days, and WM did not request an extension. A completion report was submitted by ALRRF, which noted there were no exceedances on the approved conditional Emergency Waiver limits, and no material or vehicles in excess of the normal permitted tonnage and vehicle counts were noted.

Ms. Patil further summarized the changes seen since the Shelter-in-Place, as discussed during a conference call with Waste Management staff. The changes included: establishment of health and safety training to ALRRF staff members to protect from virus transmission; modified protocol for regulatory inspections; slight decrease in the amount of municipal solid waste received during April and May, which has returned back to usual levels. Waste Management reported that during April and May there were some closures of transfer stations that deliver to ALRRF, but these stations have

resumed operations. ALRRF has not seen an increase in medical waste. Regarding worker health and safety, a couple of cases have been detected in ALRRF field workers, WMAC reported increased awareness among employees in the past couple of months. Overall, it appears that ALRRF has been able to operate under modified protocols and continues to comply with applicable regulations. Mr. Nettz noted that the Community Monitor site visits could be resumed, and that he would facilitate coordination via e-mail.

6.7 Altamont Community Monitor Committee website

Ms. Patil explained there have been issues with the website due to the old builder software, which is poorly maintained by GoDaddy (the hosting company). The version in use for the site builder is three generations old, and will be decommissioned at the end of 2020. Ms. Patil further explained the amount of effort the Community Monitor had undertaken to upload files to the website, which recently were unsuccessful and the October meeting packet was uploaded to a temporary link hosted by Langan. The main concern is that all the documents that are currently on the website need to be downloaded and then uploaded back again when the new website is updated using a state of the art builder. Ms. Patil explained the website migration was quoted by GoDaddy at approximately \$2,500. The Community Monitor budget does not include website maintenance, and this would be outside of the usual budget. Ms. Erlandson explained the budget for the committee from the City of Livermore is zero, and that other funds assigned to the Community Monitor services could be reallocated. She further explained that funding was provided by Waste Management. The committee members and staff discussed additional funding options, including grants by the Education Advisory Board or administration funds, but they were not viable options. Ms. Patil noted that there is typically budget leftover at the end of the year, because there are certain tasks that change slightly and there is a potential for budget reallocation, pending committee approval. If authorized, the invoices would note the budget used for this purpose. Mr. Carling asked if the task would be subcontracted to GoDaddy for the \$2,500, or if the Community Monitor would migrate the site. Ms. Patil explained Langan has an internal software department, and the team had been working with them to see what kind of effort the migration would require. After the evaluation, either migration by Langan or GoDaddy would be chosen depending on which one is deemed more cost effective.

Mr. Carling asked to take a vote on a motion to authorize the Community Monitor to reallocate budget to migrate the website, with the understanding that it would not exceed \$2,500. Ms. Testa moved the motion, Ms. Cabanne seconded and the motion passed 4 to 0.

6.8 2020 Draft Annual Report Topics

The topics that are proposed to be included in the draft annual report due at the January meeting were listed in the agenda packet: Fill Area 2 operations and expansion; ongoing construction activity; groundwater monitoring wells information and concentration limits; the Five-Year permit review process; and operations during the COVID-19 health

emergency. Ms. Cabanne asked to include a topic on air quality. The proposed topics were agreed by Committee Members.

6.9 2021 Committee Meeting Schedule

Ms. Erlandson presented the 2021 Committee Meeting schedule. She noted it was still to be determined whether or not the January meeting would be held on zoom, or at the Maintenance Service Center in Livermore. The venue was reserved for the dates in the calendar. No changes were proposed to the Committee Meeting calendar, the dates for the meetings for 2021 are scheduled on the second Wednesday of the month on:

- January 13
- April 14
- July 14
- October 13

Mr. Tam moved approval, Ms. Testa seconded, and the meeting calendar was approved 4 to 0.

6.10 Announcements

Mr. Tam announced that the Altamont Landfill Open Space Committee, would be meeting in November. He then announced the Northern California Recycling Association had been communicating with Alameda County Planning Department and Stopwaste.org about tonnage reporting, and requested the LEA assisted with making tonnage reports more transparent for other landfills in Alameda County.

7. Agenda Building

No items were added to future agenda.

8. Adjournment

The meeting was adjourned at 6:06 p.m. The next meeting will be held on Wednesday January 13, 2021 at 4:00 p.m. potentially at the Livermore Maintenance Services Center at 3500 Robertson Park Road or presented virtually using Zoom.

HIS PACE WILLIAM AND THE PACE OF THE PACE



COMMUNITY MONITOR COMMITTEE STAFF REPORT

TO:

Community Monitor Committee Members

FROM:

Marisa Gan, Recycling Specialist

SUBJECT:

Community Monitor Committee Election of Chair

RECOMMENDED ACTION

Staff recommends the Community Monitor Committee elect a Committee Chairperson.

DISCUSSION

The Settlement Agreement, dated November 30, 1999, between the County of Alameda, the City of Livermore, the City of Pleasanton, Sierra Club, Northern California Recycling Association, Altamont Landowners Against Rural Mismanagement, and Waste Management of Alameda County, Inc. (Settlement Agreement), describes the duties and obligations of the Community Monitor Committee, but does not require the selection of a Committee Chairperson.

Although not required by the Settlement Agreement, staff recommends the Community Monitor Committee select a Chairperson to preside at all regular meetings and decide upon all points of order and procedure during the meeting.

If the Committee chooses to appoint a Chairperson, election shall be by majority vote of the Committee. If a quorum of three of the four Committee members is present, all three committee members would have to vote, and vote unanimously, in order to take this action.

Approved by:

Marisa Gan

Recycling Specialist

MEETING DATE:

AGENDA ITEM:

01-13-2021

CMC Agenda Packet Page 17 of 78

6.1

HIS PACE INTERVIORALLY BLANK



Memorandum

501 14th Street, 3rd Floor Oakland, CA 94612 T: 510.874.7000 F: 510.874.7001

To: ALRRF Community Monitor Committee

From: Langan – Community Monitor

Date: January 6, 2021

Re: CMC Meeting of 1/13/21 - Agenda Item 6.2 - Responses to Committee

Members' Questions

COMPOST LABELING REQUIREMENTS

At the October 14, 2020 meeting Ms. Cabanne requested clarification on compost labeling requirements and responsible agency.

The Community Monitor reached out to the LEA, and they reported not being aware of any requirement in Title 14 or 27 that specifies a responsible agency for labeling of compost for consumers. The LEA also noted that US Composting Council¹ is one of the agencies certifying compost at the Altamont CASP.

Article 7 of Title 14 of the California Code of Regulations requires all composting operations that sell or give away a quantity greater than 1,000 cubic yards of compost annually to verify that compost meets the maximum acceptable metal concentration limits, pathogen concentrations and physical contamination. The operator must receive test results of samples prior to removing compost from the composting operation or facility where it was produced. The LEA reviews the testing results.

BIRD STRIKE INCIDENT

At the October 14, 2020 meeting Ms. Cabanne requested to follow up regarding the March 14, 2020 bird strike that disrupted the gas system.

Waste Management staff reported their logs did not have any additional information for the incident.

-

¹ https://www.compostingcouncil.org/page/CertifiedCompostSTA

HIS PACE WILLIAM AND THE PACE OF THE PACE



Memorandum

501 14th Street, 3rd Floor Oakland, CA 94612 T: 510.874.7000 F: 510.874.7001

To: ALRRF Community Monitor Committee

From: Langan – Community Monitor

Date: January 6, 2021

Re: CMC Meeting of 1/13/21 - Agenda Item 6.3 - Five-Year Permit Review

On April 13, 2020 Waste Management submitted a complete application package for the Five Year Solid Waste Facility Permit (SWFP) review for ALRRF to the LEA. The Community Monitor summarized the documents submitted by ALRRF to comply with the Five-Year Permit in the CMC packet for the July 8, 2020 meeting. Based on the review of the Permit Review Report (PRR) and changes to the Joint Technical Document (JTD), no significant modifications were included, with the exception of the following:

- The estimated closure date was modified from 2025 to 2070;
- The area of the site was reduced from the original 2,170 acres to 2,063.6 acres; and
- Updated Waste Discharge Requirements (WDRs) for ALRRF were issued in July 2016.

The LEA found that the modified SWFP is consistent with and met the requirements of Title 27 of the California Code of Regulations. CalRecycle concurred with the Five-Year permit review and modified SWFP. The SWFP was issued on September 2, 2020 and the next five-year permit review due date is on May 8, 2025.

During the review process, the LEA received Public Comments from one Livermore resident. Comments and LEA responses were provided in the October 13, 2020 meeting packet. In addition, the LEA forwarded comments to the CVRWQCB and the Bay Area Air Quality Management District (BAAQMD). The CM received CVRWQCB and BAAQMD responses via email on December 2, 2020.

CVRWQCB responses to comments:

 SWFP must contain verbiage stating quench water for composting piles would not include leachate water.

The Compost General Order, and the site's current Notice of Applicability (NOA) and Waste Discharge Requirements (WDRs), allow compost leachate to be used on the active CASP piles, but compost leachate is not to be used anywhere on the Curing Pad. Additionally, leachate from the landfill cannot be used anywhere at the compost facility.

MEMO

• Drains for composting facility and underdrains for stormwater must be completely separate and cannot share the same storage ponds.

All leachate and underdrain liquid from the landfill is currently separated and neither can be used at the compost facility. All leachate from the compost facility is contained separately from storm water. The landfill's WDRs do not allow LSI-1 or LSI-2 water to be used for compost leachate. CVRWQCB staff has directed Waste Management to provide additional compost leachate storage.

• Stormwater leaving the landfill must be tested for volatile organic compounds (VOCs) for the duration of the permit due to historical public health and safety concerns.

The landfill's Monitoring and Reporting Program (MRP) requires surface water at the landfill, prior to discharging offsite, to be analyzed semi-annually for VOCs. Additionally, the Industrial Storm Water General Permit requires additional monitoring outside that required by the MRP.

BAAQMD response to comment:

As the third largest GHG-emitting landfill in California that contributes to the Tri-Valley's status
of being the worst dirty air basins, ALRRF must take action to reduce GHG emissions in the
future.

Altamont performs quarterly monitoring of the landfill surface to locate any potential surface leaks in compliance with the BAAQMD Regulation 8-34 for Solid Waste Disposal Sites and the California Air Resources Board's (CARB) Landfill Methane Regulation. The landfill gas collection system directs the gas to a series of sources to reduce the emissions.





Memorandum

501 14th Street, 3rd Floor Oakland, CA 94612 T: 510.874.7000 F: 510.874.7001

To: ALRRF Community Monitor Committee

From: Langan – Community Monitor

Date: January 6, 2021

Re: CMC Meeting of 1/13/2021 – Agenda Item 6. 4 – Review of Documents on

Geotracker Web Site

This is the abridged version of this memorandum. It is limited to new items reported in Geotracker since the previous Community Monitor Committee packet for the October 2020 meeting was completed, plus any prior items that provide useful background information for the new items. The complete, current version of this Review of Documents is located on the Community Monitor Committee web site and can be accessed using this link.

In this memo, each topic is given its own table where relevant documents are summarized in chronological order. For ease of reference, the topics are grouped under five major headings, and in the electronic version of this memo, <u>links</u> enable the reader to skip to a topic of interest and return to the top of the list when finished.

In the list, those topics that include a recent important development or Violation are marked with a special bullet:

This topic links to a list of documents that contains a recent violation or important development.

Summaries of the documents added since the previous Community Monitor Committee meeting are indicated with a heavy black border. They largely consist of ALRRF responses to Central Valley Regional Water Quality Control Board requests and notices, as well as design reports and reports describing specific incidents.

Violations and important areas of concern are highlighted in pink and yellow, respectively. Other noteworthy new items are highlighted in green. The topic list begins on the following page. When a single document addresses multiple topics, its summary is placed under the most general category available, which is often the first topic, Refuse Disposal Operations.

-

¹ https://altamontcmc.org/agendas-etc-2020-2023

MEMO

Topic List

Monitoring Wells

- Concentration Limits for Monitoring Wells
- New or Pending Monitoring Wells
- Change in Water Quality, Future Fill Area 2 Monitoring Well PC-1C
- > Exceedances in Monitoring Wells

Other Topics

Winterization Plan

MONITORING WELLS

Concentration Limits for Monitoring Wells

Topics

CVRWQCB	Letter Jan 11, 2019	Concurred with most of the limits proposed in the October report but noted that for wells PC-2A and WM-2, not enough samples were taken. Prior limits to remain until four samples taken from each well. Also adjusted downward 17 limits at 7 different wells, excluding outliers in historical data.
ALRRF	Letter Feb 15, 2019	Provided a summary table of agreed-upon concentration limits for monitoring wells in FA1 and FA2.
ALRRF/ Geochem Applications	Report Jul 31, 2019	For FA2 monitoring wells not yet installed, provides proposed concentration limits that would be applicable immediately after well installation, so that groundwater quality can be evaluated as soon as the wells are in service. Methodology is based on values from several nearby existing wells, as discussed between ALRRF and CVRWQCB staff.
ALRRF/GeoChem Applications	Letter Report Feb 21, 2020	Provided additional concentration limits for both the alluvial and unweathered bedrock zones for monitoring wells in FA2, based on combined interwell/intrawell statistical analysis, which may be used to define concentration limits as soon as a new well is installed.
ALRRF/GeoChem Applications	Report July 27, 2020	Provided additional intra-well concentration limits for monitoring parameters and constituents of concern for Fill Area 2 compliance monitoring well MW-17R that was installed in 2018 to monitor the Fill Area 2 Class II Surface Impoundment (LSI-3). The concentration limits are based on monitoring data collected during the 2018-2019 time period.





ALRRF/GeoChem Applications	Letter & Report October 26, 2020	2020 2-year update to groundwater concentrations limits (CLs) for monitoring parameters for Fill Areas 1 and 2. The updated CLs are based on historical baseline monitoring data through June 2020 for each constituent and were statistically calculated using the intrawell data evaluation procedure. The 2020 updated CLs were similar to the previous CLs, which had been presented in 2016 and 2018.
		presented in 2016 and 2018.

New or Pending Monitoring Wells

Topics

From	Format Date	Key Point(s)
ALRRF	Letter May 28, 2019	This letter proposes a new location for the not-yet-installed monitoring well MW-27 (see first four items above), because of PG&E high voltage overhead power lines near the previously proposed location. The new location is downslope and downgradient of the earlier location, and it is away from power lines and steep slopes.
ALRRF / Geosyntec	Letter Report Jul 31, 2019	Letter summarizes an attached report which details how monitoring wells within FA2 are to be destroyed and replaced as the landfill expands downslope, phase by phase. Specifically, because Phase 2B of FA2 is currently being constructed immediately downslope of Phase 1, wells MW-14, MW-14R and MW-21 at the toe of Phase 1 will be replaced by wells MW-22, MW-23 and MW-28 at the toe of Phase 2B, as shown on a drawing within the report.
ALRRF / Geosyntec	Report Nov 15, 2019	Provides report documenting the installation of Fill Area 2 monitoring wells MW-22, MW-23A, MW-23B, MW-27, MW-28 and soil gas probe VP-2. Most of the installations were typical, but MW-23B, initially drilled to 101 feet, became artesian after the casing was installed. It was fitted with a cap and pressure gauge. Groundwater sampling by SCS was planned for November, and soil gas testing at VP-2 was being done by ALRRF staff.



MEMO

From	Format Date	Key Point(s)
ALRRF / Geosyntec	Work Plan Feb 25, 2020	Provides a work plan for Fill Area 2 Phase 3 monitoring well installation and destruction. The plan proposed the installation of three new monitoring wells, MW-24, MW-25, and MW-26 as well as one gas probe, VP-3, in Fill Area 2. The proposed schedule states that on April 27, 2020 MW-24 and VP-3 will be installed and MW-22, MW28, and VP-2 (from Phase 2) will be destroyed. In addition, in August 2020, monitoring wells MW-23A and MW-23B (from Phase 2) will be destroyed and monitoring wells MW-25 and MW-26, will be installed.
ALRRF / Geosytec	Report May 29, 2020	Provides a report documenting the installation of Fill Area 2 Phase 3 monitoring well MW-24 and soil gas probe VP-3 as well as the destruction of Fill Area 2 Phase 3 monitoring wells MW-22 and MW-28 and soil gas probe VP-2 to allow construction of FA2 Phase 3 to progress. The monitoring wells and gas probes were installed and destroyed in accordance with the February 25, 2020 Fill Area 2 Phase 3 Monitoring Well Installation and Destruction Work Plan (Geosyntec 2020). Additional monitoring wells MW-25 and MW-26 for Phase 3 are proposed in the Work Plan to be installed and MW-22A and MW-22B were proposed to be destroyed in August 2020.
ALRRF / Geosytec	Letter & Report October 29, 2020	Provides a report documenting the installation of eight FA-2 groundwater monitoring wells from September 15 to 21, 2020. The new monitoring wells were installed downgradient of the planned liner extent of FA2 Phase 3 (MW-25 and MW-26) and the final anticipated FA2 lateral extent (MW-34A/B, MW-35A/B and MW-44A/B). In addition, two monitoring wells, MW-23A/B were destroyed on September 14 and 15, 2020. The monitoring wells and gas probes were installed and destroyed in accordance with the February 25, 2020 Fill Area 2 Phase 3 Monitoring Well Installation and Destruction Work Plan (Geosyntec 2020).





From	Format Date	Key Point(s)
ALRRF/ Geosyntec	Work Plan Addendum November 11, 2020	Addendum to the February 25, 2020 FA-2 Phase 3 Monitoring Well Installation and Destruction Work Plan. Two additional monitoring well clusters (MW-45 and MW-46) were proposed to be installed, at the conceptual planned FA2 final buildout extent in the thalweg of the valley as requested by the CVRWQCB. One well in each well cluster will be installed in the first encountered groundwater, which is anticipated to occur in weathered rock. A second well will be installed at each well cluster in groundwater in unweathered rock.
CVRWQCB	Letter November 18, 2020	CVRWQCB response to November 11, 2020 Fill Area 2 Phase 3 Monitoring Well Installation and Destruction Work Plan Addendum. CVRWQCB approved the installation of wells MW-25 and MW-26 as proposed in the Addendum, Work Plan, and SOP with the following conditions: 1. As noted in the Work Plan, if first groundwater occurs in alluvium, each cluster well shall be completed with three screened intervals, with the first well screen installed across the water table in the alluvial zone, followed by wells screened in the underlying weathered and unweathered bedrock. Given groundwater has been observed in nearby well P-2 as shallow as 2.80 feet below ground surface, a third shallow alluvial screened zone is expected for cluster wells MW-45 and MW-46. 2. Following well development, these two cluster wells, along with all other final FA-2 limit wells, are to be sampled quarterly until intrawell water quality protection standard CLs have been proposed for each sampling interval.

Change in Water Quality, Fill Area 2 Monitoring Well PC-1C

Topics

From	Format Date	Key Point(s)
ALRRF	Letter Jun 24, 2019	At this well, downslope of Fill Area 2 Phase 1, several inorganic parameters increased prior to landfilling in Fill Area 2. A new pump within that well may be part of the problem. The ALRRF will keep the RWQCB informed.



MEMO

From	Format Date	Key Point(s)
ALRRF	Letter Aug 28, 2019	Provided an update regarding adjustments made to the pump and tubing in this well in August. Sampling was done and results will be provided when available.
ALRRF/SCS	Letter Report Feb 5, 2020	Update of Fill Area 2 Monitoring Well PC-1C Activities. No significant difference in water quality was observed in August 2019 data between samples collected using the traditional sampling method (triple purge with bailer) and the samples collected using the dedicated bladder pump and the low-flow technique. The sample collected in November 2019 (after well redevelopment) showed a decrease in inorganic parameter concentrations. It is recommended that additional groundwater quality information be obtained as part of the next routine semiannual monitoring event before any decisions are made concerning the next steps for this well, including potential replacement.
CVRWQCB	Letter June 1, 2020	Response to statistical exceedance of inorganic constituent concentrations in well PC-1C in FA-2. CVRWQCB notes that once the Discharger's PC-1C investigation was expanded to include other upgradient wells, a clear pattern of increasing inorganic concentrations in groundwater west of PC-1C was also observed in E-20B and MW-12. The E-20B release from FA-1 impacted groundwater in FA-2 and by August 31, 2020, Waste Management must submit: 1. A revised site conceptual model to address the far reaching impact of the E-20B release, as well as the LFG releases recorded at MW-4, GP-8, and GP-9. 2. An updated Engineering Feasibility Study (EFS) to make appropriate changes to the E-20B corrective action program. 3. A proposal to expedite the establishment of background groundwater concentration limits across FA2 before E-20B release impacts other FA-2 wells. Well will need to be installed immediately, so that a background data set for each individual well can be obtained before any other FA-2 wells are impacted. 4. An amended Report of Waste Discharge to make appropriate changes to the E-20B release correction action program 90 days after submitting the EFS as required above.





From	Format Date	Key Point(s)
ALRRF/ Geosyntec	Letter August 31, 2020	Response to RWQCB letter on June 1, 2020 concerning statistical exceedances for TDS, chloride, sulfate, and dissolved calcium at PC-1C. Geosyntec conducted further assessment of the water quality changes in PC-1C and E-20B, and expanded the evaluation to include stormwater. Geosyntec concluded that the source of water quality changes does not originate from the LFG release in the E-20B corrective action area, but instead appeared to originate from stormwater affected by plant debris placed for erosion control in FA-1. The stormwater then traveled down a drainage channel between E-20B and PC-1C, and infiltrated into groundwater. In conclusion, Geosyntec believes an updated E-20B EFS is unnecessary.

Exceedances in Monitoring Wells

Topics

From	Format Date	Key Point(s)
ALRRF/SCS	Report Aug 2018	Naphthalene first found in well PC-1B, May 2018.
ALRRF/SCS	Letter Oct 12, 2018	Naphthalene diminishing but still present, Jul & Aug 2018. Resampling proposed, with a summary report by Feb 1, 2019.
ALRRF/SCS	Letter Report Jan 3, 2019	Well PC-1B was overhauled and resampled, Nov and Dec 2018. Naphthalene continued to be detected but in diminishing trace concentrations. Source of the naphthalene is uncertain; could be the pump inside the well. Continued sampling and monitoring for naphthalene proposed, semiannually.
CVRWQCB	Letter Jan 11, 2019	Responded to ALRRF Oct 12, 2018 letter; concurred with proposed actions and required quarterly sampling.
ALRRF/SCS	Letter Report Nov 12, 2019	Follows up on initial report (August 2019) of exceedances in wells MW-2A (nitrogen), PC-1B (calcium), MW-8A (COD and tetrahydrofuran), and MW-8B (COD, tetrahydrofuran and other VOCs). The wells were resampled. Exceedances were confirmed for PC-1B (calcium), MW-8A (COD and tetrahydrofuran), and MW-8B (COD only). Asserts that the exceedances are unrelated to FA2 activities due to distance from the Phase 1 fill area. Proposes further study and an Optional Demonstration Report due in early January.



MEMO

From	Format Date	Key Point(s)
ALRRF/SCS	Letter & Report Jan 9, 2020	Optional Demonstration Report. Verified statistical exceedances. Exceedances do not appear to be due to landfill leachate or LFG migration. The presence of the unlined storm water basin SB-H adjacent to wells MW-8A and MW-8B, soil disturbance during construction, and increased infiltration of storm water through the underlying soil and into groundwater, may be the causes of the increases in COD concentrations that triggered the statistical exceedances. Pipe-joining materials used for pipe installation during construction of the storm water basin appears to be the source of the THF detections in these wells.
		The report recommends continued semiannual groundwater monitoring and tracking the resulting data.
CVRWQCB	Letter Jan 24, 2020	Agrees with optional demonstration and requires: 1. Quarterly sampling of PC-2A, PC-2C, P-2, and ARC-2 (surrounding wells). This sampling shall begin with the Second Quarter 2020 sampling event and shall extend for a minimum two-years. 2. Comparison of exceedance wells to surrounding wells. 3. Reporting 30 days after sampling events



MEMO

From	Format Date	Key Point(s)
ALRRF	Letter May 21, 2020	Verification resampling results for groundwater monitoring wells MW-8B, MW-10, PC-1B, and PC-2A in Fill Area 2 that had initial exceedances of concentration limits during the second semiannual 2019 monitoring event. Resampling was performed on March 11, 2020 and April 1, 2020. The results confirmed the initial statistical exceedances for chloride in MW-10 and bicarbonate alkalinity in PC-1B were not confirmed; however, the statistical exceedances for chloride, and TDS in PC-2A were confirmed. Fill Area 2 wells with the confirmed statistical exceedances (MW-8B and PC-2A) are not located in close proximity or directly downgradient to the current active Phases 1 or 2 fill areas. Therefore based on the earlier Optional Demonstration Report (ODR) and this supplementary information, WMAC considered the changes in water chemistry to be unrelated to Fill Area 2 landfill activities and most likely due to the presence of the unlined storm water Basin H adjacent to the well, soil disturbance during construction of the basin, and/or increased infiltration of storm water. PC-2A is also located adjacent to storm water basin H and is thus likely to be affected by the same processes. WMAC proposed that MW-8A and MW-8B were added to the list of wells sampled on a quarterly basis and that the forthcoming summary document for the study area include a review of the parameter changes noted during the second semiannual 2019 period.
ALRRF/SCS	Letter & Report August 25, 2020	Groundwater monitoring conducted in FA-2 wells MW-8A, MW-8B, MW-13B, PC-1B, PC-1C, PC-2A, PC-2C, and P-2. MW-8B showed an initial statistical exceedance for dissolved calcium and total dissolved solids. Other than MW-8B, no new initial concentration limit exceedances were identified for inorganic monitoring. Recurring statistical exceedances for MW-8B (chloride), PC-1B (dissolved calcium), PC-1C (dissolved calcium, chloride, sulfate, and total dissolved solids) and PC-2A (dissolved calcium, chloride, and total dissolved solids) were observed. Previous concentrations of THF and naphthalene were not detected in the samples, and other than a single below RL concentration of toluene, no VOCs were detected in the samples. PC-2A, PC-2C, P-2 and ARC-2 are continued to be sampled quarterly to monitor statistical exceedances.





From	Format Date	Key Point(s)
ALRRF	Letter October 16, 2020	Letter states that during the first semiannual 2020 monitoring event, naphthalene in MW-2B and bis(2-ethylhexyl) phthalate in E-05 were observed above the reporting limit. Naphthalene was detected in the May 2020 MW-2B sample at 1.1 µg/L, slightly above the reporting limit (1.0 µg/L). Re-sampling occurred on August 12, 2020 where naphthalene was not observed and September 3, 2020 where naphthalene was detected below the RL. Therefore, the initial naphthalene detection from May 2020 was not confirmed. Bis(2-ethylhexyl) phthalate was detected at 26 µg/L, above the RL of 10 µg/L in May 2020 at E-05. After re-sampling once in August and twice September 2020, it was reported at 22 µg/L, 16 µg/L and 13 µg/L respectively; resampling confirms the initial detection in May 2020 but showed decreasing concentration over time. This confirmed detection in E-05 does not appear to be due to the influence of either LFG or leachate from ALRRF as bis(2-ethylhexyl) phthalate is not generally found in LFG and historical concentration in leachate samples since 2005 have not been elevated. WM proposed to conduct a study to determine the nature of bis(2-ethylhexyl) phthalate detection in an ODR which will be submitted within 90 days from October 9, 2020.

OTHER TOPICS

Winterization Plan Topics

From	Format Date	Key Point(s)
ALRRF	Report November 13, 2020	2020 – 2021 Winterization Plan to meet the requirements of the WDR. The report summarizes winterization work to prepare the Site for wet weather, improve site drainage controls and minimize erosion. A wet season inspection was performed in September 2020, and winter preparation activities were undertaken prior to the October 31 deadline specified in the WDR.





Memorandum

501 14th Street, 3rd Floor Oakland, CA 94612 T: 510.874.7000 F: 510.874.7001

To: ALRRF Community Monitor Committee

From: Langan, Community Monitor

Date: January 6, 2021

Re: CMC Meeting of 1/13/21 – Agenda Item 6.5 – Reports From Community

Monitor

Altamont Monthly Operations and Records Review

Community Monitor site visits have been suspended by ALRRF during the Shelter-in-Place period. Waste Management has declared that the COVID-19 pandemic is a force majeure event, and therefore their policy formally "only allows for agency inspectors, or regulators who perform compliance related activities, to have access to the site at this time." A site visit was allowed for the month of November, during a period when the state and county allowed additional activities to be conducted.

In lieu of site visit reports, summaries of LEA inspections available on CalRecycle's website, are provided for the months where site visits were not completed. The reports in this item include:

- LEA Inspection for September, which took place on September 21, 2020.
- LEA Inspection for October, which took place on October 26, 2020.
- Community Monitor Site Visit for November, which took place on November 11, 2020.

Details about operations-related matters are provided in the attached reports. Issues that cause special concern are marked with yellow rectangles in the monthly reports. For the fourth quarter, construction of additional landfill space in Fill Area 2, Phase 3 was ongoing. Windblown litter issues continued. Fill Area 2 Phase 2/2B began operations at the end of March 2020, and Phase 2/2B has been the active disposal area.

Also attached are graphs showing monthly tonnages by type of material for the most recent 12-month period. Figure 6.5-1 shows the breakdown of materials that make up Revenue-Generating Cover. Figure 6.5-2 shows these same quantities, plus the Municipal Solid Waste (MSW) and Special Waste tonnage for each month.

ALRRF Community Monitor Monthly Report

September 2020

LKKF Comn	September 2020			
Monthly Tonr	nage Report for September 2020, received (October 15, 2020		
Tonnage	<u>tons</u>			
Dis	sposed, By Source Location			
1.1	1.1 Tons Disposed from Within Alameda County			
1.2	Other Out of County Disposal Tons		1,728.20	
		subtotal Disposed	87,319.99	
Dis	sposed, By Source Type			
2.1	C&D		378.09	
2.2	MSW		83,774.93	
2.3	Special Wastes	_	3,166.97	
		subtotal Disposed	87,319.99	
			0.00	0.00%
Ot	her Major Categories			
2.4	Re-Directed Wastes (Shipped Off Site or Beneficially Used)		0.98	
2.5	Revenue Generating Cover		30,833.66	
		Total, 2.1 - 2.5	118,154.63	
Ma	aterials of Interest			
2.3.1	Friable Asbestos		291.38	
2.3.2	Class 2 Cover Soils		10,168.62	
2.5.1	Auto Shredder Fluff		10,145.77	
2.5.2	Processed Green Waste/MRF fines, Beneficial Use (GSET)		0.00	
2.5.3	MRF Fines for ADC		739.07	

Review of LEA Site Inspection on September 21, 2020

For the month of September, ALRRF did not allow site visits from the Community Monitor because of the COVID-19 emergency and Shelter-in-Place order. The LEA conducted inspection using a modified procedure to limit person-to-person contact. There were signs posted at the ALRRF office door with COVID-19 safety protocols visible for employees.

The LEA conducted an inspection on September 21, 2020. The general conditions noted in the report and pictures appear to be good, and the weather was sunny with light winds. Unusual litter was observed along access roads while approaching the facility, which appeared to be unrelated to Landfill operations. V-ditches along main paved roads were maintained clear and with green filter socks. The inspector observed newly installed straw wattles near the office. No issues observed

Fill Area 1 was reportedly in good condition. Minimal activity was occurring on the top deck of Fill Area 1 at the time. The inspector did not observe any bird activity during the inspection at Fill Area 1. Fill Area 1 slopes were observed to remain in good condition and free of erosion. A pile of inert debris was observed on the top deck of Fill Area 1, which was being used for Winterization in Fill Area 2 and drainage improvements.

The Solidification Pit Area was observed to be in good condition. A new tank that will hold fresh water had been placed near the pits to provide clean water for washing down/cleaning vehicles at the area.

The active face was observed in the southern portion of Fill Area 2 Phase 2. Fill Area 2, Phase 1 is complete for the time being, except for minor unloading of large loads that could pierce the bottom fluff layer (first 10 feet of Fill Area 2 Phase 2). The LEA did not observe bird activity during the inspection at Fill Area 2. The previous active faces were covered and no issues were noted with the integrity of the cover. Phase 3 earthwork continued. Several areas appeared to be cleared and graded in preparation of the placement of the liner systems. Some slopes to the east/southeast of the current Active Face had liner/operation fill layer placed on the slope.

Wind screens were observed in order to control windblown litter. The inspector observed a litter crew and several black bags of previously collected litter. Debris was not observed escaping the facility.

No violations or areas of concern were reported in the September inspection report.

Special Occurrences

There were no special occurrences for the month of September 2020.

ALRRF Community Monitor Monthly Report

October 2020

Monthly Tonn	nage Report for October 2020, received November 11, 2020		
Tonnage	<u>tons</u>		
Dis	sposed, By Source Location		
1.1	1.1 Tons Disposed from Within Alameda County		
1.2	Other Out of County Disposal Tons	1,327.81	
	subtotal Disposed	86,458.93	
Dis	sposed, By Source Type		
2.1	C&D	277.05	
2.2	MSW	82,843.76	
2.3	Special Wastes	3,338.12	
	subtotal Disposed	86,458.93	
		0.00	0.00%
0.11	Land Marine Colonia de la		
	her Major Categories	1.00	
2.4	Re-Directed Wastes (Shipped Off Site or Beneficially Used)	1.99	
2.5	Revenue Generating Cover Total, 2.1 - 2.5	26,910.54 113,371.46	
	Total, 2.1 - 2.5	113,371.40	
Ma	aterials of Interest		
2.3.1	Friable Asbestos	207.13	
2.3.2	Class 2 Cover Soils	27,001.03	
2.5.1	Auto Shredder Fluff	9,456.36	
2.5.2	Processed Green Waste/MRF fines, Beneficial Use (GSET)	0.00	
2.5.3	MRF Fines for ADC	659.47	

Review of LEA Site Inspection on October 26, 2020

For the month of October, ALRRF did not allow site visits from the Community Monitor because of the COVID-19 emergency and Shelter-in-Place order. The LEA conducted inspection using a modified procedure to limit person-to-person contact, and reported filling a COVID-19 Visitor Screening form prior to arrival on site. There were signs posted at the ALRRF office door with COVID-19 safety protocols visible for employees.

The LEA conducted an inspection on October 26, 2020. The general conditions noted in the report and pictures appear to be good and similar to previous inspections, and the weather was sunny and windy. Minimal litter was observed along access roads while approaching the facility. V-ditches along main paved roads were maintained clear and with green filter socks.

Fill Area 1 was reportedly in good condition. Strong winds were observed on the north side of the Bird Perch. The pile of inert debris was smaller than the previous inspection as materials continued to be used for Winterization in Fill Area 2. Drainage at Fill Area 1 has been prepared and reinforced for Winter months.

A berm was placed above the Solidification Pits to prevent flow liquid from entering this area.

The active face was observed in the southeast of Fill Area 2 Phase 2, where two tippers were unloading. The winterization area had been prepared on the top deck of Fill Area 2, Phase 1. The LEA observed a tipper located in this area and inert debris integrated into the pad. The LEA did not observe bird activity during the inspection at Fill Area 2, and reported ALRFF continue to maintain bird controls at the site.

No violations or areas of concern were reported in the October inspection report.

On September 18, 2020, the LEA received a request from ALRRF for an Emergency Waiver of minimum standards for landfill operations because of the statewide wildfires and the potential disposal of fire debris at the site. The LEA granted conditional approval of the Emergency Waiver on September 30, 2020 with the following LEA approved Terms and Conditions:

- SWFP Condition 5.c: increase of 2,500 tons per day (tpd), up to 13,650 tpd (from the maximum permitted of 11,150 tpd) for the duration of the Emergency Waiver only;
- SWFP Condition 5.d: increase of 125 refuse vehicles per day (vpd), allowing up to 682 refuse vpd (from the permitted peak daily traffic volume of 557 refuse vpd) for the duration of the Emergency Waiver only.
- The effective period of the requested Emergency Waiver began on September 30, 2020 and shall not exceed 120 days from that date.

ALRRF Community Monitor Monthly Report

November 2020

	,,		
Monthly Tonr	nage Report for November 2020, received December 10, 2020		
Tonnage	e Summary:	tons	
Dis	sposed, By Source Location		
1.1	Tons Disposed from Within Alameda County	76,973.13	
1.2	Other Out of County Disposal Tons	607.56	
	subtotal Dispose	d 77,580.69	
Dis	sposed, By Source Type		
2.1	C&D	180.42	
2.2	MSW	75,358.95	
2.3	Special Wastes	2,041.32	
	subtotal Dispose		
		0.00	0.00%
	her Major Categories	4 54	
2.4	Re-Directed Wastes (Shipped Off Site or Beneficially Used)	1.54	
2.5	Revenue Generating Cover	24,045.65	
	Total, 2.1 - 2.	5 101,627.88	
Ma	aterials of Interest		
2.3.1	Friable Asbestos	254.09	
2.3.2	Class 2 Cover Soils	7,842.52	
2.5.1	Auto Shredder Fluff	8,461.31	
2.5.2	Processed Green Waste/MRF fines, Beneficial Use (GSET)	0.00	
2.5.3	MRF Fines for ADC	552.37	

ALRRF Reports from Community Monitor

November 2020

Site Visit November 11, 2020, 1:00 PM - 3:30 PM

- Attended by Maria Lorca (Community Monitor).
- Escort: Marcus Nettz and Benjamin Wade (Waste Management). Announced.
- Weather: Partial, warm, light winds.

General Observations

- A modified site visit protocol was followed to maintain social distance between Waste Management staff and the Community Monitor. Prior to the site visit, the Community Monitor filled a COVID-19 Visitor Screening form.
- Altamont Pass Road was clear and free of windblown debris near the entrance to the site. Traffic to the site was flowing freely through the road and the entrance of the Landfill.
- The scale houses were in good condition and had a green light indicator.
- Winterization plan was ongoing. Straw rolls and adsorbent socks on the drainage ditches were observed around the site.



Fill Area 1

- New landfill gas wells have been installed on Fill Area 1
- The slopes of Fill Area 1 were observed in good condition and showed no signs of erosion. The seeps that were present in February had been controlled.

LSI ponds/basins

• The LSI ponds were in good condition. LSI-2 held little liquids (underdrain) and LSI-1 (leachate) was at about half of its capacity.

Fill Area 2 Operations

- Several birds were observed in the vicinity of Fill Area 2, but there were fewer birds than those observed in the previous Community Monitor site visits.
- Compactors were working on the toe of the active face to place Alternative Daily Cover (ADC) on top of refuse.
- Windblown litter was present in this area. A four person crew was observed removing litter in the vicinity of Fill Area 2.

- The top portion of Fill Area 2 Phase 1 had a reused concrete pad to handle disposal during wet weather.
- Fill Area 2 has received more than one million tons of material, which triggers landfill gas well requirements. Landfill gas wells were installed in Fill Area 2 and were connected to the headers of Fill Area 1.



Fill Area 2 Construction

 Phase 3 construction is on schedule. ALRRF expects to complete the construction in November and submit completion reports to the agencies in January. Once approved, the operations on Phase 3 should commence in April 2021. Also, some initial construction of Phase 4 was ongoing.

ET Cover Test Area

- This area was examined on foot on the south face of Fill Area 1.
- The ET cover area was observed in good condition and had dry plants.

Basin H and Mitigation Pond

- Sedimentation basin H and the mitigation pond were observed during this site visit. Both were observed to be dry. Vegetation was observed in the mitigation pond area. Waste Management commented that additional work needs to be undertaken to repair the pond.
- Windblown litter was observed in this area.







Figure 6.5-1 Monthly Volumes of Revenue-Generating Cover





Memorandum

501 14th Street, 3rd Floor Oakland, CA 94612 T: 510.874.7000 F: 510.874.7001

To: ALRRF Community Monitor Committee

From: Langan – Community Monitor

Date: January 6, 2021

Re: CMC Meeting of 1/13/21 - Agenda Item 6.6 - Altamont Community Monitor

Committee Website

The Altamont Community Monitor Committee website (http://altamontcmc.org/) is hosted by GoDaddy, an American internet domain registrar and hosting company. The old version of the site used an old builder software, which was scheduled to be deprecated. After discussing the issue with the CMC at the October 14, 2020 meeting, the Community Monitor team updated the website.

Langan's Information Technology team worked on the update, and completed the migration on December 23, 2020. There have been no issues reported after the website migration. All documents previously available were migrated and future agenda packets will be posted to the website.

HIS PACE WILLIAM AND THE PACE OF THE PACE



Memorandum

501 14th Street, 3rd Floor Oakland, CA 94612 T: 510.874.7000 F: 510.874.7001

To: ALRRF Community Monitor Committee

From: Langan – Community Monitor

Date: January 6, 2021

Re: CMC Meeting of 1/13/21 - Agenda Item 6.7 - Topics for 2020 Annual Report

A draft of the Annual Report for 2020 is attached. The list below summarizes the topics-of-interest for 2020 that were identified by Committee Members. Each of these is addressed or updated in the appropriate section(s) within the reports, and those sections are identified below.

<u>Topic</u>	Section(s)				
Fill Area 2 operations and expansion					
Construction activity during 2020 Monitoring well replacement Deviations from baseline concentration limits	2.2 – 3 rd bullet 2.2 – 1 st bullet 2.3.2				
Windblown litter incidents and controls	1.2, 1.4, 2.2 – 9 th bullet, 2.3				
Five-Year Permit Review	2.4.1				
Air quality concerns	2.4.4				
Landfill operations during COVID-19 Health Emergency	2.1				
PFAS investigation	2.4.6				

Information has been updated through the report to reflect changes that have occurred in this year.

HIS PACE WILLIAM AND THE PACE OF THE PACE

COMMUNITY MONITOR ANNUAL REPORT 2020

ALTAMONT LANDFILL AND RESOURCE RECOVERY FACILITY Livermore, CA

Prepared For:

ALRRF Community Monitor Committee

Prepared By:

Langan Engineering and Environmental Services, Inc. 501 14th Street, 3rd Floor Oakland, California 94612

> DRAFT Maria E. Lorca Senior Staff Geologist

DRAFT Mukta Patil, PE Senior Project Engineer

> January 6, 2021 750657601



TABLE OF CONTENTS

1.0	Intro	duction	<i>'</i>
	1.1	Background: Settlement Agreement	
	1.2	Prior Community Monitor Work	
	1.3	Regional Context and Landfill Capacity Needs	3
	1.4	Site-Specific Constraints and Opportunities	
	1.5	Overview of Operations, Regulations and Permits	
		1.5.1 Operational Functions and Requirements	5
		1.5.2 Requirements For Fill Area 2 Development and Use	
2.0	Com	munity Monitor Activities and Issues	11
	2.1	Introduction	
	2.2	Monitoring of Improvements and Changes	
	2.3	Compliance and Significant Incidents	
		2.3.1 Compliance Issues Documented by the LEA	
		2.3.2 Water Board Violations and Concerns	
		2.3.3 Other Incidents	19
	2.4	Review of Reports	20
		2.4.1 Five-Year Permit Review	20
		2.4.2 Groundwater	20
		2.4.3 Storm Water	21
		2.4.4 Air Quality	22
		2.4.5 Mitigation Monitoring	23
		2.4.6 Per- and Polyfluoroalkyl Substances (PFAS) Report	24
	2.5	Review of Records	
		2.5.1 Class 2 Soils	25
		2.5.2 Special Occurrences Log	25
		2.5.3 LEA Inspection Reports	25
	2.6	Monthly Inspections	25
3.0	Look	ing Ahead: Anticipated Efforts and Issues	27
	3.1	Introduction	
	3.2	Issues to be Tracked in 2021	
		3.2.1 Ongoing Review	
		3.2.2 Site Inspections	
		3.2.3 Class 2 Soils File Review	
		3.2.4 Permit Requirements Triggered by Expansion Date	



1.0 INTRODUCTION

1.1 Background: Settlement Agreement

In December 1999, a Settlement Agreement was reached among parties involved in a lawsuit regarding the proposed expansion of the Altamont Landfill and Resource Recovery Facility (ALRRF). The settlement limited the expansion to a second permitted operational area, known as Fill Area 2, adjacent to the existing Fill Area 1. The Settlement Agreement established the Community Monitor Committee (CMC) and a funding mechanism for its technical consultant, the Community Monitor (CM).

The Settlement Agreement defines the purview of the CMC and the CM. The CM's scope of work is further defined in a contract between the CM and the CMC. The City of Livermore provides staff and administrative support to the CMC, as well as management of the CM contract and space for CMC meetings. The City also acts as financial agent for the CMC, pursuant to a letter agreement dated July 6, 2004.

In broad terms, the CM is to review certain reports and information, as defined; monitor incoming traffic by conducting truck counts, as described in the Settlement Agreement; and inspect the ALRRF site no more than twelve times each year. The Settlement Agreement describes the CM's Scope of Work to include "issuing a written report each year summarizing the ALRRF's compliance record for the period since the last such report with respect to all applicable environmental laws and regulations." This Annual Report provides that summary for 2020.

The Settlement Agreement also requires that the ALRRF operator, Waste Management of Alameda County (WMAC), pay invoices submitted by the CM to the CMC, if the work represented in those invoices is consistent with the CM's scope of work and role as defined in the Settlement Agreement.

1.2 Prior Community Monitor Work

Records indicate that the CMC retained a technical consultant as the CM from 2005 through part of 2007.

In mid-2007, the CMC selected the current CM team of Environmental Science Associates (ESA) and Langan (formerly Treadwell & Rollo). This team began work in February 2008. From 2008 through 2019, the team carried out report reviews, Class 2 soil analysis file review, and site inspections as defined in the Settlement Agreement. From 2020, after a public procurement process to select a continuing CM, the CM team of Langan and ESA switched roles, with Langan

as the primary CM and ESA as a sub-contractor to Langan. The CM team continues to carry out report reviews, Class 2 soil analysis file review, and site inspections (when allowed), as defined in the Settlement Agreement.

- In 2008, the primary concern was the rate at which groundwater monitoring wells were purged during sampling. This was resolved satisfactorily.
- In 2009, the CM team took a close look at the methodology used by ALRRF and its consultants to track variations in groundwater quality. No areas of concern were identified.
- In 2010, landfill gas perimeter probes were installed to comply with new regulations, and one of those probes detected landfill gas at levels that exceeded regulatory limits. This was abated by installing several gas extraction wells close to those probes.
- In 2011, the ALRRF sought to use fine material¹ from the Davis Street Material Recovery Facility (MRF) as Alternative Daily Cover. The use of this material was approved by the LEA through a special study in 2013.
- In 2012, two ongoing problems, windblown litter and seagull activity, became more severe; and while the gull problem has varied seasonally, the litter problem has continued.

Since mid-2013, the CM's observations and document reviews have included the construction of Fill Area 2 and related mitigation measures. The excavation and preparation of the Phase 1 portion of Fill Area 2, together with related improvements, were monitored in 2014 and 2015.

In 2015, the Five-Year Permit Review process began when the Local Enforcement Agency (LEA), which is the Alameda County Department of Environmental Health, requested the ALRRF to submit an application and a revised draft of its Joint Technical Document² (JTD), which contains a detailed description of Fill Area 2 development plans, design details, and operating procedures. On July 31, 2015, the revised JTD was submitted to the LEA and the Central Valley Regional Water Quality Control Board (Water Board). Waste Discharge Requirements (WDRs) were issued by the Water Board in mid-2016.

Throughout this process, the LEA held its permit review in abeyance while Water Board staff prepared, and the Water Board adopted, the WDRs. Subsequently, the LEA's review has



¹ MRF fines: Fine material produced by sorting systems that recover materials at the Davis Street Transfer Station.

² Under California regulations, a Joint Technical Document (JTD) is a detailed description of all of the means and methods by which a disposal site will satisfy State requirements to protect water resources and safely dispose of permitted wastes.

required more than three years to complete. It has been difficult for the ALRRF to refine its JTD to conform to the requirements of the WDRs and subsequent directives from Water Board staff, and the sheer size and complexity of the JTD itself has also impeded progress. The JTD, after several revisions, was finalized on April 30, 2020. The Five-Year Solid Waste Facility Permit (SWFP) was finalized and issued on September 2, 2020.

1.3 Regional Context and Landfill Capacity Needs

Events in the landfill disposal industry and demographic shifts within the greater Bay Area have affected, and may continue to affect, operations and future developments at the ALRRF. Prior Annual Reports have discussed impending landfill capacity changes and changes in landfill usage that could directly affect the life expectancy of regional landfills including the ALRRF.

Those issues have largely abated, but legislative and regulatory developments have resulted in new implications for landfill life in the region and statewide. The bellwether for this trend was AB 1594, which was passed in 2014. As of January 1, 2020, the use of green material as alternate daily cover (ADC) does not constitute diversion through recycling and is considered disposal for purposes of measuring a jurisdiction's 50 percent per capita disposal rate.

The 2015-2016 legislative session in California gave rise to several new laws that are intended to dramatically reduce the disposal to landfill of organic wastes (plant debris, food scraps and similar materials that readily decompose and produce methane, a potent greenhouse gas). In Alameda County, this material is approximately 30% of the waste stream^{3,4}.

The two pieces of 2016 legislation with the most direct effect are SB 1383 and AB 901. SB 1383 established targets to achieve a 50 percent reduction in the statewide disposal of organic waste from the 2014 level by 2020, and a 75 percent reduction by 2025. AB 901 changed how disposal and recycling is reported to CalRecycle. The intended effect is to provide a more accurate assessment of progress toward State goals. Regulations that implement these measures are now in place, and CalRecycle is providing resource documents and workshops to support implementation⁵.



³ CalRecycle 2014 Waste Characterization Study: https://www2.calrecycle.ca.gov/WasteCharacterization/, accessed December 2017.

⁴ Alameda County 2017-2018 Waste Characterization Study: http://www.stopwaste.org/sites/default/files/2017-18%20Alameda%20County%20Waste%20Characterization%20Study.pdf, accessed December 2018.

⁵ https://calrecycle.ca.gov/organics/slcp/education

One result of this activity has been a tangible commitment by waste industries in California to provide additional organics diversion facilities. In Alameda County, two examples are the 500 ton per day CASP facility at the ALRRF, and the implementation of 100 tons per day of anaerobic digestion and subsequent composting capacity at the Davis Street Transfer Station. Taken together, these could reduce disposal at the ALRRF by up to 600 tons per day, which would be a 25% reduction in the current rate of disposal there. This reduction may be offset somewhat by the need for disposal of contaminants and oversize materials from compost operations.

Related State legislation passed in the 2017-2018 session provided further support for waste reduction through product stewardship, packaging, and enhanced organics-diversion requirements. The legislation passed in the first year of the 2019-2020 session has continued to focus on product stewardship while also removing some requirements to provide buy-back recycling centers.

Against this backdrop, the ALRRF began operation in Fill Area 2 on March 25, 2019. This triggered several constraints on the types, quantities and sources of materials received; these are described in the next section of this report.

1.4 Site-Specific Constraints and Opportunities

The 1999 Settlement Agreement added constraints on operations, by adding new conditions to the Use Permit for the ALRRF. Solid wastes from out-of-county sources were strictly limited to those covered by existing disposal agreements. During peak traffic hours, the number of refuse trucks entering the landfill is limited. Numerous conditions intended to protect natural resources on the ALRRF property were imposed. These were extensively refined during the development of permit conditions from the State and Federal natural resource agencies with permit authority: The US Army Corps of Engineers, the US Fish and Wildlife Service, the California Department of Fish and Wildlife, and the Central Valley Regional Water Quality Control Board. This process required several years and concluded in 2012.

Some of these conditions did not take effect until Fill Area 2 began to receive refuse, on March 25, 2019. These conditions include limitations on the amounts of sludges, inert waste and special waste accepted from certain Bay Area counties, as well as self-hauled wastes from Contra Costa County. The specific restrictions are:

 Wastes collected for disposal under a municipal franchise may only be received from Alameda County, San Francisco, and the City of San Ramon in Contra Costa County. San Francisco and San Ramon wastes can only be received if those jurisdictions meet specified waste diversion goals.



 Non-franchise waste may only be received for disposal from Alameda County and San Francisco, plus up to 25,000 tons per year of sludges, inert waste and special waste from the other seven Bay Area counties. In addition, up to 25,000 tons per year of self-hauled wastes from Contra Costa County may be disposed.

Also, under the Settlement Agreement the size of the future expansion area was limited to 40 million tons of capacity, with a footprint of approximately 250 acres. In addition to Use Permit conditions, the Settlement Agreement established the CMC and the CM role, as described above; and it established mitigation funding related to the landfill expansion.

The physical setting of the ALRRF site presents certain constraints and opportunities. Canyons provide convenient high-volume fill sites, but hilly terrain and local high winds in the Altamont area require constant attention to windblown litter, especially film plastic. As Fill Area 1 neared its final elevation, windblown litter continued to be a problem due to the exposure of the landfill's active face to wind. That problem increased through 2019, despite the move to Fill Area 2 at a lower elevation. The landfill has added staff dedicated to litter cleanup and has repaired and augmented litter fencing downwind of Fill Area 2. Although the ALRRF's litter collection crew has been able to repeatedly remove litter from large expanses of the ALRRF property, high-wind events in 2019 and 2020 quickly replenished windblown litter in those areas, requiring repeated cleanups.

1.5 Overview of Operations, Regulations and Permits

1.5.1 Operational Functions and Requirements

Like most large landfills throughout California, the ALRRF performs a variety of functions that support the region's management of solid wastes. These functions continue to evolve as increasing emphasis is placed on reducing and recovering wastes, but the primary function of the site continues to be the safe disposal of solid wastes by placing, compacting and covering these materials. Federal, State and local regulations require that at the ALRRF:

- Wastes are covered to control litter, prevent fire, and prevent the spread of disease.
- Wastes are placed and compacted to be physically stable.
- Plant debris is not to be disposed; if received, it must be separated and reclaimed by composting or other methods. The CASP (covered aerated static pile) compost system adjacent to the landfill provides a convenient location for plant debris that is inadvertently delivered to the landfill.
- A liner and liquid recovery system is in place to prevent groundwater contamination by



leachate.

- Landfill gas (LFG) is controlled by an extraction system. Currently the gas is used to produce fuel (liquefied and compressed natural gas, LNG/CNG) and electrical energy.
- Emissions from combustion and processing (diesel engines and landfill gas systems) are controlled to meet Bay Area Air Quality Management District standards.
- Other air pollutants and nuisances (dust, odor, litter, etc.) are prevented.
- Stormwater erosion is controlled and stormwater runoff is tested for pollutants.

Compliance with these requirements protects the environment and public health, and it also presents opportunities to develop and support innovative methods for improved waste management. Currently, such activities at the ALRRF include:

- Using LFG to produce electricity and fuel (LNG/CNG);
- Stockpiling and processing materials for beneficial use on site, such as using demolished concrete for wet-weather roads and access pads;
- Blending liquids with dry materials in a solidification process to make a product that can be landfilled or used as cover;
- Using contaminated soils and other wastes (biosolids, shredded tires, MRF fines, treated auto shredder fluff, etc.) for cover material, as permitted;
- Stockpiling construction and demolition (C&D) materials and scrap metal for processing elsewhere;
- Providing an area for the separation of plant debris from other wastes, to avoid landfilling plant debris; and
- Hosting site visits, by prior arrangement, for public education.

The ALRRF property covers more than three square miles. Within that area, the portion that is delineated as landfill is divided into Fill Area 1 (FA-1) and Fill Area 2 (FA-2). Fill Area 1 covers approximately 235 acres, including an Asbestos-Containing Waste landfill operation which occupies several acres within the Fill Area 1 footprint. The Fill Area 2 footprint is approximately 250 acres. Although most refuse and cover material are currently being delivered to Fill Area 2, Fill Area 1 has not closed, and it will likely receive additional refuse to reach its permitted final elevation. It is currently the site of the active asbestos landfill and two solidification basins.



Lands surrounding Fill Areas 1 and 2 are mainly grazing land and some construction-support activities related to the continuing construction of Fill Area 2, which will take place in phases over several years. These surrounding lands include a Conservation Plan Area, protected with a permanent easement that provides suitable habitat for several special status species.

Much of the work done by the CM involves the review of data and reports required of the ALRRF by regulatory and permitting agencies, as described below.

1.5.1.1 Water

In California, the State Water Resources Control Board and its Regional Water Quality Control Boards (RWQCBs) protect groundwater and surface water resources through laws, regulations and permit requirements. Because most of the ALRRF property drains into the Central Valley, the Central Valley Water Board issues and administers the Waste Discharge Requirements (WDRs) for the site. These WDRs set various operating requirements, and they also define the programs that monitor water quality by periodically testing groundwater wells as well as storm water basin contents and discharges. The Water Board also requires the ALRRF to address incidents that increase risk to groundwater, such as the inadvertent receipt of wastes that contain unpermitted levels of hazardous materials. The CM reviews semiannual groundwater monitoring reports, the stormwater pollution prevention plan, annual stormwater monitoring reports, and the annual Winterization Plan update, as well as correspondence and required reports that the Water Board posts on its GeoTracker web site.

1.5.1.2 Air

The Bay Area Air Quality Management District (BAAQMD) administers its own regulations, including Regulation 8 Rule 34 regarding landfill gas control, as well as relevant State and Federal regulations. At the Federal level these are referred to as Title V requirements. The operation of (and especially the air emissions from) the landfill gas control systems, various diesel engines, and other processes that produce air emissions are regulated through permit requirements. Every six months the ALRRF submits a comprehensive "Title V report" to the BAAQMD. This report summarizes emission test results and landfill gas control system performance as required. The CM reviews these reports as they are issued. The landfill also produces an annual estimate of greenhouse gas (GHG) emissions, as required by Federal regulations. The most recent data available, for 2019, indicate that the ALRRF is the third highest GHG-emitting landfill in California, with 38,401 metric tons of total carbon dioxide ("greenhouse gas as carbon dioxide equivalent") emitted, behind the Puente Hills landfill in Los Angeles County (114,774 metric tons of total



carbon dioxide emitted) and the Kiefer Landfill in Sacramento County (125,920 metric tons of carbon dioxide emitted).⁶

1.5.1.3 Disposed Wastes

Two agencies regulate solid waste disposal in Alameda County. The Alameda County Department of Environmental Health is the Local Enforcement Agency (LEA), and at the State level, the California Department of Resources Recycling and Recovery (CalRecycle) supports and oversees the LEA. The LEA is the main enforcement agency for the Solid Waste Facility Permit (SWFP) that governs many aspects of operations at the ALRRF, such as operating hours, landfill cover materials and cover frequency, types of materials that are allowed to be disposed, etc. The SWFP is reviewed and updated every five years, and the CMC and CM closely follow that process, as required by the Settlement Agreement. The CM also reviews ALRRF inspection reports made by the LEA, as those reports become publicly available; and each year at least four of the monthly CM site inspections are done in conjunction with the LEA, as required in the CM's Scope of Work. Due to the COVID19 pandemic, the CM was only able to conduct three site visits in 2020; Section 2.1 provides more details. Of the three CM site visits in 2020 due to COVID-19 restrictions, one was performed with the LEA.

1.5.1.4 Land Use

Concurrently with the Settlement Agreement, Land Use Permit C-5512 for the ALRRF site was updated to incorporate mitigations specified by the Settlement Agreement. These modifications include restrictions on waste quantities, limits on truck traffic, and other operational constraints, as well as certain biological resource protection measures discussed in Section 1.5.2 below. The CM tracks compliance through direct inspection, review of data from ALRRF operations, and review of periodic reports submitted to regulatory agencies by the ALRRF, including the annual Mitigation Monitoring Report submitted to County Planning. Annual monitoring surveys of the on-site Conservation Plan Area are also reviewed by the CM.

An additional Land Use Permit (PLN 2010-00041) was approved by Alameda County in March of 2013 for the future development and use of composting and material recovery operations at the ALRRF. In April 2018, the ALRRF began operation of its Covered Aerated Static Pile (CASP) compost facility northeast of Fill Area 1. Currently, Waste Management's position is that the

Air Resources Board file https://www.arb.ca.gov/cc/reporting/ghg-rep/reported-data/2019-ghg-emissions-2020-11-04.xlsx, accessed December 18, 2020.



CASP facility is not within the purview of the CMC. However, the CMC has taken the position that the additional permit *is* within its purview.

1.5.1.5 Waste Diversion Requirements

At the local level, the Alameda County Waste Management Authority and the Alameda County Source Reduction and Recycling Board formed StopWaste as a joint powers agency to pursue local and state waste reduction and diversion goals. StopWaste has implemented mandatory separation of recyclables and compostables at businesses and multifamily properties throughout the County, and it provides public education, training and other assistance. In addition, StopWaste has developed, and all of its member agencies have adopted, a single-use bag ban ordinance; and StopWaste has adopted a countywide ban on the disposal of plant debris in local landfills.

Section 1.3 of this Annual Report describes recent State legislation that requires increased solid waste diversion (or reduction) and more comprehensive reporting of disposed and diverted quantities.

1.5.2 Requirements For Fill Area 2 Development and Use

1.5.2.1 Background

In 2011, the last major permits for the development of Fill Area 2 were obtained after agreement was reached between regulatory agencies and Waste Management regarding mitigation for the loss of a wetland channel and the loss of habitat for special status species. Mitigations were established through Alameda County Use Permit C-5512 and permits from several State and Federal agencies:

- US Army Corps of Engineers, which had jurisdiction over wetlands.
- US Fish and Wildlife Service, which consulted on wildlife protective measures.
- Central Valley Regional Water Quality Control Board, which certified that the mitigations would protect water quality.
- California Department of Fish and Wildlife, which concurred with the USFWS' Biological Opinion and placed specific conditions on work in the wetland channel.

The fundamental requirements of these permits are:

• The dedication of 750 acres of ALRRF land as a Conservation Easement, in perpetuity.



- The creation of additional wetlands, in the form of a new pond between Fill Area 2 and the Eastern Alkali Wetland.
- The enhancement of a riparian channel approximately the same size as the channel to be displaced by Fill Area 2.

To guide these efforts and many related requirements, the ALRRF and its consultants prepared the following documents:

- Conservation Management Plan
- Pest Management Plan
- Grazing Plan
- Waters and Wetlands Mitigation Plan

The ALRRF dedicated the 991.6-acre Conservation Easement in 2012 and built the mitigation wetland pond in 2013. In late 2017, the ALRRF executed an agreement with the Cosumnes Floodplain Mitigation Bank to fund river channel restoration and preservation in southern Sacramento County. The current status of these efforts is described in Section 1.5.2.3 below.

1.5.2.2 Corridors and Connectivity

The Biological Opinion from the USFWS describes the need for wildlife connectivity and wildlife corridors in eastern Alameda County to provide for wildlife movement and thereby enhance species health by preventing inbreeding. The Biological Opinion states that this need exists for three of the four protected species in the area: San Joaquin Kit Fox, California Red-Legged Frog, and California Tiger Salamander. The ALRRF's Conservation Management Plan contains the following requirements in the Minimization and Mitigation sections of the document:

MIN-31 – The project proponent will contribute funding to conduct a research study of wildlife passage at local over- and under- crossings to determine if these conduits provide conductivity [sic] for wildlife through the Interstate 580 corridor. The study will entail the periodic placement of motion-activated camera station, track plates, and other approved sampling method. The project proponent will provide the Service and/or CDFW with as much as \$50,000 to perform the study. With the approval of the Service and CDFW, the project proponent may contract the study to an approved third party.

MIT-7 – The mitigation pond/wetland will be constructed in an upland area [...] immediately upstream from the Eastern Alkali Wetland. [...] This area provides suitable



upland refugial habitat for tiger salamanders and suitable dispersal habitat for red-legged frogs to the Eastern Alkali Wetland and the Southern Alkali Wetland.

These requirements are also stated in the USFWS Biological Opinion, which in turn is referenced by the CDFW Consistency Determination.

1.5.2.3 Current Status

Unfortunately, the wetland mitigation pond built in 2013 was badly damaged by sediment inflow due to unusually heavy rainfall in early 2014. Also, the channel enhancement was put on hold due to the drought that occurred between 2011 and 2016. To remedy this situation, the ALRRF has purchased off-site wetland channel mitigation credits from the Cosumnes Floodplain Mitigation Bank in southern Sacramento County and had the pond rebuilt and replanted in 2018. Also, to protect the pond from sediment inflow, in late 2018 the very extensive sedimentation basin SB-H was constructed between the pond and Fill Area 2. This basin SB-H performed well throughout the 2018-2019 wet season. In the pond itself, it appears that there has been some mortality among the plants that were installed in late 2018. ALRRF management has stated that this is being addressed.

In 2017, the CM reviewed a summary report describing wetland and wildlife mitigation activities and issues. Wetland and wildlife mitigation activities continued in 2018, 2019 and 2020, with monitoring of construction areas and wildlife protection measures (e.g., relocating sensitive species such as California Tiger Salamander, when encountered). ALRRF staff have stated that a report is being prepared by their natural resources consultant, Dudek, but no reports were provided to the CM for review in 2020.

The CM also reviews the ALRRF annual mitigation monitoring progress report, which briefly summarizes the status of compliance with each of the 106 conditions in Conditional Use Permit C-5512.

2.0 COMMUNITY MONITOR ACTIVITIES AND ISSUES

2.1 Introduction

Under the Settlement Agreement, the Community Monitor (CM) has three ongoing duties:

 Review reports, data and information that are required to be submitted by Waste Management of Alameda County to regulatory agencies, or that provide information regarding the ALRRF's compliance with applicable environmental laws and regulations (Settlement Agreement Sections 5.7.1.- 5.7.3)



- Conduct inspections of the ALRRF facility up to 12 times per year (Sections 5.7.7, 5.8)
- Review the records of testing and acceptance of "Class 2 soils", i.e. soils known to come from a contaminated site (Section 5.7.9)

In 2020, as a result of COVID-19 health emergency and the statewide Shelter-in-Place Order issued in early March, the CM site visits were suspended from March through October. The ALRRF's policy in response to the pandemic only allowed agency inspectors, or regulators who perform compliance related activities. Due to the reduction in COVID-19 cases, the county restrictions were eased, allowing for site visits to resume in November. However, as the infection rates increased again, ALRRF reinstated the health emergency precautionary measures in December 2020. The CM performed site visits in January, February and November of 2020. During the months when the site visits could not be performed, the status of ALRRF operations was obtained by reviewing the LEA's site visit reports. Throughout 2020, the CM was active in each of these areas, as described below.

2.2 Monitoring of Improvements and Changes

Through report reviews and site visits, several new developments in ALRRF facilities and operations were monitored in 2020:

- On March 27, 2020, ALRRF requested an emergency waiver of minimum standards for landfill operations pursuant to 14 CRR, section 17210 (et seq.) and ALRRF's Conditional Use Permit: C-5512. The waiver was requested as a contingency in case of a direct or indirect impact from the virus. On 3 April, 2020, the LEA granted approval of the Emergency Waiver allowing: (1) increase of 2,500 tons per day (from 11,150 tons per day to 13,650 tons per day); (2) increase of 125 vehicles per day, allowing up to 682 refuse vehicles for the duration of the emergency waiver only. The Emergency Waiver began on April 3, 2020 and continued for 120 days.
- As a result of the statewide wildfires and the potential disposal of fire debris at the site, another emergency waiver was requested by ALRRF on September 18, 2020. The LEA granted conditional approval on September 30, 2020, allowing for the increased tonnage and vehicles per day, provided the operator notifies the LEA of the potential to exceed the allowable limits of refuse and vehicles.
- On April 1, 2020 refuse disposal operations began in the Phase 2 portion of Fill Area 2.
 Excavation of the Phase 3 portion of Fill Area 2 began in February, and liner construction began in May. Fill Area 2 monitoring wells MW-23A and MW-23B were destroyed and replaced by Fill Area 2 Phase 3 monitoring wells MW-25 and MW-26, downgradient of the planned liner extent of FA-2 Phase 3. In addition, six new monitoring wells (MW-34A, MW-34B, MW-35A, MW-35B, MW-44A, and MW-44B) were installed downgradient of



the lateral extent of FA-2 Phase 3. MW-24 and soil-gas probe VP-3 were also installed to supplement FA2 Phase 3 compliance wells and soil gas monitoring devices to monitor the unsaturated zone.

- In the 12 months from June 2019 through May 2020, 16 poorly-performing landfill gas
 wells were decommissioned and 36 new wells were brought on line. Wells with higher
 than normal gas temperatures were monitored for possible subsurface combustion; none
 was detected.
- For the two Fill Area 1 ponds intended to hold leachate and underdrain water separately, installation of the liquids separation equipment and piping was completed in 2019, but earlier in 2019 the future underdrain water pond (LSI-2) was needed to hold excess stormwater from the CASP compost facility. This delayed the use of the liquid separation system through 2019. However, as of October 2020, the two streams are separated and delivered into their respective ponds.
- In 2020, efforts continued to be made to reduce stormwater pollution. Drop inlets that were fitted in 2019 with "Ertec" filter cloth barriers to screen out silt had been damaged and accumulated sediment around the down drain. The sediment was removed and damaged guards were replaced as part of the 2020 winterization plan. In 2019, specialized FiltrexxTM wattles, designed to trap metals and hydrocarbons, were placed in ditches and along the bases of slopes, to trap hydrocarbons and other pollutants. The year old FiltrexxTM wattles were displaced with debris accumulation in certain locations. The debris was removed and the wattles replaced where necessary. Wattles were also installed upslope of certain concrete open channels. Inlets that were obstructed by vegetation, debris were removed and FiltrexxTM wattles were installed in preparation for rainy weather. TRM mets and rip rap were installed within channels in the Phase 3 excavated area.
- During the 2019-2020 wet season, stormwater was sampled upstream of the Fill Area 1 stormwater basins, in an effort to identify the sources of volatile organic compounds (VOCs) that have previously been detected in the basins. It was not possible to identify specific sources, however; only low to non-detect concentrations were reported in InBasin samples but ketones continue to be detected in interior stormwater samples upstream of the basins. Overall, the detections of VOCs were less frequent, presumably due to additional BMPs put in place along the storm water conveyances.
- The 10-acre Evapotranspirative (ET) Cover Test area was observed when the site was visited as the hydroseeded plants grew in and local plants also appeared. These observations have found that the hydroseeded species germinated successfully but were joined by local species, including some invasives, as the year progressed. No erosion problems were seen. The plans for the ET Cover Test Area include annual monitoring, followed by a report to the Water Board at the conclusion of the four-year study period.



Since the ET Cover was completed on November 14, 2018, submittal of the Performance Monitoring report is scheduled for April 1, 2024.

- The windblown litter problem was expected to improve with the move to Fill Area 2, but the issues continued. The LEA received an unofficial complaint in June 2020 about litter at the entrance of the landfill. The LEA noted windblown plastic debris along a 1.5 mile stretch on roads west of the entrance but did not observe any litter to the east of the entrance and determined that the litter was likely caused by vehicles with holes in their tarps on unsecure loads. Several high-wind events, and generally windy conditions throughout the site, caused litter to repeatedly spread toward and occasionally beyond the east and north boundaries of the site. The ALRRF's litter crews continued to clear debris.
- In the period from January through November 2020, the ratio of **Class 2 cover soil** to municipal solid waste declined to 20%. In 2019 that ratio had decreased to 25% from 68% in 2018, as cover soil for Fill Area 1 was accumulated in 2018 in anticipation of the shift to Fill Area 2.

2.3 Compliance and Significant Incidents

As noted above, the Settlement Agreement defines the CM's Scope of Work to include "issuing a written report each year summarizing the ALRRF's compliance record for the period since the last such report with respect to all applicable environmental laws and regulations." This Annual Report provides that summary. The regulatory agencies that administer these laws and regulations, and the environmental permits held by the ALRRF, include the following:

- Alameda County Planning Department
- Alameda County Department of Environmental Health
- Bay Area Air Quality Management District
- US Environmental Protection Agency
- California Department of Resources Recycling and Recovery (CalRecycle)
- Central Valley Regional Water Quality Control Board
- California Department of Fish and Wildlife
- US Army Corps of Engineers
- US Fish and Wildlife Service



To determine if there are trends in the compliance record, a list of compliance issues has been compiled; it is shown in Table 2-1, below. Persistent issues appear in the upper part of the table, followed by infrequent or one-time issues. Issues from 2011–2014 are shown in the 2017 Annual Report.

To compile this table, the CM reviewed publicly available data from the regulatory agencies listed above, ALRRF correspondence with those agencies, and the CM's monthly site inspection reports. The severity of the issues was rated subjectively by the CM using the 1 to 5 scale shown below Table 2-1. Issues that were judged to be beyond the control of the ALRRF are not included in the annual total of severity scores but are listed below the total line.

For the purposes of this report and table, incidents involving the delivery of hazardous materials with incorrect profiles (showing them as non-hazardous) are considered to be beyond ALRRF's control; but the Water Board's position appears to be that ALRRF is responsible nevertheless. Fortunately, no such issues occurred in 2020.

The total severity score for 2020 is substantially lower than in 2019.

Three types of incidents that are of particular concern occurred in 2020:

- End-dump Truck Overturns. Within the ALRRF operating area, only one dump-truck overturned in 2020. No injuries were reported. The average number of overturns per year from 2012 through 2019 was 6. This is a tiny fraction of the roughly 16,000 truckloads of class 2 soil and treated auto shredder fluff brought to the facility each year, but the risk of injury and damage in such incidents continues to be a concern for Committee members and ALRRF management. In 2019, the ALRRF increased its oversight of end-dump truck unloading and provides spotters for drivers to dump safely, which moderated the problem but did not eliminate it. Most of the dump truck accidents have been attributed to inexperienced or negligent drivers.
- **Fire**. There were three fires in the ALRRF in 2020. One was a garbage fire that occurred in Fill Area 2, Phase 2. Another fire occurred on open land opposite the main entrance and the other occurred in a transfer truck load. They are described further in section 2.3.3.2 below.
- **Windblown Litter**. This may be the single most persistent problem at the ALRRF. With the move of refuse fill operations from the Fill Area 1 hilltop into the Fill Area 2 canyon, a reduction in windblown litter was expected. However, this did not occur, and due to strong west winds, litter continues to be deposited beyond the east property line. The litter cleanup crew has been enlarged and is now a permanent part of the ALRRF work force. When necessary, the crew removes litter from neighboring properties to the east



of the ALRRF. The ALRRF also redeploys other staff to retrieve litter when necessary.

• **Methane exceedance**. One perimeter gas probe (GP-9A) had readings above the 5 percent methane by volume threshold, in April 2020. The 7-day follow-up tests also showed methane above 5%, triggering a Notice of Violation by the LEA. The GP-9 cluster had also been issued a violation in July 2019. ALRRF has taken steps to improve drainage in landfill areas in the vicinity of GP-9A. Two horizontal gas collectors have also been recommissioned near GP-9A. The violation issued on April 27, 2020 was removed.

2.3.1 Compliance Issues Documented by the LEA

In 2020, two Area of Concern (AOC) notices were issued by the Local Enforcement Agency (LEA). LEA inspection reports indicate concerns about the following:

- Load of medical waste containing sharps was unloaded in Fill Area 2. Even though the
 medical waste had gone through autoclave, the manifest had not been updated correctly.
 The LEA issued an AOC on February 27. An updated manifest was provided to the LEA
 on March 3, correcting the AOC.
- The ALRRF failed to meet the submission deadline, March 31, 2020, for the Non-Water Release Corrective Action Plan (CAP) as part of the Five-Year Permit application review, triggering an AOC. ALRRF did submit the required documents, upon which the AOC was removed

On April 17, 2020, WMAC notified LEA via e-mail that perimeter gas probe 9A (GP-9A) had readings greater than 5 percent methane by volume (mbv). The 7-day follow up identified that GP-9A on April 17, 2020 had methane gas levels of 13.2% mbv. In addition, the 7-day follow up identified monitoring on April 20 through April 22, 2020 that showed methane gas levels at highs of 10%, 11.2%, and 7.5% mbv. The LEA issued a Notice of Violation for methane in perimeter gas probe GP-9A, on April 27. Two consecutive follow up readings in the afternoon of April 22 showed that gas was maintained at 4.8%, below the 5% regulatory threshold, so the Violation was removed.



Table 2-1
Compliance Issues Ranked by Severity

	Severity					
Issue	2015	2016	2017	2018	2019	2020
Contamination at E-05, E-07, E-20B	2	2	2	2	2	2
Stormwater contamination	3	3	3	3	3	2
Windblown Litter	2	4	2	3	4	3
Birds	2	2	2	2	2	2
Erosion	3	2	1	-	3	2
Cover thin / absent	4	-	-	-	1	1
Worker injury	1	2	1	-	1	1
Condensate/Leachate Leakage	3	-	3	3	3	2
Ponding in low-lying area of landfill	-	-	-	1	2	2
Sediment in Wetland Mitigation Area	3	3	2	-	-	-
Odor, on site	-	1	-	-	1	-
Leachate Seeps	1	1	2	-	4	2
Erosion control (sitewide)	-	4	-	-	3	2
Waste outside active area (trash, pallets)	-	4	-	-	-	-
Leachate Leak Disposal	-	-	4	-	-	-
Contaminants at monitoring well MW-4A	-	-	4	-	-	-
Windblown litter beyond last litter fence	-	-	-	4	2	2
Disposal of liquid into pond without prior approval	-	-	-	4	5	2
Lack of means to record liquid level in ponds	-	-	-	4	-	-
Failure to monitor landfill gas well	-	-	-	4	-	-
Incomplete groundwater monitoring report	-	-	-	4	-	-
Liquid separation not implemented, Fill Area 1					4	-
Medical waste (sharps) manifest issue	-	-	-	-	-	2
Totals	30	36	28	44	40	27
Issues Beyond Control of / Refuted by ALRRF						
Truck overturn		3	3	3	2	2
Methane Gas at Perimeter Probe(s) [cleared]	4	4	-	-	4	4
Fire in refuse &/or stored material	-	3	1	-	3	3
Fire on ALRRF property, outside active areas	-	-	2	2	3	2



Indicates that a violation was issued by a regulatory agency.

Severity Criteria

- 1: Minor or ongoing issue having little potential to harm environmental or public health; below regulatory thresholds.
- 2: Issue having some potential to harm environmental or public health; below regulatory thresholds; being addressed.
- 3: Issue having potential to harm environmental or public health; below regulatory thresholds; not improving, or new.
- 4: Issue having significant potential to harm environmental or public health, or resulting in a violation being issued.
- 5: Issue having significant potential to harm environmental or public health; violation issued; willful non-compliance.
- : Not applicable/not evaluated



2.3.2 Water Board Violations and Concerns

2.3.2.1 2020 Violations

Leachate Release: This NOV was issued for the four unauthorized discharges of compost leachate that occurred on November 29, 2018, January 21, 2019, April 29, 2019, and December 2, 2019, and the Discharger's failure to submit CalOES Spill Reports, as required by Water Code Section 13271 and 13272, for all but one of the documented leachate spills. The ALRRF responded on March 2, 2020, with documentation of site work performed to address the leachate spills/leaks. All the soil that was in contact with the contact water was removed and then reincorporated into the operations layer on the curing pad. Because these discharges originated in the CASP operation, they are not included in Table 2-1.

2.3.2.2 Other Concerns

There are several open issues that have arisen between the ALRRF and the Water Board since the current Waste Discharge Requirements (WDRs) were finalized in July 2016. They are briefly described below.

Identifying Sources of VOCs in Storm Water –The ALRRF's 2019-2020 stormwater sampling again detected VOCs in several locations, but the data still did not clearly indicate specific sources, in spite of having added sample points to narrow down the possible sources. However, the BMPs included prior to the 2019-2020 wet season, and other improvements (e.g., eliminating leachate seeps), has reduced stormwater pollution. We will continue to track this issue.

Solidification Basin Compliance –Water Board staff has expressed concern when they find standing liquid in the solidification basins. The ALRRF has responded by pointing out that this is inherent in the operation of these basins. ALRRF staff have mentioned that the basins will be moved, and constructed to be impermeable, in a location not above refuse. However, that has not yet taken place.

Statistical Exceedance in Well PC-1C – Water Board staff responded to the statistical exceedance of inorganic constituent concentrations in well PC-1C in Fill Area 2, and expressed concern that a clear pattern of increasing inorganic concentrations (calcium, chloride, magnesium, sodium, sulfate, specific conductance, and TDS) in groundwater west of PC-1C was also observed in corrective action wells E-20B and MW-12. In addition, sporadic detections of VOCs in PC-1 wells has made the Water Board suspect that the E-20B release from Fill Area 1 has impacted groundwater in Fill Area 2. The Water Board required an updated site conceptual model to understand the impact of E-20B and an updated engineering feasibility study to make



appropriate changes to E-20B corrective action program. In response, the ALRRF has reported that the source of inorganic compounds at PC-1C appears to be plant debris affected stormwater. Plant debris was placed for erosion control in FA-1, and runoff from that area flowed to Basin B, then traveled down a drainage channel between E-20B and PC-1C and infiltrated groundwater. Basin B inorganics in runoff increased significantly at the same time as the increase at PC-1C. The VOCs detected historically in E-20B have been attributed to landfill gas. ALRRF added that landfill gas controls placed in the vicinity of E-20B have led to the VOCs decreasing in E-20B. Water Board has yet to respond. This issue will be tracked.

Deviations from baseline concentration limits – A two year update to concentration limits (CLs) for monitoring parameters for Fill Area 1 and Fill Area 2 groundwater detection monitoring wells (per the 2016 WDR's) was provided. For Fill Area 2, the CLs were established for three groundwater zones for monitoring wells: alluvial, weather bedrock and unweathered bedrock. The updated CLs are based on historical baseline monitoring data through June 2020 for each constituent and were statistically calculated using the intrawell data evaluation procedure⁷. The 2020 updated CLs were similar to the previous CLs, which had been presented in 2016 and 2018. Water Board has yet to provide comments.

2.3.3 Other Incidents

The following information is based on reports filed in the site's Special Occurrences Log and on Community Monitor site inspections.

2.3.3.1 Vehicular Incidents

In addition to one trailer overturn (discussed below), there was a landslide at the Phase 3 excavation where a bulldozer was excavating rocks. No damage to the equipment or personal injuries were reported. The landslide stopped moving within 24 hours and the area was blocked for safety.

2.3.3.2 Fire

Three fires occurred at the ALRRF site in 2020:

June 9, 4:00 AM: A garbage fire occurred in Fill Area 2, Phase 2. The fire was quickly
pushed out to the south, smothered and extinguished with water truck. The material was
monitored to ensure there were no more fires. The cause of the fire is likely combustible

⁷ 2020 2-Year Groundwater Concentration Limits Update for Fill Areas 1 & 2 Report by GeoChem Applications, dated October 2020



material in the refuse.

- June 28, 8:30 PM: A fire occurred on open land opposite the main entrance. The fire was controlled by Alameda County Fire Department and did not affect the ALRRF.
- August 14: A small fire occurred in a Fremont transfer truck load while tipping the load.
 The tipper operator tried to tip the load to put the fire out but the garbage was stuck and
 the fire spread rapidly. The operator was able to dislodge the load by shaking the trailer.
 Fire extinguishers and water trucks were used to put out the fire. The apparent cause
 was hot material in refuse.

2.3.3.3 Trailer Overturns

Within the ALRRF operating area, only one dump-truck overturned in 2020. No injuries were reported. A detailed analyses was provided in the 2019 annual report suggesting that ALRRF should consider making a greater effort to prevent overturns during months when Class 2 soil deliveries are at their peak. February has not typically been a high-volume month for Class 2 soil, but in 2020, it was.

2.4 Review of Reports

2.4.1 Five-Year Permit Review

The LEA received application package for the Five-Year Solid Waste Facility Permit (SWFP) Review document on April 13, 2020. The LEA completed the review per Title 27, CCR Section 21675 and prepared a Five-Year Permit Review Report (PRR). ALRRF also concurrently submitted an application package for a Permit Modification on April 13, 2020, addressing all the comments from the LEA and CalRecycle. The LEA concluded no further action was required. A Public Notice was issued on June 10, 2020. The LEA received comments from one Livermore resident. The LEA responded to the comments, and no changes were made to the SWFP. The LEA found that the modified SWFP is consistent with and met the requirements of the regulations. On August 17, 2020, a site inspection was performed by the LEA (in-person) and CalRecycle (virtually). CalRecycle concurred with the permit review, and the SWFP was issued by the LEA on September 2, 2020.

2.4.2 Groundwater

Two groundwater monitoring reports were reviewed in 2020. The first covered the period from July through December of 2019; the second covered January through June of 2020.



The data in these reports indicate that monitoring wells with VOC contamination are responding to intensified landfill gas extraction nearby as indicated by reduced VOC concentrations, but some VOCs diminish more quickly than others.

One new development has been an increase in concentrations of inorganic constituents (dissolved calcium, chloride, sulfate, total dissolved solids, bicarbonate alkalinity), in certain wells in Fill Areas 1 and 2. Near Fill Area 1 these are MW-2A and MW-4A, on opposite sides of Fill Area 1 itself. In Fill Area 2 these are MW-8A, MW-8B, PC-1A and PC-1C, all near the bottom of the Fill Area 2 canyon and over half a mile from the active portion of Fill Area 2. The Water Board requires additional investigation, however ALRRF believes that the inorganic concentrations are related to stormwater (see Section 2.3.2.2).

In other respects, groundwater monitoring results were similar to those from prior years. Contaminants, when present, were below regulatory limits that would require immediate corrective action.

The two groundwater reports, especially the second one, presented some concerning QA/QC issues with field sampling and laboratory practices: contaminated trip and equipment blanks, hold time exceedances, and an increasing number of VOCs attributed to laboratory contamination. SCS Engineers (the ALRRF's groundwater monitoring consultant) maintains that the issues are normal for all laboratories.

2.4.3 Storm Water

A new set of annual requirements for industrial storm water monitoring and reporting took effect throughout California on July 1, 2015. Stormwater samples are to be taken when a "qualifying storm event" (QSE) occurs. Up to four such QSE's are to be sampled at each discharge point during a stormwater year (July through June). For each type of industrial facility, certain key pollutants must be monitored; and if concentrations of those pollutants exceed specified Numeric Action Levels (NALs), the facility must make a plan that describes Exceedance Response Actions (ERAs) to be implemented. In the first year of exceedance, "Level 1" ERAs are selected, which emphasize minimum Best Management Practices (BMPs). These are low-cost measures such as improving housekeeping, cleaning drain pipes, etc. If the exceedance continues into its second consecutive year, Level 2 ERAs must be developed, and these typically involve advanced BMPs such as specialized equipment, paving projects, etc.

a precipitation event that: (1) produces a discharge for at least one drainage area; and, (2) is preceded by 48 hours with no discharge from any drainage area.



Stormwater monitoring and reporting is especially complex at a landfill site, and even more so at a site that is expanding, like the ALRRF. Since the current regulations took effect, the number of sampling points has increased from three to six, and exceedances have persisted in spite of initial efforts to reduce silt, metals and organics. Each year the ALRRF has applied more BMPs; especially during the last wet season (2019-2020), new and improved BMPs were implemented. Those BMPs are continued for this wet season, with damaged components replaced. The landfill has implemented all applicable minimum BMPs and several types of advanced BMPs, including additional straw wattles, FiltrexxTM SiltSoxx wattles, flocculent logs, and rock dams. The ALRRF has also been tracking the presence of VOCs in stormwater, under a separate requirement in the WDRs. Data from last wet season's sampling indicated improvement in the stormwater quality. During the 2018-2019 and 2019-2020 wet periods, only low to non-detect VOCs were reported in InBasin samples. However, ketones continued to be detected in interior stormwater samples.

Based on these results, ALRRF proposes to track VOCs in stormwater using the semiannual WDR InBasin samples. For the 2020-2021 season, ALRRF proposes that discharge samples not be analyzed for VOCs, and that interior stormwater samples not be collected. If, however, consistent VOC detections of acetone, MEK, and MIBK return in the future, SCS recommends that additional discussions with the Water Board be arranged to determine additional sampling program. The InBasin results will be included in each semiannual monitoring report.

It is important to note that under these stormwater regulations, a violation is not triggered by the exceedance of an NAL. Rather, an industry will receive a violation if it fails to (a) sample its stormwater discharges or (b) plan and implement any necessary ERAs. ALRRF has exceeded several NALs but has not received any Notices of Violation.

2.4.4 Air Quality

Title V is one of several programs authorized by the U.S. Congress in the 1990 Amendments to the federal Clean Air Act. The Bay Area Air Quality Management District (BAAQMD) administers Title V requirements for the ALRRF. Title V operating permits incorporate the requirements of all applicable air quality regulations. Hence, the semi-annual Title V reports provide a comprehensive review of compliance with BAAQMD permits and regulations.

In 2020, the CM received the Title V reports for the periods June – November 2019, and December 2019 – May 2020. These reports describe landfill gas control operations and source testing, and they also document new or unique developments at the site that can have an effect on air emissions. Results from the current reporting year are similar to those from the previous year:



- The required surface emissions monitoring (checking for methane leaks through the landfill cap) continued to occur, and although exceedances of methane were found, they were typically remedied on the first try, without the need for repeated repairs.
- From June 2019 May 2020, 16 landfill gas wells were decommissioned, and 36 new wells were installed and began operation.
- New landfill gas wells were installed in FA-2 because FA-2 had received more than one million tons of material. The landfill gas wells were connected to the headers of FA-1.
- The LNG plant continued to operate at a fairly steady production rate. There were a few brief unscheduled down-time events (several days at most) due to motor bearing failure or piping replacement, but after each of those problems was resolved, the gas plant returned to steady production.
- All control devices passed their latest emissions tests without incident.

2.4.5 Mitigation Monitoring

The Mitigation Monitoring and Reporting Program Annual Progress Report, covering calendar year 2019, was received by the CM on April 23, 2020. It is a table that lists each of the conditions described in the current Conditional Use Permit (CUP-5512), followed by a description of the implementation status of that condition or mitigation. The status descriptions together with the verification notes generally reflected the current status of each mitigation measure. Updates to this table from the previous year are listed below, with reference to the applicable CUP Condition number.

- 3 [c] This requirement pertains to the WDR and IGP Stormwater Permit. ALRRF updated the IGP SWPPP to include Fill Area 2 operations
- 4.4 This requirement, about the sludges, inert waste, and special waste after ALRRF expansion is to not exceed 25,000 per calendar year and no such waste shall be accepted from outside the 9 Bay Area counties. The update lists that ALRRF did not exceed the 25,000 ton per calendar year requirement, but inadvertently accepted waste from outside the 9 Bay Area counties after FA-2 operations commenced (5 loads, approx. 64 tons). ALRRF has ensured waste profiles are expired/voided to prevent future acceptance and has also provided additional training to the scale house staff.

In addition to the Annual Progress Report described above, in prior years the ALRRF has prepared reports to inform the natural-resource agencies about progress on their permit requirements for Fill Area 2 expansion: establishing the Conservation Plan Area, constructing the wetland mitigation project, protecting existing wetlands and surface waters, etc. The Community Monitor did not receive any formal reports on mitigation activities in 2020. According to ALRRF staff,



biological surveys were conducted in the Conservation Plan Area, and a report on this subject is in preparation.

2.4.6 Per- and Polyfluoroalkyl Substances (PFAS) Report

The PFAS Order was given by the SWRCB as part of a statewide effort to obtain a **preliminary** understanding of PFAS compounds concentrations in groundwater and leachate at various landfills. The Order indicates this sampling is necessary to determine if PFAS compounds are present in and near waters that could be used for drinking water purposes. The State and Regional Water Boards will evaluate the data collected, and use it to support of any regulatory action to be implemented.

To be representative, samples were collected from a background well, a downgradient well, and a composite leachate sampling location, where possible. PFAS compounds were reported at higher concentrations in groundwater monitoring wells in the previously affected assessment and corrective action areas (E-05, E-07, E-20B, and MW-20) than the background or the detection monitoring program (DMP) wells. The highest PFAS concentrations in groundwater were reported in corrective action wells E-05 and E-07, located immediately downgradient of the old permitted unlined portion of Fill Area 1. Relative to corrective action wells E-05 and E-07, lower concentrations of PFAS compounds were reported in the E-20B corrective action area, situated adjacent to the old unlined Fill Area 1.

No additional PFAS sampling is proposed or required at this time. The SWRCB is analyzing the compiled data in airports, landfills and drinking water supply systems to aid in the development of Public Health Goals in drinking water. The concentrations reported at the ALRRF were below the maximum concentrations for groundwater and leachate at other landfills covered by the PFAS Order, and within the middle of the concentration ranges.

2.5 Review of Records

Several types of site records were reviewed by the CM in 2020. The CM's scope of work requires the periodic review of files that contain lab analyses and other descriptions of **Class 2 soils** (considered non-hazardous) that are brought to the site for use as cover soil.

The **Special Occurrences Log** for the ALRRF was examined four times during the year and summarized for the Committee. The **LEA's monthly inspection reports** are publicly available on the CalRecycle web site and were checked by the CM every month, to note any new issues that may have been identified by the LEA.



2.5.1 Class 2 Soils

An ongoing CM task is the periodic review of files containing profiles (sample analyses) for Class 2 soils that are imported for use as cover soil in the Class 2 portion of the ALRRF. For efficiency, this is generally conducted two to three times per year, and it requires at least one full day for a qualified specialist from Langan to review each file to be sure that it is complete and within the regulatory limits for Class 2 materials. This review was conducted twice in 2020, on January 27 and July 30. Attempts to schedule a third review near the end of the year have not been successful, but the next review will be scheduled as soon as possible in 2021. The files are made accessible electronically from Waste Management's Oakland office.

A total of 112 files were reviewed in January 2020, and a total of 12 files were reviewed in July 2020. No out-of-compliance profiles were found in any of the reviews, but there were two files that were incomplete in the July review. The CM is looking into this issue and will update the CM team when more is known.

2.5.2 Special Occurrences Log

Each permitted solid waste disposal site in California must keep a Log of Special Occurrences to document unusual and potentially disruptive incidents, including fires, injury and property damage, accidents, explosions, receipt or rejection of prohibited wastes, lack of sufficient number of personnel, flooding, earthquake damage and other unusual occurrences. The ALRRF log was either checked by the CM in person during site visits or requested via email. One dump truck overturned in February, and three fires were reported. Compared to previous years, the special occurrences were lower in number. It appears that the COVID-19 health emergency and the strict safety measures adopted has impacted the operations at the ALRRF in a positive way.

2.5.3 LEA Inspection Reports

In 2020, there were two types of Areas of Concern noted in these reports. One pertained to accepting a load of medical waste with incorrect information on the manifest, the other involved late submission of a report.

2.6 Monthly Inspections

Three site inspections were held during 2020. The inspection day and time were as shown in Table 2-2 below. Off-hours inspections, outside of the hours that the landfill is open to the public, were not conducted in 2020.



Table 2-2 Site Inspection Summary

Date	Day of Week	Inspection Time	Announced in Advance?	With LEA staff?
Jan 28	Tue	12:00 PM	no	yes
Feb 28	Fri	9:30 AM	yes	no
Nov 11	Wed	1:00 PM	yes	no

In general, satisfactory conditions were observed, although windblown litter and bird (seagull) presence were persistent issues. Minor problems generally were rectified prior to the next inspection. Details are available in the monthly site visit reports provided in CMC meeting packets. Distinct operations, such as the stockpiling and processing of specific materials, took place in well-defined areas. No instances of unpermitted activities were noted. There were no new problems seen regarding refuse placement, public safety or traffic management, whether on hours or off hours. Throughout these inspections, staff and management were forthcoming regarding operating practices and current conditions.

In 2020, observations by the CM focused on:

- The operations in Fill Area 2.
- Completion and maintenance of the mitigation pond.
- Plant growth and soil conditions in the evapotranspirative cover test area.
- Storm drainage and erosion control.
- Observation of issues of ongoing concern, including the presence of large numbers of seagulls and management of windblown litter east of Fill Area 2.
- Excavation and construction of Fill Area 2 phase 3.
- Changes at the site that could harm the environment or public health.

The Scope of Work for the CM specifies that at least three inspections be performed off hours, and that approximately four to six be performed jointly with the LEA. As discussed above, due to the COVID-19 health emergency, only three site visits could be conducted, one of which was performed jointly with the LEA.

No truck traffic counts were conducted in 2020, because ALRRF data on tonnage and traffic made it clear that the traffic volume requirements of the Conditional Use Permit were being met.



3.0 LOOKING AHEAD: ANTICIPATED EFFORTS AND ISSUES

3.1 Introduction

The 2020 contract year was the beginning of a new Community Monitor contract, with Langan providing CM services, assisted by ESA. The CM team will continue to perform report reviews, site inspections and Class 2 soils file reviews. The COVID-19 health emergency and the resulting Shelter-in-Place orders brought changes in the way the CM conducts monitoring of the landfill activities. Two Emergency Waivers, one for the COVID-19 emergency and the other for wildfires, were requested and received by the ALRRF.

The Five-Year Permit Review was completed. The four-year test of evapotranspirative (ET) cover methods is ongoing; the liquids separation system began to operate; and the mitigation pond with stormwater basin SB-H is functioning. Exceedances at several monitoring wells will continue to be tracked.

3.2 Issues to be Tracked in 2021

3.2.1 Ongoing Review

The following issues will continue to be monitored in the coming year:

- Implementation of requirements of the 2016 Waste Discharge Requirements.
- Concurrence of natural-resource agencies with off-site wetland mitigations.
- Groundwater monitoring methods and data quality.
- Groundwater quality, including the vadose zone below the landfill liners.
- Stormwater quality and management practices.
- Performance of the landfill gas system; decommissioning and installation of gas wells.
- Effects of composting or material recovery development or operations on the landfill.
- Refuse truck traffic counts, if needed.
- Performance of the 10-acre ET cover test site.

3.2.2 Site Inspections

All operations will continue to be observed, with close attention to the following areas.



3.2.2.1 Landfill Gas Control System

This system protects both air and groundwater quality, and it operates within a complex regulatory framework involving Federal permits, local permits, State regulations, and ALRRF CUP conditions. Physical changes to this system are likely to include the further addition of landfill gas extraction wells, decommissioning of wells that are no longer productive, and ongoing operation of the LNG plant, turbines, flares, etc. In 2021, four topics will be of special interest:

- The effect of the gas system on the concentrations of contaminants in wells E-20B and MW-4A.
- Concentrations of inorganic constituents in PC-1 well clusters.
- Gas temperatures, particularly in the high-temperature cluster of wells in Fill Area 1 Unit 2.
- Implementation of gas collection in Fill Area 2.

3.2.2.2 Stormwater Controls and Monitoring

Throughout the year, and especially during wet weather months, the CM will monitor conditions at all stormwater basins. The new additions to the stormwater pollution controls – skimmers, flocculant addition, FiltrexxTM check dams, and additional discharge points – have likely reduced contamination, although sporadic VOCs are still detected.

3.2.2.3 Windblown Litter

This will likely continue to be an issue for Fill Area 2 and downwind areas.

3.2.2.4 New Systems

The CM will directly observe, and review available performance data, for:

- The ET cover test area
- The reconstructed wetland mitigation pond
- Sediment basin SB-H
- Tipper and truck wash equipment in Fill Area 2
- The liquids separation system
- Modifications to solidification operations



In addition, monitoring reports on the Mitigation Wetland and the Conservation Plan Area, will be reviewed as they are provided.

3.2.2.5 Groundwater Contaminants and Groundwater Data

The CM team will continue to check concentrations of MTBE, tert-butyl alcohol, and tetrahydrofuran, which showed an increase in 2015 but have not since then. The team will also monitor data from wells E-20B, MW-4, MW-12, MW-20, PC-1C and other wells that have shown evidence of contamination. The quality of the groundwater sampling and analyses, especially the occurrence of contaminants in quality-control samples and field samples, will also continue to be monitored.

3.2.3 Class 2 Soils File Review

As required by the Scope of Work, the CM will conduct this review at least twice during 2021.

3.2.4 Permit Requirements Triggered by Expansion Date

In the Settlement Agreement, Section 4.3 defines the Expansion Date as "the date of the first deposition of solid waste in [Fill Area 2]." That occurred on March 25, 2019, triggering specific requirements in Conditional Use Permit C-5512, and in the resource-protection permit conditions that were imposed through the mitigations in the landfill-expansion EIR and the associated natural-resource-agency permits (Army Corps wetland permit, USFWS Biological Opinion, etc.; see Section 1.5.2, above).

3.2.4.1 Tonnage Limitations

Section 4 of the Settlement Agreement contains numerous restrictions on the types and source jurisdictions of wastes that can be brought to the ALRRF during specified time frames prior to and after the Expansion Date. Specifically:

- After the Expansion Date, the amounts of Sludges, Inert Waste and Special Waste from outside San Francisco and Alameda Counties is limited to 25,000 tons per year, and these materials may only originate within the nine Bay Area counties.
- Self-Hauled wastes (of all types) from Contra Costa County are limited to 25,000 tons per year.
- Materials brought for disposal may only originate from Alameda County, San Francisco, and San Ramon.



3.2.4.2 Natural Resource Protections and Reporting

The natural resource permits issued in connection with the ALRRF expansion contain over 80 explicit permit conditions, too many to enumerate here. In the near term, the following monitoring and reporting conditions are especially significant for the Community Monitor Committee:

- Every four years after the start of construction of Fill Area 2 (which began in 2015), the California Department of Fish and Wildlife (CDFW) is to receive a status report on the required periodic surveys of the Conservation Plan Area. The wildlife surveys focus on Western Burrowing Owl, San Joaquin Kit Fox, California Red-legged Frog, and California Tiger Salamander.
- Annual wetland monitoring reports are required by the Lake and Streambed Alteration Agreement, which was issued by the CDFW, for the first five years of operation of the wetland mitigations, i.e. the constructed pond.
- Reconnaissance survey reports for the Conservation Plan Area are also required by the CDFW. These include baseline and periodic surveys for sensitive wildlife species (see list above), and annual rangeland and general reconnaissance surveys. These are due on January 15 of the calendar year following the survey.

In 2019 and 2020, these reports reportedly were being prepared, but none were received by the CM.

