

PROFORMA FOR THE SAFETY OF SCHOOL BUILDING

PART- 1

(To be filled by the Head of School/ Institute)

1. Name of the School - Baba Shri Chand Public School
2. Location - Village Nurpura , P.O. Halwara , Distt Ludhiana
3. Plot Area - 20 Kanals
4. Plinth Area - 40953 Sq. Ft.
5. Number of Storey's - Six
6. Year of Construction of Building - 2004

7. If the building has been constructed under the supervision of the qualified Engineer, the following details may be given

- a. Name of the Engineer - Sukhdev Singh
- b. Address of Engineer - Raikot
- c. Set of Structural drawings used in the construction, if available - Yes
- d. Name & address of Architect - Jaspal Singh

8. Whether the building has been constructed for the purpose

- a. School - (Yes/No) - YES
- b. Residential Purpose and converted for use as a School - (Yes/No) -

9. Materials used for roofs

- a. R.C.C. Slabs/R.B.C. Slabs - (Yes/No) - YES
- b. R.S. Joist & Battons - (Yes/No) -
- c. Wooden joists & Battons - (Yes/No)

10. Materials used for walls

- a. Mud Mortar - (Yes/No)
- b. Cement Mortar - (Yes/No) - YES
- c. Lime Mortar - (Yes/No)

11. Flooring

- a. Conglomerate - (Yes/No)
- b. Terrazo - (Yes/No)
- c. Brick Paving - (Yes/No)


12. A detailed drawing indicating dimensions of the rooms Alongwith size and location of doors and windows (Attached)

- 20*25 , 2 doors , 2 windows

Principal
Baba Shri Chand Public School
Nurpura-141107 (Ludhiana)
Signature with Stamp of the seal
Of the School/Institution.

PART-II
(To be filled by the S.D.E.)

- a. I have visited the above mentioned school on dated 21/08/2025..... And have visually inspected it from all angles of safety and find it fit for normal use as School buildings.
- b. In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.
- c. In case the building is affected by food, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.
- d. This building can be safety occupied for normal use upto (indicate upto which it can be used)
31/03/2026.....


Sub Divisional Engineer,
Sub Divisional Engineer
Constn. Sub Division No.1,
PWD B&R Br., Ludhiana




ਪਿੰਨ ਨੰਬਰ ਨੰਬਰ 237-38

ਮਿਤੀ 27/08/2025

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਪ੍ਰਿੰਸੀਪਲ ਆਫ ਬਾਬਾ ਸ੍ਰੀ ਚੰਦ ਪਬਲਿਕ ਸਕੂਲ, ਨੂਰਪੁਰਾ (ਲੁਧਿਆਣਾ) ਨੂੰ ਉਹਨਾਂ ਦੇ ਪੱਤਰ ਨੰ: 2025-26/60 ਮਿਤੀ 20.08.2025 ਦੇ ਸਬੰਧ ਵਿੱਚ ਉਕਤ ਸਕੂਲ ਨੂੰ ਸਕੂਲ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਮਿਤੀ 31.03.2026 ਤੱਕ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਨੰ:1, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਲੁਧਿਆਣਾ ਜੀ ਨੂੰ ਸੂਚਨਾ ਅਤੇ ਅਗਲੇਰੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ

ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ:1 ਲੋ ਨਿ.ਵਿ.

ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਲੁਧਿਆਣਾ

