

**PROFORMA FOR THE SAFETY OF SCHOOL BUILDING
PART- 1**

(To be filled by the Head of School/ Institute)

1. Name of the School - Baba Shri Chand Public School
2. Location - Village Nurpura , P.O. Halwara , Distt Ludhiana
3. Plot Area - 20 Kanals
4. Plinth Area - 40953 Sq. Ft.
5. Number of Storey's - Six
6. Year of Construction of Building - 2004

7. If the building has been constructed under the supervision of the qualified Engineer, the following details may be given

- a. Name of the Engineer - Sukhdev Singh
- b. Address of Engineer - Raikot
- c. Set of Structural drawings used in the construction, if available - Yes
- d. Name & address of Architect - Jaspal Singh

8. Whether the building has been constructed for the purpose

- a. School - (Yes/No) - YES
- b. Residential Purpose and converted for use as a School - (Yes/No) -

9. Materials used for roofs

- a. R.C.C. Slabs/R.B.C. Slabs - (Yes/No) - YES
- b. R.S. Joist & Battons - (Yes/No) -
- c. Wooden joists & Battons - (Yes/No)

10. Materials used for walls

- a. Mud Mortar - (Yes/No)
- b. Cement Mortar - (Yes/No) - YES
- c. Lime Mortar - (Yes/No)

11. Flooring

- a. Conglomerate - (Yes/No)
- b. Terrazo - (Yes/No)
- c. Brick Paving - (Yes/No)

**12. A detailed drawing indicating dimensions of the rooms
Alongwith size and location of doors and windows
(Attached)**

- 20*25 , 2 doors , 2 windows

Gujinder Kaur
Principal
Baba Shri Chand Public School
Nisarga 141107 (Ludhiana)
Signature with Stamp of the seal
Of the School/Institution.

PART-II
(To be filled by the S.D.E.)

- a. I have visited the above mentioned school on dated 13 August 2024..... And have visually inspected it from all angles of safety and find it fit for normal use as School buildings.
- b. In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.
- c. In case the building is affected by food, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.
- d. This building can be safety occupied for normal use upto (indicate upto which it can be used) 31/3/2025.....

Sub-Divisional Engineer
Constn. Sub Division No. 1
PWD B&R Br., Ludhiana.

Sub Divisional Engineer,

ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ 308-09

ਮਿਤੀ 25/11/2024

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਪ੍ਰਿੰਸੀਪਲ ਆਫ ਬਾਬ ਸ੍ਰੀ ਚੰਦ ਪਬਲਿਕ ਸਕੂਲ, ਨੂਰਪੁਰ, ਲੁਧਿਆਣਾ ਨੂੰ ਉਹਨਾਂ ਦੇ ਬੇਨਤੀ ਪੱਤਰ ਨੰ: 2024-25/120 ਮਿਤੀ 22.10.2024 ਅਤੇ ਇਸ ਦਫਤਰ ਦੇ ਪਿੱ.ਅੰ.ਨੰ. 121-122 ਮਿਤੀ 11.07.2024 ਦੀ ਲਗਾਤਾਰਤਾ ਵਿੱਚ ਸਕੂਲ ਵਲੋਂ ਸਾਲ 2024-2025 ਲਈ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਰਿਨਿਊ ਕਰਵਾਉਣ ਉਪਰੰਤ ਉਕਤ ਸਕੂਲ ਨੂੰ ਮਿਤੀ 05.09.2024 ਤੋਂ 31.03.2025 ਤੱਕ ਸਕੂਲ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਨੰ:1, ਲੇ. ਨਿ. ਵਿ. ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਲੁਧਿਆਣਾ ਜੀ ਨੂੰ ਸੂਚਨਾ ਅਤੇ ਅਗਲੇਰੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,

ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ:1

ਲੁਧਿਆਣਾ।