




0 5 10 15 20 25


- Exhibit #1 = Running Shoe and Glasses
- Exhibit #2 = Black Plastic
- Exhibit #3 = Orange Plastic
- Exhibit #4 = Curb Stikes
- Exhibit #5 = Clear Plastic
- Exhibit #6 = Tire Scuff Mark
- Exhibit #7 = Soda Cup
- Exhibit #8 = Tire Scuff Mark
- Exhibit #9 = POI with V2
- Exhibit #10 = V2 Tire Mark







- Exhibit #1 = Running Shoe and Glasses
- Exhibit #2 = Black Plastic
- Exhibit #3 = Orange Plastic
- Exhibit #4 = Curb Stikes
- Exhibit #5 = Clear Plastic
- Exhibit #6 = Tire Scuff Mark
- Exhibit #7 = Soda Cup
- Exhibit #8 = Tire Scuff Mark
- Exhibit #9 = POI with V2
- Exhibit #10 = V2 Tire Mark





- Exhibit #1 = Running Shoe and Glasses
- Exhibit #2 = Black Plastic
- Exhibit #3 = Orange Plastic
- Exhibit #4 = Curb Stikes
- Exhibit #5 = Clear Plastic
- Exhibit #6 = Tire Scuff Mark
- Exhibit #7 = Soda Cup
- Exhibit #8 = Tire Scuff Mark
- Exhibit #9 = POI with V2
- Exhibit #10 = V2 Tire Mark









Exhibit Marker #7 & #8

Exhibit Marker #6

Exhibit Marker #5

Exhibit Marker #4

Exhibit Marker #3

Exhibit Marker #2

Exhibit Marker #1


Damage to Low Lying Shrubs


Cliff Avenue



nce

Entrance

Entrance







Vehicle Four
Final Rest

Vehicle Five
Final Rest

Entrance

Vehicle One
Final Rest

Entrance

11.47

Tire Mark

46.82

Entrance

26th Street

6.31

Vehicle Three
Vehicle Two


Entrance


Exhibit Marker #10


10.58

Exhibit Marker #9


Mall Entrance











Estimated Path of Travel to get to the Sidewalk

12.26

Resturant Entrance

