HIST. NAME:

DATE OF CONSTRUCTION: 1915

COMMON NAME: Locke property ORIGINAL USE: unknown

ADDRESS: 824 NW Mignonette Avenue

OWNER: Ollie & Marjorie Locke PRESENT USE: storage

823 NE 199th Portland 97230

T/R/S: T1S R3E Sec 10

ARCH/BLDR: N/A

MAP NO: 3353 TAX LOT (BLDG). STRUC. DIS

ADDITION:

TAX LOT (BLDG). STRUC. DIST. SITE OBJ. (circle)

THEME: social/possible meeting

hall/church

BLOCK: LOT: QUAD: Camas, Or/Wa. 7.5' series

ASSESSOR ACCT: #R 458902780

PLAN TYPE/SHAPE: rectangular

FOUNDATION MATERIAL: concrete

ROOF FORM & MATERIALS: Jerkinshead/composition shingles
WALL CONSTRUCTION: wood

PRIMARY WINDOW TYPE: 4/1 double hung, upper pane divided vertically
EXTERIOR SURFACING MATERIALS: weatherboard
DECORATIVE FEATURES: light transom over front doors
OTHER:

CONDITION: EXCELLENT GOOD (FAIR) DETERIORATED MOVED (DATE)

EXTERIOR ALTERATIONS/ADDITIONS (DATED): N/A

NOTEWORTHY LANDSCAPE FEATURES: Large conifer in rear, hedge defines northern perimeter, deciduous trees in back

ASSOCIATED STRUCTURES: N/A

KNOWN ARCHAEOLOGICAL FEATURES: N/A

SETTING: Facing west on NW Mignonette, 10 ft setback from unpaved street, small lot

STATEMENT OF SIGNIFICANCE (Historical and/or architectural importance, dates, events, persons, contexts). USE ADDITIONAL SHEETS IF NECESSARY

SOURCES:

NEGATIVE NO.: Roll 8 #10

RECORDED BY: SD

SLIDE NO .:

DATE: 1/29/87

PROPERTY

Marjorie & Ollie Locke NAME:

ADDRESS: 824 NW Mignonette ASSESSOR ACCT #:

R 458902780

T/R/S; TIS, R3E, Sec. 10 MAP NO: 3363 TAX LOT: 11


QUADRANGLE: Camas, OR/WA 7.5' Series



NEGATIVE NO .:

Roll 8 # 10

SLIDE .:



GRAPHIC & PHOTO SOURCES:

Northwest Heritage Property Associates

HIST. NAME:

DATE OF CONSTRUCTION: 1925

COMMON NAME:

ORIGINAL USE: single family residence

ADDRESS: 1005 NW Miller Avenue

PRESENT USE: single family residence

ARCH/BLDR: N/A

T/R/S:T1S R3E Sec 3

MAP NO: 3253 TAX LOT

STYLE: Prairie style

ADDITION:

BLOCK: LOT: (BLDG). STRUC. DIST. SITE OBJ. (circle) THEME: Architecture, 20th Century

QUAD: Camas, Or/Wa., 7.5' series

ASSESSOR ACCT: #

PLAN TYPE/SHAPE: rectangular FOUNDATION MATERIAL: concrete

NO. OF STORIES: 1 BASEMENT (Y/N): yes

ROOF FORM & MATERIALS: hip/composition shingles

WALL CONSTRUCTION: wood

STRUCTURAL FRAME: N/A

PRIMARY WINDOW TYPE: 1/1 double hung wood sash EXTERIOR SURFACING MATERIALS: weatherboard DECORATIVE FEATURES: arched porch entryway

OTHER:

CONDITION: (EXCELLENT) GOOD FAIR DETERIORATED MOVED

(DATE)

EXTERIOR ALTERATIONS/ADDITIONS (DATED):some windows have modifications, new storm windows, new garage

NOTEWORTHY LANDSCAPE FEATURES: Two large oak street trees, formal planting by driveway surrounded by RR ties

ASSOCIATED STRUCTURES: detached garage (1950's)

KNOWN ARCHAEOLOGICAL FEATURES: N/A

SETTING: Facing east on the NW corner of NW 11th and NW Miller, in residential area, 10 ft setback on gently sloping lot

STATEMENT OF SIGNIFICANCE (Historical and/or architectural importance, dates, events, persons, contexts). USE ADDITIONAL SHEETS IF NECESSARY

The residence is significant in that it is one of the few buildings in the Gresham Inventory study area which contains architectural characteristics showing the influence of the Prairie Style of architecture.

SOURCES:

NEGATIVE NO.: Roll 8 #20

RECORDED BY: SD

SLIDE NO .:

DATE: 1/22/87

PROPERTY NAME:

ADDRESS: 1005 NW Miller ASSESSOR ACCT #:


T/R/S; TIS, R3E, Sec. 3
MAP NO: 3267 TAX LOT:
QUADRANGLE: Camas, OR/WA 7.5' Series



NEGATIVE NO .:

Roll 8 # 20

SLIDE .:



GRAPHIC & PHOTO SOURCES:

Northwest Heritage Property Associates

HIST. NAME:

DATE OF CONSTRUCTION: c 1905

COMMON NAME: Danielson residence ORIGINAL USE: Single family residence

ADDRESS: 16214 NE Multnomah Street

OWNER: Chris Danielson PRESENT USE: Single family residence

T/R/S: T1N, R3E, Section 31 ARCH/BLDR: N/A STYLE: Bungalow

MAP NO: 2947 TAX LOT (BLDG) STRUC. DIST. SITE OBJ. (circle)

ADDITION: THEME: Arch. - 20th Century

BLOCK: LOT: QUAD: Camas, Or/Wa, 7.5' series

ASSESSOR ACCT: #

PLAN TYPE/SHAPE: Square

FOUNDATION MATERIAL: Concrete

NO. OF STORIES: 1 1/2
BASEMENT (Y/N): Yes

ROOF FORM & MATERIALS: hip, composition

WALL CONSTRUCTION: Wood STRUCTURAL FRAME: N/A

PRIMARY WINDOW TYPE: 12/1, 9/1 double hung wood sash EXTERIOR SURFACING MATERIALS: Weatherboard, shingles on dormers DECORATIVE FEATURES: Carved rafters, 3 sided wraparound porch with

paired square wood posts.

OTHER: Brick interior chimney, 4 hipped roof dormers (1 on each side of the roof), uncovered back porch.

CONDITION: (EXCELLENT) GOOD FAIR DETERIORATED MOVED (DATE)

EXTERIOR ALTERATIONS/ADDITIONS (DATED): N/A

NOTEWORTHY LANDSCAPE FEATURES: Mature redwood trees, rhododendrons

ASSOCIATED STRUCTURES: N/A

KNOWN ARCHAEOLOGICAL FEATURES: N/A

SETTING: N.E. corner 162nd/Multnomah, 50 ft. setback off road amid 1950's residential area.

STATEMENT OF SIGNIFICANCE (Historical and/or architectural importance, dates, events, persons, contexts). USE ADDITIONAL SHEETS IF NECESSARY


SOURCES: Chris Danielson

NEGATIVE NO.: Roll 2, #14 RECORDED BY: KE

SLIDE NO.: DATE: 12/22/87


PROPERTY NAME: Chris Danielson ADDRESS: A214 Multnomah Street ASSESSOR ACCT 4:

T/R/S; IN 3E Sec. 31
MAP NO: 2147 TAX LOT:
QUADRANGLE: Camas, OR/WA 7.5' Series



NEGATIVE NO.: Roll 2 # 14

SLIDE .:



GRAPHIC & PHOTO SOURCES:

Northwest Heritage Property Associates SHPO INVENTORY NO:

HIST. NAME:

DATE OF CONSTRUCTION: 1920

COMMON NAME: Whittlesy Property

ORIGINAL USE: single family residence

ADDRESS: 1775 SE Orient Drive

PRESENT USE: single family residence

OWNER: Ivan Whittlesy 21588 SE Bohna Park Boring

T/R/S: T1S R3E Sec 14

ARCH/BLDR: N/A

STYLE: English cottage

MAP NO: 3556

(BLDG). STRUC. DIST. SITE OBJ. (circle)

THEME: Architecture, 20th Century ADDITION: QUAD: Damascus, Or. 7.5' series BLOCK: LOT:

ASSESSOR ACCT: # R993141370

PLAN TYPE/SHAPE: rectangular FOUNDATION MATERIAL: concrete NO. OF STORIES: 1 1/2 BASEMENT (Y/N): yes

ROOF FORM & MATERIALS: gable/wood shingles/composition shingles STRUCTURAL FRAME: WALL CONSTRUCTION:

PRIMARY WINDOW TYPE: 6/1 double hung EXTERIOR SURFACING MATERIALS: stucco

DECORATIVE FEATURES: arched entryway, leaded mullins in dormer window OTHER:

CONDITION:

EXCELLENT (GOOD)

TAX LOT

FAIR DETERIORATED MOVED

(DATE)

EXTERIOR ALTERATIONS/ADDITIONS (DATED): some windows have new aluminum storm windows

NOTEWORTHY LANDSCAPE FEATURES: N/A

ASSOCIATED STRUCTURES: detached garage

KNOWN ARCHAEOLOGICAL FEATURES: N/A

SETTING: Facing east on SE Orient Drive and SE Kane in commercial area at busy intersection, only residence in immediate area

STATEMENT OF SIGNIFICANCE (Historical and/or architectural importance, dates, events, persons, contexts). USE ADDITIONAL SHEETS IF NECESSARY

This residence is a fine example of the English cottage style of architecture in Gresham. It is one of few remaining intact examples of this period.

SOURCES:

NEGATIVE NO.: Roll 15 #15

RECORDED BY: SD

SLIDE NO .:

DATE: 2/6/87

PROPERTY NAME: Evan Whittlesey Residence

ADDRESS: 1775 SE Orient

ASSESSOR ACCT #:


T/R/S; TIS, R3E, Sec. 14
MAP NO: 3656 TAX LOT:
QUADRANGLE: Damascus, OR/WA



NEGATIVE NO .:

Roll 15 # 15

SLIDE .:



GRAPHIC & PHOTO SOURCES:

Northwest Heritage Property Associates

HIST. NAME:

DATE OF CONSTRUCTION: 1930's

COMMON NAME: Johnson Cr Bridge

ORIGINAL USE : bridge ADDRESS: Johnson Cr at SW Pleasant View Drive

OWNER: Multnomah County

PRESENT USE: bridge

T/R/S: T1S R3E, Sec. 17

ARCH/BLDR: N/A

MAP NO: 3549

STYLE: modernistic

TAX LOT BLDG. (STRUC) DIST. SITE OBJ. (circle)

ADDITION:

THEME: transportation

BLOCK:

LOT:

QUAD: Damascus, Or., 7.5' series

ASSESSOR ACCT: #

PLAN TYPE/SHAPE: N/A

NO. OF STORIES: N/A BASEMENT (Y/N): N/A

FOUNDATION MATERIAL: N/A ROOF FORM & MATERIALS: N/A

WALL CONSTRUCTION: poured concrete STRUCTURAL FRAME: N/A

PRIMARY WINDOW TYPE: N/A

EXTERIOR SURFACING MATERIALS: N/A

DECORATIVE FEATURES: curved concrete bridge railing in modernistic

style

OTHER:

CONDITION: EXCELLENT (GOOD) FAIR DETERIORATED MOVED

(DATE)

EXFERIOR ALTERATIONS/ADDITIONS (DATED): N/A

NOTEWORTHY LANDSCAPE FEATURES: N/A

ASSOCIATED STRUCTURES: N/A

KNOWN ARCHAEOLOGICAL FEATURES: N/A

SETTING: Rural setting just south of Highway 26 on 190th - busy road.

STATEMENT OF SIGNIFICANCE (Historical and/or architectural importance, dates, events, persons, contexts). USE ADDITIONAL SHEETS IF NECESSARY

This modernistic style bridge was built in the 1930's and represents the only bridge of this style within the City of Gresham.

SOURCES: Interview with Richard Ross

NEGATIVE NO.: Roll 17, #7

SLIDE NO .:

RECORDED BY: KL, KD

DATE: 4/13/87


PROPERTY

NAME: Johnson Creek Bridge

ADDRESS:

ASSESSOR ACCT #:


T/R/S; T15 R3E SEC 17
MAP NO: 3549 TAX LOT:
QUADRANGLE:



NEGATIVE NO .:

Roll 17 # 7

SLIDE .:



GRAPHIC & PHOTO SOURCES:

Northwest Heritage Property Associates

HIST. NAME:

DATE OF CONSTRUCTION: 1910

COMMON NAME: ORIGINAL USE: single family residence

ADDRESS: 1430 SW Pleasant View Drive

OWNER: PRESENT USE: single family residence

T/R/S: T1SR3E Sec 17 ARCH/BLDR:

STYLE: bungalow

MAP NO: 3549 TAX LOT BLDG. STRUC. DIST. SITE OBJ. (circle)

ADDITION: THEME: architecture

BLOCK: LOT: QUAD: Damascus, Or., 7.5' series

ASSESSOR ACCT: #

PLAN TYPE/SHAPE: rectangular

FOUNDATION MATERIAL: concrete

ROOF FORM & MATERIALS: gable with composition shingles
WALL CONSTRUCTION: wood

PRIMARY WINDOW TYPE: 1/1 double hung
EXTERIOR SURFACING MATERIALS: narrow weatherboard

DECORATIVE FEATURES: narrow weatherboard

OTHER:

CONDITION: EXCELLENT (GOOD) FAIR DETERIORATED MOVED (DATE)

EXTERIOR ALTERATIONS/ADDITIONS (DATED):aluminum storm front door

NOTEWORTHY LANDSCAPE FEATURES: mature maples front, birch to the south, lot covered with trees, small pines in front

ASSOCIATED STRUCTURES: detached garage

KNOWN ARCHAEOLOGICAL FEATURES: N/A

SETTING: Facing west on SW Pleasant View in more rural area, 20 ft setback from street, open fields to the east and north, fruit trees to the south

STATEMENT OF SIGNIFICANCE (Historical and/or architectural importance, dates, events, persons, contexts). USE ADDITIONAL SHEETS IF NECESSARY

SOURCES:

NEGATIVE NO.: Roll 16 #13 RECORDED BY: SD

SLIDE NO.: DATE: 2/27/87

PROPERTY NAME:

ADDRESS: 1430 S.W. Pleasant View ASSESSOR ACCT #:

T/R/S; TIS, R3E, Sec. 17
MAP NO: 3549
TAX LOT:


QUADRANGLE: Damascus, OR 7.5' Series



NEGATIVE NO .:

Roll 16 # 13

SLIDE .:



HIST. NAME: Giese House

DATE OF CONSTRUCTION: 1894

COMMON NAME: Wogsberg residence ORIGINAL USE: Single family residence

ADDRESS: 2202 S.W. Pleasant View Drive

OWNER: Hazel & Harold Wogsberg PRESENT USE: Single family residence

T/R/S: T1S, R3E, Section 17 ARCH/BLDR: N/A

STYLE: Vernacular

MAP NO: 3649 TAX LOT (BLDG) STRUC. DIST. SITE OBJ. (circle)

THEME: Horticulture ADDITION:

BLOCK: LOT: QUAD: Damascus, OR 7.5 series

ASSESSOR ACCT: #

PLAN TYPE/SHAPE: T-shape NO. OF STORIES: 1 1/2 FOUNDATION MATERIAL: Concrete BASEMENT (Y/N): Yes

ROOF FORM & MATERIALS: Gables/composition shingle

WALL CONSTRUCTION: N/A STRUCTURAL FRAME: Balloon

PRIMARY WINDOW TYPE: 4/1 double hung EXTERIOR SURFACING MATERIALS: Wood shakes DECORATIVE FEATURES: Vertical batters on gable end, leaded glass, decorative corner carvings in return eaves. OTHER:

CONDITION: EXCELLENT (GOOD) FAIR DETERIORATED MOVED (DATE)

EXTERIOR ALTERATIONS/ADDITIONS (DATED): Addition to the south, sliding glass door on the north added.

NOTEWORTHY LANDSCAPE FEATURES: Originally, orchard in front yard area, holly, Cedar, Laurel and birch trees, Rhododendrons, row of conifers on the north and east, filbert orchard.

ASSOCIATED STRUCTURES: Old cabin (CA 1900), detached garage

KNOWN ARCHAEOLOGICAL FEATURES: N/A

SETTING: Facing west on S.W. Pleasant Hill Road, approximately 200 ft. from the street. House is surrounded by filbert orchard in the front, located on top of hill, new subdivision around house, Filbert Hill.

STATEMENT OF SIGNIFICANCE (Historical and/or architectural importance, dates, events, persons, contexts). USE ADDITIONAL SHEETS IF NECESSARY This property was originally part of 640 acre filbert farm owned by Percy Giese. It is said to have been the first commercial filbert grove in the United States. The original Giese cabin is still located on the site. In 1894, a large farmhouse was built which still stands, although it has been altered considerably. Giese married at age 55 and died in 1940. The Wogsbergs acquired the property in 1951. At that time it was a 24 acre filbert farm. In 1977 the Wogsbergs sold 22 acres for a housing subdivision. They still reside in the 1894 farmhouse.

SOURCES: Interview with Hazel Wogsberg, 2/27/87, SD; Chris Flagg, masters thesis at University of Oregon; Gresham Outlook, 11/1/77, Oregon Historical Society files

NEGATIVE NO.: Roll 16, #14 SLIDE NO .:


RECORDED BY: SD DATE: 2/27/87 SHPO INVENTORY NO .:

PROPERTY

NAME: Hazel Wogsberg

ADDRESS:


T/R/S; TIS, R3E, Sec. 17 MAP NO: 3649 TAX LOT: ASSESSOR ACCT # S.W. Pleasant View QUADRANGLE: Damascus, OR 7.5' Series



NEGATIVE NO .:

Roll 16 # 14

SLIDE .:



HIST. NAME:

DATE OF CONSTRUCTION: 1919

COMMON NAME: Moir residence ORIGINAL USE: Single family residence

ADDRESS: 2402 S.W. Pleasant View Drive

OWNER: Edgar & Margaret Moir PRESENT USE: Single family residence

T/R/S: T1S, R3E, Section 17 ARCH/BLDR: N/A STYLE: Bungalow

MAP NO: 3649 TAX LOT (BLDG) STRUC. DIST. SITE OBJ. (circle)

ADDITION:

THEME: Agriculture BLOCK: LOT: QUAD: Damascus, OR 7.5' series

ASSESSOR ACCT: #

PLAN TYPE/SHAPE: Rectangular FOUNDATION MATERIAL: Concrete NO. OF STORIES: 1 BASEMENT (Y/N): No

ROOF FORM & MATERIALS: Gable, composition shingle

WALL CONSTRUCTION: Wood STRUCTURAL FRAME: N/A

PRIMARY WINDOW TYPE: 1/1 double hung

EXTERIOR SURFACING MATERIALS: Wood shingles

DECORATIVE FEATURES: Molded window caps

OTHER: N/A

CONDITION: (EXCELLENT) GOOD FAIR DETERIORATED MOVED (DATE)

EXTERIOR ALTERATIONS/ADDITIONS (DATED): New foundation 1979

NOTEWORTHY LANDSCAPE FEATURES: Fruit trees, sparce planting (cherry, walnut, birch)

ASSOCIATED STRUCTURES: Shed/barn, shed

KNOWN ARCHAEOLOGICAL FEATURES: N/A

SETTING: Facing west on the corner of S.W. 25th & S.W. Pleasant View in newer subdivision, 20' setback from sidewalk. On knoll with good view to the north.

STATEMENT OF SIGNIFICANCE (Historical and/or architectural importance, dates, events, persons, contexts). USE ADDITIONAL SHEETS IF NECESSARY According to original title abstracts, this house was built in 1919. The original owner ran a 30 acre filbert and berry farm. There were filberts to the north side of the house and blueberries and strawberries to the south. George & Betty Bartholomew were the previous owners of the property. This area was formerly known as the Causey Suburban Acres.

SOURCES: Margaret Moir, interview, Spring 1987, KL & SD; Mrs. Bartholomew interviewed by Mrs. Moir, Spring 1987.

NEGATIVE NO.: Roll 16, #15

RECORDED BY: SD


SLIDE NO .:

DATE: 2/27/87

PROPERTY


NAME: Edgar & Margaret Moir ADDRESS: ADDRESS: 2402 SW Pleasant View ASSESSOR ACCT #:

T/R/S; TIS, R3E, Sec. 17
MAP NO: 3649 TAX LOT: QUADRANGLE: Damascus, OR 7.5' Series



NEGATIVE NO .:

Roll 16 # 15



HIST. NAME: Buckley residence DATE OF CONSTRUCTION: CA 1900

COMMON NAME: Davis residence ORIGINAL USE: Single family residence

ADDRESS: 2801 S.W. Pleasant View Drive

OWNER: Ernie Davis PRESENT USE: Single family residence

T/R/S: TlS, R3E, Section 17 ARCH/BLDR: N/A STYLE: Bungalow

MAP NO: 3649 TAX LOT (BLDG) STRUC. DIST. SITE OBJ. (circle)

ADDITION: THEME: Agriculture

BLOCK: LOT: QUAD: Damascus, OR 7.5' series

ASSESSOR ACCT: #

FOUNDATION MATERIAL: Concrete BASEMENT (V/N) BASEMENT (Y/N): Yes

ROOF FORM & MATERIALS: Hip/composition shingle

WALL CONSTRUCTION: Wood STRUCTURAL FRAME: Balloon

PRIMARY WINDOW TYPE: 6/1 double hung wood sash EXTERIOR SURFACING MATERIALS: Wood shingle

DECORATIVE FEATURES: N/A

OTHER: N/A

CONDITION: EXCELLENT (GOOD) FAIR DETERIORATED MOVED (DATE)

EXTERIOR ALTERATIONS/ADDITIONS (DATED): N/A

NOTEWORTHY LANDSCAPE FEATURES: Pine tree, sparse plantings, holly tree.

ASSOCIATED STRUCTURES: Outbuilding (concrete), garage

KNOWN ARCHAEOLOGICAL FEATURES: N/A

SETTING: Facing east on S.W. Pleasant View in old rural area, new subdivision to the east, flat lot, house setbacks 20 ft. from the street, open field to the south and crops to the north in field.

STATEMENT OF SIGNIFICANCE (Historical and/or architectural importance, dates, events, persons, contexts). USE ADDITIONAL SHEETS IF NECESSARY

SOURCES:

NEGATIVE NO.: Roll 16, #12 RECORDED BY: SD


SLIDE NO .: DATE: 2/27/87

PROPERTY (Buckley Residence)

ADDRESS:

T/R/S; TIS, R3E, Sec. 17 MAP NO: 3649 TAX LOT:


ASSESSOR ACCT28#1 SW Pleasant View QUADRANGLE: Damascus, OR 7.5' Series



NEGATIVE NO .:

Roll 16 # 12

SLIDE .:



GRAPHIC & PHOTO SOURCES:

Northwest Heritage Property Associates

HIST. NAME:

DATE OF CONSTRUCTION: CA 1890

COMMON NAME: Robert Burns res. ORIGINAL USE: Single family residence

ADDRESS: SW 30th at S.W. Pleasant View Drive

OWNER: Robert Burns PRESENT USE: Single family residence

Rt. 1 Box 195 ARCH/BLDR: N/A T/R/S: T1S, R3E, Sec. 17 STYLE: Craftsman

MAP NO: 3649 TAX LOT (BLDG) STRUC. DIST. SITE OBJ. (circle)

ADDITION: THEME: Agriculture

BLOCK: LOT: QUAD: Damascus, Or., 7.5 series

ASSESSOR ACCT: #

PLAN TYPE/SHAPE: Square NO. OF STORIES: 2
FOUNDATION MATERIAL: Concrete BASEMENT (Y/N): No

ROOF FORM & MATERIALS: HIP/ comp. shingles

WALL CONSTRUCTION: wood STRUCTURAL FRAME: N/A

PRIMARY WINDOW TYPE: 1/1 double hung

EXTERIOR SURFACING MATERIALS: Wood shingles

DECORATIVE FEATURES: Square columns on wrap-around porch

OTHER: N/A

CONDITION: (EXCELLENT) GOOD FAIR DETERIORATED MOVED (DATE)

EXTERIOR ALTERATIONS/ADDITIONS (DATED): Re-sided, aluminum storm windows, front window altered 1st floor, carport & garage added.

NOTEWORTHY LANDSCAPE FEATURES: Birch, pine, oak trees, Rhododendrons around house perimeter.

ASSOCIATED STRUCTURES: Small shed

KNOWN ARCHAEOLOGICAL FEATURES: N/A

SETTING: Facing east on S.W. Pleasant View Drive in rural area with new housing development encroaching. 30' setback from street. Large lot to the north. Vineyard to the south across S.W. 30th.

STATEMENT OF SIGNIFICANCE (Historical and/or architectural importance, dates, events, persons, contexts). USE ADDITIONAL SHEETS IF NECESSARY

Original owners of this house were the Snatcholds. This house was originally part of a 9 acre farm. Dr. Steward, a Chiropractor, bought and remodeled the property prior to 1946. In 1946, C.D. Fergeson bought the house and sold it in 1957 to Bob Burns.

SOURCES:

NEGATIVE NO.: Roll 16, #10A SLIDE NO.: RECORDED BY: SD DATE: 2/27/87

PROPERTY Robert Burns Residence

ADDRESS:

ASSESSOR ACCT \*\* Pleasant View


T/R/S; TIS, R3E, Sec. 17
MAP NO: 3649 TAX LOT:

QUADRANGLE: Damascus, OR 7.5' Series



NEGATIVE NO .:

Roll 16 # 10A



HIST. NAME:

DATE OF CONSTRUCTION: 1900-1910

COMMON NAME: Bradfield property

ADDRESS: 541 S.E. Park Drive

OWNER: B. Bradfield

T/R/S: T1S, R3E, Section 10

ORIGINAL USE: Single family residence

PRESENT USE: Single family residence

ARCH/BLDR: Jake Metzger STYLE: Vernacular

MAP NO: 3453 TAX LOT 140

ADDITION:

(BLDG) STRUC. DIST. SITE OBJ. (circle) THEME: Arch. - 20th Century

BLOCK:

LOT:

QUAD: Damascus OR 7.5 series

ASSESSOR ACCT: #R993101400

PLAN TYPE/SHAPE: Rectangular NO. OF STORIES: 1 1/2 FOUNDATION MATERIAL: Concrete block BASEMENT (Y/N): No

ROOF FORM & MATERIALS: Gable, wood shakes

WALL CONSTRUCTION: Wood STRUCTURAL FRAME: N/A

PRIMARY WINDOW TYPE: 1/1 double hung wood sash EXTERIOR SURFACING MATERIALS: Shiplap/shingle

DECORATIVE FEATURES: N/A

OTHER: Dentils above front picture window, east gable end - decorative fishscale shingles, slightly flared eaves.

CONDITION: EXCELLENT (GOOD) FAIR DETERIORATED MOVED (DATE)

EXTERIOR ALTERATIONS/ADDITIONS (DATED): Brick added to exterior, some aluminum storms added, picture window added, new foundation.

NOTEWORTHY LANDSCAPE FEATURES: Large cedars on the north, open yard, 3 acres, creek running through property, various trees on lot: cedars, birch, firs.

ASSOCIATED STRUCTURES: Barn, small shed attached

KNOWN ARCHAEOLOGICAL FEATURES: N/A

SETTING: Facing south on S.E. Park Drive, set on 3 acres, well manicured yard, large open area, 5' drop to house from road, barn on the west, across Johnson Creek.

STATEMENT OF SIGNIFICANCE (Historical and/or architectural importance, dates, events, persons, contexts). USE ADDITIONAL SHEETS IF NECESSARY This house was built by Jake Metzger. Original owners were the This property is notable for its landscaping. McKunnens.

SOURCES: Interview with Bradfield, Spring 1987, SD

NEGATIVE NO.: Roll 10, #32 - 35 RECORDED BY: SD

SLIDE NO .:


DATE: 2/6/87

PROPERTY

NAME: B. Bradfield


ADDRESS: 541 S.E. Park Drive ASSESSOR ACCT #:

T/R/S; TIS, R3E, Sec. 10
MAP NO: 3453
QUADRANGLE: Damascus, OR 7.5' Series



NEGATIVE NO.: Roll 10 # 32-35

SLIDE .:



GRAPHIC & PHOTO SOURCES:

Northwest Heritage Property Associates

DATE OF CONSTRUCTION: 1908

ARCH/BUILDER: Mr. Danmeine PRESENT USE: Residence

(BLDG) STRUC. DIST. SITE OBJ. (circle)

ORIGINAL USE : Residence

STYLE: Bungalow

HIST. NAME:

COMMON NAME: Birch Residence ADDRESS: 675 SE Park Drive

OWNER: Donald C Birch, 675 SE Park

T/R/S: T1S R3E Sec 10

MAP NO: 3453 TAX LOT 150

ADDITION

THEME: Architecture: 20th Century QUAD: Damascus, Or 7.5' series BLOCK: LOT:

ASSESSOR ACCT: #R993101500

PLAN TYPE/SHAPE; rectangular

NO. OF STORIES: 1 1/2 BASEMENT (Y/N): yes FOUNDATION MATERIAL: brick

ROOF FORM & MATERIALS: gable with composition shingles

STRUCTURAL FRAME: n/a WALL CONSTRUCTION: wood

PRIMARY WINDOW TYPE: 1/1 double hung wood sash EXTERIOR SURFACING MATERIALS: wood shingles

DECORATIVE FEATURES: window boxes, turned porch ballustrades, decorative

leaded glass sidelights

OTHER: paned colonial porch columns, corbelled chimney cap

(EXCELLENT) FAIR DETERIORATED MOVED CONDITION: GOOD

(DATE)

EXTERIOR ALTERATIONS/ADDITIONS (DATED): new aluminum storm windows, porch used to extend across entire front facade

NOTEWORTHY LANDSCAPE FEATURES: large Monkey tree in front yard. garden in front yard, hedge to east, conifers surround property. Loy heavily planted, Hogan cedars.

ASSOCIATED STRUCTURES; shed--flat roof

KNOWN ARCHAEOLOGICAL FEATURES: N/A

SETTING: Facing east on SE Park Drive on large acreage. Old railroad tracks to east, semi-circular driveway. Creek west of house, secluded area

STATEMENT OF SIGNIFICANCE (Historical and/or architectural importance, dates, events, persons, contexts). USE ADDITIONAL SHEETS IF NECESSARY:

Mr. Danmeier built home. He was a saloon keeper. The current owner has owned the property for 37 years.

SOURCES: Interview with Donald Birch (2/6/87), by SD

NEGATIVE NO.: Roll 10 #36 SLIDE NO .:

RECORDED BY: SD DATE: 2/6/87

PROPERTY

NAME: Donald & Ruth Birch


ADDRESS: 675 SE Park Drive ASSESSOR ACCT #:

T/R/S; T/R/S; TIS, R3ETAX LOT: 10

MAP NO: 3453
QUADRANGLE: Damascus. OR 7.5' Series



Roll 10 # 36



HIST. NAME: Palmblad Dairy

DATE OF CONSTRUCTION: 1910

COMMON NAME: Twin Cedar Dairy

ORIGINAL USE: Residence

ADDRESS: 2720 S.E. Palmblad Avenue

onzoznina oobi kesit

OWNER: Deck family

PRESENT USE: Single family residence ARCH/BLDR: N/A

T/R/S: T1S, R3E, Section 14

STYLE: Bungalow

MAP NO: 3656 TAX LOT

(BLDG) STRUC. DIST. SITE OBJ. (circle)

ADDITION: THEME: Agriculture

BLOCK: LOT:

QUAD: Damascus, OR 7.5 series

ASSESSOR ACCT: #

PLAN TYPE/SHAPE: Rectangular
FOUNDATION MATERIAL: Concrete
ROOF FORM & MATERIALS: Gable, composition shingle
WALL CONSTRUCTION: Wood
PRIMARY WINDOW TYPE: 1/1 Wood sash, 2 picture windows in front

EXTERIOR SURFACING MATERIALS: Wood weatherboard

DECORATIVE FEATURES: Exposed brackets OTHER:

CONDITION:

(EXCELLENT) GOOD FAIR DETERIORATED MOVED

(DATE)

EXTERIOR ALTERATIONS/ADDITIONS (DATED): N/A

NOTEWORTHY LANDSCAPE FEATURES: 2 Hogan Cedars, fruit trees

ASSOCIATED STRUCTURES: 1 small wooden bldg. (former dairy bldg.)

KNOWN ARCHAEOLOGICAL FEATURES: N/A

SETTING: 30 ft. back from S.E. Palmblad in rural area. View of Mt. Hood to the east. Fields south and north.

STATEMENT OF SIGNIFICANCE (Historical and/or architectural importance, dates, events, persons, contexts). USE ADDITIONAL SHEETS IF NECESSARY This property is part of what was once known as the Palmblad Dairy. An outbuilding, original to the dairy, still stands on the back of the lot. Palmblad was a well known local dairyman. The street in front of the house was named after him.

SOURCES: Interview with Mr. Deck, 2/26/87, KL

NEGATIVE NO.: Roll 16, #5A

RECORDED BY: KL & SP

SLIDE NO .:

DATE: 2/26/87

PROPERTY
NAME: (Palmblad Dairy)
ADDRESS: Deck Family
ASSESSOR ACCT 27#20 S.E. Palmblad


T/R/S; TIS, R3E, Sec. 14
MAP NO: 3666 TAX LOT:
QUADRANGLE: Damascus, OR 7.5' Series



NEGATIVE NO .:

Roll 16 # 5A

SI.TDE .



HIST. NAME: Carroll residence DATE OF CONSTRUCTION: 1910-20

COMMON NAME: Erickson residence ORIGINAL USE: Single family residence

ADDRESS: 2910 S.E. Palmquist Road

PRESENT USE: Single family residence OWNER: Adela Erickson

ARCH/BLDR: N/A

T/R/S: TlS, R3E, Section 14 STYLE: Vernacular

(BLDG) STRUC. DIST. SITE OBJ. (circle) MAP NO: 3556 TAX LOT

THEME: Arch. - 20th Century ADDITION:

QUAD: Damascus, OR 7.5 series BLOCK: LOT: 12

ASSESSOR ACCT: #

NO. OF STORIES: 1 1/2 PLAN TYPE/SHAPE: Rectangular FOUNDATION MATERIAL: Concrete BASEMENT (Y/N): Yes

ROOF FORM & MATERIALS: Gambrel/composition shingle

WALL CONSTRUCTION: Wood STRUCTURAL FRAME: N/A

PRIMARY WINDOW TYPE: 1/1 double hung wood sash

EXTERIOR SURFACING MATERIALS: Shiplap

DECORATIVE FEATURES: N/A

OTHER: N/A

FAIR (DATE) (EXCELLENT) GOOD DETERIORATED MOVED CONDITION:

EXTERIOR ALTERATIONS/ADDITIONS (DATED): Front windows altered, alumninum windows, new porch supports

NOTEWORTHY LANDSCAPE FEATURES: Several Holly trees, Birch trees, 3 kinds of cedars, rhododendrons, boxwood hedge lining sidewalk to house, garden to the west, old apple, plum, oak, cherry, fig, walnut, pear trees, lilies and grapes.

ASSOCIATED STRUCTURES: Detached garage, grape trellis

KNOWN ARCHAEOLOGICAL FEATURES: N/A

SETTING: Facing north on S.E. Palmquist and S.E. Palmblad in residential area, 60' setback to street, large lot, well maintained yard.

STATEMENT OF SIGNIFICANCE (Historical and/or architectural importance, dates, events, persons, contexts). USE ADDITIONAL SHEETS IF NECESSARY This home has been owned by the Ericksons for the last 9 years. Adela Erickson bought the house from Glen Carroll, who was the brother of Mr. Carroll, who owns the Carroll Funeral Parlor in Gresham. Glen's father was likely the first owner of the house.

SOURCES: Adela Erickson, interview, 2/27/87, KL

NEGATIVE NO.: Roll 15, #36A RECORDED BY: SD

SLIDE NO .: DATE: 2/27/87


PROPERTY (Carroll House) NAME: Adela Erickson ADDRESS: 2010CF Pal

ASSESSOR ACCT #: Palmquist

T/R/S; TIS, R3E, Sec. 14 MAP NO: 3696 TAX LOT: QUADRANGLE: Damascus, OR 7.5' Series



NEGATIVE NO .: \_\_\_\_Roll\_15\_#\_36#\_



GRAPHIC & PHOTO SOURCES:

Northwest Heritage Proeprty Associates SHPO INVENTORY NO: