

Move In

Property	Tenant(s)	Date	Agent	/
1234 Briny Ave	Liz Smith	2024-04-16	Inspector	

Adrienne Klein

Move In Condition Summary

<input type="checkbox"/> AREA <input type="checkbox"/>	DETAIL	<input type="checkbox"/> <input type="checkbox"/>	ACTION	<input type="checkbox"/> COMMENTS	<input type="checkbox"/> MEDIA
Bedroom	Wall/Ceiling	<b>D</b>	None	There are nails in the wall and there are marks on the wall below the master bedroom window. On the ceiling and looks like maybe there was some kind of leak because it's one big strike that's painted see pictures.	<input type="checkbox"/> Image <input type="checkbox"/> Image <input type="checkbox"/> Image <input type="checkbox"/> Image <input type="checkbox"/> Image <input type="checkbox"/> Image
Bedroom 2	Closet/Door/Track / Shelving	<b>D</b>	None	Drawers in closet are difficult to open and dirty two different kinds of paint on the tracking of the closet door	<input type="checkbox"/> Image <input type="checkbox"/> Image <input type="checkbox"/> Image <input type="checkbox"/> Image <input type="checkbox"/> Image
Bathroom	Plumbing/Drain	<b>D</b>	None	When you flush toilet bowl, the water is leaking out from the base of the toilet bowl system problem needs to be addressed immediately	<input type="checkbox"/> Image <input type="checkbox"/> Image <input type="checkbox"/> Image <input type="checkbox"/> Image <input type="checkbox"/> Image <input type="checkbox"/> Image

□ AREA	□ DETAIL	□	□ ACTION	□ COMMENTS	□ MEDIA
Bathroom	Toilet	D	None	Toilet bowl is leaking when you flush have the plumber I addresses immediately	<input type="checkbox"/> Image <input type="checkbox"/> Image <input type="checkbox"/> Image
Bathroom	Tub/Shower	D	None	Dirty and difficult to open sliders	<input type="checkbox"/> Image
Bathroom	Wall/Ceiling	D	None	Looks like they could've been some kind of water leak on the plastic sub ceiling and the type of light fixture they have is too close to the plastic of the sub ceiling and it looks like it's leaving almost burn marks from the heat of the lightbulbs	<input type="checkbox"/> Image <input type="checkbox"/> Image <input type="checkbox"/> Image <input type="checkbox"/> Image <input type="checkbox"/> Image <input type="checkbox"/> Image
Bathroom 2	Wall/Ceiling	D	None	There are nails and walls and there looks like the wallpaper is dirty not identifiable if it's from dirt or water leak	<input type="checkbox"/> Image <input type="checkbox"/> Image <input type="checkbox"/> Image <input type="checkbox"/> Image <input type="checkbox"/> Image <input type="checkbox"/> Image <input type="checkbox"/> Image <input type="checkbox"/> Image <input type="checkbox"/> Image <input type="checkbox"/> Image
Dining Room	Light Fixture/Fan	D	None	Electricity not on in unit can't check for lights and light fixtures	<input type="checkbox"/> Image <input type="checkbox"/> Image







AREA	DETAIL		ACTION	COMMENTS	MEDIA
Living Room	Window/Lock/Screen	D	None	Sliding glass balcony door lock not locking not closing properly if there's rain and wind, it could cause issues in the condo	<input data-bbox="1348 235 1372 268" type="checkbox"/> <a href="#">Image</a> <input data-bbox="1348 280 1372 313" type="checkbox"/> <a href="#">Image</a>

□ Move-In Conditions

N=New

S=Satisfactory

D=Damaged

□ Entry	□ CONDITION	□ ACTION	□ COMMENTS
Door/Knob/Lock	- S - -	ACTION	
Doorbell	- S - -	None	
Flooring/Baseboard	- S - -	None	
Light Fixture/Fan	- S - -	None	
Other	- S - -	None	
Security/Screen Door	- S - -	None	
Switch/Outlet	- S - -	None	
Wall/Ceiling	- S - -	None	

□ Bedroom	□ CONDITION	□ ACTION	□ COMMENTS
Closet/Door/Track/Shelving	- S - -	ACTION	
Door/Knob/Lock	- S - -	None	
Flooring/Baseboard	- S - -	None	
Switch/Outlet	- S - -	None	
Wall/Ceiling	- - D -	None	There are nails in the wall and there are marks on the wall below the master bedroom window. On the ceiling and looks like maybe there was some kind of leak because it's one big strike that's painted see pictures.
Window Covering	S - -None	None	
Window/Lock/Screen	S - -None	None	

□ Bedroom 2	□ CONDITION	□ ACTION	□ COMMENTS
Closet/Door/Track/Shelving	- - D -	None	Drawers in closet are difficult to open and dirty two different kinds of paint on the tracking of the closet door
Door/Knob/Lock	S - -None	None	
Flooring/Baseboard	S - -None	None	
Light Fixture/Fan	N - - -None	None	
Switch/Outlet	S - -None	None	

□ Bedroom 2	□ CONDITION	□	□ COMMENTS
Wall/Ceiling	- S - -	ACTION	
Window Covering	- S - -	None	
Window/Lock/Screen	- S - -	None	

□ Bathroom	□ CONDITION	□	□ COMMENTS
------------	-------------	---	------------

Cabinet/Counter/Shelving	- S - -		
Door/Knob/Lock	- S - -	ACTION	
Flooring/Baseboard	- S - -	None	
Light Fixture	N - - -	None None	No electricity on in the apartment cannot check lighting
Medicine Cabinet/Mirror	- S - -	None	
Plumbing/Drain	- - D -	None None	When you flush toilet bowl, the water is leaking out from the base of the toilet bowl system problem needs to be addressed immediately
Shower	- S - -	Non	
Door/Rail/Curtain	- S - -	e	
Sink/Faucet	- S - -	Non	
Switch/Outlet		e	
Toilet	- - D -	Non e	Toilet bowl is leaking when you flush have the plumber I addresses immediately
Toilet Paper Holder	- S - -	Non	
Towel Rack	- S - -	e	Dirty and difficult to open sliders
Tub/Shower	- - D -	Non	
Wall/Ceiling	- - D -	None e Non e	Looks like they could've been some kind of water leak on the plastic sub ceiling and the type of light fixture they have is too close to the plastic of the sub ceiling and it looks like it's leaving almost burn marks from the heat of the lightbulbs
Window Covering	N - -	Non	
Window/Lock/Screen	- N - - -	e Non	

□ Bathroom 2	□ CONDITION	□ ACTION	□ COMMENTS
Cabinet/Counter/Shelving	- S - -	ACTION	
Door/Knob/Lock	- S - -	None	
Exhaust Fan	N - - -	None	
Flooring/Baseboard	- S - -	None	
Light Fixture	N - - -	None	No electricity cannot check the light fixtures
Medicine Cabinet/Mirror	N - - -	None	
Plumbing/Drain	- S - -	None	
Shower Door/Rail/Curtain	- S - -	None	
Sink/Faucet	- S - -	None	
Switch/Outlet	- S - -	None	
Toilet	- S - -	None	
Toilet Paper Holder	- S - -	None	
Towel Rack	- S - -	None	
Tub/Shower	- S - -	None	
Wall/Ceiling	- - D -	None	There are nails and walls and there looks like the wallpaper is dirty not identifiable if it's from dirt or water leak
Window Covering	N - - -	None	
Window/Lock/Screen	N - - -	None	

□ Dining Room	□ CONDITION	□ ACTION	□ COMMENTS
Flooring/Baseboard	- S - -	None	Electricity not on in unit
Light Fixture/Fan	- - D -	None	can't check for lights and light fixtures
Switch/Outlet	N - - -	None	

□ Kitchen	□ CONDITION	□ ACTION	□ COMMENTS
Cabinets/Drawers	- - D -	None	visible peeling of laminate paper that was applied to the kitchen cabinets and the last side upper cabinet hinge is off needs to be replaced. Dirty needs to be cleaned

□ Kitchen	□ CONDITION	□ ACTION	□ COMMENTS
Counter	- - D -	None	The counter is 4 x 4, Beth tile from ceramic and the grout is filthy. Lots of spaces.
Dishwasher	N - - -	None	dishwasher coil looks burnt very old unit front door of the dishwasher is very fragile off kilter
Faucet/Plumbing	- S - -	Non	Super low water pressure coming out of the sink
Flooring/Baseboard	- S - -	e	
Light Fixture	N - -	Non	No electricity on don't know if all lighting fixtures
Microwave	-	e	
Oven	N - - - - D -	Non None	Oven needs to be professionally cleaned. It is disgusting with cooked on food filth clean before use.
Range/Fan/Hood/Filter	- - D -	None	Range oven is filthy old. The inside is disgusting super cleaning.
Refrigerator	- - D -	None	refrigerator has been painted over many times, do not know if the refrigerator and freezer work there's no electricity on in the unit to go in another refrigerator. You have to step outside into the dining room otherwise the door slams against the dishwasher appliance..
Sink/Disposal	N - - -	None	
Switch/Outlet	N - - -	None	
Wall/Ceiling	- S - -	None	
Window Covering	- S - -	None	
Window/Lock/Screen	- S - -	None	

□ Living Room	□ CONDITION	□ ACTION	□ COMMENTS
Flooring/Baseboard	- S - -	None	
Switch/Outlet	- S - -	None	Electric is not on cannot test anything

Living Room CONDITION ACTION COMMENTS

Wall/Ceiling- S - -None			
Window Covering- - D -None blinds are missing		Slacks for the vertical	
lock not locking not Window/Lock/Screen- - D -None rain and wind, it could		closing properly if there's	Sliding glass balcony door  cause issues in the condo

Keys/Remotes/Devices CONDITION ACTION COMMENTS

Keys- S - -None Key was from lockbox			
---	--	--	--

Additional Comments

Final Comments

To dispute any findings of this inspection please notify us within 3 business days.

Agent / Inspector Signature



Entry




2024-04-16 13:47:38  
 [26.23075866699219, -  
80.09078144822146](#)  
 Image \_\_\_\_\_



2024-04-16 13:48:23  
 [26.23068639733266, -  
80.09092187013188](#)  
 Image \_\_\_\_\_



2024-04-16 14:38:27  
 [26.23039245605469, -  
80.0910979815113](#)  
 Image \_\_\_\_\_



2024-04-16 14:38:34  
 [26.23039245605469, -  
80.0910979815113](#)  
 Image \_\_\_\_\_



2024-04-16 14:38:35  
 [26.23039245605469, -  
80.0910979815113](#)  
 Image \_\_\_\_\_



2024-04-16 14:38:36  
 [26.23039245605469, -  
80.0910979815113](#)  
 Image \_\_\_\_\_



2024-04-16 14:38:37  
 [26.23039245605469,](https://www.26.23039245605469.com)  
- [80.0910979815113](https://www.80.0910979815113.com)  
 Image \_\_\_\_\_



2024-04-16 14:38:38  
 [26.23039245605469,](https://www.26.23039245605469.com)  
- [80.0910979815113](https://www.80.0910979815113.com)  
 Image \_\_\_\_\_



2024-04-16 14:38:42  
 [26.23039245605469,](https://www.26.23039245605469.com)  
- [80.0910979815113](https://www.80.0910979815113.com)  
 Image \_\_\_\_\_



2024-04-16 14:38:43  
 [26.23039245605469,](https://www.26.23039245605469.com)  
- [80.0910979815113](https://www.80.0910979815113.com)  
 Image \_\_\_\_\_




2024-04-16 14:38:43  
 [26.23039245605469,](https://www.26.23039245605469.com) -  
[80.0910979815113](https://www.80.0910979815113.com)  
 Image \_\_\_\_\_



2024-04-16 14:38:44  
 [26.23039245605469,](https://www.26.23039245605469.com)  
- [80.0910979815113](https://www.80.0910979815113.com)  
 Image \_\_\_\_\_

**Bedroom 1**





2024-04-16 13:58:12 EDT

Closet/Door/Track/Shelving

□ 2024-04-16 13:58:12

□ [26.23033929215465, -80.0909318410351](#)

□ [Image](#)




2024-04-16 13:58:23 EDT

Closet/Door/Track/Shelving

□ 2024-04-16 13:58:23

□ [26.2303944561073, -80.09081953259756](#)

□ [Image](#)



2024-04-16 13:58:25 EDT

Closet/Door/Track/Shelving

□ 2024-04-16 13:58:25

□ [26.2303944561073, -80.09081953259756](#)

□ [Image](#)



2024-04-16 13:58:27 EDT

Closet/Door/Track/Shelving

□ 2024-04-16 13:58:27

□ [26.2303944561073, -80.09081953259756](#)

□ [Image](#)




2024-04-16 13:58:31 EDT

Closet/Door/Track/Shelving

□ 2024-04-16 13:58:31

□ [26.2303944561073, -80.09081953259756](#)

□ [Image](#)




2024-04-16 13:58:34 EDT

Closet/Door/Track/Shelving

□ 2024-04-16 13:58:34

□ [26.2303944561073, -80.09081953259756](#)

□ [Image](#)



2024-04-16 13:58:36 EDT

**Closet/Door/Track/Shelving**

- 2024-04-16 13:58:36
- [26.2303944561073, -80.09081953259756](#)
- [Image](#)



2024-04-16 13:58:37 EDT

**Closet/Door/Track/Shelving**

- 2024-04-16 13:58:37
- [26.2303944561073, -80.09081953259756](#)
- [Image](#)



2024-04-16 13:58:42 EDT

**Closet/Door/Track/Shelving**

- 2024-04-16 13:58:42
- [26.2303944561073, -80.09081953259756](#)
- [Image](#)



2024-04-16 13:59:02 EDT

**Door/Knob/Lock**

- 2024-04-16 13:59:02
- [26.2303944561073, -80.09081953259756](#)
- [Image](#)



2024-04-16 13:59:06 EDT

**Door/Knob/Lock**


- 2024-04-16 13:59:06
- [26.2303944561073, -80.09081953259756](#)
- [Image](#)



2024-04-16 13:59:15 EDT


**Flooring/Baseboard**

- 2024-04-16 13:59:15
- [26.2303944561073, -80.09081953259756](#)
- [Image](#)




**Flooring/Baseboard**

- 2024-04-16 13:59:16
- [26.2303944561073, -80.09081953259756](#)
- Image \_\_\_\_\_




**Flooring/Baseboard**

- 2024-04-16 13:59:17
- [26.2303944561073, -80.09081953259756](#)
- Image \_\_\_\_\_




**Flooring/Baseboard**

- 2024-04-16 13:59:18
- [26.2303944561073, -80.09081953259756](#)
- Image \_\_\_\_\_




**Flooring/Baseboard**

- 2024-04-16 13:59:20
- [26.2303944561073, -80.09081953259756](#)
- Image \_\_\_\_\_



**Flooring/Baseboard**

- 2024-04-16 13:59:21
- [26.2303944561073, -80.09081953259756](#)
- Image \_\_\_\_\_




**Flooring/Baseboard**

- 2024-04-16 13:59:22
- [26.2303944561073, -80.09081953259756](#)
- Image \_\_\_\_\_



**Flooring/Baseboard**

- 2024-04-16 13:59:24
- [26.2303944561073, -80.09081953259756](#)
- Image \_\_\_\_\_




**Flooring/Baseboard**

- 2024-04-16 13:59:25
- [26.2303944561073, -80.09081953259756](#)
- Image \_\_\_\_\_




**Flooring/Baseboard**

- 2024-04-16 13:59:26
- [26.2303944561073, -80.09081953259756](#)
- Image \_\_\_\_\_




**Flooring/Baseboard**

- 2024-04-16 13:59:28
- [26.2303944561073, -80.09081953259756](#)
- Image \_\_\_\_\_



**Flooring/Baseboard**

- 2024-04-16 13:59:29
- [26.2303944561073, -80.09081953259756](#)
- Image \_\_\_\_\_



**Flooring/Baseboard**

- 2024-04-16 13:59:30
- [26.2303944561073, -80.09081953259756](#)
- Image \_\_\_\_\_



2024-04-16 13:59:31 EDT

**Flooring/Baseboard**

- 2024-04-16 13:59:31
- [26.2303944561073, -80.09081953259756](#)
- Image \_\_\_\_\_



2024-04-16 13:49:16 EDT

- 2024-04-16 13:49:16
- [26.23068639733266, -80.09092187013188](#)
- Image \_\_\_\_\_



2024-04-16 13:49:30 EDT

- 2024-04-16 13:49:30
- [26.23068639733266, -80.09092187013188](#)
- Image \_\_\_\_\_




2024-04-16 13:49:32 EDT

- 2024-04-16 13:49:32
- [26.23068639733266, -80.09092187013188](#)
- Image \_\_\_\_\_



2024-04-16 13:49:35 EDT

- 2024-04-16 13:49:35
- [26.23068639733266, -80.09092187013188](#)
- Image \_\_\_\_\_



2024-04-16 13:49:36 EDT

- 2024-04-16 13:49:36
- [26.23068639733266, -80.09092187013188](#)
- Image \_\_\_\_\_





2024-04-16 13:49:48 EDT

□ 2024-04-16 13:49:48  
□ [26.23068639733266, -  
80.09092187013188](https://www.google.com/maps/place/26.23068639733266,-80.09092187013188)

□ Image \_\_\_\_\_



2024-04-16 13:49:57 EDT

□ 2024-04-16 13:49:57  
□ [26.23068639733266, -  
80.09092187013188](https://www.google.com/maps/place/26.23068639733266,-80.09092187013188)

□ Image \_\_\_\_\_



2024-04-16 13:50:00 EDT

□ 2024-04-16 13:50:00  
□ [26.23068639733266, -  
80.09092187013188](https://www.google.com/maps/place/26.23068639733266,-80.09092187013188)


□ Image \_\_\_\_\_



2024-04-16 13:50:05 EDT

□ 2024-04-16 13:50:05  
□ [26.23068639733266, -  
80.09092187013188](https://www.google.com/maps/place/26.23068639733266,-80.09092187013188)


□ Image \_\_\_\_\_



2024-04-16 13:50:09 EDT

□ 2024-04-16 13:50:09  
□ [26.230224609375, -  
80.09087351562285](https://www.google.com/maps/place/26.230224609375,-80.09087351562285)

□ Image \_\_\_\_\_



2024-04-16 13:50:10 EDT

□ 2024-04-16 13:50:10  
□ [26.230224609375, -  
80.09087351562285](https://www.google.com/maps/place/26.230224609375,-80.09087351562285)

□ Image \_\_\_\_\_



2024-04-16 13:50:15 EDT

☐ 2024-04-16 13:50:15  
☐ [26.230224609375, -80.09087351562285](#)


☐ Image \_\_\_\_\_



2024-04-16 13:50:17 EDT

☐ 2024-04-16 13:50:17  
☐ [26.230224609375, -80.09087351562285](#)

☐ Image \_\_\_\_\_



2024-04-16 13:50:19 EDT

☐ 2024-04-16 13:50:19  
☐ [26.230224609375, -80.09087351562285](#)

☐ Image \_\_\_\_\_



2024-04-16 13:50:24 EDT

☐ 2024-04-16 13:50:24  
☐ [26.230224609375, -80.09087351562285](#)


☐ Image \_\_\_\_\_



2024-04-16 13:50:30 EDT

☐ 2024-04-16 13:50:30  
☐ [26.230224609375, -80.09087351562285](#)

☐ Image \_\_\_\_\_



2024-04-16 13:50:32 EDT

☐ 2024-04-16 13:50:32  
☐ [26.230224609375, -80.09087351562285](#)

☐ Image \_\_\_\_\_



□ 2024-04-16 13:50:33  
□ [26.230224609375, -80.09087351562285](#)  
□ Image \_\_\_\_\_




□ 2024-04-16 13:50:38  
□ [26.230224609375, -80.09087351562285](#)  
□ Image \_\_\_\_\_




□ 2024-04-16 13:50:40  
□ [26.230224609375, -80.09087351562285](#)  
□ Image \_\_\_\_\_



□ 2024-04-16 13:50:47  
□ [26.230224609375, -80.09087351562285](#)  
□ Image \_\_\_\_\_



**Switch/Outlet**  
□ 2024-04-16 13:59:47  
□ [26.2303944561073, -80.09081953259756](#)  
□ Image \_\_\_\_\_



**Switch/Outlet**  
□ 2024-04-16 13:59:49  
□ [26.2303944561073, -80.09081953259756](#)  
□ Image \_\_\_\_\_





Switch/Outlet

- 2024-04-16 13:59:51
- [26.2303944561073, -80.09081953259756](#)
- Image \_\_\_\_\_




Wall/Ceiling

- 2024-04-16 13:52:26
- [26.23020935058594, -80.09082932814903](#)
- Image \_\_\_\_\_



Wall/Ceiling

- 2024-04-16 13:52:31
- [26.23020935058594, -80.09082932814903](#)
- Image \_\_\_\_\_



Wall/Ceiling

- 2024-04-16 13:52:32
- [26.23020935058594, -80.09082932814903](#)
- Image \_\_\_\_\_



Wall/Ceiling

- 2024-04-16 13:52:37
- [26.23020935058594, -80.09082932814903](#)
- Image \_\_\_\_\_



Wall/Ceiling

- 2024-04-16 13:52:40
- [26.23020935058594, -80.09082932814903](#)
- Image \_\_\_\_\_

**Bedroom 2**




2024-04-16 13:54:24 EDT

**Closet/Door/Track/Shelving**

□ 2024-04-16 13:54:24

□ [26.23037539712876](https://www.26.23037539712876.com), - [80.09086110597478](https://www.80.09086110597478.com)

□ [Image](#)



2024-04-16 13:54:27 EDT

**Closet/Door/Track/Shelving**

□ 2024-04-16 13:54:27

□ [26.23037539712876](https://www.26.23037539712876.com), - [80.09086110597478](https://www.80.09086110597478.com)

□ [Image](#)



2024-04-16 13:54:29 EDT

**Closet/Door/Track/Shelving**

□ 2024-04-16 13:54:29

□ [26.23037539712876](https://www.26.23037539712876.com), - [80.09086110597478](https://www.80.09086110597478.com)

□ [Image](#)



2024-04-16 13:54:34 EDT

**Closet/Door/Track/Shelving**

□ 2024-04-16 13:54:34

□ [26.23037539712876](https://www.26.23037539712876.com), - [80.09086110597478](https://www.80.09086110597478.com)

□ [Image](#)




2024-04-16 13:54:36 EDT

**Closet/Door/Track/Shelving**

□ 2024-04-16 13:54:36

□ [26.23037539712876](https://www.26.23037539712876.com), - [80.09086110597478](https://www.80.09086110597478.com)

□ [Image](#)



2024-04-16 13:54:55 EDT

**Door/Knob/Lock**

□ 2024-04-16 13:54:55


□ [26.23037539712876](https://www.26.23037539712876.com), - [80.09086110597478](https://www.80.09086110597478.com)

□ [Image](#)




Flooring/Baseboard

- 2024-04-16 13:55:05
- [26.23037539712876,](https://www.26.23037539712876.com)
- [- 80.09086110597478](https://www.80.09086110597478.com)
- Image [\\_\\_\\_\\_\\_](#)



Flooring/Baseboard

- 2024-04-16 13:55:06
- [26.23037539712876,](https://www.26.23037539712876.com)
- [- 80.09086110597478](https://www.80.09086110597478.com)
- Image [\\_\\_\\_\\_\\_](#)



Flooring/Baseboard

- 2024-04-16 13:55:09
- [26.23037539712876,](https://www.26.23037539712876.com)
- [- 80.09086110597478](https://www.80.09086110597478.com)
- Image [\\_\\_\\_\\_\\_](#)



Flooring/Baseboard

- 2024-04-16 13:55:11
- [26.23037539712876,](https://www.26.23037539712876.com)
- [- 80.09086110597478](https://www.80.09086110597478.com)
- Image [\\_\\_\\_\\_\\_](#)




Flooring/Baseboard

- 2024-04-16 13:55:12
- [26.23037539712876,](https://www.26.23037539712876.com)
- [- 80.09086110597478](https://www.80.09086110597478.com)
- Image [\\_\\_\\_\\_\\_](#)




Flooring/Baseboard

- 2024-04-16 13:55:13
- [26.23037539712876,](https://www.26.23037539712876.com)
- [- 80.09086110597478](https://www.80.09086110597478.com)
- Image [\\_\\_\\_\\_\\_](#)




**Flooring/Baseboard**

- 2024-04-16 13:55:13
- [26.23037539712876,](https://www.26.23037539712876.com)
- [- 80.09086110597478](https://www.80.09086110597478.com)
- Image [\\_\\_\\_\\_\\_](#)




**Flooring/Baseboard**

- 2024-04-16 13:55:16
- [26.23037539712876,](https://www.26.23037539712876.com)
- [- 80.09086110597478](https://www.80.09086110597478.com)
- Image [\\_\\_\\_\\_\\_](#)




**Flooring/Baseboard**

- 2024-04-16 13:55:17
- [26.23037539712876,](https://www.26.23037539712876.com)
- [- 80.09086110597478](https://www.80.09086110597478.com)
- Image [\\_\\_\\_\\_\\_](#)




**Flooring/Baseboard**

- 2024-04-16 13:55:18
- [26.23037539712876,](https://www.26.23037539712876.com)
- [- 80.09086110597478](https://www.80.09086110597478.com)
- Image [\\_\\_\\_\\_\\_](#)



**Flooring/Baseboard**

- 2024-04-16 13:55:19
- [26.23037539712876,](https://www.26.23037539712876.com)
- [- 80.09086110597478](https://www.80.09086110597478.com)
- Image [\\_\\_\\_\\_\\_](#)



**Flooring/Baseboard**

- 2024-04-16 13:55:20
- [26.23037539712876,](https://www.26.23037539712876.com)
- [- 80.09086110597478](https://www.80.09086110597478.com)
- Image [\\_\\_\\_\\_\\_](#)



2024-04-16 13:55:23 EDT

**Flooring/Baseboard**

- 2024-04-16 13:55:23
- [26.23037539712876,](#)
- [- 80.09086110597478](#)
- Image \_\_\_\_\_



2024-04-16 13:53:03 EDT

- 2024-04-16 13:53:03
- [26.23020935058594,](#)
- [- 80.09082932814903](#)
- Image \_\_\_\_\_




2024-04-16 13:53:04 EDT

- 2024-04-16 13:53:04
- [26.23020935058594,](#)
- [- 80.09082932814903](#)
- Image \_\_\_\_\_




2024-04-16 13:53:13 EDT

- 2024-04-16 13:53:13
- [26.23020935058594,](#)
- [- 80.09082932814903](#)
- Image \_\_\_\_\_



2024-04-16 13:53:14 EDT

- 2024-04-16 13:53:14
- [26.23020935058594,](#)
- [- 80.09082932814903](#)
- Image \_\_\_\_\_



2024-04-16 13:53:15 EDT

- 2024-04-16 13:53:15
- [26.23020935058594,](#)
- [- 80.09082932814903](#)
- Image \_\_\_\_\_






2024-04-16 13:53:16  
[26.23020935058594, -80.09082932814903](#)  
Image \_\_\_\_\_



2024-04-16 13:53:16  
[26.23020935058594, -80.09082932814903](#)  
Image \_\_\_\_\_



2024-04-16 13:53:26  
[26.23020935058594, -80.09082932814903](#)  
Image \_\_\_\_\_



2024-04-16 13:53:28  
[26.23020935058594, -80.09082932814903](#)  
Image \_\_\_\_\_



2024-04-16 13:53:39  
[26.23020935058594, -80.09082932814903](#)  
Image \_\_\_\_\_



2024-04-16 13:53:40  
[26.23020935058594, -80.09082932814903](#)  
Image \_\_\_\_\_




2024-04-16 13:53:42 EDT

□ 2024-04-16 13:53:42

□ [26.23020935058594, -](#)  
[80.09082932814903](#)

□ Image \_\_\_\_\_




2024-04-16 13:55:36 EDT

Switch/Outlet

□ 2024-04-16 13:55:36

□ [26.23037539712876, -](#)  
[80.09086110597478](#)

□ Image \_\_\_\_\_



2024-04-16 13:55:40 EDT

Switch/Outlet

□ 2024-04-16 13:55:40

□ [26.23037539712876, -](#)  
[80.09086110597478](#)

□ Image \_\_\_\_\_



2024-04-16 13:56:34 EDT

Wall/Ceiling

□ 2024-04-16 13:56:34

□ [26.23011779785156, -](#)  
[80.0909163218984](#)

□ Image \_\_\_\_\_




2024-04-16 13:56:35 EDT

Wall/Ceiling

□ 2024-04-16 13:56:35

□ [26.23011779785156, -](#)  
[80.0909163218984](#)

□ Image \_\_\_\_\_




2024-04-16 13:56:36 EDT

Wall/Ceiling

□ 2024-04-16 13:56:36


□ [26.23011779785156, -](#)  
[80.0909163218984](#)

□ Image \_\_\_\_\_




Wall/Ceiling

- 2024-04-16 13:56:36
- [26.23011779785156,](#)
- [- 80.0909163218984](#)
- Image [\\_\\_\\_\\_\\_](#)




Wall/Ceiling

- 2024-04-16 13:56:37
- [26.23011779785156,](#)
- [- 80.0909163218984](#)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 13:56:38
- [26.23011779785156,](#)
- [- 80.0909163218984](#)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 13:56:39
- [26.23011779785156,](#)
- [- 80.0909163218984](#)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 13:56:40
- [26.23011779785156,](#)
- [- 80.0909163218984](#)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling


- 2024-04-16 13:56:45
- [26.23011779785156,](#)
- [- 80.0909163218984](#)
- Image [\\_\\_\\_\\_\\_](#)





Wall/Ceiling

- 2024-04-16 13:56:46
- [26.23011779785156,](https://www.26.23011779785156.com)
- [- 80.0909163218984](https://www.80.0909163218984.com)
- Image [\\_\\_\\_\\_\\_](#)




Wall/Ceiling

- 2024-04-16 13:56:46
- [26.23011779785156,](https://www.26.23011779785156.com)
- [- 80.0909163218984](https://www.80.0909163218984.com)
- Image [\\_\\_\\_\\_\\_](#)




Wall/Ceiling

- 2024-04-16 13:56:47
- [26.23011779785156,](https://www.26.23011779785156.com)
- [- 80.0909163218984](https://www.80.0909163218984.com)
- Image [\\_\\_\\_\\_\\_](#)




Wall/Ceiling

- 2024-04-16 13:56:48
- [26.23011779785156,](https://www.26.23011779785156.com)
- [- 80.0909163218984](https://www.80.0909163218984.com)
- Image [\\_\\_\\_\\_\\_](#)




Wall/Ceiling

- 2024-04-16 13:56:49
- [26.23011779785156,](https://www.26.23011779785156.com)
- [- 80.0909163218984](https://www.80.0909163218984.com)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 13:56:50
- [26.23011779785156,](https://www.26.23011779785156.com)
- [- 80.0909163218984](https://www.80.0909163218984.com)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 13:56:51
- [26.23011779785156,](#)
- [- 80.0909163218984](#)
- Image [\\_\\_\\_\\_\\_](#)



Window Covering

- 2024-04-16 13:55:52
- [26.23037539712876,](#)
- [- 80.09086110597478](#)
- Image [\\_\\_\\_\\_\\_](#)



Window Covering

- 2024-04-16 13:56:06
- [26.23037539712876,](#)
- [- 80.09086110597478](#)
- Image [\\_\\_\\_\\_\\_](#)



Window Covering

- 2024-04-16 13:56:08
- [26.23011779785156,](#)
- [- 80.0909163218984](#)
- Image [\\_\\_\\_\\_\\_](#)



Window Covering

- 2024-04-16 13:56:16
- [26.23011779785156,](#)
- [- 80.0909163218984](#)
- Image [\\_\\_\\_\\_\\_](#)




Window Covering

- 2024-04-16 13:56:17
- [26.23011779785156,](#)
- [- 80.0909163218984](#)
- Image [\\_\\_\\_\\_\\_](#)



**Window Covering**

- 2024-04-16 13:56:18
- [26.23011779785156,](#)
- [- 80.0909163218984](#)
- Image [\\_\\_\\_\\_\\_](#)




**Window Covering**

- 2024-04-16 13:56:19
- [26.23011779785156,](#)
- [- 80.0909163218984](#)
- Image [\\_\\_\\_\\_\\_](#)



**Window/Lock/Screen**

- 2024-04-16 13:57:08
- [26.23011779785156,](#)
- [80.0909163218984](#)
- Image [\\_\\_\\_\\_\\_](#)



**Window/Lock/Screen**

- 2024-04-16 13:57:12
- [26.23011779785156,](#)
- [- 80.0909163218984](#)
- Image [\\_\\_\\_\\_\\_](#)

**Bathroom 1**



**Cabinet/Counter/Shelving**

- 2024-04-16 14:00:15
- [26.23020935058594,](#)
- [80.09080391566292](#)
- Image [\\_\\_\\_\\_\\_](#)



**Cabinet/Counter/Shelving**

- 2024-04-16 14:00:19
- [26.23051344094844,](#)
- [80.09097950580443](#)
- Image [\\_\\_\\_\\_\\_](#)



Cabinet/Counter/Shelving

□ 2024-04-16 14:00:23

□ [26.23051344094844, - 80.09097950580443](#)

□ [Image](#)



Cabinet/Counter/Shelving

□ 2024-04-16 14:00:26

□ [26.23051344094844, - 80.09097950580443](#)

□ [Image](#)




Cabinet/Counter/Shelving

□ 2024-04-16 14:00:27

□ [26.23051344094844, - 80.09097950580443](#)

□ [Image](#)



Cabinet/Counter/Shelving

□ 2024-04-16 14:00:28

□ [26.23051344094844, - 80.09097950580443](#)

□ [Image](#)




Cabinet/Counter/Shelving

□ 2024-04-16 14:00:36

□ [26.23051344094844, - 80.09097950580443](#)

□ [Image](#)



Door/Knob/Lock

□ 2024-04-16 14:00:46

□ [26.23051344094844, - 80.09097950580443](#)


□ [Image](#)





**Door/Knob/Lock**

- 2024-04-16 14:00:49
- [26.23051344094844,](https://www.26.23051344094844.com)
- [- 80.09097950580443](https://www.80.09097950580443.com)
- Image [\\_\\_\\_\\_\\_](#)




**Flooring/Baseboard**

- 2024-04-16 14:01:10
- [26.23051344094844,](https://www.26.23051344094844.com)
- [- 80.09097950580443](https://www.80.09097950580443.com)
- Image [\\_\\_\\_\\_\\_](#)




**Flooring/Baseboard**

- 2024-04-16 14:01:11
- [26.23051344094844,](https://www.26.23051344094844.com)
- [- 80.09097950580443](https://www.80.09097950580443.com)
- Image [\\_\\_\\_\\_\\_](#)



**Flooring/Baseboard**

- 2024-04-16 14:01:12
- [26.23051344094844,](https://www.26.23051344094844.com)
- [- 80.09097950580443](https://www.80.09097950580443.com)
- Image [\\_\\_\\_\\_\\_](#)



**Flooring/Baseboard**

- 2024-04-16 14:01:13
- [26.23051344094844,](https://www.26.23051344094844.com)
- [- 80.09097950580443](https://www.80.09097950580443.com)
- Image [\\_\\_\\_\\_\\_](#)




**Flooring/Baseboard**

- 2024-04-16 14:01:14
- [26.23051344094844,](https://www.26.23051344094844.com)
- [- 80.09097950580443](https://www.80.09097950580443.com)
- Image [\\_\\_\\_\\_\\_](#)



Flooring/Baseboard

- 2024-04-16 14:01:16
- [26.23051344094844,](#)
- [- 80.09097950580443](#)
- Image [\\_\\_\\_\\_\\_](#)




Flooring/Baseboard

- 2024-04-16 14:01:17
- [26.23051344094844,](#)
- [- 80.09097950580443](#)
- Image [\\_\\_\\_\\_\\_](#)




Flooring/Baseboard

- 2024-04-16 14:01:18
- [26.23051344094844,](#)
- [- 80.09097950580443](#)
- Image [\\_\\_\\_\\_\\_](#)



Flooring/Baseboard

- 2024-04-16 14:01:19
- [26.23051344094844,](#)
- [- 80.09097950580443](#)
- Image [\\_\\_\\_\\_\\_](#)



Flooring/Baseboard

- 2024-04-16 14:01:20
- [26.23051344094844,](#)
- [- 80.09097950580443](#)
- Image [\\_\\_\\_\\_\\_](#)




Light Fixture

- 2024-04-16 14:34:35
- [26.23039245605469,](#)
- [- 80.09109798160819](#)
- Image [\\_\\_\\_\\_\\_](#)



**Light Fixture**

- 2024-04-16 14:34:41
- [26.23039245605469,](#)
- [- 80.09109798160819](#)
- Image [\\_\\_\\_\\_\\_](#)



**Medicine Cabinet/Mirror**

- 2024-04-16 14:02:01
- [26.23051344094844,](#)
- [- 80.09097950580443](#)
- Image [\\_\\_\\_\\_\\_](#)



**Medicine Cabinet/Mirror**

- 2024-04-16 14:02:11
- [26.23020935058594,](#)
- [- 80.09091498487997](#)
- Image [\\_\\_\\_\\_\\_](#)



**2024-04-16 14:34:15**

- 2024-04-16 14:34:15
- [26.23039245605469,](#)
- [- 80.09109798160819](#)
- Image [\\_\\_\\_\\_\\_](#)



**Plumbing/Drain**

- 2024-04-16 14:02:30
- [26.23039361272644,](#)
- [- 80.09094001131686](#)
- Image [\\_\\_\\_\\_\\_](#)



**Plumbing/Drain**

- 2024-04-16 14:02:33
- [26.23039361272644,](#)
- [- 80.09094001131686](#)
- Image [\\_\\_\\_\\_\\_](#)



Plumbing/Drain

- 2024-04-16 14:02:43
- [26.23039361272644](tel:26.23039361272644),
- [- 80.09094001131686](tel:80.09094001131686)
- [Image](#)



Plumbing/Drain

- 2024-04-16 14:02:50
- [26.23039361272644](tel:26.23039361272644),
- [- 80.09094001131686](tel:80.09094001131686)
- [Image](#)



Shower Door/Rail/Curtain

- 2024-04-16 14:03:34
- [26.23039361272644](tel:26.23039361272644),
- [- 80.09094001131686](tel:80.09094001131686)
- [Image](#)



Shower Door/Rail/Curtain

- 2024-04-16 14:03:35
- [26.23039361272644](tel:26.23039361272644),
- [- 80.09094001131686](tel:80.09094001131686)
- [Image](#)



Shower Door/Rail/Curtain

- 2024-04-16 14:03:39
- [26.23039361272644](tel:26.23039361272644),
- [- 80.09094001131686](tel:80.09094001131686)
- [Image](#)



Shower Door/Rail/Curtain

- 2024-04-16 14:03:41
- [26.23039361272644](tel:26.23039361272644),
- [- 80.09094001131686](tel:80.09094001131686)
- [Image](#)





Shower Door/Rail/Curtain

□ 2024-04-16 14:03:43

□ [26.23039361272644](https://www.26.23039361272644.com), -  
[80.09094001131686](https://www.80.09094001131686.com)

□ [Image](#)



Shower Door/Rail/Curtain

□ 2024-04-16 14:03:44

□ [26.23039361272644](https://www.26.23039361272644.com), -  
[80.09094001131686](https://www.80.09094001131686.com)

□ [Image](#)



Shower Door/Rail/Curtain

□ 2024-04-16 14:03:46

□ [26.23039361272644](https://www.26.23039361272644.com), -  
[80.09094001131686](https://www.80.09094001131686.com)

□ [Image](#)



Shower Door/Rail/Curtain

□ 2024-04-16 14:03:48

□ [26.23039361272644](https://www.26.23039361272644.com), -  
[80.09094001131686](https://www.80.09094001131686.com)

□ [Image](#)



Shower Door/Rail/Curtain

□ 2024-04-16 14:35:03

□ [26.23039245605469](https://www.26.23039245605469.com), -  
[80.09109798160819](https://www.80.09109798160819.com)

□ [Image](#)



Sink/Faucet

□ 2024-04-16 14:04:02

□ [26.23039361272644](https://www.26.23039361272644.com),  
□ [80.09094001131686](https://www.80.09094001131686.com)

□ [Image](#)



**Sink/Faucet**

- 2024-04-16 14:04:04
- [26.23039361272644,](#)
- [- 80.09094001131686](#)
- Image [\\_\\_\\_\\_\\_](#)



**Sink/Faucet**

- 2024-04-16 14:04:05
- [26.23039361272644,](#)
- [- 80.09094001131686](#)
- Image [\\_\\_\\_\\_\\_](#)



**Switch/Outlet**

- 2024-04-16 14:04:19
- [26.23046875, -80.09099528127425](#)
- Image [\\_\\_\\_\\_\\_](#)




**Toilet**

- 2024-04-16 14:35:27
- [26.23039245605469,](#)
- [- 80.09109798160819](#)
- Image [\\_\\_\\_\\_\\_](#)



**Toilet**

- 2024-04-16 14:35:32
- [26.23039245605469,](#)
- [- 80.09109798160819](#)
- Image [\\_\\_\\_\\_\\_](#)



**Toilet**

- 2024-04-16 14:35:33
- [26.23039245605469,](#)
- [- 80.09109798160819](#)
- Image [\\_\\_\\_\\_\\_](#)




**Toilet Paper Holder**

▫ 2024-04-16 14:05:18

▫ [26.23046875, -80.09099528127425](#)

▫ [Image](#)



**Towel Rack**

▫ 2024-04-16 14:05:29

▫ [26.23046875, -80.09099528127425](#)

▫ [Image](#)



**Towel Rack**

▫ 2024-04-16 14:05:50

▫ [26.23046875, -80.09099528127425](#)

▫ [Image](#)



**Towel Rack**

▫ 2024-04-16 14:05:52

▫ [26.23046875, -80.09099528127425](#)

▫ [Image](#)




**Towel Rack**

▫ 2024-04-16 14:05:53

▫ [26.23046875, -80.09099528127425](#)

▫ [Image](#)



**Towel Rack**

▫ 2024-04-16 14:05:53

▫ [26.23046875, -80.09099528127425](#)

▫ [Image](#)



**Tub/Shower**

- 2024-04-16 14:35:49
- [26.23039245605469, -80.09109798160819](#)
- Image [\\_\\_\\_\\_\\_](#)



**Wall/Ceiling**

- 2024-04-16 14:06:25
- [26.2304230654447, -80.09095395720217](#)
- Image [\\_\\_\\_\\_\\_](#)



**Wall/Ceiling**

- 2024-04-16 14:06:28
- [26.2304230654447, -80.09095395720217](#)
- Image [\\_\\_\\_\\_\\_](#)



**Wall/Ceiling**

- 2024-04-16 14:06:33
- [26.2304230654447, -80.09095395720217](#)
- Image [\\_\\_\\_\\_\\_](#)



**Wall/Ceiling**


- 2024-04-16 14:06:34
- [26.2304230654447, -80.09095395720217](#)
- Image [\\_\\_\\_\\_\\_](#)



**Wall/Ceiling**

- 2024-04-16 14:06:36
- [26.2304230654447, -80.09095395720217](#)
- Image [\\_\\_\\_\\_\\_](#)






Wall/Ceiling  
 2024-04-16 14:06:39  
 26.2304230654447, -  
 80.09095395720217  
 Image \_\_\_\_\_

**Bathroom 2**




Cabinet/Counter/Shelving  
 2024-04-16 14:08:18  
 26.23048705195413, -  
 80.09081215488257  
 Image \_\_\_\_\_



Cabinet/Counter/Shelving  
 2024-04-16 14:08:19  
 26.23048705195413, -  
 80.09081215488257  
 Image \_\_\_\_\_



Cabinet/Counter/Shelving  
 2024-04-16 14:08:20  
 26.23048705195413, -  
 80.09081215488257  
 Image \_\_\_\_\_



Cabinet/Counter/Shelving  
 2024-04-16 14:08:25  
 26.23048705195413, -  
 80.09081215488257  
 Image \_\_\_\_\_






Door/Knob/Lock

- 2024-04-16 14:12:32
- [26.23060607910156,](https://www.26.23060607910156.com)
- [- 80.09087684889228](https://www.80.09087684889228.com)
- Image [\\_\\_\\_\\_\\_](#)




Door/Knob/Lock

- 2024-04-16 14:12:37
- [26.23060607910156,](https://www.26.23060607910156.com)
- [- 80.09087684889228](https://www.80.09087684889228.com)
- Image [\\_\\_\\_\\_\\_](#)




Flooring/Baseboard

- 2024-04-16 14:13:59
- [26.23060607910156,](https://www.26.23060607910156.com)
- [- 80.09087684889228](https://www.80.09087684889228.com)
- Image [\\_\\_\\_\\_\\_](#)




Flooring/Baseboard

- 2024-04-16 14:14:03
- [26.23060607910156,](https://www.26.23060607910156.com)
- [- 80.09087684889228](https://www.80.09087684889228.com)
- Image [\\_\\_\\_\\_\\_](#)



Flooring/Baseboard

- 2024-04-16 14:14:04
- [26.23060607910156,](https://www.26.23060607910156.com)
- [- 80.09087684889228](https://www.80.09087684889228.com)
- Image [\\_\\_\\_\\_\\_](#)




Flooring/Baseboard

- 2024-04-16 14:14:05
- [26.23060607910156,](https://www.26.23060607910156.com)
- [- 80.09087684889228](https://www.80.09087684889228.com)
- Image [\\_\\_\\_\\_\\_](#)



**Flooring/Baseboard**

- 2024-04-16 14:14:07
- [26.23043823242188,](https://www.26.23043823242188.com)
- [- 80.09087422639578](https://www.80.09087422639578.com)
- Image [\\_\\_\\_\\_\\_](#)



**Flooring/Baseboard**

- 2024-04-16 14:14:11
- [26.23043823242188,](https://www.26.23043823242188.com)
- [- 80.09087422639578](https://www.80.09087422639578.com)
- Image [\\_\\_\\_\\_\\_](#)



**Plumbing/Drain**

- 2024-04-16 14:09:07
- [26.23048705195413,](https://www.26.23048705195413.com)
- [- 80.09081215488257](https://www.80.09081215488257.com)
- Image [\\_\\_\\_\\_\\_](#)



**Plumbing/Drain**

- 2024-04-16 14:09:08
- [26.23048705195413,](https://www.26.23048705195413.com)
- [- 80.09081215488257](https://www.80.09081215488257.com)
- Image [\\_\\_\\_\\_\\_](#)



**Plumbing/Drain**

- 2024-04-16 14:09:09
- [26.23048705195413,](https://www.26.23048705195413.com)
- [- 80.09081215488257](https://www.80.09081215488257.com)
- Image [\\_\\_\\_\\_\\_](#)



**Shower Door/Rail/Curtain**

- 2024-04-16 14:09:25
- [26.23048705195413,](https://www.26.23048705195413.com) -
- [80.09081215488257](https://www.80.09081215488257.com)
- Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:09:29 EDT

**Shower Door/Rail/Curtain**

▫ 2024-04-16 14:09:29

▫ [26.23048705195413](https://www.26.23048705195413.com), - [80.09081215488257](https://www.80.09081215488257.com)

▫ [Image](#)



2024-04-16 14:09:33 EDT

**Shower Door/Rail/Curtain**

▫ 2024-04-16 14:09:33

▫ [26.23048705195413](https://www.26.23048705195413.com), - [80.09081215488257](https://www.80.09081215488257.com)

▫ [Image](#)



2024-04-16 14:09:51 EDT

**Shower Door/Rail/Curtain**

▫ 2024-04-16 14:09:51

▫ [26.23048705195413](https://www.26.23048705195413.com), - [80.09081215488257](https://www.80.09081215488257.com)

▫ [Image](#)



2024-04-16 14:09:56 EDT

**Shower Door/Rail/Curtain**

▫ 2024-04-16 14:09:56

▫ [26.23048705195413](https://www.26.23048705195413.com), - [80.09081215488257](https://www.80.09081215488257.com)

▫ [Image](#)



2024-04-16 14:10:46 EDT

**Sink/Faucet**

▫ 2024-04-16 14:10:46

▫ [26.23020935058594](https://www.26.23020935058594.com), - [80.09087376212669](https://www.80.09087376212669.com)

▫ [Image](#)



2024-04-16 14:11:03 EDT

**Switch/Outlet**

▫ 2024-04-16 14:11:03

▫ [26.23020935058594](https://www.26.23020935058594.com), - [80.09087376212669](https://www.80.09087376212669.com)

▫ [Image](#)



**Toilet**

- 2024-04-16 14:10:15
- [26.23020935058594,](#)
- [- 80.09087376212669](#)
- Image [\\_\\_\\_\\_\\_](#)



**Toilet**

- 2024-04-16 14:10:24
- [26.23020935058594,](#)
- [- 80.09087376212669](#)
- Image [\\_\\_\\_\\_\\_](#)



**Toilet**

- 2024-04-16 14:10:32
- [26.23020935058594,](#)
- [- 80.09087376212669](#)
- Image [\\_\\_\\_\\_\\_](#)



**Toilet Paper Holder**

- 2024-04-16 14:11:16
- [26.23020935058594,](#)
- [- 80.09087376212669](#)
- Image [\\_\\_\\_\\_\\_](#)



**Toilet Paper Holder**

- 2024-04-16 14:11:26
- [26.23020935058594,](#)
- [- 80.09087376212669](#)
- Image [\\_\\_\\_\\_\\_](#)



**Towel Rack**


- 2024-04-16 14:11:35
- [26.23020935058594,](#)
- [- 80.09087376212669](#)
- Image [\\_\\_\\_\\_\\_](#)





Wall/Ceiling

- 2024-04-16 14:11:54
- [26.23020935058594,](#)
- [- 80.09087376212669](#)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 14:11:57
- [26.23020935058594,](#)
- [- 80.09087376212669](#)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 14:12:02
- [26.23020935058594,](#)
- [- 80.09087376212669](#)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 14:12:06
- [26.23020935058594,](#)
- [- 80.09087376212669](#)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 14:13:03
- [26.23060607910156,](#)
- [- 80.09087684889228](#)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 14:13:05
- [26.23060607910156,](#)
- [- 80.09087684889228](#)
- Image [\\_\\_\\_\\_\\_](#)





Wall/Ceiling

- 2024-04-16 14:13:07
- [26.23060607910156,](#)
- [- 80.09087684889228](#)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 14:13:09
- [26.23060607910156,](#)
- [- 80.09087684889228](#)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 14:13:13
- [26.23060607910156,](#)
- [- 80.09087684889228](#)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 14:13:14
- [26.23060607910156,](#)
- [- 80.09087684889228](#)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 14:13:17
- [26.23060607910156,](#)
- [- 80.09087684889228](#)
- Image [\\_\\_\\_\\_\\_](#)



Flooring/Baseboard

- 2024-04-16 14:32:13
- [26.23039245605469,](https://www.26.23039245605469.com)
- [- 80.09109768718024](https://www.80.09109768718024.com)
- Image [\\_\\_\\_\\_\\_](#)



Flooring/Baseboard

- 2024-04-16 14:32:14
- [26.23039245605469,](https://www.26.23039245605469.com)
- [- 80.09109768718024](https://www.80.09109768718024.com)
- Image [\\_\\_\\_\\_\\_](#)



Flooring/Baseboard

- 2024-04-16 14:32:15
- [26.23039245605469,](https://www.26.23039245605469.com)
- [- 80.09109768718024](https://www.80.09109768718024.com)
- Image [\\_\\_\\_\\_\\_](#)



Flooring/Baseboard

- 2024-04-16 14:32:16
- [26.23039245605469,](https://www.26.23039245605469.com)
- [- 80.09109768718024](https://www.80.09109768718024.com)
- Image [\\_\\_\\_\\_\\_](#)



Flooring/Baseboard

- 2024-04-16 14:32:17
- [26.23039245605469,](https://www.26.23039245605469.com)
- [- 80.09109768718024](https://www.80.09109768718024.com)
- Image [\\_\\_\\_\\_\\_](#)




Flooring/Baseboard

- 2024-04-16 14:32:19
- [26.23040216822894,](https://www.26.23040216822894.com)
- [- 80.09109799483339](https://www.80.09109799483339.com)
- Image [\\_\\_\\_\\_\\_](#)



Flooring/Baseboard

- 2024-04-16 14:32:21
- [26.23040216822894,](https://www.26.23040216822894.com)
- [- 80.09109799483339](https://www.80.09109799483339.com)
- Image [\\_\\_\\_\\_\\_](#)



Flooring/Baseboard

- 2024-04-16 14:32:22
- [26.23040216822894,](https://www.26.23040216822894.com)
- [- 80.09109799483339](https://www.80.09109799483339.com)
- Image [\\_\\_\\_\\_\\_](#)



Flooring/Baseboard

- 2024-04-16 14:32:25
- [26.23040216822894,](https://www.26.23040216822894.com)
- [- 80.09109799483339](https://www.80.09109799483339.com)
- Image [\\_\\_\\_\\_\\_](#)



Flooring/Baseboard

- 2024-04-16 14:32:27
- [26.23040216822894,](https://www.26.23040216822894.com)
- [- 80.09109799483339](https://www.80.09109799483339.com)
- Image [\\_\\_\\_\\_\\_](#)



Flooring/Baseboard

- 2024-04-16 14:32:27
- [26.23040216822894,](https://www.26.23040216822894.com)
- [- 80.09109799483339](https://www.80.09109799483339.com)
- Image [\\_\\_\\_\\_\\_](#)



Flooring/Baseboard

- 2024-04-16 14:32:29
- [26.23040216822894,](https://www.26.23040216822894.com)
- [- 80.09109799483339](https://www.80.09109799483339.com)
- Image [\\_\\_\\_\\_\\_](#)



**Flooring/Baseboard**

- 2024-04-16 14:32:30
- [26.23040216822894,](#)
- [- 80.09109799483339](#)
- Image [\\_\\_\\_\\_\\_](#)



**Flooring/Baseboard**

- 2024-04-16 14:32:31
- [26.23040216822894,](#)
- [- 80.09109799483339](#)
- Image [\\_\\_\\_\\_\\_](#)



**Light Fixture/Fan**

- 2024-04-16 14:32:38
- [26.23040216822894,](#)
- [- 80.09109799483339](#)
- Image [\\_\\_\\_\\_\\_](#)



**Light Fixture/Fan**


- 2024-04-16 14:32:39
- [26.23040216822894,](#)
- [- 80.09109799483339](#)
- Image [\\_\\_\\_\\_\\_](#)

**Kitchen**



**Cabinets/Drawers**

- 2024-04-16 14:15:11
- [26.23043823242188,](#)
- [- 80.09087422639578](#)
- Image [\\_\\_\\_\\_\\_](#)



**Cabinets/Drawers**

- 2024-04-16 14:15:12
- [26.23043823242188,](#)
- [- 80.09087422639578](#)
- Image [\\_\\_\\_\\_\\_](#)





**Cabinets/Drawers**

- 2024-04-16 14:15:18
- [26.23043823242188,](https://www.26.23043823242188.com)
- [- 80.09087422639578](https://www.80.09087422639578.com)
- Image [\\_\\_\\_\\_\\_](#)



**Cabinets/Drawers**

- 2024-04-16 14:15:21
- [26.23043823242188,](https://www.26.23043823242188.com)
- [- 80.09087422639578](https://www.80.09087422639578.com)
- Image [\\_\\_\\_\\_\\_](#)



**Cabinets/Drawers**

- 2024-04-16 14:15:25
- [26.23043823242188,](https://www.26.23043823242188.com)
- [- 80.09087422639578](https://www.80.09087422639578.com)
- Image [\\_\\_\\_\\_\\_](#)



**Cabinets/Drawers**

- 2024-04-16 14:15:34
- [26.23043823242188,](https://www.26.23043823242188.com)
- [- 80.09087422639578](https://www.80.09087422639578.com)
- Image [\\_\\_\\_\\_\\_](#)



**Cabinets/Drawers**

- 2024-04-16 14:15:43
- [26.23043823242188,](https://www.26.23043823242188.com)
- [- 80.09087422639578](https://www.80.09087422639578.com)
- Image [\\_\\_\\_\\_\\_](#)



**Cabinets/Drawers**

- 2024-04-16 14:15:44
- [26.23043823242188,](https://www.26.23043823242188.com)
- [- 80.09087422639578](https://www.80.09087422639578.com)
- Image [\\_\\_\\_\\_\\_](#)





**Cabinets/Drawers**

- 2024-04-16 14:15:47
- [26.23043823242188,](#)
- [- 80.09087422639578](#)
- Image [\\_\\_\\_\\_\\_](#)



**Cabinets/Drawers**

- 2024-04-16 14:15:48
- [26.23043823242188,](#)
- [- 80.09087422639578](#)
- Image [\\_\\_\\_\\_\\_](#)



**Cabinets/Drawers**

- 2024-04-16 14:16:29
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)



**Cabinets/Drawers**

- 2024-04-16 14:16:31
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)



**Cabinets/Drawers**

- 2024-04-16 14:16:35
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)




**Cabinets/Drawers**

- 2024-04-16 14:16:45
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)



Cabinets/Drawers

- 2024-04-16 14:16:50
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)



Cabinets/Drawers

- 2024-04-16 14:16:52
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)



Cabinets/Drawers

- 2024-04-16 14:16:53
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)



Cabinets/Drawers

- 2024-04-16 14:16:57
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)



Cabinets/Drawers

- 2024-04-16 14:16:58
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)




Cabinets/Drawers

- 2024-04-16 14:17:01
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)



**Cabinets/Drawers**

- 2024-04-16 14:17:05
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)



**Counter**

- 2024-04-16 14:17:14
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)



**Counter**

- 2024-04-16 14:17:16
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)




**Counter**

- 2024-04-16 14:17:18
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)



**Counter**

- 2024-04-16 14:17:20
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)



**Counter**

- 2024-04-16 14:17:21
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)



Counter

- 2024-04-16 14:17:22
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)




Counter

- 2024-04-16 14:17:23
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)




Counter

- 2024-04-16 14:17:24
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)



Counter

- 2024-04-16 14:17:28
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)



Counter

- 2024-04-16 14:17:30
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)



Counter

- 2024-04-16 14:17:31
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)





Counter

- 2024-04-16 14:17:32
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)



Counter

- 2024-04-16 14:17:33
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)



Counter

- 2024-04-16 14:17:37
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)



Counter

- 2024-04-16 14:17:38
- [26.23040773072364,](#)
- [- 80.0913032670204](#)
- Image [\\_\\_\\_\\_\\_](#)



Dishwasher

- 2024-04-16 14:18:18
- [26.23038603149433,](#)
- [- 80.09104654163781](#)
- Image [\\_\\_\\_\\_\\_](#)



Dishwasher

- 2024-04-16 14:18:20
- [26.23038603149433,](#)
- [- 80.09104654163781](#)
- Image [\\_\\_\\_\\_\\_](#)





2024-04-16 14:18:22 EDT

**Dishwasher**

- 2024-04-16 14:18:22
- [26.23038603149433,](https://www.26.23038603149433.com)
- [- 80.09104654163781](https://www.80.09104654163781.com)
- Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:18:23 EDT

**Dishwasher**

- 2024-04-16 14:18:23
- [26.23038603149433,](https://www.26.23038603149433.com)
- [- 80.09104654163781](https://www.80.09104654163781.com)
- Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:18:30 EDT

**Dishwasher**


- 2024-04-16 14:18:30
- [26.23038603149433,](https://www.26.23038603149433.com)
- [- 80.09104654163781](https://www.80.09104654163781.com)
- Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:18:31 EDT

**Dishwasher**


- 2024-04-16 14:18:31
- [26.23038603149433,](https://www.26.23038603149433.com)
- [- 80.09104654163781](https://www.80.09104654163781.com)
- Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:18:32 EDT

**Dishwasher**

- 2024-04-16 14:18:32
- [26.23038603149433,](https://www.26.23038603149433.com)
- [- 80.09104654163781](https://www.80.09104654163781.com)
- Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:18:36 EDT

**Dishwasher**

- 2024-04-16 14:18:36
- [26.23038603149433,](https://www.26.23038603149433.com)
- [- 80.09104654163781](https://www.80.09104654163781.com)
- Image [\\_\\_\\_\\_\\_](#)



Dishwasher

- 2024-04-16 14:18:37
- [26.23038603149433,](https://www.26.23038603149433.com)
- [- 80.09104654163781](https://www.80.09104654163781.com)
- Image [\\_\\_\\_\\_\\_](#)



Dishwasher

- 2024-04-16 14:18:39
- [26.23038603149433,](https://www.26.23038603149433.com)
- [- 80.09104654163781](https://www.80.09104654163781.com)
- Image [\\_\\_\\_\\_\\_](#)



Dishwasher

- 2024-04-16 14:18:46
- [26.23038603149433,](https://www.26.23038603149433.com)
- [- 80.09104654163781](https://www.80.09104654163781.com)
- Image [\\_\\_\\_\\_\\_](#)



Faucet/Plumbing

- 2024-04-16 14:26:12
- [26.230224609375,](https://www.26.230224609375.com)
- [- 80.09087718455139](https://www.80.09087718455139.com)
- Image [\\_\\_\\_\\_\\_](#)



Faucet/Plumbing

- 2024-04-16 14:26:14
- [26.230224609375,](https://www.26.230224609375.com)
- [- 80.09087718455139](https://www.80.09087718455139.com)
- Image [\\_\\_\\_\\_\\_](#)



Faucet/Plumbing

- 2024-04-16 14:26:19
- [26.230224609375,](https://www.26.230224609375.com)
- [- 80.09087718455139](https://www.80.09087718455139.com)
- Image [\\_\\_\\_\\_\\_](#)



2024-04-16-14:26:20 EDT


**Faucet/Plumbing**

2024-04-16 14:26:20

[26.230224609375, -](#)

[80.09087718455139](#)

Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:19:32 EDT

**Flooring/Baseboard**

2024-04-16 14:19:32

[26.23038603149433,](#)

[- 80.09104654163781](#)

Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:19:33 EDT


**Flooring/Baseboard**

2024-04-16 14:19:33

[26.23038603149433,](#)

[- 80.09104654163781](#)

Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:19:34 EDT

**Flooring/Baseboard**

2024-04-16 14:19:34

[26.23038603149433,](#)

[- 80.09104654163781](#)

Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:19:35 EDT

**Flooring/Baseboard**

2024-04-16 14:19:35

[26.23038603149433,](#)

[- 80.09104654163781](#)

Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:19:37 EDT

**Flooring/Baseboard**

2024-04-16 14:19:37

[26.23038603149433,](#)

[- 80.09104654163781](#)


Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:19:39 EDT

**Flooring/Baseboard**

- 2024-04-16 14:19:39
- [26.23038603149433,](#)
- [- 80.09104654163781](#)
- Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:19:43 EDT

**Flooring/Baseboard**

- 2024-04-16 14:19:43
- [26.23038603149433,](#)
- [- 80.09104654163781](#)
- Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:19:47 EDT

**Flooring/Baseboard**

- 2024-04-16 14:19:47
- [26.23038603149433,](#)
- [- 80.09104654163781](#)
- Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:20:09 EDT

**Light Fixture**

- 2024-04-16 14:20:09
- [26.23017340866638,](#)
- [- 80.09099052232895](#)
- Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:20:11 EDT

**Light Fixture**

- 2024-04-16 14:20:11
- [26.23017340866638,](#)
- [- 80.09099052232895](#)
- Image [\\_\\_\\_\\_\\_](#)




2024-04-16 14:20:12 EDT

**Light Fixture**

- 2024-04-16 14:20:12
- [26.23017340866638,](#)
- [- 80.09099052232895](#)
- Image [\\_\\_\\_\\_\\_](#)





Light Fixture

- 2024-04-16 14:20:14
- [26.23017340866638,](#)
- [- 80.09099052232895](#)
- Image [\\_\\_\\_\\_\\_](#)



Light Fixture

- 2024-04-16 14:20:15
- [26.23017340866638,](#)
- [- 80.09099052232895](#)
- Image [\\_\\_\\_\\_\\_](#)



Oven

- 2024-04-16 14:25:05
- [26.23023986816406,](#)
- [- 80.09088931686391](#)
- Image [\\_\\_\\_\\_\\_](#)



Oven

- 2024-04-16 14:25:06
- [26.23023986816406,](#)
- [- 80.09088931686391](#)
- Image [\\_\\_\\_\\_\\_](#)



Range/Fan/Hood/Filter

- 2024-04-16 14:20:51
- [26.23041915232003,](#)
- [80.09107935817246](#)
- Image [\\_\\_\\_\\_\\_](#)



Range/Fan/Hood/Filter

- 2024-04-16 14:20:53
- [26.23041915232003,](#)
- [80.09107935817246](#)
- Image [\\_\\_\\_\\_\\_](#)





2024-04-16 14:20:55 EDT

Range/Fan/Hood/Filter

□ 2024-04-16 14:20:55

□ [26.23041915232003, -](#)

[80.09107935817246](#)

□ Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:20:56 EDT

Range/Fan/Hood/Filter

□ 2024-04-16 14:20:56

□ [26.23041915232003, -](#)

[80.09107935817246](#)

□ Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:20:57 EDT

Range/Fan/Hood/Filter

□ 2024-04-16 14:20:57

□ [26.23041915232003, -](#)

[80.09107935817246](#)

□ Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:21:03 EDT

Range/Fan/Hood/Filter

□ 2024-04-16 14:21:03

□ [26.23041915232003, -](#)

[80.09107935817246](#)

□ Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:21:05 EDT

Range/Fan/Hood/Filter

□ 2024-04-16 14:21:05

□ [26.23041915232003, -](#)

[80.09107935817246](#)

□ Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:21:06 EDT

Range/Fan/Hood/Filter

□ 2024-04-16 14:21:06

□ [26.23041915232003, -](#)

[80.09107935817246](#)

□ Image [\\_\\_\\_\\_\\_](#)



Range/Fan/Hood/Filter  
 2024-04-16 14:21:08  
 [26.23041915232003, - 80.09107935817246](#)  
 Image [\\_\\_\\_\\_\\_](#)



Range/Fan/Hood/Filter  
 2024-04-16 14:21:09  
 [26.23041915232003, - 80.09107935817246](#)  
 Image [\\_\\_\\_\\_\\_](#)



Range/Fan/Hood/Filter  
 2024-04-16 14:21:51  
 [26.23041915232003, - 80.09107935817246](#)  
 Image [\\_\\_\\_\\_\\_](#)



Range/Fan/Hood/Filter  
 2024-04-16 14:21:54  
 [26.23041915232003, - 80.09107935817246](#)  
 Image [\\_\\_\\_\\_\\_](#)



Range/Fan/Hood/Filter  
 2024-04-16 14:21:55  
 [26.23041915232003, - 80.09107935817246](#)  
 Image [\\_\\_\\_\\_\\_](#)



Range/Fan/Hood/Filter  
 2024-04-16 14:22:08  
 [26.23019409179688, - 80.09096105265829](#)  
 Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:22:08 EDT

Range/Fan/Hood/Filter

2024-04-16 14:22:08

[26.23019409179688, -](#)

[80.09096105265829](#)

Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:22:09 EDT

Range/Fan/Hood/Filter

2024-04-16 14:22:09

[26.23019409179688, -](#)

[80.09096105265829](#)

Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:22:11 EDT

Range/Fan/Hood/Filter

2024-04-16 14:22:11

[26.23019409179688, -](#)

[80.09096105265829](#)

Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:22:13 EDT

Range/Fan/Hood/Filter

2024-04-16 14:22:13

[26.23019409179688, -](#)

[80.09096105265829](#)

Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:22:23 EDT

Range/Fan/Hood/Filter

2024-04-16 14:22:23

[26.23030689303729, -](#)

[80.09092535800582](#)

Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:22:25 EDT

Range/Fan/Hood/Filter

2024-04-16 14:22:25

[26.23030689303729, -](#)

[80.09092535800582](#)

Image [\\_\\_\\_\\_\\_](#)





2024-04-16 14:22:28 EDT

**Range/Fan/Hood/Filter**

2024-04-16 14:22:28

[26.23030689303729, -](#)

[80.09092535800582](#)

Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:22:35 EDT

**Range/Fan/Hood/Filter**

2024-04-16 14:22:35

[26.23030689303729, -](#)

[80.09092535800582](#)

Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:27:00 EDT

**Refrigerator**

2024-04-16 14:27:00

[26.230224609375, -](#)

[80.09087718455139](#)

Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:23:50 EDT

**Switch/Outlet**

2024-04-16 14:23:50

[26.23030689303729,](#)

[- 80.09092535800582](#)

Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:23:52 EDT

**Switch/Outlet**

2024-04-16 14:23:52

[26.23030689303729,](#)

[- 80.09092535800582](#)

Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:23:54 EDT

**Switch/Outlet**

2024-04-16 14:23:54

[26.23030689303729,](#)


[- 80.09092535800582](#)

Image [\\_\\_\\_\\_\\_](#)




**Switch/Outlet**

- 2024-04-16 14:23:55
- [26.23030689303729,](#)
- [- 80.09092535800582](#)
- Image [\\_\\_\\_\\_\\_](#)




**Wall/Ceiling**

- 2024-04-16 14:24:05
- [26.23030689303729,](#)
- [- 80.09092535800582](#)
- Image [\\_\\_\\_\\_\\_](#)



**Wall/Ceiling**

- 2024-04-16 14:24:06
- [26.23030689303729,](#)
- [- 80.09092535800582](#)
- Image [\\_\\_\\_\\_\\_](#)



**Wall/Ceiling**

- 2024-04-16 14:24:07
- [26.23030689303729,](#)
- [- 80.09092535800582](#)
- Image [\\_\\_\\_\\_\\_](#)



**Wall/Ceiling**

- 2024-04-16 14:24:08
- [26.23023986816406,](#)
- [- 80.09088931686391](#)
- Image [\\_\\_\\_\\_\\_](#)



**Wall/Ceiling**


- 2024-04-16 14:24:09
- [26.23023986816406,](#)
- [- 80.09088931686391](#)
- Image [\\_\\_\\_\\_\\_](#)





Wall/Ceiling

- 2024-04-16 14:24:10
- [26.23023986816406,](https://www.26.23023986816406.com)
- [- 80.09088931686391](https://www.80.09088931686391.com)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 14:24:11
- [26.23023986816406,](https://www.26.23023986816406.com)
- [- 80.09088931686391](https://www.80.09088931686391.com)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 14:24:12
- [26.23023986816406,](https://www.26.23023986816406.com)
- [- 80.09088931686391](https://www.80.09088931686391.com)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 14:24:18
- [26.23023986816406,](https://www.26.23023986816406.com)
- [- 80.09088931686391](https://www.80.09088931686391.com)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 14:24:18
- [26.23023986816406,](https://www.26.23023986816406.com)
- [- 80.09088931686391](https://www.80.09088931686391.com)
- Image [\\_\\_\\_\\_\\_](#)



Window Covering

- 2024-04-16 14:24:29
- [26.23023986816406,](https://www.26.23023986816406.com)
- [- 80.09088931686391](https://www.80.09088931686391.com)
- Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:24:31 EDT

**Window Covering**

- 2024-04-16 14:24:31
- [26.23023986816406,](https://www.26.23023986816406.com)
- [- 80.09088931686391](https://www.80.09088931686391.com)
- Image \_\_\_\_\_



2024-04-16 14:24:38 EDT

**Window Covering**


- 2024-04-16 14:24:38
- [26.23023986816406,](https://www.26.23023986816406.com)
- [- 80.09088931686391](https://www.80.09088931686391.com)
- Image \_\_\_\_\_



2024-04-16 14:24:50 EDT

**Window/Lock/Screen**

- 2024-04-16 14:24:50
- [26.23023986816406,](https://www.26.23023986816406.com)
- [80.09088931686391](https://www.80.09088931686391.com)
- Image \_\_\_\_\_



2024-04-16 14:24:54 EDT

**Window/Lock/Screen**

- 2024-04-16 14:24:54
- [26.23023986816406,](https://www.26.23023986816406.com)
- [- 80.09088931686391](https://www.80.09088931686391.com)
- Image \_\_\_\_\_

**Living Room**


---



2024-04-16 14:27:37 EDT

**Flooring/Baseboard**


- 2024-04-16 14:27:37
- [26.230224609375,](https://www.26.230224609375.com)
- [- 80.09087718455139](https://www.80.09087718455139.com)
- Image \_\_\_\_\_




2024-04-16 14:27:39 EDT

**Flooring/Baseboard**

- 2024-04-16 14:27:39
- [26.230224609375,](https://www.26.230224609375.com)
- [- 80.09087718455139](https://www.80.09087718455139.com)
- Image \_\_\_\_\_




Flooring/Baseboard  
 2024-04-16 14:27:40  
 [26.230224609375, -](https://www.26.230224609375.com)  
[80.09087718455139](https://www.80.09087718455139.com)  
 Image [\\_\\_\\_\\_\\_](#)




Flooring/Baseboard  
 2024-04-16 14:27:41  
 [26.230224609375, -](https://www.26.230224609375.com)  
[80.09087718455139](https://www.80.09087718455139.com)  
 Image [\\_\\_\\_\\_\\_](#)



Flooring/Baseboard  
 2024-04-16 14:27:42  
 [26.230224609375, -](https://www.26.230224609375.com)  
[80.09087718455139](https://www.80.09087718455139.com)  
 Image [\\_\\_\\_\\_\\_](#)




Flooring/Baseboard  
 2024-04-16 14:27:42  
 [26.230224609375, -](https://www.26.230224609375.com)  
[80.09087718455139](https://www.80.09087718455139.com)  
 Image [\\_\\_\\_\\_\\_](#)



Flooring/Baseboard  
 2024-04-16 14:27:43  
 [26.230224609375, -](https://www.26.230224609375.com)  
[80.09087718455139](https://www.80.09087718455139.com)  
 Image [\\_\\_\\_\\_\\_](#)



Flooring/Baseboard  
 2024-04-16 14:27:43  
 [26.230224609375, -](https://www.26.230224609375.com)  
[80.09087718455139](https://www.80.09087718455139.com)  
 Image [\\_\\_\\_\\_\\_](#)




Flooring/Baseboard

2024-04-16 14:27:45

[26.230224609375, -](#)

[80.09087718455139](#)

Image [\\_\\_\\_\\_\\_](#)




Flooring/Baseboard

2024-04-16 14:27:46

[26.230224609375, -](#)

[80.09087718455139](#)

Image [\\_\\_\\_\\_\\_](#)



Flooring/Baseboard

2024-04-16 14:27:46

[26.230224609375, -](#)

[80.09087718455139](#)

Image [\\_\\_\\_\\_\\_](#)



Flooring/Baseboard

2024-04-16 14:27:48

[26.230224609375, -](#)

[80.09087718455139](#)

Image [\\_\\_\\_\\_\\_](#)




Flooring/Baseboard

2024-04-16 14:27:49

[26.230224609375, -](#)

[80.09087718455139](#)

Image [\\_\\_\\_\\_\\_](#)



Flooring/Baseboard


2024-04-16 14:27:49

[26.230224609375, -](#)


[80.09087718455139](#)

Image [\\_\\_\\_\\_\\_](#)







2024-04-16 14:27:50 EDT  
**Flooring/Baseboard**  
 2024-04-16 14:27:50  
 [26.230224609375, -80.09087718455139](#)  
 Image \_\_\_\_\_



2024-04-16 14:27:51 EDT  
**Flooring/Baseboard**  
 2024-04-16 14:27:51  
 [26.230224609375, -80.09087718455139](#)  
 Image \_\_\_\_\_



2024-04-16 14:27:52 EDT  
**Flooring/Baseboard**  
 2024-04-16 14:27:52  
 [26.230224609375, -80.09087718455139](#)  
 Image \_\_\_\_\_



2024-04-16 14:27:52 EDT  
**Flooring/Baseboard**  
 2024-04-16 14:27:52  
 [26.230224609375, -80.09087718455139](#)  
 Image \_\_\_\_\_



2024-04-16 14:27:53 EDT  
**Flooring/Baseboard**  
 2024-04-16 14:27:53  
 [26.230224609375, -80.09087718455139](#)  
 Image \_\_\_\_\_



2024-04-16 14:28:13 EDT  
**Switch/Outlet**  
 2024-04-16 14:28:13  
 [26.23019265140436, -80.09097166049912](#)  
 Image \_\_\_\_\_





Switch/Outlet

- 2024-04-16 14:28:17
- [26.23019265140436,](#)
- [- 80.09097166049912](#)
- Image [\\_\\_\\_\\_\\_](#)




Switch/Outlet

- 2024-04-16 14:28:23
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)



Switch/Outlet

- 2024-04-16 14:28:26
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)




Switch/Outlet

- 2024-04-16 14:28:28
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)




Wall/Ceiling

- 2024-04-16 14:28:37
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)




Wall/Ceiling

- 2024-04-16 14:28:42
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 14:28:44
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)




Wall/Ceiling

- 2024-04-16 14:28:45
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 14:28:48
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 14:28:50
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)




Wall/Ceiling

- 2024-04-16 14:28:52
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling


- 2024-04-16 14:28:57
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:28:58 EDT

Wall/Ceiling

- 2024-04-16 14:28:58
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:28:59 EDT

Wall/Ceiling


- 2024-04-16 14:28:59
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:28:59 EDT

Wall/Ceiling

- 2024-04-16 14:28:59
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:29:00 EDT

Wall/Ceiling


- 2024-04-16 14:29:00
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:29:01 EDT

Wall/Ceiling

- 2024-04-16 14:29:01
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:29:02 EDT


Wall/Ceiling

- 2024-04-16 14:29:02
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 14:29:08
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 14:29:11
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 14:29:12
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 14:29:13
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 14:29:14
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 14:29:19
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)





Wall/Ceiling

- 2024-04-16 14:29:32
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)



Wall/Ceiling

- 2024-04-16 14:29:32
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)



Window Covering

- 2024-04-16 14:29:40
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)




Window Covering

- 2024-04-16 14:29:41
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)



Window Covering

- 2024-04-16 14:29:42
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)



Window Covering

- 2024-04-16 14:29:43
- [26.23021141425568,](#)
- [- 80.09097647697534](#)
- Image [\\_\\_\\_\\_\\_](#)





2024-04-16 14:29:47 EDT

**Window Covering**

- 2024-04-16 14:29:47
- [26.23021141425568,](https://www.26.23021141425568.com)
- [- 80.09097647697534](https://www.80.09097647697534.com)
- Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:29:48 EDT

**Window Covering**

- 2024-04-16 14:29:48
- [26.23021141425568,](https://www.26.23021141425568.com)
- [- 80.09097647697534](https://www.80.09097647697534.com)
- Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:29:50 EDT

**Window Covering**

- 2024-04-16 14:29:50
- [26.23021141425568,](https://www.26.23021141425568.com)
- [- 80.09097647697534](https://www.80.09097647697534.com)
- Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:29:51 EDT

**Window Covering**

- 2024-04-16 14:29:51
- [26.23021141425568,](https://www.26.23021141425568.com)
- [- 80.09097647697534](https://www.80.09097647697534.com)
- Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:29:52 EDT

**Window Covering**

- 2024-04-16 14:29:52
- [26.23021141425568,](https://www.26.23021141425568.com)
- [- 80.09097647697534](https://www.80.09097647697534.com)
- Image [\\_\\_\\_\\_\\_](#)



2024-04-16 14:30:20 EDT

**Window/Lock/Screen**

- 2024-04-16 14:30:20
- [26.23040185545739,](https://www.26.23040185545739.com)
- [- 80.09109724823621](https://www.80.09109724823621.com)
- Image [\\_\\_\\_\\_\\_](#)



**Window/Lock/Screen**

- 2024-04-16 14:30:33
- [26.23040185545739,](#)
- [- 80.09109724823621](#)
- Image [\\_\\_\\_\\_\\_](#)

## Keys/Remotes/Devices

---



**Keys**

- 2024-04-16 14:31:26
- [26.23040185545739,](#)
- [- 80.09109724823621](#)
- Image [\\_\\_\\_\\_\\_](#)