

Move In

Property	Tenant(s)	Date	Agent / Inspector
5161 Collins Avenue #614	Rachel & Adam Gold	2024-04-18	Adrienne Klein

Move-In Conditions

S=Satisfactory

Entry	CONDITION	ACTION	COMMENTS
Door/Knob/Lock-	S - -	None	
Doorbell-	S - -	None	
Light Fixture/Fan-	S - -	None	
Other-	S - -	None	
Wall/Ceiling-	S - -	None	

Bathroom: Master	CONDITION	ACTION	COMMENTS
Cabinet/Counter/Shelving-	S - -	None	
Door/Knob/Lock-	S - -	None	
Exhaust Fan-	S - -	None	
Flooring/Baseboard-	S - -	None	
Light Fixture-	S - -	None	
Medicine Cabinet/Mirror-	S - -	None	
Plumbing/Drain-	S - -	None	
Shower Door/Rail/Curtain-	S - -	None	
Sink/Faucet-	S - -	None	
Switch/Outlet-	S - -	None	
Toilet-	S - -	None	
Toilet Paper Holder-	S - -	None	

□ Bathroom: Master	□ CONDITION	□ ACTION	□ COMMENTS
Towel Rack	- S - -	ACTION	
Tub/Shower	- S - -	None	
Wall/Ceiling- S - -None		None	There is caulking that is missing where the wall joints together with the tiles located below the light switch

□ Bathroom 2	□ CONDITION	□ ACTION	□ COMMENTS
Cabinet/Counter/Shelving- S - -None			
Door/Knob/Lock- S - -None			
Exhaust Fan- S - -None			
Flooring/Baseboard- S - -None			
Light Fixture- S - -None			
Medicine Cabinet/Mirror- S - -None			
Plumbing/Drain- S - -None			
Shower Door/Rail/Curtain- S - -None			
Sink/Faucet- S - -None			
Switch/Outlet- S - -None			
Toilet- S - -None			
Toilet Paper Holder- S - -None			
Towel Rack- S - -None			
Tub/Shower- S - -None			
Wall/Ceiling- S - -None			

□ Bedroom: Master	□ CONDITION	□ ACTION	□ COMMENTS
Closet/Door/Track/Shelving- S - -None			
Door/Knob/Lock- S - -None			
Flooring/Baseboard- S - -None			
Light Fixture/Fan- S - -None			
Switch/Outlet- S - -None			
Wall/Ceiling- S - -None			
Window/Lock/Screen- S - -None			Hurricane Impact windows

□ Bedroom 2	□ CONDITION	□ ACTION	□ COMMENTS
Closet/Door/Track/Shelving- S - -None			

□ Bedroom 2 □ CONDITION □ ACTION Door/Knob/Lock- S - -

□ COMMENTS

None			There is missing door knob blocker
Flooring/Baseboard- S - -None			
Switch/Outlet- S - -None			
Wall/Ceiling- S - -None			
Window/Lock/Screen- S - -None			Hurricane Impact windows

□ Balcony □ CONDITION □ ACTION

□ COMMENTS

Flooring- S - -None			Ceramic tile primer being stored on balcony
Other- S - -None Railing- S - -None			Balcony sliding hurricane Impact doors

□ Dining Room □ CONDITION □ ACTION

Flooring/Baseboard- S - -None			
-------------------------------	--	--	--

Light Fixture/Fan- S - -None

□ COMMENTS

Switch/Outlet- S - -None			
Wall/Ceiling- S - -None			
Window/Lock/Screen- S - -None			

□ Kitchen □ CONDITION □ ACTION

hurricane impact windows/sliding balcony doors

Cabinets/Drawers- S - -None			
-----------------------------	--	--	--

Counter- S - -None

□ COMMENTS

Dishwasher: 307KWXD1A706 LG- S - -None			
Faucet/Plumbing- S - -None			
Flooring/Baseboard- S - -None			new
Light Fixture- S - -None			
Microwave: LG- S - -None			
Range/Fan/Hood/Filter: LG- S - -None			ne
Refrigerator: LG- S - -None			w
Sink/Disposal- S - -None			w
Switch/Outlet- S - -None			ne
Wall/Ceiling- S - -None			w
MY RENTAL INSPECTIONS, LLC Page 3 of 87			ne

w

Living Room CONDITION ACTION COMMENTS

Flooring/Baseboard- S - -None			
Switch/Outlet- S - -None			
Wall/Ceiling- S - -None			
Window/Lock/Screen- S - -None	hurricane impact windows		

Keys/Remotes/Devices CONDITION ACTION COMMENTS

Remotes/Devices- S - -None			
----------------------------	--	--	--

Systems CONDITION ACTION COMMENTS

Breaker Box- S - -None			
Thermostat- S - -None			

Additional Comments

Final Comments

To dispute any findings of this inspection please notify us within 3 business days.

Agent / Inspector Signature



Tenant Signature




Entry



Door/Knob/Lock

- 2024-04-18 13:25:44
- [25.82939147949219, -80.12068778467145](#)
- [Image](#)




Door/Knob/Lock

- 2024-04-18 13:25:48
- [25.82939147949219, -80.12068778467145](#)
- [Image](#)



Door/Knob/Lock

- 2024-04-18 13:25:49
- [25.82939147949219, -80.12068778467145](#)
- [Image](#)



Doorbell

- 2024-04-18 13:25:58
- [25.82939147949219, -80.12068778467145](#)
- [Image](#)




Doorbell

- 2024-04-18 13:25:59
- [25.82939147949219, -80.12068778467145](#)
- [Image](#)



Light Fixture/Fan

- 2024-04-18 13:26:40
- [25.82939147949219, -80.12068778467145](#)
- [Image](#)




2024-04-18 14:18:13
 [25.8295396156509, -80.12093007655372](#)
 Image _____



2024-04-18 14:18:17
 [25.8295396156509, -80.12093007655372](#)
 Image _____



2024-04-18 14:18:18
 [25.8295396156509, -80.12093007655372](#)
 Image _____



2024-04-18 14:18:19
 [25.8295396156509, -80.12093007655372](#)
 Image _____




2024-04-18 14:18:20
 [25.8295396156509, -80.12093007655372](#)
 Image _____



2024-04-18 14:18:23
 [25.8295396156509, -80.12093007655372](#)
 Image _____




□ 2024-04-18 14:18:23
□ [25.8295396156509, -](#)
□ [80.12093007655372](#)
□ Image _____



□ 2024-04-18 14:18:53
□ [25.8295396156509, -](#)
□ [80.12093007655372](#)
□ Image _____



□ 2024-04-18 14:18:55
□ [25.8295396156509, -](#)
□ [80.12093007655372](#)
□ Image _____



□ 2024-04-18 14:18:59
□ [25.8295396156509, -](#)
□ [80.12093007655372](#)
□ Image _____




□ 2024-04-18 14:19:00
□ [25.8295396156509, -](#)
□ [80.12093007655372](#)
□ Image _____




□ 2024-04-18 14:19:00
□ [25.8295396156509, -](#)
□ [80.12093007655372](#)
□ Image _____




2024-04-18 14:19:01
25.8295396156509, -
80.12093007655372
Image _____



2024-04-18 14:19:09
25.8295396156509, -
80.12093007655372
Image _____



2024-04-18 14:19:10
25.8295396156509, -
80.12093007655372
Image _____



2024-04-18 14:19:10
25.8295396156509, -
80.12093007655372
Image _____



2024-04-18 14:19:11
25.8295396156509, -
80.12093007655372
Image _____

Bathroom 1: Master




Cabinet/Counter/Shelving
 □ 2024-04-18 13:27:30
 □ [25.82951194211311,](https://www.25.82951194211311.com) -
[80.12079559072873](https://www.80.12079559072873.com)
 □ [Image](#)



Cabinet/Counter/Shelving
 □ 2024-04-18 13:27:33
 □ [25.82951194211311,](https://www.25.82951194211311.com) -
[80.12079559072873](https://www.80.12079559072873.com)
 □ [Image](#)



Door/Knob/Lock
 □ 2024-04-18 13:27:48
 □ [25.82951194211311,](https://www.25.82951194211311.com)
[- 80.12079559072873](https://www.80.12079559072873.com)
 □ [Image](#)



Door/Knob/Lock
 □ 2024-04-18 13:27:52
 □ [25.82951194211311,](https://www.25.82951194211311.com)
[- 80.12079559072873](https://www.80.12079559072873.com)
 □ [Image](#)



Exhaust Fan
 □ 2024-04-18 13:28:04
 □ [25.82951194211311,](https://www.25.82951194211311.com)
[- 80.12079559072873](https://www.80.12079559072873.com)
 □ [Image](#)



Flooring/Baseboard
 □ 2024-04-18 13:28:15
 □ [25.82951194211311,](https://www.25.82951194211311.com)
[- 80.12079559072873](https://www.80.12079559072873.com)
 □ [Image](#)



2024-04-18 13:28:18 EDT

Flooring/Baseboard

- 2024-04-18 13:28:18
- [25.82951194211311,](tel:25.82951194211311)
- [- 80.12079559072873](tel:80.12079559072873)
- Image [_____](#)



2024-04-18 13:28:21 EDT

Flooring/Baseboard

- 2024-04-18 13:28:21
- [25.82951194211311,](tel:25.82951194211311)
- [- 80.12079559072873](tel:80.12079559072873)
- Image [_____](#)



2024-04-18 13:28:26 EDT

Flooring/Baseboard

- 2024-04-18 13:28:26
- [25.82951194211311,](tel:25.82951194211311)
- [- 80.12079559072873](tel:80.12079559072873)
- Image [_____](#)



2024-04-18 13:28:27 EDT

Flooring/Baseboard

- 2024-04-18 13:28:27
- [25.82951194211311,](tel:25.82951194211311)
- [- 80.12079559072873](tel:80.12079559072873)
- Image [_____](#)



2024-04-18 13:28:28 EDT

Flooring/Baseboard

- 2024-04-18 13:28:28
- [25.82951194211311,](tel:25.82951194211311)
- [- 80.12079559072873](tel:80.12079559072873)
- Image [_____](#)



2024-04-18 13:28:31 EDT

Flooring/Baseboard

- 2024-04-18 13:28:31
- [25.82951194211311,](tel:25.82951194211311)
- [- 80.12079559072873](tel:80.12079559072873)
- Image [_____](#)



Light Fixture

- 2024-04-18 13:28:49
- [25.82945251464844,](#)
- [- 80.12086283270013](#)
- [Image](#)



Light Fixture

- 2024-04-18 13:28:50
- [25.82945251464844,](#)
- [- 80.12086283270013](#)
- [Image](#)



Light Fixture

- 2024-04-18 13:28:58
- [25.82945251464844,](#)
- [- 80.12086283270013](#)
- [Image](#)



Medicine Cabinet/Mirror

- 2024-04-18 13:29:07
- [25.82945251464844,](#)
- [- 80.12086283270013](#)
- [Image](#)



Medicine Cabinet/Mirror

- 2024-04-18 13:29:22
- [25.82945251464844,](#)
- [- 80.12086283270013](#)
- [Image](#)




Medicine Cabinet/Mirror

- 2024-04-18 13:29:24
- [25.82945251464844,](#)
- [- 80.12086283270013](#)
- [Image](#)



Plumbing/Drain

- 2024-04-18 13:29:33
- [25.82945251464844,](tel:25.82945251464844)
- [- 80.12086283270013](tel:80.12086283270013)
- [Image](#)



Plumbing/Drain

- 2024-04-18 13:29:43
- [25.82945251464844,](tel:25.82945251464844)
- [- 80.12086283270013](tel:80.12086283270013)
- [Image](#)



Shower Door/Rail/Curtain

- 2024-04-18 13:31:06
- [25.82941246444159,](tel:25.82941246444159)
- [- 80.12085502571426](tel:80.12085502571426)
- [Image](#)



Shower Door/Rail/Curtain

- 2024-04-18 13:31:41
- [25.82941246444159,](tel:25.82941246444159)
- [- 80.12085502571426](tel:80.12085502571426)
- [Image](#)



Sink/Faucet

- 2024-04-18 13:32:00
- [25.82941246444159,](tel:25.82941246444159)
- [- 80.12085502571426](tel:80.12085502571426)
- [Image](#)



Sink/Faucet

- 2024-04-18 13:32:03
- [25.82941246444159,](tel:25.82941246444159)
- [- 80.12085502571426](tel:80.12085502571426)
- [Image](#)



2024-04-18 13:32:16 EDT

Sink/Faucet

- 2024-04-18 13:32:16
- [25.82941246444159,](#)
- [- 80.12085502571426](#)
- Image [_____](#)



2024-04-18 13:32:29 EDT

Switch/Outlet

- 2024-04-18 13:32:29
- [25.82941246444159,](#)
- [- 80.12085502571426](#)
- Image [_____](#)



2024-04-18 13:32:37 EDT

Switch/Outlet

- 2024-04-18 13:32:37
- [25.82941246444159,](#)
- [- 80.12085502571426](#)
- Image [_____](#)



2024-04-18 13:32:52 EDT

Toilet

- 2024-04-18 13:32:52
- [25.829345703125, -80.1207925879188](#)
- Image [_____](#)



2024-04-18 13:33:00 EDT

Toilet

- 2024-04-18 13:33:00
- [25.829345703125, -80.1207925879188](#)
- Image [_____](#)



2024-04-18 13:33:06 EDT

Toilet

- 2024-04-18 13:33:06
- [25.829345703125, -80.1207925879188](#)
- Image [_____](#)



Toilet Paper Holder

▫ 2024-04-18 13:33:13

▫ 25.829345703125, -80.1207925879188

▫ Image



Towel Rack

▫ 2024-04-18 13:33:24

▫ 25.829345703125, -80.1207925879188

▫ Image



Tub/Shower

▫ 2024-04-18 13:33:34

▫ 25.829345703125, -80.1207925879188

▫ Image



Tub/Shower

▫ 2024-04-18 13:33:35

▫ 25.829345703125, -80.1207925879188

▫ Image




Tub/Shower

▫ 2024-04-18 13:33:42

▫ 25.829345703125, -80.1207925879188

▫ Image




Wall/Ceiling

▫ 2024-04-18 13:33:58

▫ 25.829345703125, -80.1207925879188

▫ Image




Wall/Ceiling

2024-04-18 13:33:59

25.829345703125, -80.1207925879188

Image



Wall/Ceiling

2024-04-18 13:34:01

25.829345703125, -80.1207925879188

Image




Wall/Ceiling

2024-04-18 13:34:02

25.829345703125, -80.1207925879188

Image



Wall/Ceiling

2024-04-18 13:34:04

25.829345703125, -80.1207925879188

Image




Wall/Ceiling

2024-04-18 13:34:04

25.829345703125, -80.1207925879188

Image



Wall/Ceiling

2024-04-18 13:34:09

25.829345703125, -80.1207925879188

Image



Wall/Ceiling

▣ 2024-04-18 13:34:10

▣ [25.829345703125, -80.1207925879188](#)

▣ [Image](#)



Wall/Ceiling

▣ 2024-04-18 13:34:13

▣ [25.829345703125, -80.1207925879188](#)

▣ [Image](#)



Wall/Ceiling

▣ 2024-04-18 13:34:14

▣ [25.829345703125, -80.1207925879188](#)

▣ [Image](#)



Wall/Ceiling

▣ 2024-04-18 13:34:17

▣ [25.829345703125, -80.1207925879188](#)

▣ [Image](#)



Wall/Ceiling

▣ 2024-04-18 13:34:19

▣ [25.829345703125, -80.1207925879188](#)

▣ [Image](#)



Wall/Ceiling

▣ 2024-04-18 13:34:21

▣ [25.829345703125, -80.1207925879188](#)

▣ [Image](#)

Bathroom 2



Cabinet/Counter/Shelving

□ 2024-04-18 13:36:36

□ [25.82945251464844](https://www.rentalinspections.com/25.82945251464844), -
[80.12084569897767](https://www.rentalinspections.com/80.12084569897767)

□ [Image](#)



Cabinet/Counter/Shelving

□ 2024-04-18 13:36:38

□ [25.82945251464844](https://www.rentalinspections.com/25.82945251464844), -
[80.12084569897767](https://www.rentalinspections.com/80.12084569897767)

□ [Image](#)




Cabinet/Counter/Shelving

□ 2024-04-18 13:36:42

□ [25.82945251464844](https://www.rentalinspections.com/25.82945251464844), -
[80.12084569897767](https://www.rentalinspections.com/80.12084569897767)

□ [Image](#)



Door/Knob/Lock

□ 2024-04-18 13:36:49

□ [25.829345703125](https://www.rentalinspections.com/25.829345703125), -
[80.12077359661056](https://www.rentalinspections.com/80.12077359661056)

□ [Image](#)



Door/Knob/Lock

□ 2024-04-18 13:36:53

□ [25.829345703125](https://www.rentalinspections.com/25.829345703125), -
[80.12077359661056](https://www.rentalinspections.com/80.12077359661056)

□ [Image](#)



Door/Knob/Lock

□ 2024-04-18 13:36:59

□ [25.829345703125](https://www.rentalinspections.com/25.829345703125), -
[80.12077359661056](https://www.rentalinspections.com/80.12077359661056)

□ [Image](#)




Exhaust Fan

2024-04-18 13:37:08

[25.829345703125, -](#)

[80.12077359661056](#)

Image [_____](#)



Flooring/Baseboard

2024-04-18 13:37:19

[25.829345703125, -](#)

[80.12077359661056](#)

Image [_____](#)



Flooring/Baseboard

2024-04-18 13:37:21

[25.829345703125, -](#)

[80.12077359661056](#)

Image [_____](#)



Flooring/Baseboard

2024-04-18 13:37:26

[25.829345703125, -](#)

[80.12077359661056](#)

Image [_____](#)




Flooring/Baseboard

2024-04-18 13:37:28

[25.829345703125, -](#)

[80.12077359661056](#)

Image [_____](#)



Flooring/Baseboard

2024-04-18 13:37:30

[25.829345703125, -](#)

[80.12077359661056](#)

Image [_____](#)




Flooring/Baseboard

2024-04-18 13:37:33

[25.829345703125, -](#)

[80.12077359661056](#)

Image [_____](#)



Flooring/Baseboard

2024-04-18 13:37:34

[25.829345703125, -](#)

[80.12077359661056](#)

Image [_____](#)



Flooring/Baseboard

2024-04-18 13:37:39

[25.829345703125, -](#)

[80.12077359661056](#)

Image [_____](#)



Flooring/Baseboard

2024-04-18 13:37:40

[25.829345703125, -](#)

[80.12077359661056](#)

Image [_____](#)




Light Fixture

2024-04-18 13:37:52

[25.829345703125, -](#)

[80.12077359661056](#)

Image [_____](#)



Light Fixture

2024-04-18 13:37:54

[25.829345703125, -](#)

[80.12077359661056](#)

Image [_____](#)



Light Fixture

□ 2024-04-18 13:37:55

□ [25.829345703125, -](#)

□ [80.12077359661056](#)

□ [Image](#)



Light Fixture

□ 2024-04-18 13:38:01

□ [25.829345703125, -](#)

□ [80.12077359661056](#)

□ [Image](#)



Medicine Cabinet/Mirror

□ 2024-04-18 13:38:17

□ [25.829345703125, -](#)

□ [80.12077359661056](#)

□ [Image](#)



Medicine Cabinet/Mirror

□ 2024-04-18 13:38:21

□ [25.829345703125, -](#)

□ [80.12077359661056](#)

□ [Image](#)



Medicine Cabinet/Mirror

□ 2024-04-18 13:38:22

□ [25.829345703125, -](#)

□ [80.12077359661056](#)

□ [Image](#)



Medicine Cabinet/Mirror

□ 2024-04-18 13:38:33

□ [25.829345703125, -](#)

□ [80.12077359661056](#)

□ [Image](#)



Plumbing/Drain

- 2024-04-18 13:43:09
- [25.82946749613477,](tel:25.82946749613477)
- [- 80.1207648761902](tel:80.1207648761902)
- [Image](#)




Plumbing/Drain

- 2024-04-18 13:43:11
- [25.82946749613477,](tel:25.82946749613477)
- [- 80.1207648761902](tel:80.1207648761902)
- [Image](#)



Plumbing/Drain

- 2024-04-18 13:43:24
- [25.82946749613477,](tel:25.82946749613477)
- [- 80.1207648761902](tel:80.1207648761902)
- [Image](#)




Plumbing/Drain

- 2024-04-18 13:43:26
- [25.82946749613477,](tel:25.82946749613477)
- [- 80.1207648761902](tel:80.1207648761902)
- [Image](#)



Shower Door/Rail/Curtain

- 2024-04-18 13:43:42
- [25.82946749613477,](tel:25.82946749613477) -
- [80.1207648761902](tel:80.1207648761902)
- [Image](#)



Shower Door/Rail/Curtain

- 2024-04-18 13:43:45
- [25.82946749613477,](tel:25.82946749613477) -
- [80.1207648761902](tel:80.1207648761902)
- [Image](#)



2024-04-18 13:43:47 EDT
Shower Door/Rail/Curtain
□ 2024-04-18 13:43:47
□ [25.82946749613477](https://www.25.82946749613477.com), -
[80.1207648761902](https://www.80.1207648761902.com)
□ [Image](#)



2024-04-18 13:43:48 EDT
Shower Door/Rail/Curtain
□ 2024-04-18 13:43:48
□ [25.82946749613477](https://www.25.82946749613477.com), -
[80.1207648761902](https://www.80.1207648761902.com)
□ [Image](#)




2024-04-18 13:43:50 EDT
Shower Door/Rail/Curtain
□ 2024-04-18 13:43:50
□ [25.82946749613477](https://www.25.82946749613477.com), -
[80.1207648761902](https://www.80.1207648761902.com)
□ [Image](#)



2024-04-18 13:38:51 EDT
Sink/Faucet
□ 2024-04-18 13:38:51
□ [25.82920837402344](https://www.25.82920837402344.com),
□ [80.12074975268315](https://www.80.12074975268315.com)
□ [Image](#)



2024-04-18 13:38:55 EDT
Sink/Faucet
□ 2024-04-18 13:38:55
□ [25.82937283734319](https://www.25.82937283734319.com),
□ [80.12077059459172](https://www.80.12077059459172.com)
□ [Image](#)



2024-04-18 13:39:04 EDT
Sink/Faucet
□ 2024-04-18 13:39:04
□ [25.82937283734319](https://www.25.82937283734319.com),
□ [80.12077059459172](https://www.80.12077059459172.com)
□ [Image](#)



2024-04-18 13:39:19 EDT

Switch/Outlet

- 2024-04-18 13:39:19
- [25.82937283734319,](#)
- [- 80.12077059459172](#)
- Image [_____](#)



2024-04-18 13:39:29 EDT

Switch/Outlet

- 2024-04-18 13:39:29
- [25.82937283734319,](#)
- [- 80.12077059459172](#)
- Image [_____](#)



2024-04-18 13:39:42 EDT

Toilet

- 2024-04-18 13:39:42
- [25.82937283734319,](#)
- [- 80.12077059459172](#)
- Image [_____](#)



2024-04-18 13:39:45 EDT

Toilet

- 2024-04-18 13:39:45
- [25.82937283734319,](#)
- [- 80.12077059459172](#)
- Image [_____](#)



2024-04-18 13:39:50 EDT

Toilet

- 2024-04-18 13:39:50
- [25.82937283734319,](#)
- [- 80.12077059459172](#)
- Image [_____](#)



2024-04-18 13:40:02 EDT

Toilet

- 2024-04-18 13:40:02
- [25.82937283734319,](#)
- [- 80.12077059459172](#)
- Image [_____](#)



Toilet Paper Holder

- 2024-04-18 13:40:13
- [25.82937283734319,](https://www.25.82937283734319.com)
- [- 80.12077059459172](https://www.80.12077059459172.com)
- Image [_____](#)



Toilet Paper Holder

- 2024-04-18 13:40:22
- [25.82937283734319,](https://www.25.82937283734319.com)
- [- 80.12077059459172](https://www.80.12077059459172.com)
- Image [_____](#)



Towel Rack

- 2024-04-18 13:40:33
- [25.82937283734319,](https://www.25.82937283734319.com)
- [- 80.12077059459172](https://www.80.12077059459172.com)
- Image [_____](#)




Towel Rack

- 2024-04-18 13:40:42
- [25.82937283734319,](https://www.25.82937283734319.com)
- [- 80.12077059459172](https://www.80.12077059459172.com)
- Image [_____](#)



Tub/Shower

- 2024-04-18 13:41:00
- [25.82933221052768,](https://www.25.82933221052768.com)
- [- 80.12079397737104](https://www.80.12079397737104.com)
- Image [_____](#)




Tub/Shower

- 2024-04-18 13:41:03
- [25.82933221052768,](https://www.25.82933221052768.com)
- [- 80.12079397737104](https://www.80.12079397737104.com)
- Image [_____](#)



Tub/Shower

- 2024-04-18 13:41:04
- [25.82933221052768,](#)
- [- 80.12079397737104](#)
- Image [_____](#)



Tub/Shower

- 2024-04-18 13:41:10
- [25.82933221052768,](#)
- [- 80.12079397737104](#)
- Image [_____](#)



Tub/Shower

- 2024-04-18 13:41:32
- [25.82933221052768,](#)
- [- 80.12079397737104](#)
- Image [_____](#)




Tub/Shower

- 2024-04-18 13:41:38
- [25.82933221052768,](#)
- [- 80.12079397737104](#)
- Image [_____](#)



Tub/Shower

- 2024-04-18 13:41:58
- [25.82933221052768,](#)
- [- 80.12079397737104](#)
- Image [_____](#)



Tub/Shower


- 2024-04-18 13:41:59
- [25.82933221052768,](#)
- [- 80.12079397737104](#)
- Image [_____](#)



2024-04-18 13:42:02 EDT

Tub/Shower

- 2024-04-18 13:42:02
- [25.82933221052768,](#)
- [- 80.12079397737104](#)
- Image [_____](#)



2024-04-18 13:42:19 EDT

Wall/Ceiling


- 2024-04-18 13:42:19
- [25.82933221052768,](#)
- [- 80.12079397737104](#)
- Image [_____](#)



2024-04-18 13:42:20 EDT

Wall/Ceiling


- 2024-04-18 13:42:20
- [25.82933221052768,](#)
- [- 80.12079397737104](#)
- Image [_____](#)



2024-04-18 13:42:21 EDT

Wall/Ceiling


- 2024-04-18 13:42:21
- [25.82933221052768,](#)
- [- 80.12079397737104](#)
- Image [_____](#)



2024-04-18 13:42:22 EDT

Wall/Ceiling

- 2024-04-18 13:42:22
- [25.82933221052768,](#)
- [- 80.12079397737104](#)
- Image [_____](#)



2024-04-18 13:42:24 EDT

Wall/Ceiling

- 2024-04-18 13:42:24
- [25.82933221052768,](#)
- [- 80.12079397737104](#)
- Image [_____](#)



Wall/Ceiling

- 2024-04-18 13:42:25
- [25.82933221052768,](#)
- [- 80.12079397737104](#)
- Image [_____](#)



Wall/Ceiling

- 2024-04-18 13:42:29
- [25.82933221052768,](#)
- [- 80.12079397737104](#)
- Image [_____](#)




Wall/Ceiling

- 2024-04-18 13:42:31
- [25.82933221052768,](#)
- [- 80.12079397737104](#)
- Image [_____](#)




Wall/Ceiling

- 2024-04-18 13:42:32
- [25.82933221052768,](#)
- [- 80.12079397737104](#)
- Image [_____](#)




Wall/Ceiling

- 2024-04-18 13:42:35
- [25.82933221052768,](#)
- [- 80.12079397737104](#)
- Image [_____](#)



Wall/Ceiling

- 2024-04-18 13:42:39
- [25.82933221052768,](#)
- [- 80.12079397737104](#)
- Image [_____](#)



Wall/Ceiling

□ 2024-04-18 13:42:41

□ [25.82933221052768](#), -

[80.12079397737104](#)

□ [Image](#)



Wall/Ceiling

□ 2024-04-18 13:42:49

□ [25.82951270853194](#),

- [80.12069206126444](#)

□ [Image](#)

Bedroom 1: Master



Closet/Door/Track/Shelving

□ 2024-04-18 13:47:13

□ [25.82942199707031](#), -

[80.12068697494092](#)

□ [Image](#)



Closet/Door/Track/Shelving

□ 2024-04-18 13:47:14

□ [25.82942199707031](#), -

[80.12068697494092](#)

□ [Image](#)



Closet/Door/Track/Shelving

□ 2024-04-18 13:47:15

□ [25.82942199707031](#), -

[80.12068697494092](#)

□ [Image](#)



Closet/Door/Track/Shelving

□ 2024-04-18 13:47:17

□ [25.82942199707031](#), -

[80.12068697494092](#)

□ [Image](#)




2024-04-18 13:47:18 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:47:18

□ [25.82942199707031, - 80.12068697494092](#)

□ [Image](#)



2024-04-18 13:47:19 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:47:19

□ [25.82942199707031, - 80.12068697494092](#)

□ [Image](#)



2024-04-18 13:47:21 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:47:21

□ [25.82942199707031, - 80.12068697494092](#)

□ [Image](#)



2024-04-18 13:47:35 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:47:35

□ [25.82942199707031, - 80.12068697494092](#)

□ [Image](#)



2024-04-18 13:47:42 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:47:42

□ [25.82942199707031, - 80.12068697494092](#)

□ [Image](#)



2024-04-18 13:47:45 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:47:45

□ [25.82942199707031, - 80.12068697494092](#)

□ [Image](#)



2024-04-18 13:47:49 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:47:49

□ [25.82942199707031, - 80.12068697494092](https://www.rentalinspections.com/25.82942199707031,-80.12068697494092)

□ [Image](#)



2024-04-18 13:47:55 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:47:55

□ [25.82942199707031, - 80.12068697494092](https://www.rentalinspections.com/25.82942199707031,-80.12068697494092)

□ [Image](#)



2024-04-18 13:47:57 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:47:57

□ [25.82942199707031, - 80.12068697494092](https://www.rentalinspections.com/25.82942199707031,-80.12068697494092)

□ [Image](#)



2024-04-18 13:47:59 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:47:59

□ [25.82942199707031, - 80.12068697494092](https://www.rentalinspections.com/25.82942199707031,-80.12068697494092)

□ [Image](#)



2024-04-18 13:48:00 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:48:00

□ [25.82942199707031, - 80.12068697494092](https://www.rentalinspections.com/25.82942199707031,-80.12068697494092)

□ [Image](#)



2024-04-18 13:48:04 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:48:04

□ [25.82942199707031, - 80.12068697494092](https://www.rentalinspections.com/25.82942199707031,-80.12068697494092)

□ [Image](#)



Closet/Door/Track/Shelving
□ 2024-04-18 13:48:05
□ [25.82942199707031, - 80.12068697494092](#)
□ [Image](#)



Closet/Door/Track/Shelving
□ 2024-04-18 13:48:07
□ [25.82942199707031, - 80.12068697494092](#)
□ [Image](#)



Closet/Door/Track/Shelving
□ 2024-04-18 13:48:08
□ [25.82942199707031, - 80.12068697494092](#)
□ [Image](#)



Closet/Door/Track/Shelving
□ 2024-04-18 13:48:16
□ [25.82942199707031, - 80.12068697494092](#)
□ [Image](#)



Closet/Door/Track/Shelving
□ 2024-04-18 13:48:17
□ [25.82942199707031, - 80.12068697494092](#)
□ [Image](#)



Closet/Door/Track/Shelving
□ 2024-04-18 13:48:21
□ [25.82942199707031, - 80.12068697494092](#)
□ [Image](#)



2024-04-18 13:48:29 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:48:29

□ [25.82942199707031, -80.12068697494092](#)

□ [Image](#)



2024-04-18 13:48:32 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:48:32

□ [25.82942199707031, -80.12068697494092](#)

□ [Image](#)



2024-04-18 13:48:33 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:48:33

□ [25.82942199707031, -80.12068697494092](#)

□ [Image](#)



2024-04-18 13:48:34 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:48:34

□ [25.82942199707031, -80.12068697494092](#)

□ [Image](#)



2024-04-18 13:48:35 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:48:35

□ [25.82942199707031, -80.12068697494092](#)

□ [Image](#)



2024-04-18 13:48:37 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:48:37

□ [25.82942199707031, -80.12068697494092](#)

□ [Image](#)



2024-04-18 13:48:41 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:48:41

□ [25.82942199707031, -](#)
[80.12068697494092](#)

□ [Image](#)



2024-04-18 13:48:42 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:48:42

□ [25.82942199707031, -](#)
[80.12068697494092](#)

□ [Image](#)



2024-04-18 13:48:46 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:48:46

□ [25.82936305170629, -](#)
[80.12083191369587](#)

□ [Image](#)




2024-04-18 13:48:47 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:48:47

□ [25.82936305170629, -](#)
[80.12083191369587](#)

□ [Image](#)




2024-04-18 13:49:15 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:49:15

□ [25.82936867968149, -](#)
[80.12087801402389](#)

□ [Image](#)



2024-04-18 13:49:16 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:49:16

□ [25.82936867968149, -](#)
[80.12087801402389](#)

□ [Image](#)



2024-04-18 13:49:26 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:49:26

□ [25.82936867968149](https://www.25.82936867968149.com), - [80.12087801402389](https://www.80.12087801402389.com)

□ [Image](#)



2024-04-18 13:49:35 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:49:35

□ [25.82936867968149](https://www.25.82936867968149.com), - [80.12087801402389](https://www.80.12087801402389.com)

□ [Image](#)



2024-04-18 13:49:47 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:49:47

□ [25.82936867968149](https://www.25.82936867968149.com), - [80.12087801402389](https://www.80.12087801402389.com)

□ [Image](#)



2024-04-18 13:49:54 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:49:54

□ [25.82936867968149](https://www.25.82936867968149.com), - [80.12087801402389](https://www.80.12087801402389.com)

□ [Image](#)




2024-04-18 13:49:59 EDT

Closet/Door/Track/Shelving

□ 2024-04-18 13:49:59

□ [25.82936867968149](https://www.25.82936867968149.com), - [80.12087801402389](https://www.80.12087801402389.com)

□ [Image](#)



2024-04-18 13:44:07 EDT

Door/Knob/Lock

□ 2024-04-18 13:44:07

□ [25.82946749613477](https://www.25.82946749613477.com), - [80.1207648761902](https://www.80.1207648761902.com)

□ [Image](#)



Door/Knob/Lock

- 2024-04-18 13:44:10
- [25.82946749613477,](https://www.25.82946749613477.com)
- [- 80.1207648761902](https://www.80.1207648761902.com)
- Image [_____](#)




Door/Knob/Lock

- 2024-04-18 13:44:14
- [25.82946749613477,](https://www.25.82946749613477.com)
- [- 80.1207648761902](https://www.80.1207648761902.com)
- Image [_____](#)



Flooring/Baseboard

- 2024-04-18 13:44:22
- [25.82946749613477,](https://www.25.82946749613477.com)
- [- 80.1207648761902](https://www.80.1207648761902.com)
- Image [_____](#)




Flooring/Baseboard

- 2024-04-18 13:44:23
- [25.82946749613477,](https://www.25.82946749613477.com)
- [- 80.1207648761902](https://www.80.1207648761902.com)
- Image [_____](#)




Flooring/Baseboard

- 2024-04-18 13:44:24
- [25.82946749613477,](https://www.25.82946749613477.com)
- [- 80.1207648761902](https://www.80.1207648761902.com)
- Image [_____](#)



Flooring/Baseboard

- 2024-04-18 13:44:27
- [25.82946749613477,](https://www.25.82946749613477.com)
- [- 80.1207648761902](https://www.80.1207648761902.com)
- Image [_____](#)



Flooring/Baseboard

- 2024-04-18 13:44:28
- [25.82946749613477,](https://www.25.82946749613477.com)
- [- 80.1207648761902](https://www.80.1207648761902.com)
- Image [_____](#)




Flooring/Baseboard

- 2024-04-18 13:44:29
- [25.82946749613477,](https://www.25.82946749613477.com)
- [- 80.1207648761902](https://www.80.1207648761902.com)
- Image [_____](#)



Flooring/Baseboard

- 2024-04-18 13:44:30
- [25.82946749613477,](https://www.25.82946749613477.com)
- [- 80.1207648761902](https://www.80.1207648761902.com)
- Image [_____](#)



Flooring/Baseboard

- 2024-04-18 13:44:34
- [25.82946749613477,](https://www.25.82946749613477.com)
- [- 80.1207648761902](https://www.80.1207648761902.com)
- Image [_____](#)



Flooring/Baseboard

- 2024-04-18 13:44:35
- [25.82946749613477,](https://www.25.82946749613477.com)
- [- 80.1207648761902](https://www.80.1207648761902.com)
- Image [_____](#)




Flooring/Baseboard

- 2024-04-18 13:44:36
- [25.82946749613477,](https://www.25.82946749613477.com)
- [- 80.1207648761902](https://www.80.1207648761902.com)
- Image [_____](#)



Flooring/Baseboard

- 2024-04-18 13:44:37
- [25.82946749613477,](https://www.25.82946749613477.com)
- [- 80.1207648761902](https://www.80.1207648761902.com)
- Image [_____](#)



Flooring/Baseboard

- 2024-04-18 13:44:39
- [25.82946749613477,](https://www.25.82946749613477.com)
- [- 80.1207648761902](https://www.80.1207648761902.com)
- Image [_____](#)



Flooring/Baseboard

- 2024-04-18 13:44:40
- [25.82946749613477,](https://www.25.82946749613477.com)
- [- 80.1207648761902](https://www.80.1207648761902.com)
- Image [_____](#)




Flooring/Baseboard

- 2024-04-18 13:44:41
- [25.82946749613477,](https://www.25.82946749613477.com)
- [- 80.1207648761902](https://www.80.1207648761902.com)
- Image [_____](#)




Flooring/Baseboard

- 2024-04-18 13:44:42
- [25.82946749613477,](https://www.25.82946749613477.com)
- [- 80.1207648761902](https://www.80.1207648761902.com)
- Image [_____](#)




Flooring/Baseboard

- 2024-04-18 13:44:43
- [25.82939147949219,](https://www.25.82939147949219.com)
- [- 80.12072297473715](https://www.80.12072297473715.com)
- Image [_____](#)




Flooring/Baseboard

- 2024-04-18 13:44:44
- [25.82939147949219,](https://www.25.82939147949219.com)
- [- 80.12072297473715](https://www.80.12072297473715.com)
- Image [_____](#)




Flooring/Baseboard

- 2024-04-18 13:44:46
- [25.82939147949219,](https://www.25.82939147949219.com)
- [- 80.12072297473715](https://www.80.12072297473715.com)
- Image [_____](#)




Flooring/Baseboard

- 2024-04-18 13:44:48
- [25.82939147949219,](https://www.25.82939147949219.com)
- [- 80.12072297473715](https://www.80.12072297473715.com)
- Image [_____](#)




Flooring/Baseboard

- 2024-04-18 13:44:51
- [25.82939147949219,](https://www.25.82939147949219.com)
- [- 80.12072297473715](https://www.80.12072297473715.com)
- Image [_____](#)




Flooring/Baseboard

- 2024-04-18 13:44:54
- [25.82939825946795,](https://www.25.82939825946795.com)
- [- 80.12074638399433](https://www.80.12074638399433.com)
- Image [_____](#)




Light Fixture/Fan

- 2024-04-18 13:45:02
- [25.82939825946795,](https://www.25.82939825946795.com)
- [- 80.12074638399433](https://www.80.12074638399433.com)
- Image [_____](#)



Light Fixture/Fan

- 2024-04-18 13:45:04
- [25.82939825946795,](https://www.25.82939825946795.com)
- [- 80.12074638399433](https://www.80.12074638399433.com)
- Image [_____](#)




Light Fixture/Fan

- 2024-04-18 13:45:09
- [25.82939825946795,](https://www.25.82939825946795.com)
- [- 80.12074638399433](https://www.80.12074638399433.com)
- Image [_____](#)



Light Fixture/Fan

- 2024-04-18 13:45:10
- [25.82939825946795,](https://www.25.82939825946795.com)
- [- 80.12074638399433](https://www.80.12074638399433.com)
- Image [_____](#)




Switch/Outlet

- 2024-04-18 13:46:24
- [25.82939825946795,](https://www.25.82939825946795.com)
- [- 80.12074638399433](https://www.80.12074638399433.com)
- Image [_____](#)



Switch/Outlet

- 2024-04-18 13:46:26
- [25.82939825946795,](https://www.25.82939825946795.com)
- [- 80.12074638399433](https://www.80.12074638399433.com)
- Image [_____](#)



Switch/Outlet

- 2024-04-18 13:46:31
- [25.82939825946795,](https://www.25.82939825946795.com)
- [- 80.12074638399433](https://www.80.12074638399433.com)
- Image [_____](#)



Switch/Outlet

- 2024-04-18 13:46:34
- [25.82939825946795,](#)
- [- 80.12074638399433](#)
- Image [_____](#)




Switch/Outlet

- 2024-04-18 13:46:36
- [25.82939825946795,](#)
- [- 80.12074638399433](#)
- Image [_____](#)




Switch/Outlet

- 2024-04-18 13:46:39
- [25.82939825946795,](#)
- [- 80.12074638399433](#)
- Image [_____](#)




Wall/Ceiling

- 2024-04-18 13:46:07
- [25.82939825946795,](#)
- [- 80.12074638399433](#)
- Image [_____](#)



Wall/Ceiling

- 2024-04-18 13:46:08
- [25.82939825946795,](#)
- [- 80.12074638399433](#)
- Image [_____](#)



Wall/Ceiling

- 2024-04-18 13:46:10
- [25.82939825946795,](#)
- [- 80.12074638399433](#)
- Image [_____](#)



Wall/Ceiling

- 2024-04-18 13:46:11
- [25.82939825946795,](#)
- [- 80.12074638399433](#)
- Image [_____](#)



Wall/Ceiling

- 2024-04-18 13:46:12
- [25.82939825946795,](#)
- [- 80.12074638399433](#)
- Image [_____](#)



Wall/Ceiling

- 2024-04-18 13:46:13
- [25.82939825946795,](#)
- [- 80.12074638399433](#)
- Image [_____](#)




Wall/Ceiling

- 2024-04-18 13:46:15
- [25.82939825946795,](#)
- [- 80.12074638399433](#)
- Image [_____](#)



Window/Lock/Screen

- 2024-04-18 13:45:34
- [25.82939825946795,](#)
- [- 80.12074638399433](#)
- Image [_____](#)



Window/Lock/Screen

- 2024-04-18 13:45:36
- [25.82939825946795,](#)
- [- 80.12074638399433](#)
- Image [_____](#)



Window/Lock/Screen

- 2024-04-18 13:45:38
- [25.82939825946795,](#)
- [- 80.12074638399433](#)
- Image [_____](#)



Window/Lock/Screen

- 2024-04-18 13:45:39
- [25.82939825946795,](#)
- [- 80.12074638399433](#)
- Image [_____](#)



Window/Lock/Screen

- 2024-04-18 13:45:40
- [25.82939825946795,](#)
- [- 80.12074638399433](#)
- Image [_____](#)



Window/Lock/Screen

- 2024-04-18 13:45:41
- [25.82939825946795,](#)
- [- 80.12074638399433](#)
- Image [_____](#)



Window/Lock/Screen

- 2024-04-18 13:45:46
- [25.82939825946795,](#)
- [80.12074638399433](#)
- Image [_____](#)



Window/Lock/Screen

- 2024-04-18 13:45:47
- [25.82939825946795,](#)
- [- 80.12074638399433](#)
- Image [_____](#)

Bedroom 2



Closet/Door/Track/Shelving

□ 2024-04-18 13:50:21

□ [25.82936867968149](https://www.rentalinspections.com/25.82936867968149), - [80.12087801402389](https://www.rentalinspections.com/80.12087801402389)

□ [Image](#)



Closet/Door/Track/Shelving

□ 2024-04-18 13:50:22

□ [25.82936867968149](https://www.rentalinspections.com/25.82936867968149), - [80.12087801402389](https://www.rentalinspections.com/80.12087801402389)

□ [Image](#)



Closet/Door/Track/Shelving

□ 2024-04-18 13:50:33

□ [25.82936867968149](https://www.rentalinspections.com/25.82936867968149), - [80.12087801402389](https://www.rentalinspections.com/80.12087801402389)

□ [Image](#)



Closet/Door/Track/Shelving

□ 2024-04-18 13:50:41

□ [25.82936867968149](https://www.rentalinspections.com/25.82936867968149), - [80.12087801402389](https://www.rentalinspections.com/80.12087801402389)

□ [Image](#)




Closet/Door/Track/Shelving

□ 2024-04-18 13:50:47

□ [25.82929992675781](https://www.rentalinspections.com/25.82929992675781), - [80.12075541773564](https://www.rentalinspections.com/80.12075541773564)

□ [Image](#)




Door/Knob/Lock

□ 2024-04-18 13:50:55

□ [25.82931658466789](https://www.rentalinspections.com/25.82931658466789), - [80.12081138590176](https://www.rentalinspections.com/80.12081138590176)

□ [Image](#)



2024-04-18 13:50:59 EDT

Door/Knob/Lock

- 2024-04-18 13:50:59
- [25.82931658466789,](https://www.25.82931658466789.com)
- [- 80.12081138590176](https://www.80.12081138590176.com)
- Image [_____](#)



2024-04-18 13:51:02 EDT

Door/Knob/Lock

- 2024-04-18 13:51:02
- [25.82931658466789,](https://www.25.82931658466789.com)
- [- 80.12081138590176](https://www.80.12081138590176.com)
- Image [_____](#)



2024-04-18 13:51:30 EDT

Flooring/Baseboard


- 2024-04-18 13:51:30
- [25.82931658466789,](https://www.25.82931658466789.com)
- [- 80.12081138590176](https://www.80.12081138590176.com)
- Image [_____](#)



2024-04-18 13:51:31 EDT

Flooring/Baseboard


- 2024-04-18 13:51:31
- [25.82931658466789,](https://www.25.82931658466789.com)
- [- 80.12081138590176](https://www.80.12081138590176.com)
- Image [_____](#)



2024-04-18 13:51:32 EDT

Flooring/Baseboard

- 2024-04-18 13:51:32
- [25.82931658466789,](https://www.25.82931658466789.com)
- [- 80.12081138590176](https://www.80.12081138590176.com)
- Image [_____](#)



2024-04-18 13:51:33 EDT

Flooring/Baseboard

- 2024-04-18 13:51:33
- [25.82931658466789,](https://www.25.82931658466789.com)
- [- 80.12081138590176](https://www.80.12081138590176.com)
- Image [_____](#)



Flooring/Baseboard

- 2024-04-18 13:51:34
- [25.82931658466789](tel:25.82931658466789),
- [- 80.12081138590176](tel:80.12081138590176)
- Image _____




Flooring/Baseboard

- 2024-04-18 13:51:35
- [25.82931658466789](tel:25.82931658466789),
- [- 80.12081138590176](tel:80.12081138590176)
- Image _____



Flooring/Baseboard

- 2024-04-18 13:51:40
- [25.82931658466789](tel:25.82931658466789),
- [- 80.12081138590176](tel:80.12081138590176)
- Image _____




Flooring/Baseboard

- 2024-04-18 13:51:41
- [25.82931658466789](tel:25.82931658466789),
- [- 80.12081138590176](tel:80.12081138590176)
- Image _____



Flooring/Baseboard

- 2024-04-18 13:51:42
- [25.82931658466789](tel:25.82931658466789),
- [- 80.12081138590176](tel:80.12081138590176)
- Image _____



Flooring/Baseboard

- 2024-04-18 13:51:43
- [25.82931658466789](tel:25.82931658466789),
- [- 80.12081138590176](tel:80.12081138590176)
- Image _____



Flooring/Baseboard

- 2024-04-18 13:51:44
- [25.82931658466789,](https://www.25.82931658466789.com)
- [- 80.12081138590176](https://www.80.12081138590176.com)
- Image _____




Flooring/Baseboard

- 2024-04-18 13:51:49
- [25.82931658466789,](https://www.25.82931658466789.com)
- [- 80.12081138590176](https://www.80.12081138590176.com)
- Image _____



- 2024-04-18 13:53:45
- [25.82929992675781,](https://www.25.82929992675781.com)
- [- 80.1208124693457](https://www.80.1208124693457.com)
- Image _____



- 2024-04-18 13:53:46
- [25.82929992675781,](https://www.25.82929992675781.com)
- [- 80.1208124693457](https://www.80.1208124693457.com)
- Image _____



- 2024-04-18 13:53:52
- [25.82929992675781,](https://www.25.82929992675781.com)
- [- 80.1208124693457](https://www.80.1208124693457.com)
- Image _____



- 2024-04-18 13:53:53
- [25.82929992675781,](https://www.25.82929992675781.com)
- [- 80.1208124693457](https://www.80.1208124693457.com)
- Image _____



2024-04-18 13:53:54
 [25.82929992675781, -80.1208124693457](#)
 Image _____



2024-04-18 13:53:55
 [25.82929992675781, -80.1208124693457](#)
 Image _____



Switch/Outlet
 2024-04-18 13:52:02
 [25.82931658466789, -80.12081138590176](#)
 Image _____




Switch/Outlet
 2024-04-18 13:52:06
 [25.82931658466789, -80.12081138590176](#)
 Image _____



Switch/Outlet
 2024-04-18 13:52:09
 [25.82931658466789, -80.12081138590176](#)
 Image _____



Switch/Outlet
 2024-04-18 13:52:23
 [25.82931658466789, -80.12081138590176](#)
 Image _____



2024-04-18 13:52:25 EDT

Switch/Outlet

- 2024-04-18 13:52:25
- [25.82931658466789,](#)
- [- 80.12081138590176](#)
- Image _____



2024-04-18 13:52:33 EDT

Wall/Ceiling

- 2024-04-18 13:52:33
- [25.82931658466789,](#)
- [- 80.12081138590176](#)
- Image _____



2024-04-18 13:52:34 EDT

Wall/Ceiling

- 2024-04-18 13:52:34
- [25.82931658466789,](#)
- [- 80.12081138590176](#)
- Image _____



2024-04-18 13:52:34 EDT

Wall/Ceiling

- 2024-04-18 13:52:34
- [25.82931658466789,](#)
- [- 80.12081138590176](#)
- Image _____



2024-04-18 13:52:35 EDT

Wall/Ceiling

- 2024-04-18 13:52:35
- [25.82931658466789,](#)
- [- 80.12081138590176](#)
- Image _____



2024-04-18 13:52:36 EDT

Wall/Ceiling

- 2024-04-18 13:52:36
- [25.82931658466789,](#)
- [- 80.12081138590176](#)
- Image _____



Wall/Ceiling

- 2024-04-18 13:52:37
- [25.82931658466789,](#)
- [- 80.12081138590176](#)
- Image _____



Wall/Ceiling

- 2024-04-18 13:52:38
- [25.82931658466789,](#)
- [- 80.12081138590176](#)
- Image _____




Wall/Ceiling

- 2024-04-18 13:52:40
- [25.82931658466789,](#)
- [- 80.12081138590176](#)
- Image _____




Wall/Ceiling

- 2024-04-18 13:52:41
- [25.82931658466789,](#)
- [- 80.12081138590176](#)
- Image _____




Wall/Ceiling

- 2024-04-18 13:52:47
- [25.82929992675781,](#)
- [- 80.1208124693457](#)
- Image _____



Wall/Ceiling

- 2024-04-18 13:52:48
- [25.82929992675781,](#)
- [- 80.1208124693457](#)
- Image _____



2024-04-18 13:52:50 EDT

Wall/Ceiling

- 2024-04-18 13:52:50
- [25.82929992675781,](#)
- [- 80.1208124693457](#)
- Image _____



2024-04-18 13:53:03 EDT

Window/Lock/Screen

- 2024-04-18 13:53:03
- [25.82929992675781,](#)
- [- 80.1208124693457](#)
- Image _____



2024-04-18 13:53:04 EDT

Window/Lock/Screen

- 2024-04-18 13:53:04
- [25.82929992675781,](#)
- [- 80.1208124693457](#)
- Image _____



2024-04-18 13:53:05 EDT

Window/Lock/Screen


- 2024-04-18 13:53:05
- [25.82929992675781,](#)
- [- 80.1208124693457](#)
- Image _____



2024-04-18 13:53:07 EDT

Window/Lock/Screen

- 2024-04-18 13:53:07
- [25.82929992675781,](#)
- [80.1208124693457](#)
- Image _____



2024-04-18 13:53:10 EDT

Window/Lock/Screen

- 2024-04-18 13:53:10
- [25.82929992675781,](#)
- [- 80.1208124693457](#)
- Image _____

Balcony



Flooring

- 2024-04-18 14:15:35
- [25.82890747914901,](#)
- [- 80.12098705854997](#)
- Image [_____](#)



Flooring

- 2024-04-18 14:15:37
- [25.82890747914901,](#)
- [- 80.12098705854997](#)
- Image [_____](#)



Flooring

- 2024-04-18 14:15:38
- [25.82890747914901,](#)
- [- 80.12098705854997](#)
- Image [_____](#)



Flooring

- 2024-04-18 14:15:39
- [25.82890747914901,](#)
- [- 80.12098705854997](#)
- Image [_____](#)



Flooring

- 2024-04-18 14:15:40
- [25.82890747914901,](#)
- [- 80.12098705854997](#)
- Image [_____](#)



Flooring

- 2024-04-18 14:15:41
- [25.82890747914901,](#)
- [- 80.12098705854997](#)
- Image [_____](#)



Flooring

- 2024-04-18 14:15:42
- [25.82890747914901,](https://www.25.82890747914901.com)
- [- 80.12098705854997](https://www.80.12098705854997.com)
- Image [_____](#)



Flooring

- 2024-04-18 14:15:43
- [25.82890747914901,](https://www.25.82890747914901.com)
- [- 80.12098705854997](https://www.80.12098705854997.com)
- Image [_____](#)




Flooring

- 2024-04-18 14:15:44
- [25.82890747914901,](https://www.25.82890747914901.com)
- [- 80.12098705854997](https://www.80.12098705854997.com)
- Image [_____](#)



Flooring

- 2024-04-18 14:15:45
- [25.82890747914901,](https://www.25.82890747914901.com)
- [- 80.12098705854997](https://www.80.12098705854997.com)
- Image [_____](#)



Flooring

- 2024-04-18 14:15:46
- [25.82890747914901,](https://www.25.82890747914901.com)
- [- 80.12098705854997](https://www.80.12098705854997.com)
- Image [_____](#)



Flooring

- 2024-04-18 14:15:47
- [25.82890747914901,](https://www.25.82890747914901.com)
- [- 80.12098705854997](https://www.80.12098705854997.com)
- Image [_____](#)



Flooring

- 2024-04-18 14:15:47
- [25.82890747914901,](https://www.25.82890747914901.com)
- [- 80.12098705854997](https://www.80.12098705854997.com)
- Image [_____](#)



Flooring

- 2024-04-18 14:15:48
- [25.82890747914901,](https://www.25.82890747914901.com)
- [- 80.12098705854997](https://www.80.12098705854997.com)
- Image [_____](#)



Flooring

- 2024-04-18 14:15:49
- [25.82890747914901,](https://www.25.82890747914901.com)
- [- 80.12098705854997](https://www.80.12098705854997.com)
- Image [_____](#)



Other

- 2024-04-18 14:16:44
- [25.82890747914901,](https://www.25.82890747914901.com)
- [- 80.12098705854997](https://www.80.12098705854997.com)
- Image [_____](#)



Other

- 2024-04-18 14:16:45
- [25.82890747914901,](https://www.25.82890747914901.com)
- [- 80.12098705854997](https://www.80.12098705854997.com)
- Image [_____](#)



Other

- 2024-04-18 14:16:46
- [25.82890747914901,](https://www.25.82890747914901.com)
- [- 80.12098705854997](https://www.80.12098705854997.com)
- Image [_____](#)



Other

- 2024-04-18 14:16:47
- [25.82890747914901,](#)
- [- 80.12098705854997](#)
- Image [_____](#)



Other

- 2024-04-18 14:16:49
- [25.82890747914901,](#)
- [- 80.12098705854997](#)
- Image [_____](#)



Other

- 2024-04-18 14:16:50
- [25.82890747914901,](#)
- [- 80.12098705854997](#)
- Image [_____](#)




Other

- 2024-04-18 14:16:51
- [25.82890747914901,](#)
- [- 80.12098705854997](#)
- Image [_____](#)



Other

- 2024-04-18 14:16:52
- [25.82890747914901,](#)
- [- 80.12098705854997](#)
- Image [_____](#)



Other

- 2024-04-18 14:16:53
- [25.82890747914901,](#)
- [- 80.12098705854997](#)
- Image [_____](#)



Other

- 2024-04-18 14:16:55
- [25.82890747914901,](https://www.25.82890747914901.com)
- [- 80.12098705854997](https://www.80.12098705854997.com)
- Image [_____](#)



Other

- 2024-04-18 14:16:55
- [25.82890747914901,](https://www.25.82890747914901.com)
- [- 80.12098705854997](https://www.80.12098705854997.com)
- Image [_____](#)



Other

- 2024-04-18 14:16:56
- [25.82890747914901,](https://www.25.82890747914901.com)
- [- 80.12098705854997](https://www.80.12098705854997.com)
- Image [_____](#)



Other

- 2024-04-18 14:17:02
- [25.82890747914901,](https://www.25.82890747914901.com)
- [- 80.12098705854997](https://www.80.12098705854997.com)
- Image [_____](#)



Other

- 2024-04-18 14:17:03
- [25.82890747914901,](https://www.25.82890747914901.com)
- [- 80.12098705854997](https://www.80.12098705854997.com)
- Image [_____](#)




Other

- 2024-04-18 14:17:05
- [25.82890747914901,](https://www.25.82890747914901.com)
- [- 80.12098705854997](https://www.80.12098705854997.com)
- Image [_____](#)



Other

- 2024-04-18 14:17:08
- [25.82890747914901,](tel:25.82890747914901)
- [- 80.12098705854997](tel:80.12098705854997)
- Image [_____](#)




Other

- 2024-04-18 14:17:12
- [25.82890747914901,](tel:25.82890747914901)
- [- 80.12098705854997](tel:80.12098705854997)
- Image [_____](#)




Other

- 2024-04-18 14:17:12
- [25.82890747914901,](tel:25.82890747914901)
- [- 80.12098705854997](tel:80.12098705854997)
- Image [_____](#)



Railing

- 2024-04-18 14:14:55
- [25.82952875758057,](tel:25.82952875758057)
- [- 80.12073932224826](tel:80.12073932224826)
- Image [_____](#)



Railing

- 2024-04-18 14:14:55
- [25.82952875758057,](tel:25.82952875758057)
- [- 80.12073932224826](tel:80.12073932224826)
- Image [_____](#)



Railing

- 2024-04-18 14:14:58
- [25.82952875758057,](tel:25.82952875758057)
- [- 80.12073932224826](tel:80.12073932224826)
- Image [_____](#)



Railing

- 2024-04-18 14:15:00
- [25.82952875758057,](#)
- [- 80.12073932224826](#)
- Image [_____](#)




Railing

- 2024-04-18 14:15:03
- [25.82952875758057,](#)
- [- 80.12073932224826](#)
- Image [_____](#)



Railing

- 2024-04-18 14:15:05
- [25.82952875758057,](#)
- [- 80.12073932224826](#)
- Image [_____](#)



Railing

- 2024-04-18 14:15:07
- [25.82952875758057,](#)
- [- 80.12073932224826](#)
- Image [_____](#)



Railing

- 2024-04-18 14:15:08
- [25.82952875758057,](#)
- [- 80.12073932224826](#)
- Image [_____](#)



Railing

- 2024-04-18 14:15:09
- [25.82952875758057,](#)
- [- 80.12073932224826](#)
- Image [_____](#)



2024-04-18 14:15:10 EDT

Railing

- 2024-04-18 14:15:10
- [25.82952875758057,](#)
- [- 80.12073932224826](#)
- Image [_____](#)



2024-04-18 14:15:11 EDT

Railing

- 2024-04-18 14:15:11
- [25.82952875758057,](#)
- [- 80.12073932224826](#)
- Image [_____](#)



2024-04-18 14:15:12 EDT

Railing

- 2024-04-18 14:15:12
- [25.82952875758057,](#)
- [- 80.12073932224826](#)
- Image [_____](#)



2024-04-18 14:15:13 EDT

Railing


- 2024-04-18 14:15:13
- [25.82957458496094,](#)
- [- 80.12070463373664](#)
- Image [_____](#)



2024-04-18 14:15:14 EDT

Railing

- 2024-04-18 14:15:14
- [25.82957458496094,](#)
- [80.12070463373664](#)
- Image [_____](#)



2024-04-18 14:15:16 EDT

Railing


- 2024-04-18 14:15:16
- [25.82957458496094,](#)
- [- 80.12070463373664](#)
- Image [_____](#)

Dining Room




Flooring/Baseboard

- 2024-04-18 13:54:41
- [25.82929992675781,](#)
- [- 80.1208124693457](#)
- Image [_____](#)




Flooring/Baseboard

- 2024-04-18 13:54:42
- [25.82929992675781,](#)
- [- 80.1208124693457](#)
- Image [_____](#)



Flooring/Baseboard

- 2024-04-18 13:54:43
- [25.82929992675781,](#)
- [- 80.1208124693457](#)
- Image [_____](#)




Flooring/Baseboard

- 2024-04-18 13:54:44
- [25.82960510253906,](#)
- [- 80.12064502680091](#)
- Image [_____](#)



Flooring/Baseboard

- 2024-04-18 13:54:53
- [25.82960510253906,](#)
- [- 80.12064502680091](#)
- Image [_____](#)



Flooring/Baseboard

- 2024-04-18 13:54:54
- [25.82960510253906,](#)
- [- 80.12064502680091](#)
- Image [_____](#)



Light Fixture/Fan

- 2024-04-18 13:55:03
- [25.82960510253906,](#)
- [- 80.12064502680091](#)
- Image [_____](#)




Light Fixture/Fan

- 2024-04-18 13:55:05
- [25.82960510253906,](#)
- [- 80.12064502680091](#)
- Image [_____](#)



Light Fixture/Fan

- 2024-04-18 13:55:06
- [25.82960510253906,](#)
- [- 80.12064502680091](#)
- Image [_____](#)




Light Fixture/Fan

- 2024-04-18 13:55:09
- [25.82960510253906,](#)
- [- 80.12064502680091](#)
- Image [_____](#)



Light Fixture/Fan

- 2024-04-18 13:56:33
- [25.82960510253906,](#)
- [- 80.12064502680091](#)
- Image [_____](#)



Light Fixture/Fan

- 2024-04-18 13:56:34
- [25.82960510253906,](#)
- [- 80.12064502680091](#)
- Image [_____](#)




Switch/Outlet

- 2024-04-18 13:55:24
- [25.82960510253906,](#)
- [- 80.12064502680091](#)
- Image [_____](#)




Switch/Outlet

- 2024-04-18 13:55:27
- [25.82960510253906,](#)
- [- 80.12064502680091](#)
- Image [_____](#)



Wall/Ceiling

- 2024-04-18 13:55:35
- [25.82960510253906,](#)
- [- 80.12064502680091](#)
- Image [_____](#)



Wall/Ceiling

- 2024-04-18 13:55:36
- [25.82960510253906,](#)
- [- 80.12064502680091](#)
- Image [_____](#)



Wall/Ceiling

- 2024-04-18 13:55:37
- [25.82960510253906,](#)
- [- 80.12064502680091](#)
- Image [_____](#)




Wall/Ceiling

- 2024-04-18 13:55:38
- [25.82960510253906,](#)
- [- 80.12064502680091](#)
- Image [_____](#)



Wall/Ceiling

- 2024-04-18 13:55:39
- [25.82960510253906,](#)
- [- 80.12064502680091](#)
- Image [_____](#)



Wall/Ceiling

- 2024-04-18 13:55:41
- [25.82960510253906,](#)
- [- 80.12064502680091](#)
- Image [_____](#)



Window/Lock/Screen

- 2024-04-18 13:55:50
- [25.82960510253906,](#)
- [- 80.12064502680091](#)
- Image [_____](#)



Window/Lock/Screen

- 2024-04-18 13:55:52
- [25.82960510253906,](#)
- [- 80.12064502680091](#)
- Image [_____](#)



Window/Lock/Screen

- 2024-04-18 13:55:53
- [25.82960510253906,](#)
- [- 80.12064502680091](#)
- Image [_____](#)



Window/Lock/Screen

- 2024-04-18 13:55:53
- [25.82960510253906,](#)
- [- 80.12064502680091](#)
- Image [_____](#)



2024-04-18 13:55:54 EDT

Window/Lock/Screen

- 2024-04-18 13:55:54
- [25.82960510253906,](#)
- [- 80.12064502680091](#)
- Image _____

Kitchen



2024-04-18 14:01:04 EDT

Cabinets/Drawers

- 2024-04-18 14:01:04
- [25.82954672423606,](#)
- [- 80.12070783414052](#)
- Image _____



2024-04-18 14:01:05 EDT

Cabinets/Drawers

- 2024-04-18 14:01:05
- [25.82954672423606,](#)
- [- 80.12070783414052](#)
- Image _____



2024-04-18 14:01:06 EDT

Cabinets/Drawers

- 2024-04-18 14:01:06
- [25.82954672423606,](#)
- [- 80.12070783414052](#)
- Image _____



2024-04-18 14:01:08 EDT

Cabinets/Drawers

- 2024-04-18 14:01:08
- [25.82954672423606,](#)
- [- 80.12070783414052](#)
- Image _____



Cabinets/Drawers

- 2024-04-18 14:01:09
- [25.82954672423606,](https://www.25.82954672423606.com)
- [- 80.12070783414052](https://www.80.12070783414052.com)
- Image [_____](#)



Cabinets/Drawers

- 2024-04-18 14:01:43
- [25.82954672423606,](https://www.25.82954672423606.com)
- [- 80.12070783414052](https://www.80.12070783414052.com)
- Image [_____](#)



Cabinets/Drawers

- 2024-04-18 14:01:44
- [25.82954672423606,](https://www.25.82954672423606.com)
- [- 80.12070783414052](https://www.80.12070783414052.com)
- Image [_____](#)



Cabinets/Drawers

- 2024-04-18 14:02:11
- [25.82954672423606,](https://www.25.82954672423606.com)
- [- 80.12070783414052](https://www.80.12070783414052.com)
- Image [_____](#)



Cabinets/Drawers

- 2024-04-18 14:02:14
- [25.82954672423606,](https://www.25.82954672423606.com)
- [- 80.12070783414052](https://www.80.12070783414052.com)
- Image [_____](#)



Cabinets/Drawers

- 2024-04-18 14:02:15
- [25.82954672423606,](https://www.25.82954672423606.com)
- [- 80.12070783414052](https://www.80.12070783414052.com)
- Image [_____](#)



Cabinets/Drawers

- 2024-04-18 14:02:16
- [25.82954672423606,](https://www.25.82954672423606.com)
- [- 80.12070783414052](https://www.80.12070783414052.com)
- Image _____



Cabinets/Drawers

- 2024-04-18 14:02:35
- [25.82954672423606,](https://www.25.82954672423606.com)
- [- 80.12070783414052](https://www.80.12070783414052.com)
- Image _____



Cabinets/Drawers

- 2024-04-18 14:02:42
- [25.82954672423606,](https://www.25.82954672423606.com)
- [- 80.12070783414052](https://www.80.12070783414052.com)
- Image _____



Cabinets/Drawers

- 2024-04-18 14:02:49
- [25.82962036132812,](https://www.25.82962036132812.com)
- [- 80.12064442821946](https://www.80.12064442821946.com)
- Image _____



Cabinets/Drawers

- 2024-04-18 14:02:55
- [25.82962036132812,](https://www.25.82962036132812.com)
- [- 80.12064442821946](https://www.80.12064442821946.com)
- Image _____



Cabinets/Drawers

- 2024-04-18 14:03:01
- [25.82962036132812,](https://www.25.82962036132812.com)
- [- 80.12064442821946](https://www.80.12064442821946.com)
- Image _____



Cabinets/Drawers

- 2024-04-18 14:03:18
- [25.82962036132812,](https://www.25.82962036132812.com)
- [- 80.12064442821946](https://www.80.12064442821946.com)
- Image [_____](#)



Cabinets/Drawers

- 2024-04-18 14:03:47
- [25.82962036132812,](https://www.25.82962036132812.com)
- [- 80.12064442821946](https://www.80.12064442821946.com)
- Image [_____](#)



Cabinets/Drawers

- 2024-04-18 14:04:04
- [25.82962036132812,](https://www.25.82962036132812.com)
- [- 80.12064442821946](https://www.80.12064442821946.com)
- Image [_____](#)



Cabinets/Drawers

- 2024-04-18 14:04:05
- [25.82962036132812,](https://www.25.82962036132812.com)
- [- 80.12064442821946](https://www.80.12064442821946.com)
- Image [_____](#)



Counter

- 2024-04-18 14:04:17
- [25.82962036132812,](https://www.25.82962036132812.com)
- [- 80.12064442821946](https://www.80.12064442821946.com)
- Image [_____](#)



Counter

- 2024-04-18 14:04:18
- [25.82962036132812,](https://www.25.82962036132812.com)
- [- 80.12064442821946](https://www.80.12064442821946.com)
- Image [_____](#)



Counter

- 2024-04-18 14:04:20
- [25.82962036132812,](#)
- [- 80.12064442821946](#)
- Image [_____](#)



Counter

- 2024-04-18 14:04:21
- [25.82962036132812,](#)
- [- 80.12064442821946](#)
- Image [_____](#)



Counter

- 2024-04-18 14:04:22
- [25.82962036132812,](#)
- [- 80.12064442821946](#)
- Image [_____](#)



Counter

- 2024-04-18 14:04:23
- [25.82962036132812,](#)
- [- 80.12064442821946](#)
- Image [_____](#)



Counter

- 2024-04-18 14:04:24
- [25.82962036132812,](#)
- [- 80.12064442821946](#)
- Image [_____](#)




Dishwasher

- 2024-04-18 14:04:31
- [25.82962036132812,](#)
- [- 80.12064442821946](#)
- Image [_____](#)



Dishwasher

- 2024-04-18 14:05:56
- [25.82956074861213,](https://www.25.82956074861213.com)
- [- 80.12076523670808](https://www.80.12076523670808.com)
- Image [_____](#)



Faucet/Plumbing

- 2024-04-18 14:12:02
- [25.82948567364077,](https://www.25.82948567364077.com)
- [- 80.12068816926191](https://www.80.12068816926191.com)
- Image [_____](#)



Faucet/Plumbing

- 2024-04-18 14:12:11
- [25.82948567364077,](https://www.25.82948567364077.com)
- [- 80.12068816926191](https://www.80.12068816926191.com)
- Image [_____](#)



Faucet/Plumbing

- 2024-04-18 14:12:13
- [25.82948567364077,](https://www.25.82948567364077.com)
- [- 80.12068816926191](https://www.80.12068816926191.com)
- Image [_____](#)



Faucet/Plumbing

- 2024-04-18 14:12:15
- [25.82948567364077,](https://www.25.82948567364077.com)
- [- 80.12068816926191](https://www.80.12068816926191.com)
- Image [_____](#)



Faucet/Plumbing

- 2024-04-18 14:12:20
- [25.82948567364077,](https://www.25.82948567364077.com)
- [- 80.12068816926191](https://www.80.12068816926191.com)
- Image [_____](#)



Flooring/Baseboard

- 2024-04-18 14:06:10
- [25.82956074861213,](https://www.25.82956074861213.com)
- [- 80.12076523670808](https://www.80.12076523670808.com)
- Image [_____](#)



Flooring/Baseboard

- 2024-04-18 14:06:11
- [25.82956074861213,](https://www.25.82956074861213.com)
- [- 80.12076523670808](https://www.80.12076523670808.com)
- Image [_____](#)



Flooring/Baseboard

- 2024-04-18 14:06:13
- [25.82956074861213,](https://www.25.82956074861213.com)
- [- 80.12076523670808](https://www.80.12076523670808.com)
- Image [_____](#)




Flooring/Baseboard

- 2024-04-18 14:06:14
- [25.82956074861213,](https://www.25.82956074861213.com)
- [- 80.12076523670808](https://www.80.12076523670808.com)
- Image [_____](#)




Flooring/Baseboard

- 2024-04-18 14:06:15
- [25.82956074861213,](https://www.25.82956074861213.com)
- [- 80.12076523670808](https://www.80.12076523670808.com)
- Image [_____](#)



Flooring/Baseboard


- 2024-04-18 14:06:16
- [25.82956074861213,](https://www.25.82956074861213.com)
- [- 80.12076523670808](https://www.80.12076523670808.com)
- Image [_____](#)



2024-04-18 14:06:17 EDT

Flooring/Baseboard

- 2024-04-18 14:06:17
- [25.82956074861213,](https://www.25.82956074861213.com)
- [- 80.12076523670808](https://www.80.12076523670808.com)
- Image [_____](#)



2024-04-18 14:06:18 EDT

Flooring/Baseboard


- 2024-04-18 14:06:18
- [25.82956074861213,](https://www.25.82956074861213.com)
- [- 80.12076523670808](https://www.80.12076523670808.com)
- Image [_____](#)



2024-04-18 14:06:20 EDT

Flooring/Baseboard

- 2024-04-18 14:06:20
- [25.82956074861213,](https://www.25.82956074861213.com)
- [- 80.12076523670808](https://www.80.12076523670808.com)
- Image [_____](#)



2024-04-18 14:06:21 EDT

Flooring/Baseboard

- 2024-04-18 14:06:21
- [25.82956074861213,](https://www.25.82956074861213.com)
- [- 80.12076523670808](https://www.80.12076523670808.com)
- Image [_____](#)



2024-04-18 14:06:27 EDT

Light Fixture

- 2024-04-18 14:06:27
- [25.82956074861213,](https://www.25.82956074861213.com)
- [- 80.12076523670808](https://www.80.12076523670808.com)
- Image [_____](#)



2024-04-18 14:06:28 EDT

Light Fixture

- 2024-04-18 14:06:28
- [25.82956074861213,](https://www.25.82956074861213.com)
- [- 80.12076523670808](https://www.80.12076523670808.com)
- Image [_____](#)




Light Fixture

- 2024-04-18 14:06:29
- [25.82956074861213,](#)
- [- 80.12076523670808](#)
- Image [_____](#)




Light Fixture

- 2024-04-18 14:06:30
- [25.82956074861213,](#)
- [- 80.12076523670808](#)
- Image [_____](#)



Light Fixture

- 2024-04-18 14:06:31
- [25.82956074861213,](#)
- [- 80.12076523670808](#)
- Image [_____](#)




Light Fixture

- 2024-04-18 14:06:32
- [25.82956074861213,](#)
- [- 80.12076523670808](#)
- Image [_____](#)




Light Fixture

- 2024-04-18 14:06:33
- [25.82956074861213,](#)
- [- 80.12076523670808](#)
- Image [_____](#)



Light Fixture

- 2024-04-18 14:06:34
- [25.82956074861213,](#)
- [- 80.12076523670808](#)
- Image [_____](#)



Light Fixture

- 2024-04-18 14:06:35
- [25.82956074861213,](#)
- [- 80.12076523670808](#)
- Image [_____](#)



Microwave

- 2024-04-18 14:12:51
- [25.82948567364077,](#)
- [- 80.12068816926191](#)
- Image [_____](#)



Microwave

- 2024-04-18 14:12:52
- [25.82948567364077,](#)
- [- 80.12068816926191](#)
- Image [_____](#)



Microwave

- 2024-04-18 14:12:57
- [25.82948567364077,](#)
- [- 80.12068816926191](#)
- Image [_____](#)



Microwave

- 2024-04-18 14:13:01
- [25.82948567364077,](#)
- [- 80.12068816926191](#)
- Image [_____](#)



Range/Fan/Hood/Filter

- 2024-04-18 14:09:08
- [25.8294677734375,](#)
- [- 80.12077211827331](#)
- Image [_____](#)



2024-04-18 14:09:28 EDT

Range/Fan/Hood/Filter

□ 2024-04-18 14:09:28

□ [25.82947773396472, -](#)

[80.12077911183938](#)

□ [Image](#)



2024-04-18 14:09:29 EDT

Range/Fan/Hood/Filter

□ 2024-04-18 14:09:29

□ [25.82947773396472, -](#)

[80.12077911183938](#)

□ [Image](#)



2024-04-18 14:09:30 EDT

Range/Fan/Hood/Filter

□ 2024-04-18 14:09:30

□ [25.82947773396472, -](#)

[80.12077911183938](#)

□ [Image](#)



2024-04-18 14:09:31 EDT

Range/Fan/Hood/Filter

□ 2024-04-18 14:09:31

□ [25.82947773396472, -](#)

[80.12077911183938](#)

□ [Image](#)



2024-04-18 14:09:42 EDT

Range/Fan/Hood/Filter

□ 2024-04-18 14:09:42

□ [25.82947773396472, -](#)

[80.12077911183938](#)

□ [Image](#)



2024-04-18 14:09:50 EDT

Range/Fan/Hood/Filter

□ 2024-04-18 14:09:50

□ [25.82947773396472, -](#)

[80.12077911183938](#)

□ [Image](#)



2024-04-18 14:10:02 EDT

Refrigerator

- 2024-04-18 14:10:02
- [25.82947773396472,](#)
- [- 80.12077911183938](#)
- Image [_____](#)



2024-04-18 14:10:14 EDT

Refrigerator

- 2024-04-18 14:10:14
- [25.82947773396472,](#)
- [- 80.12077911183938](#)
- Image [_____](#)



2024-04-18 14:10:14 EDT

Refrigerator

- 2024-04-18 14:10:14
- [25.82947773396472,](#)
- [- 80.12077911183938](#)
- Image [_____](#)



2024-04-18 14:10:15 EDT

Refrigerator

- 2024-04-18 14:10:15
- [25.82947773396472,](#)
- [- 80.12077911183938](#)
- Image [_____](#)



2024-04-18 14:10:17 EDT

Refrigerator

- 2024-04-18 14:10:17
- [25.82947773396472,](#)
- [- 80.12077911183938](#)
- Image [_____](#)



2024-04-18 14:10:18 EDT

Refrigerator

- 2024-04-18 14:10:18
- [25.82947773396472,](#)
- [- 80.12077911183938](#)
- Image [_____](#)



Refrigerator

- 2024-04-18 14:10:19
- [25.82947773396472,](#)
- [- 80.12077911183938](#)
- Image [_____](#)



Refrigerator

- 2024-04-18 14:11:02
- [25.82947773396472,](#)
- [- 80.12077911183938](#)
- Image [_____](#)



Refrigerator

- 2024-04-18 14:11:06
- [25.82947773396472,](#)
- [- 80.12077911183938](#)
- Image [_____](#)



Refrigerator

- 2024-04-18 14:11:15
- [25.82955932617188,](#)
- [- 80.1207359572007](#)
- Image [_____](#)



Sink/Disposal

- 2024-04-18 14:13:22
- [25.82952875758057,](#)
- [- 80.12073932224826](#)
- Image [_____](#)



Sink/Disposal


- 2024-04-18 14:13:25
- [25.82952875758057,](#)
- [- 80.12073932224826](#)
- Image [_____](#)



2024-04-18 14:13:26 EDT

Sink/Disposal

- 2024-04-18 14:13:26
- [25.82952875758057,](https://www.25.82952875758057.com)
- [- 80.12073932224826](https://www.80.12073932224826.com)
- Image [_____](#)



2024-04-18 14:13:27 EDT

Sink/Disposal


- 2024-04-18 14:13:27
- [25.82952875758057,](https://www.25.82952875758057.com)
- [- 80.12073932224826](https://www.80.12073932224826.com)
- Image [_____](#)



2024-04-18 14:13:38 EDT

Sink/Disposal

- 2024-04-18 14:13:38
- [25.82952875758057,](https://www.25.82952875758057.com)
- [- 80.12073932224826](https://www.80.12073932224826.com)
- Image [_____](#)



2024-04-18 14:13:39 EDT

Sink/Disposal

- 2024-04-18 14:13:39
- [25.82952875758057,](https://www.25.82952875758057.com)
- [- 80.12073932224826](https://www.80.12073932224826.com)
- Image [_____](#)



2024-04-18 14:13:40 EDT

Sink/Disposal

- 2024-04-18 14:13:40
- [25.82952875758057,](https://www.25.82952875758057.com)
- [- 80.12073932224826](https://www.80.12073932224826.com)
- Image [_____](#)



2024-04-18 14:13:45 EDT

Sink/Disposal

- 2024-04-18 14:13:45
- [25.82952875758057,](https://www.25.82952875758057.com)
- [- 80.12073932224826](https://www.80.12073932224826.com)
- Image [_____](#)



Sink/Disposal

- 2024-04-18 14:13:51
- [25.82952875758057,](#)
- [- 80.12073932224826](#)
- Image [_____](#)




Sink/Disposal

- 2024-04-18 14:13:52
- [25.82952875758057,](#)
- [- 80.12073932224826](#)
- Image [_____](#)



Switch/Outlet

- 2024-04-18 14:11:31
- [25.82948567364077,](#)
- [- 80.12068816926191](#)
- Image [_____](#)



Switch/Outlet

- 2024-04-18 14:11:32
- [25.82948567364077,](#)
- [- 80.12068816926191](#)
- Image [_____](#)



Switch/Outlet

- 2024-04-18 14:11:34
- [25.82948567364077,](#)
- [- 80.12068816926191](#)
- Image [_____](#)



Switch/Outlet

- 2024-04-18 14:11:36
- [25.82948567364077,](#)
- [- 80.12068816926191](#)
- Image [_____](#)



2024-04-18 14:11:38 EDT

Switch/Outlet

- 2024-04-18 14:11:38
- [25.82948567364077,](https://www.google.com/maps/place/25.82948567364077,-80.12068816926191)
- [- 80.12068816926191](https://www.google.com/maps/place/25.82948567364077,-80.12068816926191)
- Image [_____](#)



2024-04-18 14:11:42 EDT

Switch/Outlet

- 2024-04-18 14:11:42
- [25.82948567364077,](https://www.google.com/maps/place/25.82948567364077,-80.12068816926191)
- [- 80.12068816926191](https://www.google.com/maps/place/25.82948567364077,-80.12068816926191)
- Image [_____](#)



2024-04-18 14:14:09 EDT

Wall/Ceiling

- 2024-04-18 14:14:09
- [25.82952875758057,](https://www.google.com/maps/place/25.82952875758057,-80.12073932224826)
- [- 80.12073932224826](https://www.google.com/maps/place/25.82952875758057,-80.12073932224826)
- Image [_____](#)



2024-04-18 14:14:10 EDT

Wall/Ceiling

- 2024-04-18 14:14:10
- [25.82952875758057,](https://www.google.com/maps/place/25.82952875758057,-80.12073932224826)
- [- 80.12073932224826](https://www.google.com/maps/place/25.82952875758057,-80.12073932224826)
- Image [_____](#)



2024-04-18 14:14:10 EDT

Wall/Ceiling

- 2024-04-18 14:14:10
- [25.82952875758057,](https://www.google.com/maps/place/25.82952875758057,-80.12073932224826)
- [- 80.12073932224826](https://www.google.com/maps/place/25.82952875758057,-80.12073932224826)
- Image [_____](#)



2024-04-18 14:14:15 EDT

Wall/Ceiling

- 2024-04-18 14:14:15
- [25.82952875758057,](https://www.google.com/maps/place/25.82952875758057,-80.12073932224826)
- [- 80.12073932224826](https://www.google.com/maps/place/25.82952875758057,-80.12073932224826)
- Image [_____](#)



Wall/Ceiling

- 2024-04-18 14:14:16
- [25.82952875758057,](#)
- [- 80.12073932224826](#)
- Image [_____](#)



Wall/Ceiling

- 2024-04-18 14:14:17
- [25.82952875758057,](#)
- [- 80.12073932224826](#)
- Image [_____](#)



Wall/Ceiling

- 2024-04-18 14:14:22
- [25.82952875758057,](#)
- [- 80.12073932224826](#)
- Image [_____](#)




Wall/Ceiling

- 2024-04-18 14:14:22
- [25.82952875758057,](#)
- [- 80.12073932224826](#)
- Image [_____](#)



Wall/Ceiling

- 2024-04-18 14:14:24
- [25.82952875758057,](#)
- [80.12073932224826](#)
- Image [_____](#)



Wall/Ceiling

- 2024-04-18 14:14:24
- [25.82952875758057,](#)
- [- 80.12073932224826](#)
- Image [_____](#)

Living Room



Flooring/Baseboard

- 2024-04-18 13:57:09
- [25.82955932617188,](https://www.google.com/maps/place/25.82955932617188,-80.12073701741461)
- [- 80.12073701741461](https://www.google.com/maps/place/25.82955932617188,-80.12073701741461)
- Image [_____](#)




Flooring/Baseboard

- 2024-04-18 13:57:10
- [25.82955932617188,](https://www.google.com/maps/place/25.82955932617188,-80.12073701741461)
- [- 80.12073701741461](https://www.google.com/maps/place/25.82955932617188,-80.12073701741461)
- Image [_____](#)



Flooring/Baseboard

- 2024-04-18 13:57:13
- [25.82955932617188,](https://www.google.com/maps/place/25.82955932617188,-80.12073701741461)
- [- 80.12073701741461](https://www.google.com/maps/place/25.82955932617188,-80.12073701741461)
- Image [_____](#)



Flooring/Baseboard

- 2024-04-18 13:57:14
- [25.82955932617188,](https://www.google.com/maps/place/25.82955932617188,-80.12073701741461)
- [- 80.12073701741461](https://www.google.com/maps/place/25.82955932617188,-80.12073701741461)
- Image [_____](#)




Flooring/Baseboard

- 2024-04-18 13:57:15
- [25.82955932617188,](https://www.google.com/maps/place/25.82955932617188,-80.12073701741461)
- [- 80.12073701741461](https://www.google.com/maps/place/25.82955932617188,-80.12073701741461)
- Image [_____](#)



Flooring/Baseboard


- 2024-04-18 13:57:16
- [25.82955932617188,](https://www.google.com/maps/place/25.82955932617188,-80.12073701741461)
- [- 80.12073701741461](https://www.google.com/maps/place/25.82955932617188,-80.12073701741461)
- Image [_____](#)



2024-04-18 13:57:17 EDT

Flooring/Baseboard

- 2024-04-18 13:57:17
- [25.82955932617188,](https://www.25.82955932617188.com)
- [- 80.12073701741461](https://www.80.12073701741461.com)
- Image [_____](#)



2024-04-18 13:57:17 EDT

Flooring/Baseboard

- 2024-04-18 13:57:17
- [25.82955932617188,](https://www.25.82955932617188.com)
- [- 80.12073701741461](https://www.80.12073701741461.com)
- Image [_____](#)



2024-04-18 13:56:45 EDT

- 2024-04-18 13:56:45
- [25.82955932617188,](https://www.25.82955932617188.com)
- [- 80.12073701741461](https://www.80.12073701741461.com)
- Image [_____](#)



2024-04-18 13:56:46 EDT

- 2024-04-18 13:56:46
- [25.82955932617188,](https://www.25.82955932617188.com)
- [- 80.12073701741461](https://www.80.12073701741461.com)
- Image [_____](#)



2024-04-18 13:56:47 EDT

- 2024-04-18 13:56:47
- [25.82955932617188,](https://www.25.82955932617188.com)
- [- 80.12073701741461](https://www.80.12073701741461.com)
- Image [_____](#)



2024-04-18 13:56:50 EDT

- 2024-04-18 13:56:50
- [25.82955932617188,](https://www.25.82955932617188.com)
- [- 80.12073701741461](https://www.80.12073701741461.com)
- Image [_____](#)



2024-04-18 13:56:55
 [25.82955932617188, -80.12073701741461](#)
 Image _____




2024-04-18 13:56:56
 [25.82955932617188, -80.12073701741461](#)
 Image _____



Switch/Outlet
 2024-04-18 13:57:28
 [25.82955932617188, -80.12073701741461](#)
 Image _____



Switch/Outlet
 2024-04-18 13:57:32
 [25.82955932617188, -80.12073701741461](#)
 Image _____



Switch/Outlet
 2024-04-18 13:57:33
 [25.82955932617188, -80.12073701741461](#)
 Image _____



Wall/Ceiling
 2024-04-18 13:57:41
 [25.82955932617188, -80.12073701741461](#)
 Image _____



2024-04-18 13:57:41 EDT

Wall/Ceiling

- 2024-04-18 13:57:41
- [25.82955932617188,](#)
- [- 80.12073701741461](#)
- Image _____



2024-04-18 13:57:42 EDT

Wall/Ceiling


- 2024-04-18 13:57:42
- [25.82955932617188,](#)
- [- 80.12073701741461](#)
- Image _____



2024-04-18 13:57:43 EDT

Wall/Ceiling


- 2024-04-18 13:57:43
- [25.82955932617188,](#)
- [- 80.12073701741461](#)
- Image _____



2024-04-18 13:57:45 EDT

Wall/Ceiling


- 2024-04-18 13:57:45
- [25.82955932617188,](#)
- [- 80.12073701741461](#)
- Image _____



2024-04-18 13:57:45 EDT

Wall/Ceiling

- 2024-04-18 13:57:45
- [25.82955932617188,](#)
- [- 80.12073701741461](#)
- Image _____



2024-04-18 13:57:46 EDT


Wall/Ceiling

- 2024-04-18 13:57:46
- [25.82955932617188,](#)
- [- 80.12073701741461](#)
- Image _____



Wall/Ceiling

- 2024-04-18 13:57:47
- [25.82955932617188,](#)
- [- 80.12073701741461](#)
- Image [_____](#)



Wall/Ceiling

- 2024-04-18 13:57:48
- [25.82955932617188,](#)
- [- 80.12073701741461](#)
- Image [_____](#)



Wall/Ceiling

- 2024-04-18 13:57:53
- [25.82955932617188,](#)
- [- 80.12073701741461](#)
- Image [_____](#)



Wall/Ceiling

- 2024-04-18 13:57:54
- [25.82955932617188,](#)
- [- 80.12073701741461](#)
- Image [_____](#)



Window/Lock/Screen

- 2024-04-18 13:58:06
- [25.82955932617188,](#)
- [- 80.12073701741461](#)
- Image [_____](#)



Window/Lock/Screen

- 2024-04-18 13:58:07
- [25.82955932617188,](#)
- [- 80.12073701741461](#)
- Image [_____](#)



Window/Lock/Screen

- 2024-04-18 13:58:08
- [25.82955932617188,](#)
- [- 80.12073701741461](#)
- Image [_____](#)

Keys/Remotes/Devices



Remotes/Devices

- 2024-04-18 14:17:54
- [25.8295396156509,](#)
- [80.12093007655372](#)
- Image [_____](#)



Remotes/Devices

- 2024-04-18 14:17:55
- [25.8295396156509,](#)
- [80.12093007655372](#)
- Image [_____](#)



Remotes/Devices

- 2024-04-18 14:17:57
- [25.8295396156509,](#)
- [80.12093007655372](#)
- Image [_____](#)



Breaker Box

- 2024-04-18 13:59:00
- [25.8294677734375,](#)
- [- 80.1207665672401](#)
- Image [_____](#)



Breaker Box

- 2024-04-18 13:59:02
- [25.8294677734375,](#)
- [- 80.1207665672401](#)
- Image [_____](#)



Breaker Box

- 2024-04-18 13:59:03
- [25.8294677734375,](#)
- [- 80.1207665672401](#)
- Image [_____](#)



Thermostat

- 2024-04-18 13:59:36
- [25.8294677734375,](#)
- [- 80.1207665672401](#)
- Image [_____](#)



Thermostat

- 2024-04-18 13:59:49
- [25.8294677734375,](#)
- [- 80.1207665672401](#)
- Image [_____](#)

