

Occupational
Health and Safety

Field Visit Report

Page 1 of 2

OHS Case ID: **8933DQRSPHC**
Field Visit no: **8933DQRSPHC-8933-FV001**

Visit Date: **2025-SEP-10**

Field Visit Type: **INITIAL**

Workplace Identification: **ENERGY NETWORK SERVICES INC.**
110 TENTH STREET, ETOBICOKE, ON CA M8V 3G1

Notice ID: **25eN801876**

Telephone:
(437) 241-4585

JHSC Status:
Not required

Work Force #:
4

Completed %:
40

Persons Contacted: **K. Eapen, Project coordinator - ENS, T. Gomez, Supervisor - CLC, J. Pires, Project supervisor - TCDSB, I. Kurusenko, Principal - TCDSB, A. Manso, DWM - TECT, C. Macatangay, Caretaker - TCDSB**

Visit Purpose: **Reactive inspection - Complaint**

Visit Location: **Level 3 - library**

Visit Summary: **Order issued**

Detailed Narrative:

This inspector visited the above project on a reactive visit along with A. Juric (MLITSD) for a complaint received to the MLITSD contact centre.

Complaint:

Concerns for containment measures in place - no sealed-off work areas, no tarping, and no extra air filtration.

Project Description:

Lighting upgrade

Discussions and observations:

- Reviewed administration documentation (NOP, emergency procedures) (Order issued)
- No workers were observed working on active abatement
- Supervisor told this inspector that work only takes place during the weekends
- No contraventions were observed
- Supervisor told this inspector that active containment measures are in place, active air monitoring and vacuuming
- The internal responsibility system (I.R.S.)

Hygienist Comments – A. Juric, MLITSD Hygiene Consultant, CIH:

- The scope of asbestos abatement work being conducted by CLC Infrastructure workers was discussed during this visit. The work involves a Type 2 abatement of ceiling tiles in various parts of the school occurring over weekends in phases, and a planned Type 3 abatement of plaster ceilings at a later date. Initial work occurred over the September 5 weekend on the 3 floor. Measures and procedures that were in place for the abatement on the September 5 weekend were discussed/ reviewed. No abatement activities were occurring at the time of this visit.

End of Hygiene Comments

See order issued

Recipient	Inspector Data	Worker Representative
Name <u>Kevin Eapen</u>	Kalyan Anne	
Title <u>Project Coordinator</u>	O.H.S.A. & B.O.S.T.A INSPECTOR PROVINCIAL OFFENCES OFFICER	
	1600-5001 Yonge St, North York ON M7A 0A3	
	MOLComplianceCHSTorW@ontario.ca	
	Tel: (437) 226-9102	
	Fax: (647) 777-5012	
Signature <u>[Signature]</u>	Signature <u>[Signature]</u>	Signature <u>[Signature]</u>

You are required under the Occupational Health and Safety Act to post a copy of this report in a conspicuous place at the workplace and provide a copy to the health and safety representative or the joint health and safety committee if any. Failure to comply with an order, decision or requirement of an inspector is an offence under Section 66 of the Occupational Health and Safety Act. You have the right to appeal any order or decision within 30 days of the date of the order issued and to request suspension of the order or decision by filing your appeal and request in writing on the appropriate forms with the Ontario Labour Relations Board, 505 University Ave., 2nd Floor, Toronto, Ontario M5G 2P1. You may also contact the Board by phone at (416) 326-7500 or 1-877-339-3335 (toll free), mail or by website at <http://www.olrb.gov.on.ca/> for more information.

The Government of Ontario wants to hear from you. You can provide feedback on this visit at 1-888-745-8888

Occupational
Health and Safety

Field Visit Report

Page 2 of 2

OHS Case ID: **8933DQRSPHC**
Field Visit no: **8933DQRSPHC-8933-FV001**

Visit Date: **2025-SEP-10**

Field Visit Type: **INITIAL**

Order(s) /Requirement(s) Issued:

To:
ENERGY NETWORK SERVICES INC.

Org/Ind Role:
Constructor

Mailing Address:
2-125 WEST BEAVER CREEK ROAD, RICHMOND HILL, ON, CA L4B1C6

Order(s) /Requirement(s) Description:

You are required to comply with the order(s) /requirement(s) by the Comply by dates listed below.

No	Type Code	ActReg	Year	Sec.	Sub Sec.	Clause	Text of Order/Requirement	Comply by Date
1	Fort	OHS	1990				Constructor shall post the completed Notice of Project form in a conspicuous place or make available at the project for review by an inspector. Copy of the NOP was not posted or available at the Project. Order complied with.	
8933DQRSPHC-8933-OR001		213	1991	6	6			

Recipient	Inspector Data	Worker Representative
Name _____	Kalyan Anne	Name _____
Title _____	O.H.S.A. & B.O.S.T.A INSPECTOR PROVINCIAL OFFENCES OFFICER 1600-5001 Yonge St, North York ON M7A 0A3 MOLComplianceCHSTorW@ontario.ca Tel: (437) 226-9102 Fax: (647) 777-5012	Title _____
Signature 	Signature 	Signature _____

You are required under the Occupational Health and Safety Act to post a copy of this report in a conspicuous place at the workplace and provide a copy to the health and safety representative or the joint health and safety committee if any. Failure to comply with an order, decision or requirement of an inspector is an offence under Section 66 of the Occupational Health and Safety Act. You have the right to appeal any order or decision within 30 days of the date of the order issued and to request suspension of the order or decision by filing your appeal and request in writing on the appropriate forms with the Ontario Labour Relations Board, 505 University Ave., 2nd Floor, Toronto, Ontario M5G 2P1. You may also contact the Board by phone at (416) 326-7500 or 1-877-339-3335 (toll free), mail or by website at <http://www.qlrb.gov.on.ca/> for more information.

The Government of Ontario wants to hear from you. You can provide feedback on this visit at 1-888-745-8888