

OHS Case ID: **4548DKWBMD5**

Field Visit no: **4548DKWBMD5-4548-FV005**

Visit Date: **2025-SEP-22**

Field Visit Type: **FOLLOW-UP**

Workplace Identification:

BISHOP ALLEN ACADEMY

Notice ID:

721 ROYAL YORK ROAD, ETOBICOKE, ON CA M8Y 2T3

Telephone:
(416) 393-5549

JHSC Status:
Active

Work Force #:
115

Completed %:

Persons Contacted:

Doug McDougall - Head Custodian/JHSC Worker Representative

Jose (Joe) Couto - Operations Supervisor

Laura Pilarski - Designated Worker Representative (Certified JHSC member) - On phone

Visit Purpose:

To follow up

Visit Location:

Wooden stairs/Bleachers near the portables, front of the school (catch basin area)

Visit Summary:

No orders issued. See detailed narrative.

Detailed Narrative:

This field visit is a follow up to the previous visits conducted by the Ministry of Labour, Immigration, Training and Skills Development (MLITSD).

During the visit, following areas were observed:

- front area of the school for the repairs done to the asphalt around the catch basin.
- wooden stairs leading to the portables have been replaced with new wooden stairs.
- bleachers have been fenced off from the top and bottom, however the access from the stairs is still available. The employer representative agreed to suitably barricade the bleachers from the sides (from stairs to bleachers) as well.
- A couple of handrails are yet to be installed.

The following STOP work orders have been withdrawn:

- 4548DKWBMD5-4548-OR002
- 4548DKWBMD5-4548-OR006

The following orders have been complied with:

- 4548DKWBMD5-4548-OR003
- 4548DKWBMD5-4548-OR004
- 4548DKWBMD5-4548-OR007
- 4548DKWBMD5-4548-OR008

It was indicated by the employer representative that the couple of handrails have yet to be installed and they agreed to suitably barricade the stairs where are handrails are not installed. The other stairs with installed handrails are suitable for use.

=====NOTE=====

- NOT ALL AREAS OF THE WORKPLACE WERE INSPECTED DURING THE VISIT.
- A COPY OF THIS REPORT SHALL BE POSTED IN THE WORKPLACE.

Recipient	Inspector Data	Worker Representative
Name _____	Rajneesh Paul O.H.S.A. & B.O.S.T.A INSPECTOR PROVINCIAL OFFENCES OFFICER	Name _____
Title _____	1600-5001 Yonge St, North York ON M7A 0A3 MOLCOMPLIANCEIHSTORW@ontario.ca Tel: (365) 366-5168 Fax: (647) 777-5013	Title _____
Signature _____	Signature _____	Signature _____

You are required under the Occupational Health and Safety Act to post a copy of this report in a conspicuous place at the workplace and provide a copy to the health and safety representative or the joint health and safety committee if any. Failure to comply with an order, decision or requirement of an inspector is an offence under Section 66 of the Occupational Health and Safety Act. You have the right to appeal any order or decision within 30 days of the date of the order issued and to request suspension of the order or decision by filing your appeal and request in writing on the appropriate forms with the Ontario Labour Relations Board, 505 University Ave., 2nd Floor, Toronto, Ontario M5G 2P1. You may also contact the Board by phone at (416) 326-7500 or 1-877-339-3335 (toll free), mail or by website at <http://www.olrb.gov.on.ca/> for more information.

The Government of Ontario wants to hear from you. You can provide feedback on this visit at 1-888-745-8888