

Material Test Report

Report Number: 7555/1-2
Issue Number: 3 - This version supersedes all previous issues
Reissue Reason: updated
Date Issued: 21/01/2025
Client: DIXON SAND (PENRITH) PTY LTD
, PENRITH NSW 2751
Contact: Michael Munnoch
Project Number: 7555/1
Project Name: MATERIAL ANALYSIS MATERIAL TESTING - 4610 OLD
NORTHERN ROAD, MAROOTA
Work Request: 144
Sample Number: S-144D
Date Sampled: 13/01/2025
Dates Tested: 13/01/2025 - 14/01/2025
Sampling Method: AS 1141.3.1 8.4.3 - Sampling from the sides of the stockpile
Preparation Method: AS 1289.1.1 - Sampling and Preparation of Soils
Site Selection: Selected by Client
Material: December Medium Washed

GEOTECH
TESTING PTY LTD
ABN 71 076 676 321

Geotech Testing Pty Ltd
Penrith Laboratory
34 Borec Road Penrith NSW 2750
Phone: (02) 4722 2744
Email: matthew@geotech.com.au



Accredited for compliance with ISO/IEC 17025 - Testing

Approved Signatory: Mathew Morley
Laboratory Manager
NATA Accredited Laboratory Number: 2734

Particle Size Distribution (AS1141.11.1)			
Sample Washing	Sample was Washed		
Sieve	Passed %	Passing Limits	
19 mm	100		
13.2 mm	100		
4.75 mm	100		
2.36 mm	100		
1.18 mm	99		
0.6 mm	84		
0.425 mm	55		
0.3 mm	31		
0.15 mm	7		
0.075 mm	3		

