Material Test Report

Report Number: 7555/1-2

Issue Number: 3 - This version supersedes all previous issues

Reissue Reason: updated

Date Issued: 21/01/2025

Client: DIXON SAND (PENRITH) PTY LTD

, PENRITH NSW 2751

Contact: Michael Munnoch

Project Number: 7555/1

Report Number: 7555/1-2

Project Name: MATERIAL ANALYSIS MATERIAL TESTING - 4610 OLD

NORTHERN ROAD, MAROOTA

Work Request: 144
Sample Number: S-144E
Date Sampled: 13/01/2025

Dates Tested: 13/01/2025 - 14/01/2025

Sampling Method: AS 1141.3.1 8.4.3 - Sampling from the sides of the stockpile

Preparation Method: AS 1289.1.1 - Sampling and Preparation of Soils

Site Selection: Selected by Client Material: December Coarse

Particle Size Distribution (AS1141.11.1)		
Sample Washing	Sample was Washed	
Sieve	Passed %	Passing Limits
19 mm	100	
13.2 mm	100	
4.75 mm	100	
2.36 mm	91	
1.18 mm	76	
0.6 mm	49	
0.425 mm	24	
0.3 mm	10	
0.15 mm	1	
0.075 mm	0	



TESTING PTY LTD
ABN 71 076 676 321

Geotech Testing Pty Ltd Penrith Laboratory 34 Borec Road Penrith NSW 2750

Phone: (02) 4722 2744 Email: matthew@geotech.com.au

Accredited for compliance with ISO/IEC 17025 - Testing

WORLD RECOGNISED
ACCREDITATION

Approved Signatory: Mathew Morley

Laboratory Manager

NATA Accredited Laboratory Number: 2734

